

Thilawa Special Economic
Zone (Zone B) Development

Environmental Monitoring Report Phase-1,2 and 3 (Operation Phase)



Myanmar Japan Thilawa
Development Limited.

March 2022



CONTENTS

1. Executive Summary
2. Summary of Monitoring Activities
3. Monitoring Results
4. Environmental Monitoring Form

Appendix

- A. Water and Waste Water Monitoring Report for October, 2021
- B. Water and Waste Water Monitoring Report for December, 2021
- C. Air Monitoring Report for December, 2021
- D. Noise and Vibration Monitoring Report for December, 2021
- E. Traffic Volume Monitoring Report for December, 2021
- F. General Waste Disposal Record (September 2021 to March 2022)
- G. Sewage Treatment Monitoring Record (September 2021 to March 2022)



1. Executive Summary

The environmental inspection and compliance monitoring program will be implemented under the direction of Ministry of Natural Resources and Environmental Conservation (MONREC) with oversight by Thilawa SEZ Management Committee.

The monitoring record from September 2021 to March 2022 according to the Environment Monitoring Plan is submitted in conformity with the provision of Chapter 10, 10.1 Table 10.1-3 and 10.2, Table 10.2-3 Content of the EIA Report of Thilawa SEZ Development Project (Zone B).

2. Summary of Monitoring Activities

- a) **Progress made to date on the implementation of the EMP against the submitted implementation schedule;**

We submitted EMP for TSEZ Zone-B as following table.

Report No.	Description	Phase	Submission
1	Environmental Monitoring Report	Phase-1 Operation Phase	September, 2019
2	Environmental Monitoring Report	Phase-1 & 2 Operation Phase	March, 2020
3	Environmental Monitoring Report	Phase-1 & 2 Operation Phase	September, 2020
4	Environmental Monitoring Report	Phase-1 & 2 Operation Phase	March, 2021
5	Environmental Monitoring Report	Phase-1,2 & 3 Operation Phase	September, 2021
6	Environmental Monitoring Report	Phase-1,2 & 3 Operation Phase	March, 2022

Report (No.6) is submitted this day attached with Operation Phase implementation schedule. Subsequent Operation Phase reports will be submitted on Bi-annually.

- b) **Difficulties encountered in implementing of the EMP and recommendations for remedying those difficulties and steps proposed to prevent or avoid similar future difficulties;**

None

- c) **Number and type of non-compliance with the EMP and proposed remedial measures and timelines for completion of remediation;**

- Depend on the exceeding parameters and situation

- d) **Accidents or incidents relating to the occupational and community health and safety, and the environment;**

Please refer to the attached Environmental Monitoring Form.

- e) **Monitoring data on environmental parameters and conditions as committed in the EMP or otherwise required.**

Please refer to the attached Environmental Monitoring Form.



3. Monitoring Result

Environmental Monitoring Plan report for operation phase implemented according to the following table, reference on Table 10.2-3, Chapter 10, EIA for Industrial Area of Zone-B.

Monitoring Plan (Operation Phase)

Category	Item	Location	Frequency	Remark
Air Quality	NO _x , SO _x , CO, PM ₁₀ , PM _{2.5}	Representative point inside the project area	1 week each in the dry and rainy seasons	December 2021: Air Quality Monitoring Report
Water Quality	Water temperature, pH, SS, DO, BOD ₅ , COD, color and odor, Total Nitrogen, Total Phosphorus, Sulphide, HCN, Oil, Grease, Formaldehyde, Phenols, Free chlorine, Zinc, Chromium, Arsenic, Copper, Mercury, Cadmium, Barium, Selenium, Lead, and Nickel	Outflow of retention pond to the creek (at least 3 sampling points/mixing point: discharge water, upstream water, and downstream water)	Every 2 month: Water temperature, pH, SS, DO, BOD ₅ , COD, color and odor, Every 6 month: all parameters	October 2021 Water and Wastewater Quality Monitoring Report (Bi-monthly report) December 2021 Water and Wastewater Quality Monitoring Report (Bi-annually report)
Waste	-Amount of Non-hazardous waste management -Amount of hazardous waste management	Each Tenant	Twice/year (Submission of the environmental report by the tenants)	General waste disposal record
Soil Contamination	-Status of control of solid and liquid waste which causes soil contamination	Each Tenant	Twice/year (Submission of the environmental report by the tenants)	Monitoring will be started when the whole Zone-B is in Operation Stage
Noise and Vibration	-Noise and vibration level -Traffic Count	Tenants including Project Proponent	One time each in the dry and rainy seasons	Noise and Vibration Monitoring Report December 2021 Traffic Count Monitoring Report December 2021
Bottom Sediment	-Water quality monitoring (as indicator of the pollution of the bottom sediment)	Same as the water quality monitoring	-Additional analysis on the bottom sediment of creek, in case of finding continuous high concentration	Refer in Environmental Monitoring report
Hydrological Situation	-Checking the function of retention pond at heavy rain	Retention Pond	When the heavy rain	
Living and Livelihood/ Vulnerable Group/ Misdistribution of Benefit and Damage/ Children's Right	-The implementation status for CSR activities such as community support program	Around Project Site	Once/year	Refer in Environmental Monitoring report
Risks for Infectious Disease such as AIDS/HIV	-Status of measure against infectious diseases	Each tenant	Twice/year (Submission of the environmental report by the tenants)	
Occupational Health and Safety	-Record of accident and infectious diseases	Work site and office	Twice/year (Submission of the environmental report by the tenants)	Refer in Environmental Monitoring form
Community Health and Safety	Record of accidents and infectious diseases related to the community	Around the project site	Twice/year	Refer in Environmental Monitoring form
	The implementation status for CSR activities such as community support program	Around project site	Once/year	Refer in Environmental Monitoring form



Category	Item	Location	Frequency	Remark
Usage of Chemicals	Record of the type and quantity of chemicals and implementation status of control measures through self inspection.	Each tenant (that uses chemicals).	Biannually	-

*Remark: Each locator will report their monitoring result directly to Environmental Section, One Stop Service Center, Thilawa SEZ Management Committee.



Thilawa Special Economic Zone
Zone B- Phase 1,2 & 3 (Operation phase)

Environment Monitoring Form

Environment Monitoring Form

The latest results of the below monitoring items shall be submitted to Authorities on once at Pre -Construction Phase and on quarterly basis at Construction Phase, and on bi-annually base at Operation Phase. The items, standards to be applied, measurement points, and frequency for each monitoring parameter are established based on the EIA Report for Thilawa Special Economic Zone Development Project (Industrial Area of Zone B). Should there be any changes to the original plan, such change shall be reviewed and evaluated by environmental expert.

(1) General

1) Phase of the Project

- Please mark the current phase.

☐ Pre-Construction Phase

☐ Construction Phase

☒ Operation Phase

2) Obtainment of Environmental Permits

Name of permits	Expected issuance date	Actual issuance date	Concerned authority	Remarks (Conditions, etc.)
Approved letter for Environmental Impact Assessment (EIA) Report of Industrial Area, Thilawa Special Economic Zone (Zone-B)		29 th December 2016	Thilawa SEZ Management Committee	
Notification of the comments of Ministry of Natural Resources and Environmental Conservation regarding with the Standard Change of Wastewater Quality of Industrial Zone, Internal Regulations of Thilawa SEZ Zone-A and Zone-B	5 th January 2018	10 th January 2018	Thilawa SEZ Management Committee	

3) Response/Actions to Comments and Guidance from Government Authorities and the Public

Monitoring Item	Monitoring Results during Report Period	Duration of Report Period	Frequency
Number and contents of formal comments made by the public			Upon receipt of comments/ complaints
Number and contents of responses from Government agencies			

(2) Monitoring Results

1) Ambient Air Quality (December 2021)

NO_2 , SO_2 , CO , $\text{PM}_{2.5}$, PM_{10}

Location	Item	Unit	Measured Value (Mean)	Measured Value (Max)	Country's Standard	Target value to be applied*1	Referred International Standard	Frequency	Method	Note (Reason of excess of the standard)
AQ-1	NO_2	mg/m^3	0.083	0.177	0.2 mg/m^3 (1 Hour)	0.1 mg/m^3 (24 Hour)	-	One time / 6 months	Haz-Scanner EPAS	Refer to air quality report
	SO_2	mg/m^3	0.020	0.084	0.02 mg/m^3 (24 Hours)	0.02 mg/m^3 (24 Hours)	-			
	CO	mg/m^3	0.132	2.228	-	10.26 mg/m^3 (24 Hours)	-			
	$\text{PM}_{2.5}$ **	mg/m^3	0.035	0.119	0.025 mg/m^3 (24 Hours)	0.025 mg/m^3 (24 Hours)	-			
	PM_{10}	mg/m^3	0.043	0.143	0.05 mg/m^3 (24 Hours)	0.05 mg/m^3 (24 Hours)	-			

*1Remarks: Referred to the tentative target value of ambient air quality (EIA Report for industrial area, Table 2.4-1), Reference to the air quality monitoring report (December 2021)

*2 Remark: $\text{PM}_{2.5}$ exceeded due to affected from natural origin such as dust from unpaved land area form outside of Zone-B and Transportation in and around the monitoring



AP085

Complaints from Residents

- Are there any complaints from residents regarding air quality in this monitoring period? ☐ Yes ☒ No

If yes, please describe the contents of complains and its countermeasures to fill in below the table.

Contents of Complaints from Residents	Countermeasures

2) (a) Water Quality - October 2021

Measurement Point: Effluent of Wastewater (SW-2 and SW-4 are attached as reference point only and they are natural creek water which are combine all the wastewater from the Local industrial water and domestic water from existing living environment. SW-7 is the main discharging point. GW-2 is also as reference point for monitoring of existing tube well located in the Monastery Compound near Zone-B area)

- Are there any effluents to water body in this monitoring period? ☐ Yes, ☒ No

If yes, please attach "Analysis Record" and fill in the items not to comply with Referenced International Standard

Location	Item	Unit	Measured Value (Max)	Country's Standard ²	Target value to be applied ¹	Frequency	Method	Note (Reason of excess of the standard)
SW-2 (Reference point)	Temperature	°C	26	< 3 (increase)	≤ 35	Once per 2 months	Instrument Analysis Method	Refer to water quality report
	pH	-	8.8	6-9	6.0 - 9.0		Instrument Analysis Method	
	SS	mg/L	50	50	50		APHA 2540 (Dry at 105-107°C Method)	
	DO	mg/L	2.57	-	-		Instrument Analysis Method	
	BOD ₅	mg/L	10.45	50	30		APHA 5210 B (5days BOD Test)	
	COD _{Cr}	mg/L	12.8	250	125		APHA 5220 D (Close Reflux Colorimetric Method)	
	Total Coliform ³	MPN/100	>160,000	400	600		APHA 9221 B (Standard Total Coliform Fermentation	



Location	Item	Unit	Measured Value (Max)	Country's Standard ²	Target value to be applied ¹	Frequency	Method	Note (Reason of excess of the standard)
SW-2 (Reference point)	Oil and Grease	ml	<3.1	10	10		Technique)	
	Total Dissolved solids (TDS) %	mg/L	118	-	2000		APHA 5520 B (partition Gravimetric Method) APHA 2540C (Total Dissolved Solids Dried at 180°C)	
	Iron ³⁺	mg/L	3.84	3.5	3.5		APHA 3120 B (Inductively Coupled Plasma (ICP) Method)	
	Mercury ³⁺	mg/L	≤ 0.002	0.01	0.005		APHA 3120 B (Inductively Coupled Plasma (ICP) Method)	
SW-4 (Reference point)	Temperature	°C	26	< 3 (increase)	≤ 35	Once per 2 months	Instrument Analysis Method	Refer to water quality report
	pH	-	7.3	6-9	6.0 - 9.0		Instrument Analysis Method	
	SS ²	mg/L	302	50	50		APHA 2540D (Dry at 103-105°C Method)	
	DO	mg/L	4.35	-	-		Instrument Analysis Method	
	BOD ₅	mg/L	3.58	50	30		APHA 5210 B (5days BOD Test)	
	COD _{Cr}	mg/L	4.1	250	125		APHA 5220 D (Close Reflux Colorimetric Method)	
	Total Coliform ³	MPN/100 ml	160,000	400	400		APHA 9221 B (Standard Total Coliform Fermentation Technique)	
	Oil and Grease	mg/L	<3.1	10	10		APHA 5520 B (partition Gravimetric Method)	
	Total Dissolved solids (TDS) %	mg/L	182	-	2000		APHA 2540C (Total Dissolved Solids Dried at 180°C)	
	Iron ³⁺	mg/L	12.628	3.5	3.5		APHA 3120 B (Inductively Coupled Plasma (ICP) Method)	
	Mercury ³⁺	mg/L	≤ 0.002	0.01	0.005		APHA 3120 B (Inductively Coupled Plasma (ICP) Method)	
SW-7 (Discharge d Point)	Temperature	°C	27	< 3 (increase)	≤ 35	Once per 2 months	Instrument Analysis Method	Refer to water quality report
	pH	-	7.2	6-9	6.0 - 9.0		Instrument Analysis Method	
	SS ²	mg/L	170	50	50		APHA 2540D (Dry at 103-105°C Method)	
	DO	mg/L	4.51	-	-		Instrument Analysis Method	
	BOD ₅	mg/L	4.60	50	30		APHA 5210 B (5days BOD Test)	
	COD _{Cr}	mg/L	5.6	250	125		APHA 5220 D (Close Reflux Colorimetric Method)	
	Total Coliform ³	MPN/100 ml	160,000	400	400		APHA 9221 B (Standard Total Coliform Fermentation Technique)	
	Oil and Grease	mg/L	<3.1	10	10		APHA 5520 B (partition Gravimetric Method)	



Location	Item	Unit	Measured Value (Max)	Country's Standard ²	Target value to be applied ¹	Frequency	Method	Note (Reason of excess of the standard)
	Total Dissolved solids (TDS) ³	mg/L	0.540	-	2000		APHA 2540C (Total Dissolved Solids Dried at 180°C)	
	Iron ⁴	mg/L	≤0.002	3.5	3.5		APHA 3120 B (Inductively Coupled Plasma (ICP) Method)	
	Mercury ⁵	mg/L		0.01	0.005		APHA 3120 B (Inductively Coupled Plasma (ICP) Method)	
GW-2 (reference point)	Temperature	°C	26	< 3 (increase)	≤ 35	Once per 2 months	Instrument Analysis Method	Refer to water quality report
	pH	-	7.0	6-9	6.0 - 9.0		Instrument Analysis Method	
	SS	mg/L	10	50	50		APHA 2540D (Dry at 103-105°C Method)	
	DO	mg/L	5.69	-	-		Instrument Analysis Method	
	BOD ₅	mg/L	4.99	50	30		APHA 5210 B (5days BOD Test)	
	COD _{Cr}	mg/L	18.8	250	125		APHA 5220 D (Close Reflux Colorimetric Method)	
	Total Coliform	MPN/100 ml	79	400	400		APHA 9221 B (Standard Total Coliform Fermentation Technique)	
	Oil and Grease	mg/L	<3.1	10	10			
	Total Dissolved solids (TDS) ³	mg/L	180	-	2000		APHA 5520 B (partition Gravimetric Method)	
	Iron ⁴	mg/L	8.31	3.5	3.5		APHA 3120 B (Inductively Coupled Plasma (ICP) Method)	
	Mercury ⁵	mg/L	≤ 0.002	0.01	0.005		APHA 3120 B (Inductively Coupled Plasma (ICP) Method)	

¹Remark: Reference to the Water and Wastewater Quality Monitoring Report (October 2021)

²Remark: Referred to the National Emission Quality Guideline (NEQG) 29th December 2015

³Remark: SS result exceeded in the monitoring point of SW-4 than the target value due to expected reasons i) delivered from upstream area such as natural origin and wastewater from local industrial zone outside of Thilawa SEZ, and ii) influence by water from the downstream of monitoring point due to flow back by tidal fluctuation.

⁴Remark: For the monitoring point of SW2, SW4 the result of total coliform exceeded than the target value due to expected reasons i) natural bacteria existed in discharged creek because there are various kinds of vegetation of creature such as birds, and small animals in and along the discharged creek ii) wastewater from the local industrial zone outside of Thilawa SEZ and iii) delivered from surrounding area by tidal effect.

⁵Remark: For the monitoring points of SW-2 and SW-4, the result of iron exceeded due to expected reason i) due to influence of natural origin (iron can reach out from

soil by run-off).

* Remark: Recommendation from JICA Environmental expert (TSMC), to be more emphasized on Environmental and analyzing only.

* Remark: For the monitoring point of SW-7, the results of SS exceeded due to expected reason i) due to surface water runoff Zone-B.

* Remark: For the monitoring point of SW-7, the results of Total Coliform exceeded due to i) natural bacteria existed in all area of Zone B because there are various kinds of vegetation and creature such as birds, and small animals in and along the retention pond. Total coliforms do not affect human health directly, self-monitoring was carried out to identify health impact by coliform bacteria. As for the result of E-Coli SW-7 was 4. It is considered that there is no significant impact to human health.

* Remark: For the monitoring point of GW-2, the results of iron exceeded due to expected reason i) may be due to the influence of natural origin (iron can reach out from soil by run-off). In Yangon, soil is naturally rich in iron.

2) (b) Water Quality - December 2021

Measurement Point: Effluent of Wastewater (SW-2 and SW-4 are attached as reference point only and they are natural creek water which are combine all the wastewater from the Local industrial water and domestic water from existing living environment. SW-7 is the main discharging point. GW-2 is also as reference point for monitoring of existing tube well located in the Monastery Compound near Zone-B area).

- Are there any effluents to water body in this monitoring period?

☐ Yes, ☒ No



If yes, please attach "Analysis Record" and fill in the items not to comply with Refereed International Standard.

Location	Item	Unit	Measured Value (Max)	Country's Standard ²⁾	Target value to be applied ¹⁾	Frequency	Method	Note (Reason of excess of the standard)
SW-2 (Reference point)	Temperature	°C	19	< 3 (increase)	≤ 35	Once per 6 months	Instrument Analysis Method	Refer to water quality report.
	pH	-	7.2	6-9	6-9		Instrument Analysis Method	
	SS ³⁾	mg/L	78	50	Max 50		APHA 2540 D Method	
	DO	mg/L	3.36	-	-		Instrument Analysis Method	
	BOD (5)	mg/L	7.99	50	Max 30		APHA 5210 B Method	
	COD (Cr)	mg/L	30.9	250	Max 125		APHA 5220 D Method	
	Total Coliform ⁴⁾	MPN/100 ml	92000	400	Max 400		APHA 9221B Method	
	T-N	mg/L	7	-	Max 80		HACH Method 10072 Method	
	T-P	mg/L	-	2	Max 2		APHA 4500-TP E Method	
	Color	TCU	17.06	-	Max 150		APHA 2120C Method	

Location	Item	Unit	Measured Value (Max)	Country's Standard ²	Target value to be applied ¹	Frequency	Method	Note (Reason of excess of the standard)
SW-2 (Reference point)	Odor	TCN	1	-	-	Once per 6 months	APHA 2150 B Method	
	Oil and Grease	mg/L	<3.1	10	Max 10		APHA 5530B Method	
	Mercury	mg/L	≤ 0.002	0.01	Max 0.005		APHA 3120 B Method	
	Zinc	mg/L	0.026	2	Max 2		APHA 3120 B Method	
	Arsenic	mg/L	≤ 0.010	0.1	Max 0.1		APHA 3120 B Method	
	Chromium	mg/L	≤ 0.002	0.5	Max 0.5		APHA 3120 B Method	
	Cadmium	mg/L	≤ 0.002	0.1	Max 0.05		APHA 3120 B Method	
	Selenium	mg/L	≤ 0.010	0.1	Max 0.02		APHA 3120 B Method	
	Lead	mg/L	≤ 0.002	0.1	Max 0.1		APHA 3120 B Method	
	Copper	mg/L	≤ 0.002	0.5	Max 0.5		APHA 3120 B Method	
	Barium	mg/L	0.062	-	Max 1		APHA 3120 B Method	
	Nickel	mg/L	≤ 0.002	0.5	Max 0.2		APHA 3120 B Method	
	Cyanide	mg/L	< 0.002	0.1	Max 0.1		HACH 8007 Method	
	Total Cyanide	mg/L	0.006	1	Max 1		APHA 4500-CN-C Method	
	Free Chlorine	mg/L	0.1	-	Max 1		APHA 4500-CL-G Method	
	Sulphide (S ²⁻)	mg/L	0.068	1	Max 1		HACH 8131 Method	
	Formaldehyde	mg/L	0.015	-	Max 1		HACH 8130 Method	
	Phenols	mg/L	0.007	0.5	Max 0.5		USEPA Method 420.1	
	Iron	mg/L	1.632	3.5	Max 3.5		APHA 3120 B Method	
	Total Dissolved Solids	mg/L	1026	-	Max 2000		APHA 2540 C Method	
	Total Residual Chlorine	mg/L	0.2	0.2	Max 0.2		APHA 4500-CL-G Method	
	Chromium (Hexavalent)	mg/L	< 0.05	0.1	Max 0.1		ISO 11883:1994 Method	
	Ammonia	mg/L	2.03	10	Max 10		HACH Method 10205 Method	
	Fluoride	mg/L	0.154	20	Max 20		APHA 4110 B Method	
	Silver	mg/L	≤ 0.002	0.5	Max 0.5		APHA 3120 B Method	
SW-4 (Reference point)	Temperature	°C	21	< 3 (increase)	≤ 35	Once per 6 months	Instrument Analysis Method	Refer to quality report
	pH	-	7.2	6-9	6-9		Instrument Analysis Method	
	SS ²	mg/L	194	50	Max 50		APHA 2540 D Method	
	DO	mg/L	4.66	-	-		Instrument Analysis Method	
	BOD (5)	mg/L	3.42	50	Max 30		APHA 5210 B Method	
	COD (Cr)	mg/L	19.8	250	Max 125		APHA 5220 D Method	
	Total Coliform ²	MPN/100	>160000	400	Max 400		APHA 9221B Method	

Location	Item	Unit	Measured Value (Max)	Country's Standard ²⁾	Target value to be applied ¹⁾	Frequency	Method	Note (Reason of excess of the standard)
SW-4 (Reference point)	T-N	mg/L	6.4	-	Max 80	Once per 6 months	HACH Method 10072 Method APHA 4500-FE Method APHA 2120C Method APHA 2150 B Method APHA 5520B Method APHA 3120 B Method APHA 3120 B Method APHA 3120 B Method APHA 3120 B Method APHA 3120 B Method APHA 3120 B Method APHA 3120 B Method APHA 3120 B Method APHA 3120 B Method APHA 3120 B Method APHA 3120 B Method HACH 8007 Method APHA 4500-CN-C Method APHA 4500-CL-G Method HACH 8131 Method HACH 8110 Method USEPA Method 420.1 APHA 3120 B Method APHA 2540 C Method APHA 4500-CL-G Method ISO 11063:1994 Method HACH Method 10205 Method APHA 4110 B Method APHA 3120 B Method	
	T-P	mg/L	-	2	Max 2			
	Color	TCU	7.86	-	Max 150			
	Odor	TON	1	-	-			
	Oil and Grease	mg/L	< 3.1	10	Max 10			
	Mercury	mg/L	≤ 0.002	0.01	Max 0.005			
	Zinc	mg/L	0.060	2	Max 2			
	Arsenic	mg/L	≤ 0.010	0.1	Max 0.1			
	Chromium	mg/L	≤ 0.002	0.5	Max 0.5			
	Cadmium	mg/L	≤ 0.002	0.1	Max 0.03			
	Selenium	mg/L	≤ 0.01	0.1	Max 0.02			
	Lead	mg/L	≤ 0.002	0.1	Max 0.1			
	Copper	mg/L	≤ 0.002	0.5	Max 0.5			
	Barium	mg/L	0.020	-	Max 1			
	Nickel	mg/L	≤ 0.002	0.5	Max 0.2			
	Cyanide	mg/L	0.002	0.1	Max 0.1			
	Total Cyanide	mg/L	0.015	1	Max 1			
	Free Chlorine	mg/L	< 0.1	-	Max 1			
	Sulphide (S ²⁻)	mg/L	0.377	1	Max 1			
	Formaldehyde	mg/L	0.072	-	Max 1			
	Phenols	mg/L	0.002	0.5	Max 0.5			
	Iron ⁵⁾	mg/L	6.884	3.5	Max 3.5			
	Total Dissolved Solids	mg/L	624	-	Max 2000			
	Total Residual Chlorine	mg/L	0.1	0.2	Max 0.2			
	Chromium (Hexavalent)	mg/L	< 0.05	0.1	Max 0.1			
	Ammonia	mg/L	1.44	10	Max 10			
	Fluoride	mg/L	1.325	20	Max 20			
	Silver	mg/L	≤ 0.002	0.5	Max 0.5			
	Temperature	°C	21	< 3 (increase)	≤ 35	Once per 6 months	Instrument Analysis Method	Refer to quality report
	pH	-	8	6-9	6-9		Instrument Analysis Method	

Location	Item	Unit	Measured Value (Max)	Country's Standard ²	Target value to be applied ¹	Frequency	Method	Note (Reason of excess of the standard)
SW-7 (Discharge point)	SS ⁷	mg/L	58	50	Max 50		APHA 2540-D Method	
	DO	mg/L	6.31	-	-		Instrument Analysis Method	
	BOD (5)	mg/L	6.26	50	Max 30		APHA 5210-B Method	
	COD (Cr)	mg/L	13.6	250	Max 125		APHA 5220-D Method	
	Total Coliform ⁸	MPN/100 ml	1600	400	Max 400		APHA 9221H Method	
	T-N	mg/L	7.1	-	Max 80			
	T-P	mg/L	-	2	Max 2		HACH Method 10072 Method	
							APHA 4500-P E Method	
	Color	TCU	4.31	-	Max 150			
	Odor	TCN	1	-	-			
	Oil and Grease	mg/L	<3.1	10	Max 50		APHA 2120C Method	
	Mercury	mg/L	≤0.002	0.01	Max 0.005		APHA 2150 B Method	
	Zinc	mg/L	0.006	2	Max 2		APHA 5520B Method	
	Arsenic	mg/L	≤0.010	0.1	Max 0.1		APHA 3120-B Method	
	Chromium	mg/L	≤0.002	0.3	Max 0.3		APHA 3120-B Method	
	Cadmium	mg/L	≤0.002	0.1	Max 0.03		APHA 3120-B Method	
	Selenium	mg/L	≤0.010	0.1	Max 0.02		APHA 3120-B Method	
	Lead	mg/L	≤0.002	0.1	Max 0.1		APHA 3120-B Method	
	Copper	mg/L	≤0.002	0.5	Max 0.5		APHA 3120-B Method	
	Barium	mg/L	0.018	-	Max 1		APHA 3120-B Method	
	Nickel	mg/L	≤0.002	0.3	Max 0.2		APHA 3120-B Method	
	Cyanide	mg/L	<0.002	0.1	Max 0.1		HACH 8127 Method	
	Total Cyanide	mg/L	0.003	1	Max 1		APHA 4500-CN-C Method	
	Free Chlorine	mg/L	<0.1	-	Max 1		APHA 4500-CL G Method	
	Sulphide (S ²⁻)	mg/L	0.054	1	Max 1		HACH 8131 Method	
	Formaldehyde	mg/L	0.019	-	Max 1		HACH 8110 Method	
	Phenols	mg/L	0.004	0.5	Max 0.5		USEPA Method 421.1	
	Iron	mg/L	1.5	3.5	Max 3.5		APHA 3120-B Method	
	Total Dissolved Solids	mg/L	1006	-	Max 2000		APHA 2540 C Method	
	Total Residual Chlorine	mg/L	0.1	0.2	Max 0.2		APHA 4500-CL G Method	
	Chromium (Hexavalent)	mg/L	<0.05	0.1	Max 0.1		ISO 11085:1994 Method	

Location	Item	Unit	Measured Value (Max)	Country's Standard ²	Target value to be applied ¹	Frequency	Method	Note (Reason of excess of the standard)
	Ammonia	mg/L	0.11	10	Max 10		HACH Method 10205 Method	
	Fluoride	mg/L	0.124	20	Max 20		APHA 4110 B Method	
	Silver	mg/L	≤ 0.002	0.5	Max 0.5		APHA 3120 B Method	
GW-2 (Reference point)	Temperature	°C	24	< 3 (increase)	≤ 35	Once per 6 months	Instrument Analysis Method	
	pH	-	6.9	6-9	6-9		Instrument Analysis Method	
	SS	mg/L	4	50	Max 50		APHA 2540 D Method	
	DO	mg/L	7.13	-	-		Instrument Analysis Method	
	BOD (5)	mg/L	6.82	50	Max 30		APHA 5210 B Method	
	COD (Cr)	mg/L	< 0.7	250	Max 125		APHA 5220 D Method	
	Total Coliform	MPN/100 ml	7.8	400	Max 400		APHA 9221 B Method	
	T-N	mg/L	0.8	-	Max 80		HACH Method 10072 Method	
	T-P	mg/L	-	2	Max 2		APHA 4500-P E Method	
	Color	TCU	42.34	-	Max 150		APHA 2130 C Method	
	Odor	TON	1	-	-		APHA 2130 B Method	
	Oil and Grease	mg/L	< 3.1	10	Max 10		APHA 5520 B Method	
	Mercury	mg/L	≤ 0.002	0.01	Max 0.005		APHA 3120 B Method	
	Zinc	mg/L	0.008	2	Max 2		APHA 3120 B Method	
	Arsenic	mg/L	≤ 0.010	0.1	Max 0.1		APHA 3120 B Method	
	Chromium	mg/L	≤ 0.002	0.5	Max 0.5		APHA 3120 B Method	
	Cadmium	mg/L	≤ 0.002	0.1	Max 0.05		APHA 3120 B Method	
	Selenium	mg/L	≤ 0.010	0.1	Max 0.02		APHA 3120 B Method	
	Lead	mg/L	≤ 0.002	0.1	Max 0.1		APHA 3120 B Method	
	Copper	mg/L	≤ 0.002	0.5	Max 0.5		APHA 3120 B Method	
	Barium	mg/L	0.006	-	Max 1		APHA 3120 B Method	
	Nickel	mg/L	≤ 0.002	0.5	Max 0.2		APHA 3120 B Method	
	Cyanide	mg/L	< 0.002	0.1	Max 0.1		APHA 3120 B Method	
	Total Cyanide	mg/L	0.003	1	Max 1		HACH 8027 Method	
	Free Chlorine	mg/L	< 0.1	-	Max 1		APHA 4500-CN-C Method	
	Sulphide (S ²⁻)	mg/L	0.006	1	Max 1		APHA 4500-CL-G Method	
	Formaldehyde	mg/L	0.005	-	Max 1		HACH 8131 Method	
	Phenols	mg/L	0.004	0.5	Max 0.5		HACH 8110 Method	
	Iron ³⁺	mg/L	3.566	3.5	Max 3.5		USEPA Method 4201	
	Total Dissolved	mg/L	152	-	Max 2000		APHA 3120 B Method	
							APHA 2540 C Method	

Location	Item	Unit	Measured Value (Max)	Country's Standard ²⁾	Target value to be applied ¹⁾	Frequency	Method	Note (Reason of excess of the standard)
GW-2 (Reference point)	Solids- Total Residual	mg/L	< 0.1	0.2	Max 0.2		APHA 4500-CL.G Method	
	Chlorine	mg/L	< 0.05	0.1	Max 0.1		ISO 11081:1994 Method	
	Chromium (Hexavalent)	mg/L	0.22	10	Max 10		HACH Method 10205 Method	
	Ammonia	mg/L	0.014	20	Max 20		APHA 4110 B Method	
	Fluoride	mg/L	≤ 0.002	0.5	Max 0.5		APHA 3120 B Method	
	Silver	mg/L						

¹⁾Remark: Reference to the Water and Wastewater Quality Monitoring Report (December 2021)

²⁾Remark: Referred to the National Emission Quality Guideline (NEQG) 29th December 2015

³⁾Remark: SS result exceeded in the monitoring point of SW-2, SW-4 than the target value due to expected reasons i) delivered from upstream area such as natural origin and wastewater from local industrial zone outside of Thilawa SEZ, and ii) influence by water from the downstream of monitoring point due to flow back by tidal fluctuation.

⁴⁾Remark: For the monitoring point of SW2, SW4 the result of total coliform exceeded than the target value due to expected reasons i) natural bacteria existed in discharged creek because there are various kinds of vegetation of creature such as birds, and small animals in and along the discharged creek ii) wastewater from the local industrial zone outside of Thilawa SEZ and iii) delivered from surrounding area by tidal effect.

⁵⁾Remark: For the monitoring point of SW-4, the result of iron exceeded due to expected reason i) due to influence of natural origin iron can reach out from the soil by run-off. Japan Standard for living environment for iron is 10mg/L.

⁶⁾Remark: The result of iron at the monitoring point of reference tube well (GW-2) exceeded the target value. Comparison with previous monitoring results of reference tube well (GW-2), the iron concentration results ranged from 3.07 mg/l (August, 2019) - 8.310 mg/l (October, 2021) and most of the iron concentration measured results (from April 2019 to December, 2021) exceeded the target value except the iron concentration result of August, 2019. Therefore, the possible reasons may due to the influence of natural

origin (iron can reach out from soil by run-off). In Yangon, soil is naturally rich in iron.

* Remark: For the monitoring point of SW-7, the results of SS exceeded due to expected reason i) due to surface water runoff Zone-B.

* Remark: For the monitoring point of SW-7, the results of Total Coliform exceeded due to i) natural bacteria existed in all area of Zone B because there are various kinds of vegetation and creature such as birds, and small animals in and along the retention pond. Total coliforms do not affect human health directly, self-monitoring was carried out to identify health impact by coliform bacteria. As for the result of E-Coli SW-7 was 4.5. It is considered that there is no significant impact to human health.

3) Soil Contamination (only operation phase)

Situations environmental report from tenants

- Are there any serious issues regarding soil contamination in this monitoring period? ☐ Yes, ☒ No

If yes please describe the contents of complains and its countermeasures to fill in below the table.

Contents of Issues on Soil Contamination	Countermeasures

Remark: Soil contamination survey will be done after the whole Zone-B is operation stage.

4) Noise Level (December 2021)

Location	Item	Unit	Measured Value (Mean)	Measured Value (Max)	Country's Standard	Target value to be applied*	Referred International Standard	Frequency	Method	Note (Reason of excess of the standard)
Residential Area NV-2	Leq (day)	dB(A)	23	35	Refer to NEQG Article 1.3	75	Refer the section 2.4 in EIA main report	One time / 3 months		
	Leq (evening)	dB(A)	-	-		60				
	Leq (night)	dB(A)	-	-		55				
Along the road (NV-1)	Leq (day)	dB(A)	40	65		75				
	Leq (night)	dB(A)	-	-		70				

*Remarks: Referred to the tentative target value of ambient air quality (EIA Report for industrial area, Table 2.4-8). Reference to the noise and vibration monitoring report (December 2021)

Remark: Due to has Curfew and we could monitor only day time only.



Complaints from Residents

- Are there any complaints from residents regarding noise in this monitoring period? ☐ Yes, ☒ No

If yes, please describe the contents of complains and its countermeasures to fill in below the table.

Contents of Complaints from Residents	Countermeasures

5) Solid Waste

Measurement Point: Storage for Sludge (Operation Phase)

Are there any wastes if sludge in this monitoring period? ☒ Yes, ☐ No

If yes, please report the amount of sludge and fill in the results of solid waste management activities.

Item	Date	Generated from	Unit	Value	Solid Waste Management Activities
Amount of Sludge	September-2021	General Waste	Kg	350	Waste disposing to YCDC
Amount of Sludge	October-2021	General Waste	Kg	350	Waste disposing to YCDC
Amount of Sludge	November-2021	General Waste	Kg	-	-
Amount of Sludge	December-2021	General Waste	Kg	350	Waste disposing to YCDC
Amount of Sludge	January-2022	General Waste	Kg	700	Waste disposing to YCDC
Amount of Sludge	February-2022	General Waste	Kg	350	Waste disposing to YCDC

Remarks: Waste amount is not only in TSEZ-B but also combine with TSEZ-A General Waste. Generate wastes are dried waste and weight value are estimated base on trash bin specification.

6) (a) Ground Subsidence Hydrology (GPS Location 16.67 N, 96.29E)

Duration (Week)	Water Consumption		Ground Level		Note
	Quantity	Unit	Quantity	Unit	
January-2022		m ³ / week	+6.3	m	We started monitor Ground Subsidence on January 2022 with arrangement.





6) (b) Ground Subsidence Hydrology (GPS Location 16.67 N, 96.29E)

Duration (Week)	Water Consumption		Ground Level		Note
	Quantity	Unit	Quantity	Unit	
February -2022		m ³ / week	+6.303	m	

7) Offensive Odor (only operation phase)

Complaints from Residents

- Are there any complaints from residents regarding offensive odor in this monitoring period? ☐ Yes, ☒ No
If yes, please describe the contents of complains and its countermeasures to fill in below the table.

Contents of Complaints from Residents	Countermeasures

Situations environmental report from tenants

- Are there any serious issues regarding offensive odor in this monitoring period? ☐ Yes, ☒ No
If yes, please describe the contents of complains and its countermeasures to fill in below the table.

Contents of Issues on Soil Contamination	Countermeasures

8) Infectious disease, Working Environment, Accident

Information from contractor (construction phase) or tenants (operation phase)

- Are there any incidents regarding infectious disease, Working Environment, Accident in this monitoring period? ☐ Yes, ☒ No
If yes, please describe the contents of complains and its countermeasures to fill in below the table.



Contents of Incidents	Countermeasures
There is no accident and incident during monitoring period.	

Note: If emergency incidents are occurred, the information shall be reported to the relevant organizations and authorities immediately.

9) Resettlement Works for Project Affected Persons (PAPs) and Common Assets

Information from TSMC

- Please describe the progress and remarkable issues (if any) to fill in below the table.

Resettlement Works		Progress in Narrative	Remarkable Issues
Projected Affected Persons (PAPs)	Land Acquisition and Relocation	From September 2021 to February 2022, no PAPs is relocated and received compensation.	
	Income Restoration Program	1) <u>PAP Welfare Support Program</u> Supporting rice and cooking oil to PAPs for Valuable People Program in Zone B (Phase 1&2, 3 and 4) for every month. 26 HHs from Zone B relocation site, 14 HHs from Zone B (Phase 3) and 4 HHs from Zone B (Phase 4) are received for rice and cooking oil. 2) <u>PAP Facility Support Program</u> Providing electricity charges for streetlight and trash cleaning charges for Zone B PAPs every month.	

		3) <u>PAP Bereavement Program</u> Social Welfare Support (100,000 Ks to one Valuable people who was passed away in February 2021.	
Common Assets	Relocation		

- Are there any grievances submitted, solved and pending regarding resettlement works?
If yes, please describe the contents of grievances to fill in below the table.

☒ Yes, ☐ No

Contents of Grievance	Response/ Countermeasures
There was 1 grievance received during September 2021 to February 2022. That complain is about Labor crop compensation.	This complain is successfully resolved status.

10) CSR activities such as Community Support Program

- Are there any CSR activities implemented in this monitoring period?

☒ Yes, ☐ No

If yes, please describe the outline of CSR activities implemented to fill in below the table.

Date	Activities	Description (Location, Participant etc)
Oct 2021	TSEZ Covid-19 Vaccination Program	Sinovac/ Sinopharm vaccines to Employees in TSEZ at their respective factories
Nov 2021	Kahtina Robe Offering Ceremony	At East Monastery, Aye Mya Thida Ward
Nov 2021	TSEZ Covid-19 Vaccination Program	Sinovac/ Sinopharm vaccines to Employees in TSEZ at Zone A Rental Factory C and TPD

Dec 2021	TSEZ Covid-19 Vaccination Program	Sinovac/ Sinopharm vaccines to Employees and their family members at TPD compound
Jan 2022	Job assistance to local community	Relaying information of Job Vacancy from Alidae Health Care Myanmar Company Limited and Guston Amaya Company Limited to neighboring communities
Feb 2022	Job assistance to local community	Relaying information of Job Vacancy from OKAMURA Trading Myanmar Company Limited and Guston Amaya Company Limited to neighboring communities
March 2022	TSEZ Covid-19 Vaccination Program	Booster dose for employees above 50 years (Covishield) and unvaccinated people in TSEZ (Covishield) at TPD compound.

End of Document



Thilawa Special Economic Zone
Zone B- Phase 1,2 & 3 (Operation phase)

Appendix-A

Water and Waste Water Monitoring Report
October 2021

**WATER QUALITY MONITORING REPORT
FOR DEVELOPMENT OF INDUSTRIAL AREA
IN THILAWA SEZ ZONE B
(PHASE 1, 2 & 3 OPERATION STAGE)**

(Bi-Monthly Monitoring)

**October 2021
Myanmar Koci International Ltd.**




TABLE OF CONTENTS

CHAPTER 1: INTRODUCTION	1
1.1 General	1
CHAPTER 2: WATER QUALITY MONITORING	2
2.1 Monitoring Items	2
2.2 Description of Sampling Points	2
2.3 Monitoring Method	4
2.4 Monitoring Period	4
2.5 Monitoring Results	5
CHAPTER 3: CONCLUSION AND RECOMMENDATIONS	8
APPENDIX-1 FIELD SURVEY PHOTOS	A1-1
APPENDIX-2 LABORATORY RESULTS	A2-1

LIST OF TABLES

Table 2.1-1 Monitoring Items for Water Quality	2
Table 2.2-1 Outline of Sampling Points	2
Table 2.3-1 Analytic Method for Water Quality	4
Table 2.4-1 Sampling Time of Each Station	4
Table 2.4-2 Tide Record for Yangon River, Myanmar	4
Table 2.5-1 Results of Water Quality Monitoring at Discharged point and Discharged Creek	6
Table 2.5-2 Results of Water Quality Monitoring at Reference Tube Well	7

LIST OF FIGURES

Figure 1.1-1 Location of Sampling Points of Water Quality Monitoring	1
--	---



CHAPTER 1: INTRODUCTION

1.1 General

Thilawa Special Economic Zone (SEZ) is located in southern district of Yangon region and about 23 km southeast of Yangon city. As the developer of Thilawa SEZ, Myanmar Japan Thilawa Development Ltd. (MJTD) has a responsibility to carry out regular monitoring in the industrial area of Zone B in accordance with the approved Environmental Impact Assessment (EIA) report and Environmental Management Plan (EMP). MJTD has implemented monitoring various environmental items with the specified time frame to know the environmental conditions in and around the area. As for the monitoring of the water quality, total four sampling points are set for water quality survey, named SW-2, SW-4, SW-7 and GW-2 have been monitored in Thilawa SEZ and its surrounding area in timely manner. Among the four locations, SW-7 is main discharged point of Zone B during the operation stage. Moreover, GW-2 is monitored as a reference of existing tube well which located in the monastery compound of Phalan village. Location of sampling points for water quality monitoring is shown in Figure 1.1-1.



Source: Google Earth

Figure 1.1-1 Location of Sampling Points of Water Quality Monitoring



CHAPTER 2: WATER QUALITY MONITORING

2.1 Monitoring Items

Sampling points and parameters for water quality monitoring are determined to cover the environmental monitoring plan of the EIA report.

Water quality sampling was carried out at four locations. Among the four locations, water flow measurement was carried out at three locations (SW-2, SW-4 and SW-7) where can be measured by current meter. Monitoring items and sampling points are summarized in Table 2.1-1.

Table 2.1-1 Monitoring Items for Water Quality

No.	Parameters	SW-2	SW-4	SW-7	GW-2	Remarks
1	Water Temperature	○	○	○	○	On-site measurement
2	pH	○	○	○	○	On-site measurement
3	DO	○	○	○	○	On-site measurement
4	BOD ₅	○	○	○	○	Laboratory analysis
5	COD _{Cr}	○	○	○	○	Laboratory analysis
6	Total Nitrogen	○	○	○	○	Laboratory analysis
7	Suspended Solids	○	○	○	○	Laboratory analysis
8	Total Coliform	○	○	○	○	Laboratory analysis
9	Total Phosphorous	○	○	○	○	Laboratory analysis
10	Color	○	○	○	○	Laboratory analysis
11	Odor	○	○	○	○	Laboratory analysis
12	Oil and Grease	○	○	○	○	Laboratory analysis
13	Total Dissolved solids (TDS) (Self-monitoring)	○	○	○	○	Laboratory analysis
14	Iron (Self-monitoring)	○	○	○	○	Laboratory analysis
15	Mercury (Self-monitoring)	○	○	○	○	Laboratory analysis
16	Escherichia Coli (Self-monitoring)	○	○	○	○	Laboratory analysis
17	Flow Rate	○	○	○	○	On-site measurement

Source: Myanmar Koei International Ltd

2.2 Description of Sampling Points

The outline of sampling points is mentioned in Table 2.2-1. The photos of conducting field survey at each sampling points are mentioned in Appendix-1.

Table 2.2-1 Outline of Sampling Points

No.	Station	Detailed Information
1	SW-2	Coordinate - N - 16° 40' 20.69", E - 96° 17' 18.04" Location - Upstream of Shwe Pyaw Creek Survey Item - Surface water sampling and water flow rate measurement
2	SW-4	Coordinate - N - 16° 39' 42.84", E - 96° 16' 27.42" Location - Downstream of Shwe Pyaw Creek Survey Item - Surface water sampling and water flow rate measurement
3	SW-7	Coordinate - N - 16° 40' 13.25", E - 96° 17' 5.66" Location - Outlet of retention pond of Zone B construction site before connecting to Shwe Pyaw Creek Survey Item - Discharge water sampling and water flow rate measurement
4	GW-2	Coordinate - N - 16° 39' 25.30", E - 96° 17' 13.60" Location - In the monastery compound of Phalan village Survey Item - Ground water sampling

Source: Myanmar Koei International Ltd

SW-2 (Reference Point)

SW-2 was collected at the upstream of Shwe Pyauk creek. This sampling point is located in the northeast of Zone B area and at the south of Dagon-Thilawa road. The surrounding areas are Zone A in the northwest and local industrial zone in the east respectively.

SW-4 (Reference Point)

SW-4 was collected at the downstream of Shwe Pyauk creek, after mixing of discharge water from local industrial zone, construction site of Zone B and Zone A, which is flowing from east to west and then entering into the Yangon River. The distance is about 2.15 km downstream of SW-2. This sampling point is located in the west of Zone B area and in the south of Dagon-Thilawa road. The surrounding areas are Zone A in the northeast, local industrial zone in the east and paddy fields in the south and west respectively.

SW-7 (Discharged Point)

SW-7 is main discharged point of Zone B during operation stage. The distance is about 434 m downstream of SW-2. This sampling point is located at outlet of retention pond of Zone B, in the north of Zone B area and in the south of Dagon-Thilawa road. The surrounding areas are Zone A in the north and local industrial zone in the east respectively.

GW-2 (Reference of Existing Tube Well)

GW-2 was collected from tube well as ground water sample. It is located in the monastery compound of Phalan village. The surrounding areas are Thilawa SEZ Zone A in the north, Phalan village in the south and fields in the west and local industrial zone in the northeast and operation of Thilawa SEZ Zone B in the east and northeast respectively.



2.3 Monitoring Method

All water samples were collected with cleaned sampling bottles and analyzed by the following standard method as shown in Table 2.3-1. All samples were kept in iced boxes keeping at 2-4 °C and were transported to the laboratory. Among the parameters; water temperature, pH and DO were measured by the on-site instrument "Horiba, U-52" and water flow rate was also conducted by using the on-site instrument "JFE Digital Current Meter".

Table 2.3-1 Analytic Method for Water Quality

No.	Parameter	Method
1	Water Temperature	Instrument Analysis Method (Horiba, U-52, Multi Water Quality Checker)
2	pH	Instrument Analysis Method (Horiba, U-52, Multi Water Quality Checker)
3	Suspended Solids (SS)	APHA 2540D (Dry at 103-105°C Method)
4	Dissolved Oxygen (DO)	Instrument Analysis Method (Horiba, U-52, Multi Water Quality Checker)
5	BOD ₅	APHA 5210 B (5 days BOD Test)
6	COD _{Cr}	APHA 5220D (Close Reflux Colorimetric Method)
7	Total Coliform	APHA 9221B (Standard Total Coliform Fermentation Technique)
8	Total Nitrogen (T-N)	HACH Method 10072 (TNT Persulfate Digestion Method)
9	Total Phosphorus (T-P)	APHA 4500-P E (Ascorbic Acid Method)
10	Color	APHA 2120C (Spectrophotometric Method)
11	Odor	APHA 2150 B (Threshold Odor Test)
12	Oil and Grease	APHA 5520B (Partition-Gravimetric Method)
13	Mercury	APHA 3120 B (Inductively Coupled Plasma (ICP) Method)
14	Iron	APHA 3120 B (Inductively Coupled Plasma (ICP) Method)
15	Total Dissolved solids (TDS)	APHA 2540C (Total Dissolved Solids Dried at 180°C Method)
16	Escherichia Coli	APHA 9221 F (Escherichia Coli Procedure Using Fluorogenic Substrate)
17	Flow Rate	Detection of Electromagnetic Elements (Real-time measurement by AEM 213-D Digital Current Meters)

Source: Myanmar Koei International Ltd

2.4 Monitoring Period

Water quality and water flow rate monitoring were conducted on 6 October 2021 and sampling time is shown in Table 2.4-1 to avoid tidal effect. The tide record for Yangon River, Myanmar on 6 October 2021 is shown in Table 2.4-2.

Table 2.4-1 Sampling Time of Each Station

No.	Station	Sampling Time
1	SW-2	6/10/2021 08:15
2	SW-4	6/10/2021 07:21
3	SW-7	6/10/2021 08:38
4	GW-2	6/10/2021 11:37

Source: Myanmar Koei International Ltd

Table 2.4-2 Tide Record for Yangon River, Myanmar

Date	Time	Height	Tide Conditions
6/10/2021	03:58	6.22	High Tide
	11:57	1.20	Low Tide
	16:05	6.26	High Tide

Source: Myanmar Port Authority, Tide Table for the Yangon River and Elephant Point, 2021.



2.5 Monitoring Results

Results of water quality monitoring at discharged point and discharged creek are summarized in Table 2.5-1. Analytical results of the laboratory are described in Appendix-2. The results were compared with the target value of effluent water quality discharged to water body stipulated in the EIA report.

2.5.1 Results of Discharged Point and Discharged Creek

As the comparison with the target value, the results of Suspended Solid (SS), total coliform and iron exceeded the target value.

Result of Discharged point

As for the result of SS, result at the main discharging point of Zone B (SW-7) before discharging to the creek, exceeded the target value due to the surface water run-off from bare land in Zone B.

As for the result of total coliform of surface water, result at the main discharging point of Zone B (SW-7) before discharging to the creek, exceeded the target value due to the expected reason; the potential expected reason might be natural bacteria existed in all area of Zone B because there are various kinds of vegetation and creature such as birds, and small animals in and along the retention pond.

Since the composition of the total coliform include bacteria from natural origin, and even after total coliform do not affect human health directly, self-monitoring for E. Coli analysis was carried out to identify health impact by coliform bacteria. As for the result of E. Coli of surface water at the main discharging point of Zone B (SW-7), the result was under the reference value. Therefore, although the target value of total coliform was exceeded at the main discharging point of Zone B (SW-7) but it is considered that there is no significant impact on human health.

Result of Reference Monitoring points (Discharged Creek)

As for the result of SS, results at the surface water monitoring point (SW-4) exceeded the target value. The exceed results for SS maybe due to two expected reasons; i) delivered from upstream area such as natural origin and wastewater from local industrial zone which outside of Thilawa SEZ, and ii) influence by water from the downstream of monitoring points due to flow back by tidal fluctuation.

As for the result of total coliform of surface water, results at surface water monitoring points (SW-2 and SW-4) exceeded the target value due to three expected reasons; i) natural bacteria existed in discharged creek because there are various kinds of vegetation and creature such as birds and small animals in and along the discharged creek and ii) wastewater from the local industrial zone outside of Thilawa SEZ and iii) delivered from surrounding area by tidal effect.

As for the result of iron, the result at the monitoring point of surface water monitoring points (SW-2 and SW-4) exceeded the target value. The possible reasons may due to the influence of natural origin (iron can reach out from soil by run-off). In Yangon, soil is naturally rich in iron.



Table 2.5-1 Results of Water Quality Monitoring at Discharged point and Discharged Creek

No.	Parameters	Unit	SW-2	SW-4	SW-7	Target Value (Reference Value for Self-Monitoring)
1	Water Temperature	°C	26	26	27	≤ 35
2	pH	-	8.8	7.3	7.2	6-9
3	Suspended Solid (SS)	mg/L	50	302	170	50
4	Dissolved Oxygen (DO)	mg/L	2.57	4.35	4.51	-
5	BOD ₅	mg/L	10.45	3.38	4.60	50
6	COD _{Cr}	mg/L	12.8	4.1	5.6	125
7	Total Nitrogen (T-N)	mg/L	1.0	1.6	1.9	80
8	Total Phosphorous (T-P)	mg/L	-	-	-	2
9	Color	TCU (True Color Unit)	10.77	3.23	2.79	150
10	Odor	TON (Threshold Odor Number)	1	1	1	-
11	Total Coliform	MPN/100ml	>160000	160000.0	160000	400
12	Oil and Grease	mg/L	< 3.1	< 3.1	< 3.1	10
13	Total Dissolved solids (TDS)	mg/L	118	182	174	2000
14	Iron	mg/L	3.840	12.628	0.540	3.5
15	Mercury	mg/L	≤ 0.002	≤ 0.002	≤ 0.002	0.005
16	Escherichia Coli	MPN/100ml	-	-	4.0	(1000)* (CFU/100ml)
17	Flow Rate	m³/s	0.36	0.71	0.13	-

Note: Red color means exceeded value than target value. Total Phosphorous (T-P) can't be analysed at lab during this monitoring period.

*Note: Based on the water utilization at discharged creek, the quality standard for water baths in Japan, (Ministry of Environment, 1997) is set as a reference value for self-monitoring of E. coli for surface water monitoring. However, due to limitation of capacity for analytical laboratory in Myanmar, the method to analyze the "Colony Forming Unit (CFU)" is not available in Myanmar. Therefore, the results of "Most Probable Number (MPN)" are assumed similar to CFU values and compared with reference values. Once the method to analyze the CFU will be available in Myanmar, the analytical method will be changed.

Source: Myanmar Koei International Ltd.

2.5.2 Result of Reference Tube Well

Result of water quality monitoring at reference tube well monitoring point is shown in Table 2.5-2. As the comparison with the target value, the result of iron exceeded the target value.

As for the result of the iron, the result at the monitoring point of reference tube well (GW-2) exceeded the target value. Comparison with previous monitoring results of reference tube well (GW-2), the iron concentration results ranged from 3.076 mg/l (August, 2019) – 8.310 mg/l (October, 2021) and most of the iron concentration measured results (from April, 2019 to October, 2021) exceeded the target value except the iron concentration result of August, 2019. Therefore, the possible reasons may due to the influence of natural origin (iron can reach out from soil by run-off). In Yangon, soil is naturally rich in iron.

Table 2.5-2 Results of Water Quality Monitoring at Reference Tube Well

No.	Parameters	Unit	GW-2	Target Value (Reference Value for Self-Monitoring)
1	Water Temperature	°C	26	≤ 35
2	pH	-	7.0	6-9
3	Suspended Solid (SS)	mg/L	10	50
4	Dissolved Oxygen (DO)	mg/L	5.69	-
5	BOD ₅	mg/L	4.99	30
6	COD _{Cr}	mg/L	18.8	125
7	Total Nitrogen (T-N)	mg/L	2.8	80
8	Total Phosphorous (T-P)	mg/L	-	2
9	Color	TCU (True Color Unit)	58.74	150
10	Odor	TON (Threshold Odor Number)	1	-
11	Total Coliform	MPN/100ml	79.0	400
12	Oil and Grease	mg/L	< 3.1	10
13	Total Dissolved solids (TDS)	mg/L	180	2000
14	Iron	mg/L	8.310	3.5
15	Mercury	mg/L	≤ 0.002	0.005
16	Escherichia Coli	MPN/100ml	< 1.8	(100)* (CFU/100ml)
17	Flow Rate	m ³ /s	-	-

Note: Red color means exceeded value than target value. Total Phosphorous (T-P) can't be analysed at lab during this monitoring period.

*Note: Based on the water utilization at monitoring point for ground water, BI (Irrigation water) of National Technical Regulation on Surface Water Quality in Vietnam (No. QCVN 08/2008/NTNMT) is set as a reference value of self-monitoring for ground water monitoring.

Source: Myanmar Koei International, Ltd.



CHAPTER 3: CONCLUSION AND RECOMMENDATIONS

As described in Chapter 2 (Section 2.5), the results of Suspended Solids (SS) at (SW-4 and SW-7), total coliform at (SW-2, SW-4 and SW-7) in surface water, and iron at (SW-2 and SW-4) in surface water and iron at (GW-2) in ground water exceeded the target value in this monitoring period for operation stage of Thilawa SEZ Zone B.

There are some possible reasons for exceeding the target values of SS and total coliform at main discharging point of Zone B (SW-7). As for the result of SS, result at the main discharging point of Zone B (SW-7) before discharging to the creek, exceeded the target value due to the surface water run-off from bare land in Zone B.

As for the result of total coliform of surface water, result at the main discharging point of Zone B (SW-7) before discharging to the creek, exceeded the target value due to the expected reason; the potential expected reason might be natural bacteria existed in all area of Zone B because there are various kinds of vegetation and creature such as birds, and small animals in and along the retention pond. As for the result of E. Coli of surface water at (SW-7), the result was under the reference value. Therefore, although the target value of total coliform was exceeded at the main discharging point of Zone B (SW-7) but it is considered that there is no significant impact on human health.

As for the result of SS, results at the surface water monitoring point (SW-4) exceeded the target value. The exceed results for SS maybe due to two expected reasons; i) delivered from upstream area such as natural origin and wastewater from local industrial zone which outside of Thilawa SEZ, and ii) influence by water from the downstream of monitoring points due to flow back by tidal fluctuation.

The expected reasons for exceeding the target value of total coliform at (SW-2 and SW-4) are by i) natural bacteria existed in discharged creek because there are various kinds of vegetation and creature such as birds and small animals in and along the discharged creek and ii) wastewater from the local industrial zone outside of Thilawa SEZ and iii) delivered from surrounding area by tidal effect.

As for the result of iron, the result at the monitoring point of surface water monitoring points (SW-2 and SW-4) exceeded the target value. The possible reasons may due to the influence of natural origin (iron can reach out from soil by run-off). In Yangon, soil is naturally rich in iron.

As for the result of the iron, the result at the monitoring point of reference tube well (GW-2) exceeded the target value. Comparison with previous monitoring results of reference tube well (GW-2), the iron concentration results ranged from 3.076 mg/l (August, 2019) – 8.310 mg/l (October, 2021) and most of the iron concentration measured results (from April, 2019 to October, 2021) exceeded the target value except the iron concentration result of August, 2019. Therefore, the possible reasons may due to the influence of natural origin (iron can reach out from soil by run-off). In Yangon, soil is naturally rich in iron.

As for future subject for main discharged points of Thilawa SEZ Zone B, the following action may be taken to maintain the target value of SS and total coliform and appropriate water quality monitoring:

- 1) To continue monitoring *Escherichia coli* (E. coli) level to identify health impact by coliform bacteria,
- 2) To monitor the possibility of the overflow water from construction sites and
- 3) To monitor the possibility of the domestic wastewater from construction sites.

End of the Document



APPENDIX-1 FIELD SURVEY PHOTOS



FOR DISCHARGED POINT OF THILAWA SEZ ZONE B



Surface water sampling and onsite measurement at SW-7



**FOR REFERENCE MONITORING POINTS FOR COMPARISON WITH DISCHARGED
POINTS AND BASELINE OF DISCHARGED CREEK**



Surface water sampling and onsite measurement at SW-2



Surface water sampling and onsite measurement at SW-4



Ground water sampling and onsite measurement at GW-2



APPENDIX-2 LABORATORY RESULTS



FOR DISCHARGED POINT

DDWA

General Services Development Co., Ltd.
Unit 401, Tower B, South Bridge Road, Myanmar
Phone No. 09-5555555



Report No. : GEM-LAB-2021-062
Revised No. : 2
Report Date : 28 October, 2021
Application No. : (001) COI

Analysis Report

Client Name : Myanmar Rice International (P) (MRI)
Address : No. 25/A, 1st Floor, Sanchaya San Chaddamwin, The South East, Tanintharyi Region, Myanmar
Project Name : Government Monitoring report for Zone A & B
Sample Description :
Sample Name : PMS-DW-F-1000s
Sample No. : W-2110027
Water Profile No. :
Sampling Date : 8 October, 2021
Sampling By : Customer
Sample Received Date : 8 October, 2021

No.	Parameter	Method	Unit	Result	LOQ
1	SS	APHA 2540D (Dry at 103-105°C Method)	mg/l	170	-
2	BOD (5)	APHA 5210 B (5 Days BOD Test)	mg/l	4.80	0.00
3	COD (Cr)	APHA 5220D (Closed Reflux Colorimetric Method)	mg/l	3.6	0.7
4	Total Coliform	APHA 9221B (Standard Total Coliform Enumeration Technique)	MPN/100ml	16000	1.8
5	Oil and Grease	APHA 5520B (Petroleum Gravimetric Method)	mg/l	< 3.1	3.1
6	Total Nitrogen	HACH Method 10072 (TN Persulfate Digestion Method)	mg/l	1.6	0.1
7	Color	APHA 2120C (Spectrophotometric Method)	PCU	2.78	0.00
8	Clarity	APHA 2150 B (Turbidimetric Color Test)	YDS	2	0
9	TDS	APHA 2540 E (Total Dissolved Solids Dried at 180°C Method)	mg/l	174	-
10	Mercury	APHA 3120 B (Inductively Coupled Plasma (ICP) Method)	mg/L	< 0.002	0.002
11	Chromium	APHA 3120 B (Inductively Coupled Plasma (ICP) Method)	mg/L	< 0.002	0.002
12	Cadmium	APHA 3120 B (Inductively Coupled Plasma (ICP) Method)	mg/L	< 0.040	0.002
13	Escherichia Coli	APHA 9221 F Escherichia Coli Membrane Using Phage-type Substrate	MPN/100ml	40	1.8

Remarks : LOQ - Limit of Quantitation
APHA - American Public Health Association (APHA), the American Water Works Association (AWWA), and the Water Environment Federation (WEF), Standard Methods for the Examination of Water and Wastewater, 22nd edition

Analysed by

Ching Myint Thun
Supervisor



Approved by

N. Aye Lin
Assistant Manager



**FOR REFERENCE MONITORING POINTS FOR COMPARISON WITH DISCHARGED
POINTS AND BASELINE OF DISCHARGED CREEK**

DOWA

100 (M) Road (C/O) MPT Co. (Pvt) Ltd., 100 (M) Road (C/O) MPT Co. (Pvt) Ltd.,
100 (M) Road (C/O) MPT Co. (Pvt) Ltd., 100 (M) Road (C/O) MPT Co. (Pvt) Ltd.,
100 (M) Road (C/O) MPT Co. (Pvt) Ltd., 100 (M) Road (C/O) MPT Co. (Pvt) Ltd.,



Report No.: GEM-LAB-2021-0009
Revision No.: 2
Report Date: 28 October, 2021
Appraisal No.: 0001-C001

Analysis Report

Client Name: Myanmar Kasa International, Ltd. (MKI)
Address: No. 36/A, 1st Floor, G-101, The Star Community, The Star Road, Tamar Townships, Yangon, Myanmar
Project Name: Environment Monitoring report for Zone A & B
Sample Description:
Sample Name: MKI-SW-2-1008
Sample No: W-2110124
Waste Profile No.:
Sampling Date: 6 October, 2021
Sampling By: Customer
Sample Received Date: 6 October, 2021

No.	Parameter	Method	Unit	Result	SDQ
1	SS	APHA 2540D (Dry at 103-105°C Method)	mg/l	50	—
2	BOD (5)	APHA 5210 B (5 Days BOD Test)	mg/l	10.45	0.00
3	COD (Cr)	APHA 5220D (Open Reflux Colorimetric Method)	mg/l	12.8	0.7
4	Total Coliform	APHA 9221B (Standard Plate Count-Fermentative Technique)	MPN/100ml	>160000	1.8
5	Oil and Grease	APHA 5520B (Petroleum Gravimetric Method)	mg/l	< 3.1	1.1
6	Total Nitrogen	HACH Method 10072 (TNT Persulfate Digestion Method)	mg/l	1.0	0.5
7	Color	APHA 2120C (Spectrophotometric Method)	PCU	10.77	0.00
8	Odor	APHA 2130 B (Threshold Odor Test)	TOR	1	0
9	TSS	APHA 2540 C (Total Suspended Solids Dried at 102°C Method)	mg/l	118	—
10	Mercury	APHA 3120 B (Inductively Coupled Plasma (ICP) Method)	mg/l	0.0002	0.002
11	Chromium	APHA 3120 B (Inductively Coupled Plasma (ICP) Method)	mg/l	0.0002	0.002
12	Iron	APHA 3120 B (Inductively Coupled Plasma (ICP) Method)	mg/l	3.840	0.002

Remark: LOD - Limit of Quantitation
APHA - American Public Health Association (APHA), the American Water Works Association (AWWA), and the Water Environment Federation (WEF), Standard Methods for the Examination of Water and Wastewater, 22nd edition.

Analyst By:

Chitry Hsiao Thin
Supervisor



Approved By:

H. H. Aye Linn
Assistant Manager



**Water Quality Monitoring Report for Development of Industrial Area in Thilawa SEZ Zone B
(Bi-Monthly Monitoring in FY October - 2021)**

ODWA

ODWA (Pvt.) Ltd. (Company Registration No. 113)
Central Office: Thilawa SEZ, Thilawa Township, Yangon Region, Myanmar
Phone No: 09-555 138888



Report No. : ODM-LAB/2021/0080
Revised No. : 2
Report Date : 28 October, 2021
Application No. : 0001-0001

Analysis Report

Client Name	Myanmar Kobi International LTD (MKT)		
Address	No. 36/A, 1st Floor, Grand Pina Siam Condominium, Pina Siam Road, Thilawa Township, Yangon Region		
Project Name	Environmental Monitoring report for Zone A & B		
Sample Description			
Sample Name	MS1 S&P 4 (100L)	Sampling Date	6 October, 2021
Sample No.	W-2110021	Sampling By	Customer
Water Profile No.		Sample Received Date	6 October, 2021

No.	Parameter	Method	Unit	Result	LOQ
1	SS	APHA 2540D (Dry at 103-105°C Method)	mg/l	322	-
2	BOD (5)	APHA 5212 B (5 Days BOD Test)	mg/l	3.34	0.00
3	COD (Cr)	APHA 5220D (Close Reflux Colorimetric Method)	mg/l	4.1	0.2
4	Total Calcium	APHA 9221B (Standard Total Calcium Fermentation Technique)	mg/l (ppm)	100000.0	1.0
5	Oil and Grease	APHA 9220B (Partition Gravimetric Method)	mg/l	< 3.3	3.3
6	Total Nitrogen	HACH Method 10072 (TKT Persulfate Digestion Method)	mg/l	1.8	0.5
7	Color	APHA 2120C (Spectrophotometric Method)	PCU	3.23	0.00
8	Chlorine	APHA 2120 B (Thiosulfate Oxide Test)	TCN	1	0
9	TDS	APHA 2540 C (Total Dissolved Solids Dried at 180°C Method)	mg/l	182	-
10	Mercury	APHA 3120 B (Inductively Coupled Plasma (ICP) Method)	mg/l	< 0.002	0.002
11	Chromium	APHA 3120 B (Inductively Coupled Plasma (ICP) Method)	mg/l	< 0.002	0.002
12	Iron	APHA 3120 B (Inductively Coupled Plasma (ICP) Method)	mg/l	12.638	0.002

Remarks : LOQ = Limit of Quantitation

APHA = American Public Health Association (APHA), the American Water Works Association (AWWA), and the Water Environment Federation (WEF), Standard Methods for the Examination of Water and Wastewater, 22nd edition.

Analysed By

Cherry Myint Thant
Supervisor



Approved By

N. N. Aye Win
Assistant Manager



Water Quality Monitoring Report for Development of Industrial Area in Thilawa SEZ Zone B
(Bi-Monthly Monitoring in FY October - 2021)

DOWA

DOWA (Dhaka Water and Sewerage Development Authority) Ltd. (DOWA)
Plot No. 11, Tejgaon Industrial Estate, Dhaka-1215, Bangladesh
Phone No. 1711 222111, 1711 222112



Report No. : GEM-LAB-222110063

Revision No. : 2

Report Date : 28 October, 2021

Application No. : 0005-0001

Analysis Report

Client Name	Myanmar Kazi International LTD (MKI)		
Address	No. 25/A, 1st Floor, Grand Phe Sien Condominium, Phe Sien Road, Fathema Township, Yangon, Myanmar		
Project Name	Environment Monitoring report for Zone A & B		
Sample Description			
Sample Name	MKI-DW-2-1000	Sampling Date	5 October, 2021
Sample No.	W-211001B	Sampling By	Customer
Waste Profile No.	-	Sample Received Date	5 October, 2021

No.	Parameter	Method	Unit	Result	LOQ
1	pH	APHA 2540D (Dry at 123-125°C Method)	mg/l	10	-
2	BOD (5)	APHA 5210 B (5 Days BOD Test)	mg/l	4.99	0.01
3	COD (Cr)	APHA 5210C (Closed Reflux Colorimetric Method)	mg/l	18.8	0.7
4	Total Coliform	APHA 9215B (Standard Total Coliform Fermentation Technique)	MPN/100ml	79.2	1.8
5	Oil and Grease	APHA 5520B (Rapid-Crowlometric Method)	mg/l	< 3.1	3.1
6	Total Nitrogen	HACH Method 10012 (TNT Persulfate Digestion Method)	mg/l	2.8	0.5
7	Color	APHA 2120C (Spectrophotometric Method)	TCU	58.74	0.00
8	Chlor	APHA 2130 B (Threshold Chlor Test)	mg/l	1	0
9	TDS	APHA 2540 C (Total Dissolved Solids Dried at 180°C Method)	mg/l	180	-
10	Mercury	APHA 3120 B (Inductively Coupled Plasma (ICP) Method)	mg/l	< 0.002	0.002
11	Chromium	APHA 3120 B (Inductively Coupled Plasma (ICP) Method)	mg/l	< 0.002	0.002
12	Cadmium	APHA 3120 B (Inductively Coupled Plasma (ICP) Method)	mg/l	< 0.002	0.002
13	Escherichia Coli	APHA 9221 + Escherichia Coli Procedure Using Fluorogenic Substrate	MPN/100ml	< 1.8	1.8

Remarks: LOQ : Limit of Quantitation

APHA : American Public Health Association (APHA), the American Water Works Association (AWWA), and the Water Environment Federation (WEF), Standard Methods for the Examination of Water and Wastewater, 22nd edition

Analysed By

Cherry Myint Thain
Supervisor



Approved By

Aye Linn
Assistant Manager

Thilawa Special Economic Zone
Zone B– Phase 1 & 2 (Operation phase)

Appendix-B

Water and Waste Water Monitoring Report
December 2021

**WATER QUALITY MONITORING REPORT
FOR DEVELOPMENT OF INDUSTRIAL AREA
IN THILAWA SEZ ZONE B
(PHASE 1, 2 & 3 OPERATION STAGE)**

(Bi-Annually Monitoring)

**December 2021
Myanmar Koei International Ltd.**



TABLE OF CONTENTS

CHAPTER 1: INTRODUCTION.....	1
1.1 General.....	1
CHAPTER 2: WATER QUALITY MONITORING.....	2
2.1 Monitoring Items.....	2
2.2 Description of Sampling Points.....	3
2.3 Monitoring Method.....	4
2.4 Monitoring Period.....	5
2.5 Monitoring Results.....	5
CHAPTER 3: CONCLUSION AND RECOMMENDATIONS.....	8
APPENDIX-1 FIELD SURVEY PHOTOS.....	A1-1
APPENDIX-2 LABORATORY RESULTS.....	A2-1

LIST OF TABLES

Table 2.1-1 Monitoring Items for Water Quality.....	2
Table 2.2-1 Outline of Sampling Points.....	3
Table 2.3-1 Analytic Method for Water Quality.....	4
Table 2.4-1 Sampling Time of Each Station.....	5
Table 2.4-2 Tide Record for Yangon River, Myanmar.....	5
Table 2.5-1 Results of Water Quality Monitoring at Discharged point and Discharged Creek.....	5
Table 2.5-2 Results of Water Quality Monitoring at Reference Tube Well.....	7

LIST OF FIGURES

Figure 1.1-1 Location of Sampling Points of Water Quality Monitoring.....	1
---	---



CHAPTER 1: INTRODUCTION

1.1 General

Thilawa Special Economic Zone (SEZ) is located in southern district of Yangon region and about 23 km southeast of Yangon city. As the developer of Thilawa SEZ, Myanmar Japan Thilawa Development Ltd. (MJD) has a responsibility to carry out regular monitoring in the industrial area of Zone B in accordance with the approved Environmental Impact Assessment (EIA) report and Environmental Management Plan (EMP). MJD has implemented monitoring various environmental items with the specified time frame to know the environmental conditions in and around the area. As for the monitoring of the water quality, total four sampling points are set for water quality survey, named SW-2, SW-4, SW-7 and GW-2 have been monitored in Thilawa SEZ and its surrounding area in timely manner. Among the four locations, SW-7 is main discharged point of Zone B during the operation stage. Moreover, GW-2 is monitored as a reference of existing tube well which located in the monastery compound of Phalan village. Location of sampling points for water quality monitoring is shown in Figure 1.1-1.



Figure 1.1-1 Location of Sampling Points of Water Quality Monitoring



CHAPTER 2: WATER QUALITY MONITORING

2.1 Monitoring Items

Sampling points and parameters for water quality monitoring are determined to cover the environmental monitoring plan of the EIA report.

Water quality sampling was carried out at four locations. Among the four locations, water flow measurement was carried out at one location (SW-4) where can be measured by current meter. Monitoring items and sampling points are summarized in Table 2.1-1.

Table 2.1-1 Monitoring Items for Water Quality

No.	Parameters	SW-2	SW-4	SW-7	GW-2	Remarks
1	Water Temperature	○	○	○	○	On-site measurement
2	pH	○	○	○	○	On-site measurement
3	DO	○	○	○	○	On-site measurement
4	BOD (5)	○	○	○	○	Laboratory analysis
5	COD (Cr)	○	○	○	○	Laboratory analysis
6	Total Nitrogen	○	○	○	○	Laboratory analysis
7	Suspended Solids	○	○	○	○	Laboratory analysis
8	Total Coliforms	○	○	○	○	Laboratory analysis
9	Total Phosphorous	○	○	○	○	Laboratory analysis
10	Color	○	○	○	○	Laboratory analysis
11	Odor	○	○	○	○	Laboratory analysis
12	Zinc	○	○	○	○	Laboratory analysis
13	Arsenic	○	○	○	○	Laboratory analysis
14	Chromium	○	○	○	○	Laboratory analysis
15	Cadmium	○	○	○	○	Laboratory analysis
16	Selenium	○	○	○	○	Laboratory analysis
17	Lead	○	○	○	○	Laboratory analysis
18	Copper	○	○	○	○	Laboratory analysis
19	Barium	○	○	○	○	Laboratory analysis
20	Nickel	○	○	○	○	Laboratory analysis
21	Cyanide	○	○	○	○	Laboratory analysis
22	Total Cyanide	○	○	○	○	Laboratory analysis
23	Free Chlorine	○	○	○	○	Laboratory analysis
24	Sulphide	○	○	○	○	Laboratory analysis
25	Formaldehyde	○	○	○	○	Laboratory analysis
26	Phenols	○	○	○	○	Laboratory analysis
27	Total Residual Chlorine	○	○	○	○	Laboratory analysis
28	Chromium (Hexavalent)	○	○	○	○	Laboratory analysis
29	Ammonia	○	○	○	○	Laboratory analysis
30	Fluoride	○	○	○	○	Laboratory analysis
31	Silver	○	○	○	○	Laboratory analysis
32	Oil and Grease	○	○	○	○	Laboratory analysis
33	Total Dissolved Solids	○	○	○	○	Laboratory analysis
34	Iron	○	○	○	○	Laboratory analysis
35	Mercury	○	○	○	○	Laboratory analysis
36	Escherichia Coli	○	○	○	○	Laboratory analysis
37	Flow Rate	○	○	○	○	On-site measurement

Source: Myanmar Koei International Ltd.



2.2 Description of Sampling Points

The outline of sampling points is mentioned in Table 2.2-1. The photos of conducting field survey at each sampling points are mentioned in Appendix-1.

Table 2.2-1 Outline of Sampling Points

No.	Station	Detailed Information
1	SW-2	Coordinate - N - 16° 40' 20.69", E - 96° 17' 18.04" Location - Upstream of Shwe Pyauk Creek Survey Item - Surface water sampling
2	SW-4	Coordinate - N - 16° 39' 42.84", E - 96° 16' 27.42" Location - Downstream of Shwe Pyauk Creek Survey Item - Surface water sampling and water flow rate measurement
3	SW-7	Coordinate - N - 16° 40' 13.25", E - 96° 17' 5.66" Location - Outlet of retention pond of Zone B construction site before connecting to Shwe Pyauk Creek Survey Item - Discharge water sampling
4	GW-2	Coordinate - N - 16° 39' 25.30", E - 96° 17' 15.60" Location - In the monastery compound of Phalan village Survey Item - Ground water sampling

Source: Myanmar Kwei International Ltd.

SW-2 (Reference Point)

SW-2 was collected at the upstream of Shwe Pyauk creek. This sampling point is located in the northeast of Zone B area and at the south of Dagon-Thilawa road. The surrounding areas are Zone A in the northwest and local industrial zone in the east respectively.

SW-4 (Reference Point)

SW-4 was collected at the downstream of Shwe Pyauk creek, after mixing of discharge water from local industrial zone, construction site of Zone B and Zone A, which is flowing from east to west and then entering into the Yangon River. The distance is about 2.15 km downstream of SW-2. This sampling point is located in the west of Zone B area and in the south of Dagon-Thilawa road. The surrounding areas are Zone A in the northeast, local industrial zone in the east and paddy fields in the south and west respectively.

SW-7 (Discharged Point)

SW-7 is main discharged point of Zone B during operation stage. The distance is about 434 m downstream of SW-2. This sampling point is located at outlet of retention pond of Zone B, in the north of Zone B area and in the south of Dagon-Thilawa road. The surrounding areas are Zone A in the north and local industrial zone in the east respectively.

GW-2 (Reference of Existing Tube Well)

GW-2 was collected from tube well as ground water sample. It is located in the monastery compound of Phalan village. The surrounding areas are Thilawa SEZ Zone A in the north, Phalan village in the south and fields in the west and local industrial zone in the northeast and operation of Thilawa SEZ Zone B in the east and northeast respectively.



2.3 Monitoring Method

All water samples were collected with cleaned sampling bottles and analyzed by the following standard method as shown in Table 2.3-1. All samples were kept in iced boxes keeping at 2-4 °C and were transported to the laboratory. Among the parameters; water temperature, pH and DO were measured by the on-site instrument "Horiba, U-52" and water flow rate was also conducted by using the on-site instrument "JFE Digital Current Meter".

Table 2.3-1 Analytic Method for Water Quality

No.	Parameter	Method
1.	Water Temperature	Instrument Analysis Method (Horiba, U-52, Multi Water Quality Checker)
2.	pH	Instrument Analysis Method (Horiba, U-52, Multi Water Quality Checker)
3.	Suspended Solids (SS)	APHA 2540 D (Dry at 103-105°C Method)
4.	Dissolved Oxygen (DO)	Instrument Analysis Method (Horiba, U-52, Multi Water Quality Checker)
5.	BOD (5)	APHA 5210 B (5 Days BOD Test)
6.	COD (Cr)	APHA 5220D (Close Reflux Colorimetric Method)
7.	Total Coliform	APHA 9221B (Standard Total Coliform Fermentation Technique)
8.	Total Nitrogen (T-N)	HACH Method 10072 (TNT Persulfate Digestion Method)
9.	Total Phosphorous (T-P)	APHA 4500-PE (Ascorbic Acid Method)
10.	Color	APHA 2120C (Spectrophotometric Method)
11.	Odor	APHA 2150 B (Threshold Odor Test)
12.	Oil and Grease	APHA 5520B (Partition-Gravimetric Method)
13.	Mercury	APHA 3120 B (Inductively Coupled Plasma (ICP) Method)
14.	Zinc	APHA 3120 B (Inductively Coupled Plasma (ICP) Method)
15.	Arsenic	APHA 3120 B (Inductively Coupled Plasma (ICP) Method)
16.	Chromium	APHA 3120 B (Inductively Coupled Plasma (ICP) Method)
17.	Cadmium	APHA 3120 B (Inductively Coupled Plasma (ICP) Method)
18.	Selenium	APHA 3120 B (Inductively Coupled Plasma (ICP) Method)
19.	Lead	APHA 3120 B (Inductively Coupled Plasma (ICP) Method)
20.	Copper	APHA 3120 B (Inductively Coupled Plasma (ICP) Method)
21.	Barium	APHA 3120 B (Inductively Coupled Plasma (ICP) Method)
22.	Nickel	APHA 3120 B (Inductively Coupled Plasma (ICP) Method)
23.	Cyanide	HACH 8027 (Pyridine-Pyrazolone Method)
24.	Total Cyanide	Distillation process: APHA 4500-CN-C, Total Cyanide after Distillation, Determine cyanide Concentration Process: HACH 8027 (Pyridine - Pyrazolone Method)
25.	Free Chlorine	APHA 4500-CL G (DPD Colorimetric Method)
26.	Sulphide	HACH 8131 (USEPA Methylone Blue Method)
27.	Formaldehyde	HACH 8110 (MBTH Method)
28.	Phenols	USEPA Method 420.1 (Phenolics (Spectrophotometric, Manual 4-AAP With Distillation))
29.	Iron	APHA 3120 B (Inductively Coupled Plasma (ICP) Method)
30.	Total Dissolved Solids	APHA 2540 C (Total Dissolved Solids Dried at 180°C Method)
31.	Total Residual Chlorine	APHA 4500-CL G (DPD Colorimetric Method)
32.	Chromium (Hexavalent)	ISO 11083:1994 (Determination of chromium (VI) Spectrometric method using 1,5-diphenylcarbazide)
33.	Ammonia	HACH Method 10205 (Siliciclate TNT Plus Method)
34.	Fluoride	APHA 4110 B (Ion Chromatography with Chemical Suppression of Eluent Conductivity)
35.	Silver	APHA 3120 B (Inductively Coupled Plasma (ICP) Method)
36.	Escherichia Coli	APHA 9221 F (Escherichia Coli Procedure Using Fluorescent Substrate)
37.	Flow Rate	Detection of Electromagnetic Elements (Real-time measurement by AEM 213-D Digital Current Meters)

Source: Myanmar Koei International Ltd.



2.4 Monitoring Period

Water quality and water flow rate monitoring were conducted on 14 December 2021 and sampling time is shown in Table 2.4-1 to avoid tidal effect. The tide record for Yangon River, Myanmar on 14 December 2021 is shown in Table 2.4-2.

Table 2.4-1 Sampling Time of Each Station

No.	Station	Sampling Time
1	SW-2	14/12/2021 08:54
2	SW-4	14/12/2021 08:02
3	SW-7	14/12/2021 09:21
4	GW-2	14/12/2021 12:36

Source: Myanmar Kwei International Ltd.

Table 2.4-2 Tide Record for Yangon River, Myanmar

Date	Time	Height	Tide Conditions
14/12/2021	01:10	4.84	High Tide
	08:25	1.11	Low Tide
	13:44	4.45	High Tide
	20:25	1.09	Low Tide

Source: Myanmar Port Authority, Tide Table for the Yangon River and Elephant Point, 2021.

2.5 Monitoring Results

Results of water quality monitoring at discharged point and discharged creek are summarized in Table 2.5-1. Analytical results of the laboratory are described in Appendix-2. The results were compared with the target value of effluent water quality discharged to water body stipulated in the EIA report.

2.5.1 Results of Discharged Point and Discharged Creek

As the comparison with the target value, the results of Suspended Solid (SS), total coliform and iron exceeded the target value.

Result of Discharged point

As for the result of SS, result at the main discharging point of Zone B (SW-7) before discharging to the creek, exceeded the target value due to the surface water run-off from bare land in Zone B.

As for the result of total coliform of surface water, result at the main discharging point of Zone B (SW-7) before discharging to the creek, exceeded the target value due to the expected reason; the potential expected reason might be natural bacteria existed in all area of Zone B because there are various kinds of vegetation and creature such as birds, and small animals in and along the retention pond.

Since the composition of the total coliform include bacteria from natural origin, and even after total coliform do not affect human health directly, self-monitoring for E. Coli analysis was carried out to identify health impact by coliform bacteria. As for the result of E. Coli of surface water at the main discharging point of Zone B (SW-7), the result was under the reference value. Therefore, although the target value of total coliform was exceeded at the main discharging point of Zone B (SW-7) but it is considered that there is no significant impact on human health.

Result of Reference Monitoring points (Discharged Creek)

As for the result of SS, results at the surface water monitoring points (SW-2 and SW-4) exceeded the target value due to two expected reasons; i) delivered from upstream area such as natural origin and wastewater from local industrial zone which outside of Thilawa SEZ, and ii) influence by water from the downstream of monitoring points due to flow back by tidal fluctuation.

As for the result of total coliform of surface water, results at surface water monitoring points (SW-2 and



SW-4) exceeded the target value due to three expected reasons; i) natural bacteria existed in discharged creek because there are various kinds of vegetation and creature such as birds and small animals in and along the discharged creek and ii) wastewater from the local industrial zone (outside of Thilawa SEZ and iii) delivered from surrounding area by tidal effect.

As for the result of iron, the result at the monitoring point of surface water monitoring point (SW-4) exceeded the target value due to the influence of natural origin (iron can reach out from the soil by run-off). Japan set effluent standards for two items as follows; i) health item and ii) living environment item. In the health item, there is no standard value for iron. On the other hand, for the living environment item, the standard value for soluble iron level is 10 mg/L. As the comparison with the living environment standard value in Japan, iron results in (SW-4) is lower than the standard value. Therefore, it can be considered that there is no significant impact on the living environment.

Table 2.5-1 Results of Water Quality Monitoring at Discharged point and Discharged Creek

No.	Parameters	Unit	SW-1	SW-4	SW-7	Target Value (Reference Value for Self- Monitoring)
1	Water Temperature	°C	19	21	21	< 35
2	pH	-	7.2	7.2	8.0	6-9
3	Suspended Solid (SS)	mg/L	78	194	58	50
4	Dissolved Oxygen (DO)	mg/L	3.36	4.66	6.31	-
5	BOD ₅	mg/L	7.99	3.47	6.26	30
6	COD _{Cr}	mg/L	30.9	19.8	13.6	125
7	Total Coliform	MPN/100ml	> 20000	> 160000	1600	400
8	Total Nitrogen (T-N)	mg/L	7.6	6.4	7.1	80
9	Total Phosphorus (T-P)	mg/L	-	-	-	2
10	Color	TCU (True Color Unit)	17.06	7.86	4.31	150
11	Odor	TON (Threshold Odor Number)	1	1	1	-
12	Oil and Grease	mg/L	< 3.1	< 3.1	< 3.1	10
13	Mercury	mg/L	< 0.002	< 0.002	< 0.002	0.005
14	Zinc	mg/L	0.026	0.060	0.006	2
15	Arsenic	mg/L	< 0.010	< 0.010	< 0.010	0.1
16	Chromium	mg/L	< 0.002	< 0.002	< 0.002	0.3
17	Cadmium	mg/L	< 0.002	< 0.002	< 0.002	0.03
18	Selenium	mg/L	< 0.010	< 0.010	< 0.010	0.02
19	Lead	mg/L	< 0.002	< 0.002	< 0.002	0.1
20	Copper	mg/L	< 0.002	< 0.002	< 0.002	0.5
21	Barium	mg/L	0.062	0.020	0.018	1
22	Nickel	mg/L	< 0.002	< 0.002	< 0.002	0.2
23	Cyanide	mg/L	< 0.002	0.002	< 0.002	0.1
24	Total Cyanide	mg/L	0.006	0.015	0.003	1
25	Free Chlorine	mg/L	0.1	< 0.1	< 0.1	1
26	Sulphide	mg/L	0.068	0.377	0.054	1
27	Formaldehyde	mg/L	0.013	0.072	0.019	1
28	Phenols	mg/L	0.007	0.002	0.004	0.5
29	Iron	mg/L	1.632	6.884	1.500	3.5
30	Total Dissolved Solids	mg/L	1026	624	1008	2000
31	Total Residual Chlorine	mg/L	0.2	0.1	0.1	0.2
32	Chromium (Hexavalent)	mg/L	< 0.05	< 0.05	< 0.05	0.1
33	Ammonia	mg/L	2.01	3.44	0.11	10
34	Fluoride	mg/L	0.154	1.325	0.324	20
35	Silver	mg/L	< 0.002	< 0.002	< 0.002	0.5
36	Escherichia Coli	MPN/100ml	-	-	4.5	(1000)* (CFU/100ml)
37	Flow Rate	m ³ /s	-	0.03	-	-

Note: Red color means exceeded value than target value.

*Note: Based on the water utilization at discharged creek, the quality standard for water bath in Japan. (Ministry of Environment, 1997) is set as a reference value for self-monitoring of E. coli for surface water monitoring. However, due to the capacity of current reliable laboratory that we sent water samples (Dowa Laboratory), the method to analyze the "Colony Forming Unit (CFU)" is not available. Moreover, according to the experiences of laboratory technicians, the analytical method used for CFU is commonly used in drinking water. Therefore, the analytical method used for MPN is assumed to be more accurate and reliable for surface and discharged water. The results of "Most Probable Number (MPN)" are assumed similar to CFU values and compared with reference values.

Source: Myanmar Koei International Ltd.



2.5.2 Result of Reference Tube Well

Result of water quality monitoring at reference tube well monitoring point is shown in Table 2.5-2. As the comparison with the target value, the result of iron exceeded the target value.

As for the result of the iron, the result at the monitoring point of reference tube well (GW-2) exceeded the target value. Comparison with previous monitoring results of reference tube well (GW-2), the iron concentration results ranged from 3.076 mg/l (August, 2019) – 8.310 mg/l (October, 2021) and most of the iron concentration measured results (from April, 2019 to December, 2021) exceeded the target value except the iron concentration result of August, 2019. Therefore, the possible reasons may due to the influence of natural origin (iron can reach out from soil by run-off). In Yangon, soil is naturally rich in iron.

Table 2.5-2 Results of Water Quality Monitoring at Reference Tube Well

No.	Parameters	Unit	GW-2	Target Value (Reference Value for SHS Monitoring)
1	Water Temperature	°C	24	≤ 25
2	pH	-	6.9	6-9
3	Suspended Solid (SS)	mg/L	4	50
4	Dissolved Oxygen (DO)	mg/L	7.13	-
5	BOD ₅	mg/L	6.82	30
6	COD _{Mn}	mg/L	< 0.7	125
7	Total Coliform	MPN/100ml	7.8	400
8	Total Nitrogen (T-N)	mg/L	0.8	80
9	Total Phosphorus (T-P)	mg/L	-	2
10	Color (True Color Unit)	TCU	42.34	150
11	Odor (Threshold Odor Number)	TON	1	-
12	Oil and Grease	mg/L	< 3.1	10
13	Mercury	mg/l	< 0.002	0.005
14	Zinc	mg/l	0.008	2
15	Arsenic	mg/L	≤ 0.010	0.1
16	Chromium	mg/L	≤ 0.002	0.5
17	Cadmium	mg/L	< 0.002	0.05
18	Selenium	mg/L	≤ 0.010	0.02
19	Lead	mg/L	≤ 0.002	0.1
20	Copper	mg/L	≤ 0.002	0.5
21	Barium	mg/L	0.006	1
22	Nickel	mg/L	< 0.002	0.2
23	Cyanide	mg/L	< 0.002	0.1
24	Total Cyanide	mg/L	0.003	1
25	Free Chlorine	mg/l	< 11.1	1
26	Sulphide	mg/L	0.006	1
27	Formaldehyde	mg/l	0.003	1
28	Phenols	mg/L	0.004	0.5
29	Iron	mg/L	3.566	3.5
30	Total Dissolved Solids	mg/L	152	2000
31	Total Residual Chlorine	mg/L	< 0.1	0.2
32	Chromium (Hexavalent)	mg/L	< 0.05	0.1
33	Ammonia	mg/L	0.22	10
34	Fluoride	mg/L	0.014	20
35	Silver	mg/L	< 0.002	0.5
36	Escherichia Coli	MPN/100ml	< 1.8	(100)* (MPN/100ml)
37	Flow Rate	m³/s	-	-

Note: Red color means exceeded value than target value.

*Note: Based on the water utilization at monitoring point for ground water, B1 (irrigation water) of National Technical Regulation on Surface Water Quality in Vietnam (No. QCVN 08: 2008/BTNMT) is set as a reference value of self-monitoring for ground water monitoring.

Source: Myanmar Kosi International Ltd.



CHAPTER 3: CONCLUSION AND RECOMMENDATIONS

As described in Chapter 2 (Section 2.5), the results of Suspended Solids (SS) and total coliform at (SW-2, SW-4 and SW-7) and iron at (SW-4) in surface water exceeded the target value in this monitoring period for operation stage of Thilawa SEZ Zone B.

As for the result of SS, result at the main discharging point of Zone B (SW-7) before discharging to the creek, exceeded the target value due to the surface water run-off from bare land in Zone B.

As for the result of total coliform of surface water, result at the main discharging point of Zone B (SW-7) before discharging to the creek, exceeded the target value due to the expected reason; the potential expected reason might be natural bacteria existed in all area of Zone B because there are various kinds of vegetation and creature such as birds, and small animals in and along the retention pond. As for the result of E. Coli of surface water at (SW-7), the result was under the reference value. Therefore, although the target value of total coliform was exceeded at the main discharging point of Zone B (SW-7) but it is considered that there is no significant impact on human health.

As for parameters of SS, total coliform, and iron in surface water exceeded the target values at reference monitoring points (SW-2 and SW-4). The expected reasons for exceeding the target value of SS at (SW-2 and SW-4) is delivered from upstream area such as natural origin and wastewater from local industrial zone which outside of Thilawa SEZ, and influence by water from the downstream of monitoring points due to flow back by tidal fluctuation.

The expected reasons for exceeding the target value of total coliform at (SW-2 and SW-4) are by i) natural bacteria existed in discharged creek because there are various kinds of vegetation and creature such as birds and small animals in and along the discharged creek and ii) wastewater from the local industrial zone outside of Thilawa SEZ and iii) delivered from surrounding area by tidal effect.

As for the result of iron, the result at the monitoring point of surface water monitoring point (SW-4) exceeded the target value due to the influence of natural origin (iron can reach out from the soil by run-off). Japan set effluent standards for two items as follows; i) health item and ii) living environment item. In the health item, there is no standard value for iron. On the other hand, for the living environment item, the standard value for soluble iron level is 10 mg/L. As the comparison with the living environment standard value in Japan, iron results in (SW-4) is lower than the standard value. Therefore, it can be considered that there is no significant impact on the living environment.

As for the result of the iron, the result at the monitoring point of reference tube well (GW-2) exceeded the target value. Comparison with previous monitoring results of reference tube well (GW-2), the iron concentration results ranged from 3.076 mg/l (August, 2019) – 8.310 mg/l (October, 2021) and most of the iron concentration measured results (from April, 2019 to December, 2021) exceeded the target value except the iron concentration result of August, 2019. Therefore, the possible reasons may due to the influence of natural origin (iron can reach out from soil by run-off). In Yangon, soil is naturally rich in iron.

As for future subject for main discharged points of Thilawa SEZ Zone B, the following action may be taken to maintain the target value of SS and total coliform and appropriate water quality monitoring:

- 1) To continue monitoring *Escherichia coli* (E. coli) level to identify health impact by coliform bacteria;
- 2) To monitor the possibility of the overflow water from construction sites; and
- 3) To monitor the possibility of the domestic wastewater from construction sites.

End of the Document



APPENDIX-1 FIELD SURVEY PHOTOS



FOR DISCHARGED POINT OF THILAWA SEZ ZONE B



Surface water sampling and onsite measurement at SW-7

**FOR REFERENCE MONITORING POINTS FOR COMPARISON WITH DISCHARGED
POINTS AND BASELINE OF DISCHARGED CREEK**



Surface water sampling and onsite measurement at SW-2



Surface water sampling and onsite measurement at SW-4



Ground water sampling and onsite measurement at GW-2



APPENDIX-2 LABORATORY RESULTS



**FOR REFERENCE MONITORING POINTS FOR COMPARISON WITH DISCHARGED
POINTS AND BASELINE OF DISCHARGED CREEK**

DOWA

ANALYSIS REPORT FOR WATER MONITORING
100 No. 1, Thilawa SEZ Zone B, Thilawa Region, Myanmar
Phone No. 09-55111111



Report No. : DOW-LAB-20211214-01
Revision No. : 1
Report Date : 28 December, 2021
Application No. : 001-001

Analysis Report

Client Name : Myanmar Kim International (TD) (MKI)
Address : No. 26/A, 1st Floor, Gilded Plaza Semi-Commercial Bldg (near Road), Thilawa Township, Yangon Region
Project Name : Environmental Monitoring report for Zone A & B
Sample Description :
Sample Name : MKI-SW-2-1214
Sample No. : W-2112076
Water Profile No. :
Sampling Date : 14 December, 2021
Sampling By : Customer
Sample Received Date : 14 December, 2021

No.	Parameter	Method	Unit	Result	LOQ
1	SS	APHA 2540D (Dry at 105 °C Method)	mg/L	18	—
2	BOD (5)	APHA 5210B (5 days 20 °C Test)	mg/L	1.99	0.10
3	COD (Cr)	APHA 5210B (Open Reflux Colorimetric Method)	mg/L	14.3	0.1
4	Total Coliform	APHA 9222B (Standard Total Coliform Fermentation Technique)	MPN/100mL	2000	1.0
5	Oil and Grease	APHA 9222B (Petroleum Dispersant Method)	mg/L	< 1.1	0.1
6	Total Nitrogen	HACH Method 10072 (NBT Peroxide Digestion Method)	mg/L	1.2	0.05
7	Color	APHA 2130C (Spectrophotometric Method)	PCU	17.86	0.00
8	Chlor	APHA 2130B (Thiosulfate Color Test)	TCN	1	0
9	TSS	APHA 2540C (Total Suspended Solids Dried at 105 °C Method)	mg/L	1025	—
10	Mercury	APHA 3120B (Inductively Coupled Plasma (ICP) Method)	mg/L	< 0.002	0.002
11	Cadmium	APHA 3120B (Inductively Coupled Plasma (ICP) Method)	mg/L	< 0.002	0.002
12	Lead	APHA 3120B (Inductively Coupled Plasma (ICP) Method)	mg/L	< 0.010	0.010
13	Chromium	APHA 3120B (Inductively Coupled Plasma (ICP) Method)	mg/L	< 0.002	0.002
14	Copper	APHA 3120B (Inductively Coupled Plasma (ICP) Method)	mg/L	< 0.002	0.002
15	Selenium	APHA 3120B (Inductively Coupled Plasma (ICP) Method)	mg/L	< 0.002	0.002
16	Iron	APHA 3120B (Ind			

Water Quality Monitoring Report for Development of Industrial Area in Thilawa SEZ, Zone B
(Bi-Annually Monitoring in FY December - 2021)

DOWA

JICA Limited (100% owned subsidiary of JICA)
100-100, Thilawa SEZ Zone B Yangon Region, Myanmar
Phone No. 09-5511111111



Report No. : GEM-LAB-2021-12144
Revision No. : 1
Report Date : 26 December, 2021
Application No. : 0001/2021

Analysis Report

Client Name : Myanmar Rail International LTD (MRI)
Address : No. 35/A, 1st Floor, Grand Pina Hotel Condominium, Pina Hotel Road, Yangon Township, Yangon, Myanmar
Project Name : Environmental Monitoring (open for Zone A & B)
Sample Description :
Sample Name : WQ-SW-A-1224
Sample No. : W-21-12277
Water Profile No. :
Sampling Date : 14 December, 2021
Sampling By : Customer
Sample Received Date : 14 December, 2021

No.	Parameter	Method	Unit	Result	LOG
1	PH	APHA 2540B (Free at 25°C Method)	mg/L	7.89	-
2	BOD (5)	APHA 521B B (5 Days 20°C Test)	mg/L	3.87	0.59
3	COD (Cr)	APHA 5220B (Dichromate Reflux Titrimetric Method)	mg/L	19.8	0.3
4	Total Coliform	APHA 5211B (Standard Total Coliform Fermentation Technique)	MPN/100ml	>140000	1.8
5	Oil and Grease	APHA 5520B (Filtration-Graevess Method)	mg/L	< 3.1	3.1
6	Total Nitrogen	NACH Method 10077 (NLT Persulfate Digestion Method)	mg/L	0.4	0.6
7	Copper	APHA 3120C (Spectrophotometric Method)	TCU	1.85	0.24
8	Lead	APHA 3130 B (Threshold Lead Test)	TCM	1	0
9	CDS	APHA 2540 C (Total Dissolved Solids Dried at 180°C Method)	mg/L	624	-
10	Mercury	APHA 3120 B (Inductively Coupled Plasma (ICP) Method)	mg/L	< 0.002	0.303
11	Fluoride	APHA 3130 B (Inductively Coupled Plasma (ICP) Method)	mg/L	0.040	0.040
12	Arsenic	APHA 3130 B (Inductively Coupled Plasma (ICP) Method)	mg/L	< 0.010	0.010
13	Chromium	APHA 3130 B (Inductively Coupled Plasma (ICP) Method)	mg/L	< 0.002	0.002
14	Cadmium	APHA 3130 B (Inductively Coupled Plasma (ICP) Method)	mg/L	< 0.002	0.002
15	Selenium	APHA 3130 B (Inductively Coupled Plasma (ICP) Method)	mg/L	< 0.010	0.010
16	Iron	APHA 3120 B (Inductively Coupled Plasma (ICP) Method)	mg/L	< 0.002	0.002
17	Zinc	APHA 3130 B (Inductively Coupled Plasma (ICP) Method)	mg/L	< 0.002	0.002
18	Barium	APHA 3130 B (Inductively Coupled Plasma (ICP) Method)	mg/L	0.030	0.030
19	Strontium	APHA 3130 B (Inductively Coupled Plasma (ICP) Method)	mg/L	< 0.002	0.002
20	Silver	APHA 3130 B (Inductively Coupled Plasma (ICP) Method)	mg/L	< 0.002	0.002
21	Manganese	APHA 3130 B (Inductively Coupled Plasma (ICP) Method)	mg/L	0.004	0.004
22	Granite	NACH 8027 (Perchloric-Hydrogen Method)	mg/L	0.012	0.012
23	Total Chloride	Merckman Method 100-01 (M. C. 100-01 Chloride after 100-01 Chloride, Volatile Chloride Determination Method: NACH 8027 Method: Hydrogen Method)	mg/L	0.010	0.010
24	Ammmonia	NACH Method 10077 (Spectrophotometric Method)	mg/L	1.44	0.15
25	Resuspended Chloride (CDS)	ISO 11063:2004 (Determination of chloride (Cl) Spectrophotometric method using 2,5-dichlorophenol)	mg/L	< 0.05	0.05
26	Fluoride	APHA 3120 B (Spectrophotometric Method: Chemical Reduction of Fluoride to Fluoride)	mg/L	1.302	0.014
27	Free Chlorine	APHA 4500 Cl ₂ B (DPD-Colorimetric Method)	mg/L	< 0.1	0.1
28	Total Available Chlorine	APHA 4500 Cl ₂ B (DPD-Colorimetric Method)	mg/L	0.1	0.1
29	Sulfate	NACH 8111 (Spectrophotometric Method)	mg/L	0.271	0.025
30	Nitrate/Nitrite	NACH 8110 (NACH Method)	mg/L	0.012	0.003
31	Phosphate	NACH Method 8027 (Spectrophotometric Method: Molybdenum Blue Method)	mg/L	0.002	0.002

Notes : LOG = Limit of Quantitation
APHA : American Public Health Association (APHA), the American Water Works Association (AWWA), and the Water Environment Federation (WEF), Standard Methods for the Examination of Water and Wastewater, 22nd edition.

Analysed By :

N. N. Pye Linn
Assistant Manager



Approved By :

Manager Director
Dec 28, 2021



Water Quality Monitoring Report for Development of Industrial Area in Thilawa SEZ Zone B
(Bi-Annually Monitoring in FY December - 2021)

DOWA

2021-22, 2021-22-2021-22 (2021-22-2021-22)
2021-22, 2021-22, 2021-22, 2021-22, 2021-22
Water No. 2021-22, 2021-22, 2021-22



Report No.: DOW-LAB-2021-22-2021-22
Revision No.: 1
Report Date: 28 December, 2021
Application No.: 0001-0001


Analysis Report

Client Name: Myanmar Agricultural Ltd (MAL)
Address: No. 36/A, 1st Floor, Grand Ma Sein Condominium, The Beer Road, Tawm Township, Yangon, Myanmar
Project Name: Environment Monitoring report for Zone A & B
Sample Description: Water Profile No. 1
Sample Name: H2O-1-1234
Sample No.: W-2112000
Sampling Date: 14 December, 2021
Sampling By: Customer
Sample Received Date: 14 December, 2021

No.	Parameter	Method	Unit	Result	LOQ
1	EC	APHA 25401 (Dry at 103-103°C Method)	mg/l	0	—
2	WDO (3)	APHA 5210 B (5 Days BOD Test)	mg/l	8.80	0.00
3	DO (3)	APHA 5210 B (5 Days BOD Test)	mg/l	+ 0.7	0.7
4	Total Coliform	APHA 9222 B (Standard Total Coliform Fermentation Technique)	MPN/100ml	1.8	1.8
5	Oil and Grease	APHA 5530 B (Petroleum Grease Method)	mg/l	+ 1.1	1.1
6	Total Nitrogen	HACH Method 10072 (TNT Persulfate Digestion Method)	mg/l	0.8	0.5
7	Coke	APHA 2130 C (Spectrophotometric Method)	TCU	42.34	0.00
8	Odor	APHA 2130 B (Threshold Odor Test)	ODN	1	0
9	TSS	APHA 25401 (Total Dissolved Solids Dried at 180°C Method)	mg/l	152	—
10	Mercury	APHA 3120 B (Inductively Coupled Plasma (ICP) Method)	mg/l	+ 0.001	0.001
11	Zinc	APHA 3120 B (Inductively Coupled Plasma (ICP) Method)	mg/l	0.006	0.001
12	Arsenic	APHA 3120 B (Inductively Coupled Plasma (ICP) Method)	mg/l	0.001	0.001
13	Chromium	APHA 3120 B (Inductively Coupled Plasma (ICP) Method)	mg/l	0.001	0.001
14	Cadmium	APHA 3120 B (Inductively Coupled Plasma (ICP) Method)	mg/l	0.001	0.001
15	Lead	APHA 3120 B (Inductively Coupled Plasma (ICP) Method)	mg/l	0.001	0.001
16	Copper	APHA 3120 B (Inductively Coupled Plasma (ICP) Method)	mg/l	0.001	0.001
17	Manganese	APHA 3120 B (Inductively Coupled Plasma (ICP) Method)	mg/l	0.001	0.001
18	Selenium	APHA 3120 B (Inductively Coupled Plasma (ICP) Method)	mg/l	0.001	0.001
19	Iron	APHA 3120 B (Inductively Coupled Plasma (ICP) Method)	mg/l	0.001	0.001
20	Aluminum	APHA 3120 B (Inductively Coupled Plasma (ICP) Method)	mg/l	0.001	0.001
21	Silver	APHA 3120 B (Inductively Coupled Plasma (ICP) Method)	mg/l	0.001	0.001
22	Chlorine	APHA 3120 B (Inductively Coupled Plasma (ICP) Method)	mg/l	0.001	0.001
23	Cyanide	HACH 8007 (Pyridine-Hydroxide Method)	mg/l	0.001	0.001
24	Total Cyanide	APHA 9222 B (Standard Total Cyanide Fermentation Technique)	mg/l	0.001	0.001
25	Arsenic	HACH Method 10072 (Spectrophotometric Method)	mg/l	0.001	0.001
26	Hexavalent Chromium (Cr+6)	ISO 11083 (Spectrophotometric Method)	mg/l	0.001	0.001
27	Fluoride	APHA 4500 F (Spectrophotometric Method)	mg/l	0.014	0.014
28	Total Chlorine	APHA 4500 Cl (Spectrophotometric Method)	mg/l	0.01	0.01
29	Total Residual Chlorine	APHA 4500 Cl (Spectrophotometric Method)	mg/l	0.01	0.01
30	Ammonia	HACH 8111 (Nesslerization Method)	mg/l	0.001	0.001
31	Ammonia Nitrogen	HACH 8111 (Nesslerization Method)	mg/l	0.001	0.001
32	Bacterial Coli	APHA 9222 B (Standard Total Coliform Fermentation Technique)	MPN/100ml	1.8	1.8
33	Phenols	APHA 8210 (Spectrophotometric Method)	mg/l	0.001	0.001

Remarks: LOQ - Limit of Quantitation
APHA - American Public Health Association (APHA), the American Water Works Association (AWWA), and the Water Environment Federation (WEF), Standard Methods for the Examination of Water and Wastewater, 22nd edition

Analyst By:
N. N. Aye Linn
Assistant Manager



Approved By:
N. N. Aye Linn
Assistant Manager



**Thilawa Special Economic Zone
Zone B- Phase 1,2 & 3 (Operation phase)**

Appendix-C

Air Quality Monitoring Report

December 2021

**AIR QUALITY MONITORING
REPORT
FOR DEVELOPMENT OF INDUSTRIAL AREA
THILAWA SEZ ZONE B
(PHASE 1, 2 & 3 OPERATION STAGE)**

(BI-ANNUALLY MONITORING)

**December 2021
Myanmar Koci International Ltd.**



TABLE OF CONTENTS

CHAPTER 1: OUTLINES AND SUMMARY OF MONITORING PLAN	1
1.1 General	1
1.2 Outlines of Monitoring Plan	1
CHAPTER 2: AIR QUALITY MONITORING	2
2.1 Monitoring Item	2
2.2 Monitoring Location	2
2.3 Monitoring Period	2
2.4 Monitoring Method	3
2.5 Monitoring Results	3
CHAPTER 3: CONCLUSION AND RECOMMENDATION	8
APPENDIX-1 HOURLY AIR RESULTS	A1-1
APPENDIX-2 CERTIFICATE OF CALIBRATION	A2-1

LIST OF TABLES

Table 1.2-1 Outlines of Air Quality Monitoring Plan	1
Table 2.5-1 Air Quality Monitoring Result (Daily Average)	3
Table 2.5-2 Total Exceeded Hours	5
Table 2.5-3 Total Exceeded Hours and Wind Direction for $PM_{2.5}$	5
Table 2.5-4 Total Exceeded Hours and Wind Direction for PM_{10}	6
Table 2.5-5 Total Exceeded Hours and Wind Direction for SO_2	7
Table 2.5-6 Summary of Wind Direction at AQ-1	7

LIST OF FIGURES

Figure 2.2-1 Location of Air Quality Monitoring Point	2
Figure 2.4-1 Status of Air Quality Monitoring Point	3
Figure 2.5-1 Status of Air Quality Monitoring Point and Wind Direction	4



CHAPTER 1: OUTLINES AND SUMMARY OF MONITORING PLAN

1.1 General

Thilawa Special Economic Zone (TSEZ) is located in southern district of Yangon region and about 23 km southeast of Yangon city. As the developer of Thilawa SEZ, Myanmar Japan Thilawa Development Ltd. (MJTD) has a responsibility to carry out regular environmental monitoring in the industrial area of Zone B in accordance with the approved Environmental Impact Assessment (EIA) report with Environmental Management Plan (EMP). MJTD has implemented monitoring various environmental items with the specified time frame to know the environmental conditions in and around the area.

1.2 Outlines of Monitoring Plan

To assess the environmental condition under the operation of industrial area in and around Thilawa SEZ Zone B, air quality had been monitored from 22 December 2021 -- 29 December 2021 as follows:

Table 1.2-1 Outlines of Air Quality Monitoring Plan

Monitoring Date	Monitoring Item	Parameters	Number of Point	Duration	Monitoring Methodology
From 22 December – 29 December, 2021	Air Quality	CO, NO _x , PM _{2.5} , PM ₁₀ and SO ₂	1	7 Days	On site measurement by Hcz-Scanner Environmental Perimeter Air Station (EPAS)

Source: Myanmar Koei International Ltd



CHAPTER 2: AIR QUALITY MONITORING

2.1 Monitoring Item

The parameters for air quality monitoring were CO, NO₂, PM_{2.5}, PM₁₀ and SO₂.

2.2 Monitoring Location

The air quality measurement equipment, "Haz-Scanner Environmental Perimeter Air Station (EPAS)" was set up at the south of the Thilawa SEZ Zone B, N: 16°39'24.20", E: 96°17'15.80", inside the monastery compound of Phalan village, surrounded by the residential houses of Phalan village in the south and fields in west, Thilawa SEZ Zone A in north, local Thilawa Industrial Zone in northeast and operation of Thilawa SEZ Zone B in east, north, north-northwest, northwest and northeast respectively. The air quality monitoring is carried out above location where is near to the residential houses of Phalan village. Possible emission sources are dust emissions from construction activities and exhaust gas emissions from construction fuel-burning equipment and daily human activities in Phalan village. The location of air quality monitoring is shown in the Figure 2.2-1.



Figure 2.2-1 Location of Air Quality Monitoring Point

2.3 Monitoring Period

Air quality monitoring was conducted seven consecutive days from 22 December, 2021 – 29 December, 2021.

2.4 Monitoring Method

Monitoring of CO, NO₂, PM_{2.5}, PM₁₀ and SO₂ were conducted by referring to the recommendation of the United States Environmental Protection Agency (U.S. EPA). The Haz-Scanner EPAS was used to collect ambient air pollutants. The EPAS measures automatically every one minute and directly reads and records onsite for CO, NO₂, PM_{2.5}, PM₁₀ and SO₂. The status of air quality monitoring is shown in Figure 2.4-1.



Source: Myanmar Ksei International Ltd.

Figure 2.4-1 Status of Air Quality Monitoring Point

2.5 Monitoring Results

The daily average value of air quality monitoring results of CO, NO₂, PM_{2.5}, PM₁₀ and SO₂ are described in Table 2.5-1. Comparing with the target value of CO, NO₂, PM_{2.5}, PM₁₀ and SO₂ prescribed in EIA report for Thilawa SEZ development project Zone B, seven days average concentration of CO, NO₂, PM₁₀ and SO₂ were lower than the target value. However, daily average concentration of PM₁₀ measured results for one day and daily average concentration of SO₂ measured results for two days exceeded the target value. As for PM_{2.5}, seven days average concentration and daily average concentration for six days exceeded the target value. However, when compared with the PM_{2.5} daily average value of environmental standards by Ministry of Environment Japan (MOEJ) which is 35 µg/m³ (0.035 mg/m³), only three days exceeded.

Table 2.5-1 Air Quality Monitoring Result (Daily Average)

Date	CO	NO ₂	PM _{2.5}	PM ₁₀	SO ₂
	mg/m ³	mg/m ³	mg/m ³	mg/m ³	mg/m ³
22-23 December, 2021	0.100	0.092	0.035	0.043	0.022
23-24 December, 2021	0.146	0.085	0.019	0.027	0.016
24-25 December, 2021	0.117	0.086	0.033	0.041	0.015
25-26 December, 2021	0.200	0.076	0.038	0.047	0.027
26-27 December, 2021	0.122	0.082	0.040	0.057	0.020
27-28 December, 2021	0.112	0.080	0.038	0.045	0.018
28-29 December, 2021	0.130	0.082	0.035	0.042	0.020
7 Days Average Value	0.132	0.083	0.035	0.043	0.020
Target Value	10.26	0.1	0.025	0.05	0.02

Note: Red color mentions the exceeded value for PM_{2.5}, PM₁₀ and SO₂.

The target value of CO, NO₂ and SO₂ were converted from ppm units to mg/m³. The conversion equation are as follows.

1. $(CO, \text{mg/m}^3) = (CO, \text{ppm}) \times (\text{Molecular Weight of CO (28)}) / 24.45 \text{ at } 25^\circ\text{C and 1 atm condition}$
2. $(NO_2, \text{mg/m}^3) = (NO_2, \text{ppm}) \times (\text{Molecular Weight of NO}_2 (46)) / 24.45 \text{ at } 25^\circ\text{C and 1 atm condition}$
3. $(SO_2, \text{mg/m}^3) = (SO_2, \text{ppm}) \times (\text{Molecular Weight of SO}_2 (64)) / 24.45 \text{ at } 25^\circ\text{C and 1 atm condition}$

Source: Myanmar Ksei International Ltd.

Wind direction and wind speed were measured at AQ-1. Hourly average values of measured wind direction and wind speed data are described in Appendix-1. Status of air quality monitoring point and

wind direction are described in Figure 2.5-1. Depending on the wind direction, West-Northwest (WNW), Northwest (NW), North-Northwest (NNW), North (N), North-Northeast (NNE), Northeast (NE), East-Northeast (ENE) and East (E) directions are assumed to come from the operation site of Zone B.



Source: Google Earth

Figure 2.5-1 Status of Air Quality Monitoring Point and Wind Direction

Remark: N North **NNE** North-Northeast **NE** Northeast **ENE** East-Northeast **E** East **ESE** East-Southeast **SE** Southeast **SSE** South-Southeast
S South **SSW** South-Southwest **SW** Southwest **WSW** West-Southwest **W** West **WNW** West-Northwest **NW** Northwest **NNW** North-Northwest

There were no construction activities during this monitoring period.

Overall summary of total exceeded hours during the seven days monitoring period are shown in Table 2.5-2. According to the daily average values, (Day 1 and Day 3 to Day 7) daily values for $PM_{2.5}$, (Day 5) daily values for PM_{10} and (Day 1 and Day 4) for SO_2 are higher than the target value.

For $PM_{2.5}$, the total exceeded hours for seven days were 82 hours, Day 1 and Day 3 to Day 7 exceeded hours was 77 hours and wind direction are shown in Table 2.5-3. Most of the exceeded hours are come from North (N), North-Northeast (NNE), Northeast (NE), East-Northeast (ENE), East (E), East-Southeast (ESE), Southeast (SE), South-Southeast (SSE), South (S), South-Southwest (SSW), Southwest (SW), West-Southwest (WSW), West (W), West-Northwest (WNW) and Northwest (NW).

For PM_{10} , the total exceeded hours for seven days were 63 hours, Day 5 exceeded hours was 13 hours and wind direction are shown in Table 2.5-4. Most of the exceeded hours are come from Northeast (NE), East (E), South-Southwest (SSW), Southwest (SW), West-Southwest (WSW), West (W), West-Northwest (WNW) and Northwest (NW).



For SO₂, the total exceeded hours for seven days were 31 hours, Day 1, and Day 4 hours was 12 hours and wind direction are shown in Table 2.5-5. Most of the exceeded hours are come from Southeast (SE), South-Southeast (SSE), South-Southwest (SSW), Southwest (SW), West-Southwest (WSW), West (W), and West-Northwest (WNW).

According to the summary of wind direction at AQ-1, 34.0 % come from outside of Zone B and 66.0 % come from inside of Zone B are shown in Table 2.5-6.

Possible emission sources for PM_{2.5} and PM₁₀ are affected from natural origin such as dust from unpaved land area from outside of Zone B and transportation in and around the monitoring area.

Possible emission sources for SO₂ are affected from the combustion of fuel for vehicles from nearby roads, operation activities of Thilawa Port, operation activities of local industrial zone and operation activities of Zone B.

Table 2.5-2 Total Exceeded Hours

	Parameters	Total Exceeded Hours
Day 1 ~ Day 7	PM _{2.5}	82
	PM ₁₀	63
	SO ₂	31

Source: Myanmar Kwei International Ltd.

Table 2.5-3 Total Exceeded Hours and Wind Direction for PM_{2.5}

Day	Time	PM _{2.5}	Wind Direction
Day 1	12:00 ~ 12:59	0.119	SSW
	14:00 ~ 14:59	0.037	SE
	17:00 ~ 17:59	0.035	SE
	18:00 ~ 18:59	0.077	E
	19:00 ~ 19:59	0.080	SSW
	20:00 ~ 20:59	0.073	SE
	21:00 ~ 21:59	0.055	ENE
	02:00 ~ 02:59	0.063	WSW
	03:00 ~ 03:59	0.044	SW
Day 2	04:00 ~ 04:59	0.064	E
	12:00 ~ 12:59	0.063	E
	13:00 ~ 13:59	0.078	SE
	15:00 ~ 15:59	0.084	SSW
	16:00 ~ 16:59	0.077	S
	18:00 ~ 18:59	0.066	SW
	19:00 ~ 19:59	0.091	ESE
	20:00 ~ 20:59	0.106	SE
Day 4	21:00 ~ 21:59	0.067	WNW
	14:00 ~ 14:59	0.044	SW
	15:00 ~ 15:59	0.051	WSW
	16:00 ~ 16:59	0.040	WSW
	17:00 ~ 17:59	0.028	SW
	18:00 ~ 18:59	0.082	W
	19:00 ~ 19:59	0.090	W
	20:00 ~ 20:59	0.058	NE
	21:00 ~ 21:59	0.110	ENE
	22:00 ~ 22:59	0.119	SE
	23:00 ~ 23:59	0.063	WNW
	06:00 ~ 06:59	0.028	ESE
Day 5	07:00 ~ 07:59	0.067	NW
	15:00 ~ 15:59	0.068	SW
	16:00 ~ 16:59	0.094	SSW
	17:00 ~ 17:59	0.107	SSW
	18:00 ~ 18:59	0.043	SW
	19:00 ~ 19:59	0.029	S
	20:00 ~ 20:59	0.062	SSW
	21:00 ~ 21:59	0.090	W



	22:00 ~ 22:59	0.094	W
	23:00 ~ 23:59	0.061	NW
	00:00 ~ 00:59	0.078	NE
	01:00 ~ 01:59	0.070	NE
	02:00 ~ 02:59	0.036	SSW
	03:00 ~ 03:59	0.065	E
	04:00 ~ 04:59	0.059	NE
	05:00 ~ 05:59	0.073	WNW
	06:00 ~ 06:59	0.064	WSW
	07:00 ~ 07:59	0.030	ENE
Day 6	16:00 ~ 16:59	0.046	SE
	17:00 ~ 17:59	0.028	SE
	18:00 ~ 18:59	0.046	SE
	19:00 ~ 19:59	0.059	ESE
	20:00 ~ 20:59	0.054	S
	21:00 ~ 21:59	0.059	SW
	22:00 ~ 22:59	0.087	SSE
	23:00 ~ 23:59	0.034	E
	00:00 ~ 00:59	0.076	ENE
	01:00 ~ 01:59	0.051	SE
	02:00 ~ 02:59	0.057	S
	03:00 ~ 03:59	0.056	W
	04:00 ~ 04:59	0.050	NNE
	05:00 ~ 05:59	0.048	SE
Day 7	06:00 ~ 06:59	0.044	W
	07:00 ~ 07:59	0.043	N
	15:00 ~ 15:59	0.039	E
	17:00 ~ 17:59	0.044	SSE
	18:00 ~ 18:59	0.076	SSE
	19:00 ~ 19:59	0.077	ESE
	20:00 ~ 20:59	0.087	E
	21:00 ~ 21:59	0.077	E
	22:00 ~ 22:59	0.050	ESE
	23:00 ~ 23:59	0.068	ESE
	00:00 ~ 00:59	0.047	WSW
	02:00 ~ 02:59	0.050	SSW
	03:00 ~ 03:59	0.038	ESE
	04:00 ~ 04:59	0.031	WNW
	05:00 ~ 05:59	0.038	SW
	06:00 ~ 06:59	0.041	WSW

Note: Time Duration when PM_{2.5} Values are exceeded over Target Value (0.025 mg/m³)
Source: Myanmar Koei International Ltd.

Table 2.5-4 Total Exceeded Hours and Wind Direction for PM₁₀

Day	Time	PM ₁₀	Wind Direction
Day 5	15:00 ~ 15:59	0.080	SW
	16:00 ~ 16:59	0.099	SSW
	17:00 ~ 17:59	0.119	SSW
	20:00 ~ 20:59	0.063	SSW
	21:00 ~ 21:59	0.096	W
	22:00 ~ 22:59	0.103	W
	23:00 ~ 23:59	0.069	NW
	00:00 ~ 00:59	0.089	NE
	01:00 ~ 01:59	0.078	NE
	03:00 ~ 03:59	0.075	E
	04:00 ~ 04:59	0.064	NE
	05:00 ~ 05:59	0.082	WNW
	06:00 ~ 06:59	0.070	WSW

Note: Time Duration when PM₁₀ Values are exceeded over Target Value (0.05 mg/m³)
Source: Myanmar Koei International Ltd.



Table 2.5-5 Total Exceeded Hours and Wind Direction for SO₂

Day	Time	SO ₂	Wind Direction
Day 1	12:00 ~ 12:59	0.056	SSW
	13:00 ~ 13:59	0.080	SSE
	14:00 ~ 14:59	0.060	SE
	15:00 ~ 15:59	0.055	SE
	16:00 ~ 16:59	0.028	SE
Day 4	10:00 ~ 10:59	0.035	SE
	11:00 ~ 11:59	0.055	SSW
	12:00 ~ 12:59	0.054	W
	13:00 ~ 13:59	0.083	WSW
	14:00 ~ 14:59	0.084	WNW
	15:00 ~ 15:59	0.080	SW
	16:00 ~ 16:59	0.037	WSW

Note: Time Duration when SO₂ Values are exceeded over Target Value (0.03 mg/m³)

Source: Myanmar Koei International Ltd.

Table 2.5-6 Summary of Wind Direction at AQ-1

Wind Direction	All Day	Day-Time	Night Time	Inside/Outside Zone B	
N	16.1%	19.6%	12.5%	49.8%	Inside Zone B
NNE	7.9%	9.7%	6.2%		
NE	12.8%	9.5%	16.1%		
ENE	9.4%	3.6%	15.3%		
E	3.6%	2.6%	4.6%		
ESE	4.5%	2.6%	6.3%	34.0%	Outside Zone B
SE	5.4%	6.0%	4.8%		
SSE	2.5%	3.0%	2.0%		
S	1.8%	1.6%	2.0%		
SSW	2.1%	2.8%	1.4%		
SW	5.7%	6.2%	5.2%		
WSW	7.4%	6.5%	8.3%		
W	4.8%	3.8%	5.8%		
WNW	3.2%	3.6%	2.8%	16.2%	Inside Zone B
NW	4.3%	6.3%	2.2%		
NNW	8.7%	12.7%	4.8%		

Source: Myanmar Koei International Ltd.



CHAPTER 3: CONCLUSION AND RECOMMENDATION

The result of seven days average air quality of CO, NO₂, PM₁₀ and SO₂ during seven days monitoring did not exceed the target value, thus there are no impacts on the surrounding environments. The result of seven days average air quality of PM_{2.5}, was higher than the target value. In addition, daily average concentration of PM_{2.5} measured results for six days, daily average concentration of PM₁₀ measured results for one day and daily average concentration of SO₂ measured results for two days exceeded the target value. During the seven days monitoring period, (Day 1 and Day 3 to day 7) daily average value for PM_{2.5}, (Day 5) daily average value for PM₁₀ and (Day 1 and Day 4) daily average value for SO₂ were higher than the target value.

During the seven days monitoring period, 82 hours results were exceeded for PM_{2.5}. According to wind direction of Zone B during the monitoring period, total 77 exceeded hours are come from North (N), North-Northeast (NNE), Northeast (NE), East-Northeast (ENE), East (E), East-Southeast (ESE), Southeast (SE), South-Southeast (SSE), South (S), South-Southwest (SSW), Southwest (SW), West-Southwest (WSW), West (W), West-Northwest (WNW) and Northwest (NW).

During the seven days monitoring period, 63 hours results were exceeded for PM₁₀. According to wind direction of Zone B during the monitoring period, total 13 exceeded hours are come from Northeast (NE), East (E), South-Southwest (SSW), Southwest (SW), West-Southwest (WSW), West (W), West-Northwest (WNW) and Northwest (NW).

Possible emission sources for PM_{2.5} and PM₁₀ are affected from natural origin such as dust from unpaved land area from outside of Zone B and transportation in and around the monitoring area.

According to US Environmental Protection Agency (EPA) and WHO's health effect of particulate matter, there is no evidence of safe level of exposure or a threshold below which no adverse health effects occur. Exposure to PM_{2.5} and PM₁₀ reduces the life expectancy of the population of the Region by about 8.6 months on average. Short term (hours, days) exposure to PM_{2.5} and PM₁₀ can aggravate lung disease, causing asthma attacks and acute bronchitis, and may also increase susceptibility to respiratory infections. In people with heart disease, short term exposures have been linked to heart attacks and arrhythmias. However, healthy children and adults have not been reported to suffer serious effects from short term exposures. Long term exposures (months, years) have been associated with problems such as reduced lung function and the development of chronic bronchitis and even premature death. Even though the daily average values exceeded the target values, it does not exceed the level I guideline for alert by MOEJ which is equal to or less than 70 µg/m³ (0.07 mg/m³). Therefore, it can be considered to have no serious health impact and it is not necessary to avoid outside activities, however, it is desirable for high sensitive receptors to pay attention to their health condition considering the potential impact.

During the seven days monitoring period, 31 hours results were exceeded for SO₂. According to wind direction of Zone B during the monitoring period, total 12 exceeded hours are come from Southeast (SE), South-Southeast (SSE), South-Southwest (SSW), Southwest (SW), West-Southwest (WSW), West (W), and West-Northwest (WNW). Possible emission sources for SO₂ are affected from the combustion of fuel for vehicles from nearby roads, operation activities of Thilawa Port, operation activities of local industrial zone and operation activities of Zone B. In the public health statement SO₂ reported by ATSDR (Agency for Toxic Substances and Disease Registry) in US, 100 ppm (261.8 mg/m³) SO₂ is considered immediately dangerous to life and health (short term). Lung function changes observed when 0.4 to 3 ppm (1.05mg/m³ to 7.85 mg/m³) exposure for 20 years or more (long term). Therefore, although the target value of SO₂ was exceeded during monitoring period but it is considered that there is no significant impact on human health.

As for future subject for air quality monitoring in Zone B, the following action may be taken to achieve the target level:

- 1) To control the speed limit of all machinery & vehicle (25km/hr) on site to avoid excessive dust creation and to minimize air pollution by the exhaust fumes.



- 2) To conduct the proper operation (stop idling while no operation).
- 3) To implement the regular maintenance of machine used for construction activities.
- 4) To give awareness training to workers on machinery.
- 5) To check and maintain the generator regularly.

The periodical monitoring will be necessary to grasp the environmental conditions in operation stage of Thilawa SEZ Zone B. The mitigation measures for environmental management will be considered in collected periodical environmental data and has to be reviewed in future.



APPENDIX-1 HOURLY AIR RESULTS



Air Quality Monitoring Report for Development of Industrial Area Thilawa SEZ Zone B
(Phase 1, 2 & 3 Operation Stage, FY December 2021)

Date	Time		CO	NO _x	PM _{2.5}	PM ₁₀	SO ₂	Wind Speed	Wind Direction	
			mg/m ³ Hourly	mg/m ³ Hourly	mg/m ³ Hourly	mg/m ³ Hourly	mg/m ³ Hourly	m/s Hourly	Day	Hourly
22 Dec, 2021	10:00	-- 10:59	0.021	0.009	0.035	0.019	0.017	0.15	165	ESR
22 Dec, 2021	11:00	-- 11:59	0.023	0.009	0.008	0.013	0.023	0.58	147	SSE
22 Dec, 2021	12:00	-- 12:59	0.025	0.009	0.115	0.141	0.056	0.75	213	SSW
22 Dec, 2021	13:00	-- 13:59	0.023	0.009	0.002	0.011	0.080	0.87	151	SSP
22 Dec, 2021	14:00	-- 14:59	0.012	0.009	0.037	0.060	0.030	0.83	159	SP
22 Dec, 2021	15:00	-- 15:59	0.023	0.002	0.023	0.039	0.051	0.98	197	SE
22 Dec, 2021	16:00	-- 16:59	0.023	0.009	0.022	0.020	0.028	0.92	176	SE
22 Dec, 2021	17:00	-- 17:59	0.123	0.009	0.035	0.012	0.023	0.65	128	SE
22 Dec, 2021	18:00	-- 18:59	0.269	0.077	0.077	0.089	0.023	0.18	93	E
22 Dec, 2021	19:00	-- 19:59	0.145	0.090	0.060	0.098	0.023	0.03	195	SSW
22 Dec, 2021	20:00	-- 20:59	0.137	0.143	0.071	0.081	0.011	0.02	126	SR
22 Dec, 2021	21:00	-- 21:59	0.134	0.166	0.058	0.069	0.022	0.00	65	ENE
22 Dec, 2021	22:00	-- 22:59	0.167	0.160	0.010	0.015	0.012	0.12	148	SSE
22 Dec, 2021	23:00	-- 23:59	0.138	0.177	0.016	0.021	0.013	0.02	210	SSW
23 Dec, 2021	00:00	-- 00:59	0.035	0.157	0.021	0.026	0.023	0.00	203	SSW
23 Dec, 2021	01:00	-- 01:59	0.031	0.136	0.010	0.015	0.013	0.12	242	WSW
23 Dec, 2021	02:00	-- 02:59	0.067	0.140	0.003	0.067	0.013	0.12	249	WSW
23 Dec, 2021	03:00	-- 03:59	0.107	0.151	0.011	0.018	0.013	0.00	232	SW
23 Dec, 2021	04:00	-- 04:59	0.117	0.157	0.064	0.089	0.012	0.00	93	E
23 Dec, 2021	05:00	-- 05:59	0.150	0.156	0.010	0.015	0.012	0.07	55	NE
23 Dec, 2021	06:00	-- 06:59	0.230	0.256	0.010	0.015	0.013	0.07	52	NE
23 Dec, 2021	07:00	-- 07:59	0.083	0.171	0.020	0.015	0.013	0.02	78	ENT
23 Dec, 2021	08:00	-- 08:59	0.023	0.116	0.021	0.016	0.013	0.22	66	ENE
23 Dec, 2021	09:00	-- 09:59	0.038	0.009	0.013	0.017	0.013	0.43	279	W
Max			0.269	0.177	0.119	0.143	0.060			
Avg			0.100	0.092	0.035	0.043	0.023			
Min			0.025	0.009	0.002	0.011	0.012			



Air Quality Monitoring Report for Development of Iskcon Area Thilawa SEZ Zone B
(Phase 1, 2 & 3 Operation Stage FY December 2021)

Date	Time	CO	NO _x	PM ₁₀	PM _{2.5}	SO ₂	Wind Speed m/s	Wind Direction	
		mg/m ³ Hourly	mg/m ³ Hourly	mg/m ³ Hourly	mg/m ³ Hourly	mg/m ³ Hourly		Deg. Hourly	Direction Hourly
23 Dec, 2021	10:00 – 10:59	0.027	0.009	0.015	0.019	0.013	0.50	299.17	WNW
23 Dec, 2021	11:00 – 11:59	0.291	0.010	0.022	0.037	0.018	0.31	310.83	NW
23 Dec, 2021	12:00 – 12:59	0.023	0.010	0.010	0.022	0.024	0.37	305.67	NW
23 Dec, 2021	13:00 – 13:59	0.023	0.009	0.014	0.036	0.040	0.78	269.33	W
23 Dec, 2021	14:00 – 14:59	0.023	0.010	0.040	0.060	0.043	0.87	271.17	W
23 Dec, 2021	15:00 – 15:59	0.031	0.009	0.060	0.078	0.013	0.38	345.50	WSW
23 Dec, 2021	16:00 – 16:59	0.219	0.009	0.029	0.047	0.013	0.30	272.83	W
23 Dec, 2021	17:00 – 17:59	0.435	0.010	0.043	0.081	0.013	0.08	129.83	SE
23 Dec, 2021	18:00 – 18:59	0.361	0.010	0.062	0.060	0.013	0.03	131.33	SE
23 Dec, 2021	19:00 – 19:59	0.420	0.061	0.030	0.015	0.013	0.00	43.67	NE
23 Dec, 2021	20:00 – 20:59	0.129	0.100	0.010	0.013	0.013	0.00	41.00	NE
23 Dec, 2021	21:00 – 21:59	0.000	0.132	0.010	0.013	0.013	0.02	60.67	ENE
23 Dec, 2021	22:00 – 22:59	0.058	0.135	0.010	0.013	0.013	0.02	46.17	NE
23 Dec, 2021	23:00 – 23:59	0.116	0.147	0.000	0.013	0.013	0.02	27.33	SNE
24 Dec, 2021	00:00 – 00:59	0.087	0.132	0.010	0.013	0.013	0.06	210.83	SSW
24 Dec, 2021	01:00 – 01:59	0.036	0.137	0.010	0.015	0.013	0.05	261.50	W
24 Dec, 2021	02:00 – 02:59	0.066	0.156	0.010	0.013	0.013	0.02	249.67	WSW
24 Dec, 2021	03:00 – 03:59	0.083	0.155	0.010	0.013	0.013	0.00	219.83	SW
24 Dec, 2021	04:00 – 04:59	0.125	0.155	0.010	0.015	0.013	0.02	62.50	SNE
24 Dec, 2021	05:00 – 05:59	0.108	0.155	0.010	0.013	0.013	0.00	18.67	ENE
24 Dec, 2021	06:00 – 06:59	0.356	0.160	0.010	0.013	0.013	0.00	41.83	NE
24 Dec, 2021	07:00 – 07:59	0.249	0.172	0.010	0.015	0.013	0.10	165.50	S
24 Dec, 2021	08:00 – 08:59	0.021	0.105	0.012	0.017	0.013	0.10	71.33	ENE
24 Dec, 2021	09:00 – 09:59	0.040	0.012	0.008	0.012	0.013	0.27	82.17	E

Max	0.581	0.173	0.060	0.078	0.049
Avg	0.146	0.083	0.019	0.027	0.010
Min	0.023	0.009	0.008	0.012	0.013



AQ Quality Monitoring Report for Development of Industrial Area Talwara STZ Zone B
(Phase 1, 2 & 3 Operation Stage, FY December 2021)

Date	Time		CO	NO _x	PM ₁₀	PM _{2.5}	SO ₂	Wind Speed	Wind Direction		
			mg/m ³ Hourly	mg/m ³ Hourly	mg/m ³ Hourly	mg/m ³ Hourly	mg/m ³ Hourly	m/s Hourly	Deg Hourly		
24 Dec, 2021	10:00	--	10:59	0.023	0.009	0.014	0.022	0.013	0.35	136.59	SE
24 Dec, 2021	11:00	--	11:59	0.023	0.009	0.008	0.017	0.022	0.23	195.50	SSW
24 Dec, 2021	12:00	--	12:59	0.023	0.009	0.003	0.009	0.017	0.47	85.13	E
24 Dec, 2021	13:00	--	13:59	0.023	0.009	0.078	0.090	0.014	0.55	134.67	SE
24 Dec, 2021	14:00	--	14:59	0.023	0.009	0.013	0.015	0.052	0.72	237.17	SW
24 Dec, 2021	15:00	--	15:59	0.023	0.009	0.064	0.091	0.027	0.72	197.83	SSW
24 Dec, 2021	16:00	--	16:59	0.061	0.009	0.077	0.081	0.015	0.53	187.50	S
24 Dec, 2021	17:00	--	17:59	0.177	0.009	0.021	0.016	0.013	0.29	251.67	WSW
24 Dec, 2021	18:00	--	18:59	0.403	0.011	0.566	0.074	0.013	0.15	220.83	SW
24 Dec, 2021	19:00	--	19:59	0.349	0.053	0.991	0.100	0.013	0.00	120.57	PSE
24 Dec, 2021	20:00	--	20:59	0.024	0.107	0.108	0.121	0.013	0.00	130.50	SA
24 Dec, 2021	21:00	--	21:59	0.218	0.138	0.067	0.077	0.013	0.00	111.30	ESE
24 Dec, 2021	22:00	--	22:59	0.088	0.140	0.010	0.015	0.013	0.00	102.30	ESb
24 Dec, 2021	23:00	--	23:59	0.056	0.162	0.010	0.015	0.013	0.00	66.15	T
25 Dec, 2021	00:00	--	00:59	0.078	0.161	0.015	0.015	0.012	0.00	117.20	ESE
25 Dec, 2021	01:00	--	01:59	0.071	0.157	0.010	0.015	0.013	0.00	125.00	Sb
25 Dec, 2021	02:00	--	02:59	0.097	0.147	0.010	0.015	0.013	0.00	123.73	ESb
25 Dec, 2021	03:00	--	03:59	0.076	0.155	0.010	0.015	0.013	0.02	77.50	ENT
25 Dec, 2021	04:00	--	04:59	0.087	0.158	0.010	0.015	0.012	0.03	63.89	ENE
25 Dec, 2021	05:00	--	05:59	0.151	0.151	0.013	0.015	0.012	0.05	82.83	E
25 Dec, 2021	06:00	--	06:59	0.293	0.163	0.010	0.015	0.013	0.03	234.50	SW
25 Dec, 2021	07:00	--	07:59	0.304	0.162	0.010	0.015	0.013	0.05	157.67	SE
25 Dec, 2021	08:00	--	08:59	0.025	0.119	0.010	0.015	0.013	0.17	27.50	NNb
25 Dec, 2021	09:00	--	09:59	0.103	0.013	0.013	0.020	0.014	0.78	86.17	E

Max	0.403	0.163	0.108	0.121	0.033
Avg	0.117	0.086	0.093	0.04	0.015
Min	0.023	0.009	0.008	0.015	0.013



Air Quality Monitoring Report for Development of Industrial Area Thilawa SEZ Zone B
(Phase 1, 2 & 3) Operation Stage, 21 December 2021

Date	Time	CO	NO _x	PM ₁₀	PM _{2.5}	SO ₂	Wind Speed m/s	Wind Direction	
		mg/m ³ Hourly	mg/m ³ Hourly	mg/m ³ Hourly	mg/m ³ Hourly	mg/m ³ Hourly		Deg.	Direction
15 Dec. 2021	10:00 – 10:59	2.228	0.008	0.011	0.027	0.055	0.42	180.00	SE
17 Dec. 2021	11:00 – 11:59	0.023	0.009	0.014	0.025	0.053	0.45	208.33	SSW
28 Dec. 2021	12:00 – 12:59	0.023	0.009	0.013	0.025	0.054	0.37	268.17	W
15 Dec. 2021	13:00 – 13:59	0.023	0.009	0.013	0.039	0.093	0.35	246.35	WSW
18 Dec. 2021	14:00 – 14:59	0.023	0.009	0.044	0.081	0.064	0.35	256.67	WNW
18 Dec. 2021	15:00 – 15:59	0.024	0.008	0.051	0.065	0.060	0.85	221.83	SW
15 Dec. 2021	16:00 – 16:59	0.025	0.009	0.040	0.046	0.057	0.72	243.00	WSW
18 Dec. 2021	17:00 – 17:59	0.017	0.009	0.028	0.033	0.013	0.25	255.17	WSW
28 Dec. 2021	18:00 – 18:59	0.018	0.009	0.082	0.085	0.013	0.32	233.90	SW
15 Dec. 2021	19:00 – 19:59	0.194	0.016	0.080	0.095	0.013	0.48	280.67	W
18 Dec. 2021	20:00 – 20:59	0.180	0.017	0.088	0.083	0.013	0.30	279.67	W
28 Dec. 2021	21:00 – 21:59	0.278	0.095	0.119	0.125	0.013	0.10	38.33	NE
15 Dec. 2021	22:00 – 22:59	0.169	0.117	0.119	0.126	0.013	0.03	60.67	ENE
23 Dec. 2021	23:00 – 23:59	0.171	0.131	0.063	0.072	0.013	0.30	141.00	SE
26 Dec. 2021	00:00 – 00:59	0.164	0.136	0.012	0.017	0.013	0.10	31.20	NE
26 Dec. 2021	01:00 – 01:59	0.255	0.144	0.010	0.035	0.013	0.02	94.50	NE
26 Dec. 2021	02:00 – 02:59	0.193	0.145	0.010	0.033	0.013	0.10	70.87	ENE
26 Dec. 2021	03:00 – 03:59	0.095	0.141	0.030	0.033	0.013	0.10	55.33	NE
26 Dec. 2021	04:00 – 04:59	0.089	0.143	0.030	0.035	0.013	0.00	42.00	NE
26 Dec. 2021	05:00 – 05:59	0.107	0.149	0.010	0.033	0.013	0.02	71.30	SE
26 Dec. 2021	06:00 – 06:59	0.048	0.152	0.023	0.030	0.013	0.02	122.00	ENE
26 Dec. 2021	07:00 – 07:59	0.102	0.167	0.067	0.075	0.013	0.15	323.67	SW
26 Dec. 2021	08:00 – 08:59	0.044	0.107	0.013	0.037	0.013	0.30	237.50	WSW
26 Dec. 2021	09:00 – 09:59	0.057	0.035	0.013	0.020	0.013	0.50	338.33	SSW

Max.	2.228	0.167	0.118	0.126	0.064
Avg	0.208	0.056	0.039	0.047	0.027
Min	0.023	0.008	0.010	0.015	0.013



Air Quality Monitoring Report for Development of Industrial Area Thilawa SEZ Zone B
(Phase 1, 2 & 3 Operation Stage, FY December 2021)

Date	Time	CO		NO _x		PM ₁₀		PM _{2.5}		SO ₂		Wind Speed		Wind Direction	
		mg/m ³	Hourly	mg/m ³	Hourly	mg/m ³	Hourly	mg/m ³	Hourly	mg/m ³	Hourly	m/s	Hourly	Hourly	Hourly
26 Dec, 2021	10:00	--	10.59	0.023	0.009	0.006	0.010	0.016	0.046	0.18	228.67	SW			
26 Dec, 2021	11:00	--	11.59	0.025	0.009	0.006	0.010	0.046	0.48	203.50	SSW				
26 Dec, 2021	12:00	--	12.59	0.023	0.009	0.002	0.012	0.073	0.68	204.20	SSW				
26 Dec, 2021	13:00	--	13.59	0.023	0.009	0.003	0.013	0.028	0.48	224.83	SW				
26 Dec, 2021	14:00	--	14.59	0.023	0.009	0.003	0.047	0.013	0.55	248.50	WSW				
26 Dec, 2021	15:00	--	15.59	0.023	0.009	0.003	0.080	0.013	0.42	233.67	SW				
26 Dec, 2021	16:00	--	16.59	0.152	0.009	0.091	0.099	0.031	0.28	200.33	SSW				
26 Dec, 2021	17:00	--	17.59	0.200	0.009	0.107	0.119	0.033	0.23	198.00	SSW				
26 Dec, 2021	18:00	--	18.59	0.323	0.015	0.043	0.648	0.013	0.13	227.50	SW				
26 Dec, 2021	19:00	--	19.59	0.279	0.056	0.028	0.033	0.013	0.10	189.33	S				
26 Dec, 2021	20:00	--	20.59	0.160	0.089	0.042	0.063	0.013	0.03	196.33	SSW				
26 Dec, 2021	21:00	--	21.59	0.189	0.114	0.090	0.096	0.013	0.30	249.33	W				
26 Dec, 2021	22:00	--	22.59	0.163	0.129	0.054	0.103	0.013	0.30	269.00	W				
26 Dec, 2021	23:00	--	23.59	0.186	0.116	0.061	0.069	0.013	0.00	311.63	NW				
27 Dec, 2021	00:00	--	00.59	0.132	0.152	0.078	0.088	0.013	0.02	36.40	NE				
27 Dec, 2021	01:00	--	01.59	0.091	0.149	0.070	0.078	0.013	0.03	45.17	Nb				
27 Dec, 2021	02:00	--	02.59	0.046	0.143	0.036	0.012	0.013	0.05	196.00	SSW				
27 Dec, 2021	03:00	--	03.59	0.073	0.144	0.033	0.073	0.013	0.02	98.17	E				
27 Dec, 2021	04:00	--	04.59	0.060	0.152	0.039	0.064	0.013	0.03	56.17	Nb				
27 Dec, 2021	05:00	--	05.59	0.134	0.159	0.073	0.032	0.013	0.07	284.00	WSW				
27 Dec, 2021	06:00	--	06.59	0.562	0.161	0.064	0.070	0.013	0.27	244.33	WSW				
27 Dec, 2021	07:00	--	07.59	0.167	0.156	0.030	0.037	0.013	0.13	75.00	ENE				
27 Dec, 2021	08:00	--	08.59	0.043	0.104	0.013	0.017	0.013	0.23	383.00	ESE				
27 Dec, 2021	09:00	--	09.59	0.068	0.023	0.033	0.033	0.013	0.36	39.00	Nb				
Max			0.322	0.161	0.107	0.119	0.075								
Avg			0.124	0.082	0.049	0.037	0.020								
Min			0.021	0.009	0.002	0.003	0.012								



Air Quality Monitoring Report for Development of Industrial Area Thilawa SEZ Zone B
(Phase 1, 2 & 3 Operation Stage - FY December 2021)

Date	Time	CO	SO ₂	PM ₁₀	PM _{2.5}	NO _x	Wind Speed m/s	Wind Direction	
		mg/m ³ Hourly	mg/m ³ Hourly	mg/m ³ Hourly	mg/m ³ Hourly	mg/m ³ Hourly		Deg.	Direction
27 Dec, 2021	10:00 - 10:59	0.031	0.009	0.054	0.006	0.014	0.42	29.80	NNE
27 Dec, 2021	11:00 - 11:59	0.023	0.009	0.052	0.004	0.047	0.43	146.60	SSE
27 Dec, 2021	12:00 - 12:59	0.023	0.009	0.052	0.004	0.042	0.48	93.30	E
27 Dec, 2021	13:00 - 13:59	0.023	0.009	0.046	0.004	0.050	0.33	126.00	SE
27 Dec, 2021	14:00 - 14:59	0.023	0.009	0.057	0.027	0.011	0.46	150.40	SSE
27 Dec, 2021	15:00 - 15:59	0.023	0.009	0.028	0.047	0.011	0.40	140.40	SE
27 Dec, 2021	16:00 - 16:59	0.054	0.009	0.046	0.011	0.019	0.48	127.80	SE
27 Dec, 2021	17:00 - 17:59	0.102	0.009	0.010	0.019	0.051	0.34	55.60	NE
27 Dec, 2021	18:00 - 18:59	0.216	0.012	0.059	0.067	0.011	0.29	104.29	SSE
27 Dec, 2021	19:00 - 19:59	0.217	0.061	0.054	0.082	0.011	0.12	178.60	E
27 Dec, 2021	20:00 - 20:59	0.367	0.101	0.089	0.100	0.011	0.28	227.00	SW
27 Dec, 2021	21:00 - 21:59	0.179	0.153	0.087	0.092	0.011	0.34	168.40	SSE
27 Dec, 2021	22:00 - 22:59	0.223	0.136	0.034	0.041	0.011	0.09	88.00	E
27 Dec, 2021	23:00 - 23:59	0.132	0.128	0.016	0.089	0.011	0.08	79.00	ENE
28 Dec, 2021	00:00 - 00:59	0.129	0.126	0.031	0.056	0.011	0.09	131.40	SE
28 Dec, 2021	01:00 - 01:59	0.048	0.123	0.037	0.082	0.011	0.18	180.00	E
28 Dec, 2021	02:00 - 02:59	0.118	0.141	0.036	0.062	0.011	0.28	276.00	W
28 Dec, 2021	03:00 - 03:59	0.089	0.143	0.030	0.056	0.011	0.09	28.60	SNE
28 Dec, 2021	04:00 - 04:59	0.108	0.151	0.048	0.052	0.011	0.07	113.67	SE
28 Dec, 2021	05:00 - 05:59	0.106	0.156	0.044	0.049	0.011	0.13	278.40	W
28 Dec, 2021	06:00 - 06:59	0.127	0.160	0.043	0.048	0.011	0.14	351.00	N
28 Dec, 2021	07:00 - 07:59	0.102	0.153	0.015	0.020	0.011	0.28	148.00	NNW
28 Dec, 2021	08:00 - 08:59	0.073	0.109	0.019	0.018	0.011	0.04	281.00	W
28 Dec, 2021	09:00 - 09:59	0.063	0.018	0.002	0.004	0.011	0.28	344.50	NNW

Max	0.387	0.140	0.089	0.100	0.091
Avg	0.112	0.080	0.038	0.045	0.018
Min	0.023	0.009	0.002	0.004	0.011



An Quality Monitoring Report for Development of Industrial Area Thiruvananthapuram SEZ Zone B
(Phase 1, 2 & 3 Operation Stage, FY December 2021)

Date	Time		CO ₂	NO _x	PM _{2.5}	PM ₁₀	SO ₂	Wind Speed	Wind Direction	
			mg/m ³ Hourly	mg/m ³ Hourly	mg/m ³ Hourly	mg/m ³ Hourly	mg/m ³ Hourly	m/s Hourly	Dir Hourly	Direction Hourly
28 Dec, 2021	10:00	-	0.025	0.009	0.003	0.005	0.014	0.21	278.80	W
28 Dec, 2021	11:00	-	0.025	0.009	0.003	0.005	0.013	0.16	349.20	N
28 Dec, 2021	12:00	-	0.023	0.009	0.002	0.005	0.075	0.24	209.40	SSW
28 Dec, 2021	13:00	-	0.022	0.009	0.001	0.003	0.015	0.28	352.80	N
28 Dec, 2021	14:00	-	0.023	0.009	0.016	0.042	0.013	0.43	266.00	W
28 Dec, 2021	15:00	-	0.023	0.009	0.039	0.053	0.013	0.42	95.20	E
28 Dec, 2021	16:00	-	0.023	0.009	0.021	0.031	0.014	0.44	152.20	SSE
28 Dec, 2021	17:00	-	0.270	0.009	0.054	0.059	0.075	0.51	160.00	SSE
28 Dec, 2021	18:00	-	0.489	0.024	0.076	0.091	0.030	0.62	159.80	SSE
28 Dec, 2021	19:00	-	0.094	0.067	0.077	0.085	0.013	0.63	107.00	ESE
28 Dec, 2021	20:00	-	0.390	0.134	0.087	0.097	0.013	0.70	89.80	E
28 Dec, 2021	21:00	-	0.168	0.171	0.077	0.088	0.013	0.52	87.20	E
28 Dec, 2021	22:00	-	0.157	0.153	0.056	0.054	0.013	0.50	121.00	ESE
28 Dec, 2021	23:00	-	0.240	0.158	0.068	0.073	0.013	0.38	62.20	ENE
29 Dec, 2021	00:00	-	0.013	0.142	0.047	0.052	0.013	0.30	258.25	WSW
29 Dec, 2021	01:00	-	0.051	0.138	0.013	0.018	0.013	0.10	262.80	W
29 Dec, 2021	02:00	-	0.036	0.126	0.030	0.037	0.013	0.14	193.40	SSW
29 Dec, 2021	03:00	-	0.098	0.122	0.038	0.042	0.013	0.03	123.20	ESE
29 Dec, 2021	04:00	-	0.099	0.125	0.031	0.035	0.013	0.16	293.20	WSW
29 Dec, 2021	05:00	-	0.107	0.141	0.028	0.043	0.013	0.31	235.80	SW
29 Dec, 2021	06:00	-	0.124	0.139	0.041	0.048	0.013	0.00	259.60	WSW
29 Dec, 2021	07:00	-	0.133	0.137	0.027	0.032	0.013	0.16	306.80	SW
29 Dec, 2021	08:00	-	0.051	0.085	0.012	0.015	0.013	0.06	180.80	S
29 Dec, 2021	09:00	-	0.057	0.014	0.004	0.006	0.013	0.16	351.80	N

Max	0.489	0.171	0.087	0.097	0.075
Avg	0.126	0.082	0.033	0.042	0.020
Min	0.013	0.009	0.001	0.002	0.013



APPENDIX-2 CERTIFICATE OF CALIBRATION





SYSTEM HEALTH CHECK REPORT

INFORMATION

Instrument _____ HAZ-scanner
Model _____ EPAS
Serial number _____ 914019
Unit Sensor _____ CO, NO2, VOC, NO, SO2, PM10, PM2.5
Customer _____ MYANMAR KOEI INTERNATIONAL LTD.
Date _____ 21st December 2021

Check List

Physical Check _____ OK
Supply Voltage Check _____ OK
PM 10 Air Flow Check _____ OK
PM2.5 Air Flow Check _____ OK
Internal Backup Battery Voltage Check _____ OK
NO2 Sensor Health Check _____ Moderate
CO, VOC, SO2, NO Sensor Health Check _____ Still Good
Lithium Battery Voltage Check _____ OK
Data Logging Check _____ OK
Data Downloading Check _____ OK

Recommend

Need to replace new acid gas scrubber (schedule is 6 months)
Need to replace internal filters (schedule is 6 months)
Need to perform factory calibration or in-field calibration (schedule is 12 months)


Performed by
Phoe Saw Htoo
Technical Service Engineer


Authorized by
Myo Oo
Technical Service Manager



Thilawa Special Economic Zone
Zone B- Phase 1,2 & 3 (Operation phase)

Appendix-D

Noise and Vibration Monitoring Report

December 2021

**NOISE AND VIBRATION
MONITORING REPORT
FOR DEVELOPMENT OF INDUSTRIAL AREA
THILAWA SEZ ZONE B
(PHASE 1, 2 & 3 OPERATION STAGE)**

(BI-ANNUALLY MONITORING)

**December 2021
Myanmar Koei International Ltd.**



TABLE OF CONTENTS

CHAPTER 1: OUTLINES AND SUMMARY OF MONITORING PLAN	1
1.1 General	1
1.2 Outlines of Monitoring Plan.....	1
CHAPTER 2: NOISE AND VIBRATION LEVEL MONITORING	2
2.1 Monitoring Item	2
2.2 Monitoring Location	2
2.3 Monitoring Method	3
2.4 Monitoring Results.....	4
CHAPTER 3: CONCLUSION AND RECOMMENDATION	10

LIST OF TABLES

Table 1.2-1 Outlines of Noise and Vibration Level Monitoring	1
Table 2.1-1 Monitoring Parameters for Noise and Vibration Level.....	2
Table 2.4-1 Results of Noise Levels (L_{Aeq}) Monitoring at NV-1	4
Table 2.4-2 Results of Noise Levels (L_{Aeq}) Monitoring at NV-2.....	4
Table 2.4-3 Hourly Noise Level (L_{Aeq}) Monitoring Results at NV-1	5
Table 2.4-4 Hourly Noise Level (L_{Aeq}) Monitoring Results at NV-2	5
Table 2.4-5 Results of Vibration Levels (L_{v10}) Monitoring at NV-1.....	7
Table 2.4-6 Results of Vibration Levels (L_{v10}) Monitoring at NV-2.....	7
Table 2.4-7 Results of Hourly Vibration Levels (L_{v10}) Monitoring at NV-1	8
Table 2.4-8 Results of Hourly Vibration Levels (L_{v10}) Monitoring at NV-2	8

LIST OF FIGURES

Figure 2.2-1 Location of Noise and Vibration Level Monitoring Points	2
Figure 2.3-1 Status of Noise and Vibration Level Monitoring at NV-1 and NV-2.....	3
Figure 2.4-1 Results of Noise Levels (L_{Aeq}) Monitoring at NV-1	6
Figure 2.4-2 Results of Noise Levels (L_{Aeq}) Monitoring at NV-2	6
Figure 2.4-3 Results of Vibration Levels (L_{v10}) Monitoring at NV-1	9
Figure 2.4-4 Results of Vibration Levels (L_{v10}) Monitoring at NV-2	9



CHAPTER 1: OUTLINES AND SUMMARY OF MONITORING PLAN

1.1 General

Thilawa Special Economic Zone (TSEZ) is located in southern district of Yangon region and about 23 km southeast of Yangon city. As the developer of Thilawa SEZ, Myanmar Japan Thilawa Development Ltd., (MJTD) has a responsibility to carry out regular environmental monitoring in the industrial area of Zone B in accordance with the approved Environmental Impact Assessment (EIA) report with Environmental Management Plan (EMP). MJTD has implemented monitoring various environmental items with the specified time frame to know the environmental conditions in and around the area.

1.2 Outlines of Monitoring Plan

To assess the environmental condition under the operation of industrial area in and around Thilawa SEZ Zone B, noise and vibration levels had been monitored from 22 December 2021 – 23 December 2021 as follows:

Table 1.2-1 Outlines of Noise and Vibration Level Monitoring

Monitoring Date	Monitoring Item	Parameters	Number of Points	Duration	Monitoring Methodology
23 December 2021	Noise Level	$L_{Aeq}(dB)$	1 (NV-1)	8 hours	On-site measurement by "Rion NL-42 sound level meter"
22 December 2021	Noise Level	$L_{Aeq}(dB)$	1 (NV-2)	8 hours	On-site measurement by "Rion NL-42 sound level meter"
23 December 2021	Vibration Level	$L_{vib}(dB)$	1 (NV-1)	8 hours	On-site measurement by "Vibration Level Meter- VM-53A"
22 December 2021	Vibration Level	$L_{vib}(dB)$	1 (NV-2)	8 hours	On-site measurement by "Vibration Level Meter- VM-53A"

Source: Myanmar Koei International Ltd.

CHAPTER 2: NOISE AND VIBRATION LEVEL MONITORING

2.1 Monitoring Item

The noise and vibration level monitoring items are shown in Table 2.1-1.

Table 2.1-1 Monitoring Parameters for Noise and Vibration Level

No.	Item	Parameter
1	Noise	A-weighted loudness equivalent (L_{Aeq})
2	Vibration	Vibration level, vertical, percentile (L_{v10})

Source: Myanmar Koes International Ltd.

2.2 Monitoring Location

Noise and vibration levels were measured in the northeast corner of the Thilawa SEZ Zone B, monitoring point (NV-1); N: 16°40'18.22", E: 96°17'18.18" for traffic noise concerned and in the south of the Thilawa SEZ Zone B, monitoring point (NV-2); N: 16°39'24.90", E: 96°17'16.70", inside the monastery compound of Phalan village. The location of the noise and vibration monitoring points are shown in Figure 2.2-1.



Figure 2.2-1 Location of Noise and Vibration Level Monitoring Points

NV-1

NV-1 is located in front of temporary gate of operation site of Thilawa SEZ Zone B and next to Thilawa Development road. The surrounding area are Zone A in the northwest, local industrial zone in the east respectively. Possible sources of noise and vibration is generated from construction activities and road traffic.

NV-2

NV-2 is located at the south of the Thilawa SEZ Zone B, inside the monastery compound of Phalan village, surrounded by the residential houses of Phalan village in the south and fields in west, Thilawa SEZ Zone A in north, local industrial zone in northeast respectively. Possible sources of noise and vibration is generated from construction activities from Zone B and daily human activities from nearby Phalan village.

2.3 Monitoring Method

Noise level was measured by "Rion NL-42 sound level meter" and automatically records every 10 minutes in a memory card. The vibration level meter, VM-53A (Rion Co., Ltd., Japan), was accompanied by a 3-axis accelerometer PV-83C (Rion Co., Ltd.) and it was placed on solid soil ground. Vertical vibration (Z axis), L_v , was measured every 10 minutes within the adaptable range of (10-70) dB at NV-1 and (10-70) dB at NV-2 and recorded to a memory card.

The measurement period of noise and vibration was 8 hours for each monitoring point. The status of the noise and vibration level monitoring on NV-1 and NV-2 are shown in Figure 2.3-1.



Source: Myanmar Koei International Ltd.

Figure 2.3-1 Status of Noise and Vibration Level Monitoring at NV-1 and NV-2

2.4 Monitoring Results

Noise Monitoring Results

Noise monitoring results are separated as daytime (6:00 AM to 10:00 PM) and evening time (10:00 PM to 6:00 AM) time frames for NV-1 and daytime (7:00 AM to 7:00 PM), evening time (7:00 PM to 10:00 PM) and night time (10:00 PM to 7:00 AM) time frames respectively for NV-2. Noise measurement was carried out on an 8-hour as working time (8:00 AM to 4:00 PM) at the designated one location instead of 24-hours due to the safety reason and risk avoidance. The monitoring results are summarized in Table 2.4-1 and Table 2.4-2. Hourly noise level (L_{Aeq}) monitoring results at NV-1 and NV-2 are shown in Table 2.4-3 and Table 2.4-4. Figure 2.4-1 and Figure 2.4-2 showed the results of noise level (L_{Aeq}) at NV-1 and NV-2. Comparing with the target value of noise level in operation stage prescribed in EIA report for Thilawa SEZ development project Zone B, all results were under the target values.

Table 2.4-1 Results of Noise Levels (L_{Aeq}) Monitoring at NV-1

Date	(Traffic Noise Level) Equivalent Noise Level (L_{Aeq} , dB)	
	Day Time (6:00 AM – 10:00 PM)	Night Time (10:00 PM – 6:00 AM)
23 December, 2021	61	-
Target Value	75	70

Note: Target value is applied to the noise standard along main road stipulated in the Noise Regulation Law (Japan) (Law No. 96 of 1968, Latest Amendment by Law No 91 of 2000).

Source: Myanmar Koei International Ltd

Table 2.4-2 Results of Noise Levels (L_{Aeq}) Monitoring at NV-2

Date	(A side next to sensitive area such as monastery, hospital and school) Equivalent Noise Level (L_{Aeq} , dB)		
	Day Time (7:00 AM – 7:00 PM)	Evening Time (7:00 PM – 10:00 PM)	Night Time (10:00 PM – 7:00 AM)
22 December, 2021	43	-	-
Target Value	60	55	50

Note: Target value is applied to the noise level during the operation stage in the EIA Report for Thilawa SEZ Development Project (Industrial Area of Zone B).

Source: Myanmar Koei International Ltd

Table 2.4-3 Hourly Noise Level (L_{Aeq}) Monitoring Results at NV-1


Date	Time	(L_{Aeq} , dB)	(L_{Aeq} , dB) Each Category	(L_{Aeq} , dB) Target Value	Remark
23 December 2021	6:00-7:00	-	61	75	No construction Activities
	7:00-8:00	-			
	8:00-9:00	63			
	9:00-10:00	62			
	10:00-11:00	62			
	11:00-12:00	60			
	12:00-13:00	60			
	13:00-14:00	61			
	14:00-15:00	61			
	15:00-16:00	61			
	16:00-17:00	-			
	17:00-18:00	-			
	18:00-19:00	-			
	19:00-20:00	-			
	20:00-21:00	-			
	21:00-22:00	-			
	22:00-23:00	-	-	70	
	23:00-24:00	-			
	24:00-1:00	-			
	1:00-2:00	-			
	2:00-3:00	-			
	3:00-4:00	-			
	4:00-5:00	-			
	5:00-6:00	-			

Source: Myanmar Koei International Ltd

Table 2.4-4 Hourly Noise Level (L_{Aeq}) Monitoring Results at NV-2


Date	Time	(L_{Aeq} , dB)	(L_{Aeq} , dB) Each Category	(L_{Aeq} , dB) Target Value	Remark
22 December 2021	7:00-8:00	-	43	60	No construction Activities
	8:00-9:00	47			
	9:00-10:00	43			
	10:00-11:00	42			
	11:00-12:00	44			
	12:00-13:00	41			
	13:00-14:00	40			
	14:00-15:00	41			
	15:00-16:00	45			
	16:00-17:00	-			
	17:00-18:00	-			
	18:00-19:00	-			
	19:00-20:00	-	55		
	20:00-21:00	-			
	21:00-22:00	-			
	22:00-23:00	-			
	23:00-24:00	-	50		
	24:00-1:00	-			
	1:00-2:00	-			
	2:00-3:00	-			
	3:00-4:00	-			
	4:00-5:00	-			
	5:00-6:00	-			
	6:00-7:00	-			

Source: Myanmar Koei International Ltd



Source: Myanmar Kuei International Ltd.

Figure 2.4-1 Results of Noise Levels (L_{Aeq}) Monitoring at NV-1



Source: Myanmar Kuei International Ltd.

Figure 2.4-2 Results of Noise Levels (L_{Aeq}) Monitoring at NV-2

Vibration Monitoring Results

Vibration monitoring results are separated as daytime (7:00 AM to 7:00 PM), evening time (7:00 PM to 10:00 PM) and night time (10:00 PM to 7:00 AM) time frames respectively for both NV-1 and NV-2. Vibration measurement was carried out on an 8-hour as working time (8:00 AM to 4:00 PM) at the designated one location instead of 24-hours due to the safety reason and risk avoidance. The results of vibration level (L_{v10}) monitoring at NV-1 and NV-2 are shown in Table 2.4-5 and Table 2.4-6. Hourly vibration level (L_{v10}) monitoring results at NV-1 and NV-2 are shown in Table 2.4-7 and Table 2.4-8. Figure 2.4-3 and Figure 2.4-4 showed the graph of vibration level monitoring results at NV-1 and NV-2. By comparing with the target vibration level in operation stage in EIA report for Thilawa SEZ development project Zone B, all of results were under the target values.

Table 2.4-5 Results of Vibration Levels (L_{v10}) Monitoring at NV-1

Date	(Office, commercial facilities and factories) Equivalent Vibration Level (L_{v10} , dB)		
	Day Time (7:00 AM – 7:00 PM)	Evening Time (7:00 PM – 10:00 PM)	Night Time (10:00 PM – 7:00 AM)
23 December, 2021	40	-	-
Target Value	70	65	65

Note: Target value is applied to the vibration level during the operation stage in the EIA Report for Thilawa SEZ Development Project (Industrial Area of Zone B).

Source: Myanmar Koen International Ltd.

Table 2.4-6 Results of Vibration Levels (L_{v10}) Monitoring at NV-2

Date	(Residential houses and monastery) Equivalent Vibration Level (L_{v10} , dB)		
	Day Time (7:00 AM – 7:00 PM)	Evening Time (7:00 PM – 10:00 PM)	Night Time (10:00 PM – 7:00 AM)
22 December, 2021	25	-	-
Target Value	65	60	60

Note: Target value is applied to the vibration level during the operation stage in the EIA Report for Thilawa SEZ Development Project (Industrial Area of Zone B).

Source: Myanmar Koen International Ltd.

Table 2.4-7 Results of Hourly Vibration Levels (L_{v10}) Monitoring at NV-1


Date	Time	(L _{v10} , dB)	(L _{v10} , dB) Each Category	(L _{v10} , dB) Target Value	Remark
23 December 2021	7:00-8:00	-	40	70	No construction Activities
	8:00-9:00	40			
	9:00-10:00	40			
	10:00-11:00	41			
	11:00-12:00	39			
	12:00-13:00	39			
	13:00-14:00	40			
	14:00-15:00	41			
	15:00-16:00	39			
	16:00-17:00	-			
	17:00-18:00	-			
	18:00-19:00	-			
	19:00-20:00	-	-	65	
	20:00-21:00	-			
	21:00-22:00	-			
	22:00-23:00	-			
	23:00-24:00	-	-	65	
	24:00-1:00	-			
	1:00-2:00	-			
	2:00-3:00	-			
	3:00-4:00	-			
	4:00-5:00	-			
	5:00-6:00	-			
	6:00-7:00	-			

Source: Myanmar Koen International Ltd.

Table 2.4-8 Results of Hourly Vibration Levels (L_{v10}) Monitoring at NV-2


Date	Time	(L_{v10} , dB)	(L_{v10} , dB) Each Category	(L_{v10} , dB) Target Value	Remark
22 December 2021	7:00-8:00	-	23	65	No construction Activities
	8:00-9:00	21			
	9:00-10:00	24			
	10:00-11:00	25			
	11:00-12:00	23			
	12:00-13:00	22			
	13:00-14:00	21			
	14:00-15:00	22			
	15:00-16:00	21			
	16:00-17:00	-			
	17:00-18:00	-			
	18:00-19:00	-			
	19:00-20:00	-	-	60	
	20:00-21:00	-			
	21:00-22:00	-			
	22:00-23:00	-			
	23:00-24:00	-	-	60	
	24:00-1:00	-			
	1:00-2:00	-			
	2:00-3:00	-			
	3:00-4:00	-			
	4:00-5:00	-			
	5:00-6:00	-			
	6:00-7:00	-			

Source: Myanmar Koen International Ltd.



Source: Myanmar Koni International Ltd.

Figure 2.4-3 Results of Vibration Levels (L_{v10}) Monitoring at NV-1



Source: Myanmar Koni International Ltd.

Figure 2.4-4 Results of Vibration Levels (L_{v10}) Monitoring at NV-2

CHAPTER 3: CONCLUSION AND RECOMMENDATION

By Comparing with the target value of noise and vibration level in operation stage prescribed in EIA report for Thilawa SEZ development project Zone B, all results were under the target values at NV-1 and NV-2. Thus, there is no negative impact on noise and vibration from operation activities of Zone B to the surrounding environment.

In conclusion of this environmental monitoring, there are no specific noise and vibration impacts to the surrounding area of industrial area of Thilawa SEZ Zone B during the monitoring period.



Thilawa Special Economic Zone
Zone B- Phase 1,2 & 3 (Operation phase)

Appendix-E

Traffic Volume Monitoring Report

December 2021

**TRAFFIC VOLUME MONITORING REPORT
FOR DEVELOPMENT OF INDUSTRIAL AREA
THILAWA SEZ ZONE B
(PHASE 1, 2 & 3 OPERATION STAGE)**

(BI-ANNUALLY MONITORING)

December 2021

Myanmar Koei International Ltd.



TABLE OF CONTENTS

CHAPTER 1: OUTLINES AND SUMMARY OF MONITORING PLAN	1
1.1 General	1
1.2 Outlines of Monitoring Plan	1
CHAPTER 2: TRAFFIC VOLUME MONITORING	2
2.1 Monitoring Item	2
2.2 Monitoring Location	3
2.3 Monitoring Method	4
2.4 Monitoring Results	4
CHAPTER 3: CONCLUSION AND RECOMMENDATION	6

LIST OF TABLES

Table 1.2-1 Outlines of Traffic Volume Monitoring	1
Table 2.1-1 Monitoring Parameters for Traffic Volume	2
Table 2.1-2 Classification of Vehicles Types	2
Table 2.4-1 Summary of Traffic Volume Recorded at TV-1	4
Table 2.4-2 Hourly Traffic Volume Results at TV-1 (From Phalan Village to Dagon-Thilawa Road)	5
Table 2.4-3 Hourly Traffic Volume Results at TV-1 (From Dagon-Thilawa Road to Phalan Village)	5

LIST OF FIGURES

Figure 2.2-1 Location of Traffic Volume Monitoring Point	3
Figure 2.3-1 Status of Traffic Volume Monitoring at TV-1	4

CHAPTER 1: OUTLINES AND SUMMARY OF MONITORING PLAN

1.1 General

Thilawa Special Economic Zone (TSEZ) is located in southern district of Yangon region and about 23 km southeast of Yangon city. As the developer of Thilawa SEZ, Myanmar Japan Thilawa Development Ltd., (MJTD) has a responsibility to carry out regular environmental monitoring in the industrial area of Zone B in accordance with the approved Environmental Impact Assessment (EIA) report with Environmental Management Plan (EMP). MJTD has implemented monitoring various environmental items with the specified time frame to know the environmental conditions in and around the area.

1.2 Outlines of Monitoring Plan

To assess the environmental condition under the operation of industrial area in and around Thilawa SEZ Zone B, Traffic volume monitoring was carried out on an 8-hours as working time (8:00 to 16:00) at the designated one location instead of 24 hours due to the safety reason and risk avoidance. Traffic volume had been monitored from 23 December 2021 as follows;

Table 1.2-1 Outlines of Traffic Volume Monitoring

Monitoring Date	Monitoring Item	Parameters	Number of Points	Duration	Monitoring Methodology
23 December 2021	Traffic Volume	-	1 (TV-1)	8 hours	Manual Count

Source: Myanmar Kuei International Ltd.

CHAPTER 2: TRAFFIC VOLUME MONITORING

2.1 Monitoring Item

The traffic volume monitoring item are shown in Table 2.1-1. All vehicles were classified into four types as detailed in Table 2.1-2.

Table 2.1-1 Monitoring Parameters for Traffic Volume

No.	Item	Parameter
1	Traffic volume	Number of Vehicle (4 Types)

Source: Myanmar Koei International Ltd.

Table 2.1-2 Classification of Vehicles Types

No.	Classification		Description
1	Two-wheeled vehicle		Motorbike, Motorcycle taxi
2	Four-wheeled light vehicle	  	Pick-up car, Jeep, Taxi, Saloon car, Light truck (under 2 tons)
3	Heavy vehicle	  	Medium bus, Express, Big bus, Medium truck, Heavy truck such as 2 axles, 3 axles and more than 4 axles and Trailer (over 4.5 tons)
4	Others		Tractor

Source: Myanmar Koei International Ltd.

2.2 Monitoring Location

Traffic volume was measured at the northeast corner of the Thilawa SEZ, Zone B, monitoring point (TV-1); N: 16°40'17.90", E: 96°17'18.20". The location of the traffic volume monitoring point is shown in Figure 2.2-1.



Figure 2.2-1 Location of Traffic Volume Monitoring Point

TV-1

TV-1 is located in front of main gate of operation site of Thilawa SEZ, Zone B and next to Thilawa Development road. The surrounding area are Zone A in the northwest and local industrial zone in the east respectively.

2.3 Monitoring Method

The traffic volume monitoring was conducted for 8 hours at the same time as the traffic noise and vibration level monitoring. Traffic volume monitoring was conducted to count the number of vehicles moving in each direction. Manual count method was used and data was recorded using tally sheets. The status of the traffic volume monitoring on TV-1 is shown in Figure 2.3-1.



Source: Myanmar Koei International Ltd.

Figure 2.3-1 Status of Traffic Volume Monitoring at TV-1

2.4 Monitoring Results

The traffic volume monitoring results are summarized in Table 2.4-1. Hourly quantities of each type of vehicle were recorded. Table 2.4-1 shows that the number of 4-wheel light vehicles are distinctly and highly utilized in weekdays. The number of Heavy vehicles are three times lower than the number of 4-wheel light vehicles (Phalan village to Dagon-Thilawa road) and the number of Heavy vehicles are three times lower than the number of 4-wheel light vehicles (Dagon-Thilawa road to Phalan village) for each direction.

Table 2.4-1 Summary of Traffic Volume Recorded at TV-1

Survey Point	Direction	Date	Weekday	2-wheel Vehicles	4-wheel Light Vehicles	Heavy Vehicles	Others	Total
TV-1	Phalan village to Dagon-Thilawa road	23 December 2021	Thursday	533	649	200	21	1,403
	Dagon-Thilawa road to Phalan village			518	691	127	23	1,459

Source: Myanmar Koei International Ltd.

The summary monitoring results of hourly traffic volume at TV-1 is shown in Table 2.4-2 and Table 2.4-3 respectively. Compare the result of each direction in morning hours as 8:00 to 9:00 and in the afternoon hours as 15:00 to 16:00, traffic volume from Phalan village to Dagon Thilawa road is higher than another direction in the afternoon hours. However, in the morning hours, traffic volume from Dagon Thilawa road to Phalan village is the same with another direction. It may be possible commuting vehicles are passing Dagon Thilawa road to Phalan village in the morning hours and returning from Phalan village to Dagon Thilawa road in the afternoon during this monitoring period.

Table 2.4-2 Hourly Traffic Volume Results at TV-1 (From Phalan Village to Dagon-Thilawa Road)

From	To	Classification Type of vehicles				Total
		Two-wheeled vehicle	Four-wheeled light vehicle	Heavy vehicle	Others	
7:00	8:00	-	-	-	-	-
8:00	9:00	108	78	21	3	210
9:00	10:00	71	61	27	4	163
10:00	11:00	78	86	31	3	198
11:00	12:00	73	107	28	2	210
12:00	13:00	66	54	28	3	149
13:00	14:00	38	71	21	0	130
14:00	15:00	31	64	27	2	124
15:00	16:00	68	107	18	4	198
16:00	17:00	-	-	-	-	-
17:00	18:00	-	-	-	-	-
18:00	19:00	-	-	-	-	-
19:00	20:00	-	-	-	-	-
20:00	21:00	-	-	-	-	-
21:00	22:00	-	-	-	-	-
22:00	23:00	-	-	-	-	-
23:00	0:00	-	-	-	-	-
0:00	1:00	-	-	-	-	-
1:00	2:00	-	-	-	-	-
2:00	3:00	-	-	-	-	-
3:00	4:00	-	-	-	-	-
4:00	5:00	-	-	-	-	-
5:00	6:00	-	-	-	-	-
6:00	7:00	-	-	-	-	-
Total		533	648	290	21	1,493

Source: Myanmar Koei International Ltd

Table 2.4-3 Hourly Traffic Volume Results at TV-1 (From Dagon-Thilawa Road to Phalan Village)

From	To	Classification Type of vehicles				Total
		Two-wheeled vehicle	Four-wheeled light vehicle	Heavy vehicle	Others	
7:00	8:00	-	-	-	-	-
8:00	9:00	83	107	17	4	211
9:00	10:00	81	94	36	1	212
10:00	11:00	41	98	32	2	173
11:00	12:00	80	90	25	5	200
12:00	13:00	62	77	23	1	163
13:00	14:00	53	66	34	3	156
14:00	15:00	43	83	32	3	161
15:00	16:00	75	76	28	4	183
16:00	17:00	-	-	-	-	-
17:00	18:00	-	-	-	-	-
18:00	19:00	-	-	-	-	-
19:00	20:00	-	-	-	-	-
20:00	21:00	-	-	-	-	-
21:00	22:00	-	-	-	-	-
22:00	23:00	-	-	-	-	-
23:00	0:00	-	-	-	-	-
0:00	1:00	-	-	-	-	-
1:00	2:00	-	-	-	-	-
2:00	3:00	-	-	-	-	-
3:00	4:00	-	-	-	-	-
4:00	5:00	-	-	-	-	-
5:00	6:00	-	-	-	-	-
6:00	7:00	-	-	-	-	-
Total		518	691	227	23	1,459

Source: Myanmar Koei International Ltd

CHAPTER 3: CONCLUSION AND RECOMMENDATION

The results of the traffic volume show that the number of 4-wheel light vehicles are distinctly and highly utilized in this monitoring period. The number of heavy vehicles are three times significantly lower than the number of 4-wheel light vehicles for each direction. It seems that commuting vehicles are more utilized during this monitoring period as compared with construction related vehicles (Heavy vehicles).

The continuous monitoring will be necessary to grasp the traffic volume data in operation stage of Thilawa SEZ Zone B. Once enough traffic volume data is collected, the mitigation measures for traffic volume management will be considered in future.



Thilawa Special Economic Zone
Zone B- Phase 1,2 & 3(Operation phase)

Appendix-F

General Waste Disposal Record
(September 2021 to February 2022)

ငွေလွှဲပြောင်း/လက်ခံပြေစာ



အကြောင်းအရာ။ နေပြည်တော်၊ ၁၀/၀၉/၂၀၂၁ ခုနှစ်၊ ဇန်နဝါရီလ ၁၀ ရက်နေ့တွင်

M.I.D. Company

ငွေပေါင်း(ဂဏန်း)။ ၅၅၀၀၀/-

၃။ ငွေပေါင်း(စာဖြင့်)။ (ကျပ် ငါးဆယ့်ငါးစောင်တစ်ရာ)

(လွှဲပြောင်းပေးသူ)

(လက်ခံသူ)

အမည် Kyaw Khin Phyo
ရာထူး Assistant
နေရာ TSEZ
ရက်စွဲ 17 September 2021

အမည်
ရာထူး ၃-ဦးစီးမှူး(သန့်)
နေရာ ပြည်ထောင်စုသယံဇာတနှင့် သဘာဝပတ်ဝန်းကျင် ထိန်းသိမ်းရေး ဝန်ကြီးရုံး
ရက်စွဲ သန့်လျင်မြို့



မဟာဝိသုဒ္ဓိ

ငွေလွှဲပြောင်း/လက်ခံပြေစာ

ဒဂုံမြို့တော်ခရိုင်အဖွဲ့အစည်းများ

ငွေပေါင်း(ကုန်)။

၆,၅၅၀,၀၀၀/-

ငွေပေါင်း(စာပြု)။

ငါးဆယ့်ငါးလေး

14.10.2021

(လွှဲပြောင်းပေးသူ)

(လက်ခံသူ)

အမည် : Myo Kywe Pinyo

ရာထူး : စီးပွားရေး

နေရာ : ၆၆၆ ၇

ရက်စွဲ : ၁၄.၁၀.၂၀၂၁

အမည် : 

ရာထူး : ၃-ဦးစီးမှူး(သန့်)

နေရာ : မြို့တော်ခရိုင်အဖွဲ့အစည်းများ

ရက်စွဲ : သန့်လွှဲပြေ

4472391

မှတ်ချက် (တစ်ခု) :

၂၅၀၆၆၂

$$C_{\mathcal{G}}(\mathcal{L}_{\mathcal{G}}(n), \mathcal{L}_{\mathcal{G}}(n))$$

உரி அங்குசியோகம்

07-12-2021

(ရဲ့အပြောင်းအလဲ)

၂၀၀၇ခုနှစ်

အမျိုးအမည်	အောင်အောင်
အသက်	၁၈
အလုပ်	ကျောင်းဆရာမ
အိမ်လမ်း	မန္တလေးမြို့

2008
 2009
 2010
 2011



အမှတ်(၁)ရပ်ကွက်

ငွေလွှဲပြောင်း/လက်ခံပြေစာ

အဖွဲ့အစည်းအရပ်အတွက်

ရောင်းချသူ(ကုမ္ပဏီ)

ဦးစွာရောင်းချသူ

ရောင်းချသူ(လုပ်ငန်း)

ရောင်းချသူ(လုပ်ငန်း)

၀၆/၀၁/၂၀၂၃

(ရောင်းချသူအတွက်)

အမည် : U. Aye Win

ရာထူး : Union Minister

နေရာ : Yangon

ရက်စွဲ : ၀၆/၀၁/၂၀၂၃

(လက်ခံသူ)

အမည် :

ရာထူး :

နေရာ :

ရက်စွဲ :

ကော်မရှင် ()



စာတမ်းပြောင်းလဲ/လက်ခံပြေစာ

အောက်ပါအတိုင်း

အမည် (အဘွား)

အမည် (အဘွား)


အမည် (အဘွား)

(အမည်)

(အမည်)

အမည် (အဘွား)

အမည် (အဘွား)



ငွေလွှဲပြောင်း/လက်ခံပြုစာ

အကြောင်းအရာ ၁..... မိုးကုန်းမြို့နယ်၊ မြေပုံရေးရာဇဝတ်ဓနအဖွဲ့အစည်း

၂။ ငွေပေါင်း(လက်ခံ)။ ၁၀၀၀၀၀/-

၃။ ငွေပေါင်း(စာဖြင့်)။ နှစ်ဆယ်သိန်း

..... ၃၁.၀၃.၂၀၂၂

(လွှဲပြောင်းပေးသူ)

အမည် U Kyau Soe Win
ရာထူး
နေရာ
ရက်စွဲ ၃၁.၀၃.၂၀၂၂

အမည်
ရာထူး
နေရာ
ရက်စွဲ
.....

CONTENÜR

C700 F

Rear loading containers

38_{Kg}

± 5%

660_L

264_{Kg}

160 / 200 mm



FEATURES

The body and lid are injection moulded in solid coloured high-density polyethylene.

Manufactured using environmentally-friendly recyclable materials.

No heavy metals in the pigments.

Ideal for different types of waste collection: paper and cardboard, glass, packaging, organic matter, etc. ...

Available in a wide range of colours...

DIN, AFNOR, OSCHNER or VENTRAL lifting systems.

Customisation of lid with thermal transfer graphic, area: 230 x 45 mm.


Customisation of body with silk screen or thermal transfer graphic, area: 300 x 400 mm.

CE Marking with sound power level indicated in accordance with European Directive 2000/14/EC, 82,1 db.

Product Approval Certificate awarded by TÜV Product Service GmbH in accordance with European Standard EN 840:2012

UN certificate for the transportation of hazardous goods.

STANDARDS



These dimensions are subject to the tolerances given in EN 840-1:2012.

F100782Z / 28-2-13 / Rev 0.0

CONTENUR

C700 F
Rear loading containers


ATTRIBUTES



QUALITY



ACCESSIBILITY



FUNCTIONALITY

ACCESSORIES



GLASS APERTURE



PLASTIC APERTURE



PAPER APERTURE



CENTRAL BRAKE SYSTEM



LIFTING SYSTEM



RAIN COVER



PEDAL



AVAILABLE IN A WIDE RANGE
OF COLOURS

EQUIPMENT

160 or 200 mm diameter wheels.

Openings with sizes and features specially designed to accommodate each type of waste, making them easy to use.

Integrated sound-proofing system in the lid.

Integrated handles in the body and lid for easy handling.

Recess for electronic chips.

Can be equipped with a range of accessories providing real solutions to every requirement: pedal-operated lid opening, reflective strips, lock, side handle.



Sound-proofing



Lock



Easy to stack



Easy to clean



Break



Shock absorber

Thilawa Special Economic Zone
Zone B- Phase 1,2 & 3 (Operation phase)

Appendix-G

Sewage Treatment Plant Monitoring Record
September 2021 to February 2022

Daily Self Monitoring of STP Inlet, Outlet and Aeration

Monthly	Date	Inlet (Zone B)				Inlet-1				Inlet-2				Outlet-1				Outlet-2			
		pH	TDS	Temp	COD	pH	TDS	Temp	COD	pH	TDS	Temp	COD	pH	TDS	Temp	COD	pH	TDS	Temp	COD
Standard		6-8	2000	22	400	6-8	2000	22	400	6-8	2000	22	400	6-8	2000	22	120	6-8	2000	22	120
Unit		-	mg/L	°C	mg/L	-	mg/L	°C	mg/L	-	mg/L	°C	mg/L	-	mg/L	°C	mg/L	-	mg/L	°C	mg/L
Dec	24-12-21	7.42	207.9	22.9	-	6.71	217.7	22	212	7.4	202.4	22.1	-	6.62	218.3	22.9	7	6.66	215.7	22	8
Dec	25-12-21	7.34	217.44	22.7	107	6.62	224.4	22.7	-	6.62	223.2	22	48	6.52	220.2	22.3	26	7.13	220	22	26
Dec	26-12-21	7.36	202.3	22.3	329	6.69	192.3	22	-	6.62	215.5	22	143	6.75	205.4	22.9	6	6.98	211.2	24.1	7
Dec	28-12-21	7.22	225.8	24.7	-	6.77	226.2	25.3	-	6.75	229.5	24.4	-	6.61	225	24.4	-	6.68	225.2	23.4	-
Dec	28-12-21	7.14	244.8	24.2	-	6.55	254.7	23.8	-	6.72	238	23.4	-	6.66	228.2	24	-	6.52	229.3	24.2	-
Dec	28-12-21	7.11	172.2	24.3	-	6.7	222.2	24.7	224	7.36	223.2	22.7	-	6.61	224	24.7	18	6.62	242.2	22.9	22
Dec	29-12-21	7.14	222.2	23.2	125	6.67	222.2														

Mar	05-11-21	721	301	274	805	734	310	272	-	730	321	274	80	881	348	273	90	728	321	283	80
Mar	06-11-21	694	302	254	-	685	197	252	-	685	203	252	-	687	253	252	-	730	264	283	-
Mar	07-11-21	691	124	254	-	686	213	254	-	686	203	253	-	730	262	25	-	686	204	284	-
Mar	08-11-21	779	271	255	-	691	257	26	40	692	244	260	-	730	244	26	10	710	223	283	10
Mar	09-11-21	752	283	265	140	690	264	267	-	710	264	262	90	677	267	268	50	702	243	284	14
Mar	10-11-21	682	304	267	-	721	263	263	50	73	274	263	-	737	277	267	71	703	273	282	20
Mar	11-11-21	728	273	268	20	7	244	264	-	730	273	264	107	730	268	267	73	725	268	283	21
Mar	12-11-21	652	286	267	712	683	268	262	-	671	273	261	627	731	262	262	84	680	271	282	31
Mar	13-11-21	673	150	247	-	679	268	259	-	679	268	247	-	734	262	258	-	688	265	278	-
Mar	14-11-21	780	273	263	-	685	263	261	-	678	271	258	-	7	268	258	-	7	273	273	-
Mar	15-11-21	752	267	264	-	688	267	262	80	687	273	26	-	737	272	254	75	695	274	28	20
Mar	16-11-21	690	263	272	20	690	272	273													

Jan	2017	1.57	387.1	24.7	2539	7.09	380	35.5	-	4.97	334.2	25.3	314	7.38	440.0	25.4	138	7.11	461.3	25.5	45
Jan	2018	1.54	337.7	22	-	6.42	344.1	21.9	-	4.92	352.2	23.8	-	7.12	482.1	21.9	-	7.15	488.9	21.7	-
Jan	2019	1.57	352.9	22.9	-	6.64	340	22.2	-	4.92	363.3	22	-	6.97	486.4	22.9	-	7.12	502.4	22.7	-
Jan	2020	1.58	419.4	24.9	-	6.07	344.2	22.0	48	4.76	346	25.2	-	7.14	384.4	25.9	111	7.19	463.8	25.4	35
Jan	2021	1.55	364.2	25.9	147	5.8	294.7	24.7	-	4.76	321.3	24.9	597	7	365.5	25.7	42	7.15	382.9	25.7	11
Jan	2022	1.59	277.2	23.5	-	4.46	455.5	25.1	852	4.88	438.8	22.9	-	6.98	326.2	22.5	126	7.24	461.2	22.1	65
Jan	2023	1.58	276.7	24.4	315	4.38	461.4	25.1	-	4.4	386.7	24.7	354	6.88	339.7	22.9	75	7.29	461.5	24.4	11
Jan	2024	1.72	271.7	27	176	6.94	383.4	25.4	-	4.92	363.4	22.1	1118	6.88	425.5	25.4	54	7.04	462.2	22.7	35
Jan	2025	1.7	227	22.9	-	6.58	321.7	22.9	-	4.54	403.2	22.9	-	7.24	422.4	22.7	-	7.26	465.7	22.5	-
Jan	2026	1.64	355.4	21.2	-	6.2	322.2	22	-	4.87	307.5	22	-	7.28	415.4	22	-	7.24	467.5	22.6	-
Jan	2027	1.71	367.9	22.9	-	6.2	363.1	22.7	149	4.88	471.4	22.9	-	7.22	478.4	22.4	34	7.12	459.9	22.7	31
Jan	2028	1.64	327.3	21.2	188	6.72	429.4	21.4	-	4.88	395.2	21.4	854	-	457.9	21.4	25	7.05	474.2	21.6	35
Jan	2029	1.61	275.2	24.9	-	6.02	345.9	24.9	289	6.91	424.2	24.4	-	7.19	455.9	24	88	7.14	468	24.1	38
Jan	2030	1.61	368.4	21	88	6.88	323.3	21.2	-	7	345.4	21.9	458	6.23	467.2	21.7	52	7.11	464.3	21.9	33
Jan	2031	1.62	385.1	22.7	352	6.88	404.2	24.9	-	6.88	461.2	24.2	838	6.74	415.4	24.9	38	7.12	465.2	24.5	15
Jan	2032	1.72	358	20.7	-	6.97	347.2	21	-	6.54	388	20.7	-	6.57	388	20.7	-	7.07	465.2	20.9	-
Jan	2033	1.72	317.9	21.9	-	6.85	311.2	21.5	-	6.82	315.5	21.2	-	6.48	336.7	20.9	-	7.23	468	21.4	-
Jan	2034	1.65	344.4	24.5	-	6.87	324.2	22.9	145	7.16	246.2	24.7	-	6.87	322.4	25.2	35	7.12	464.7	24.5	22
Jan	2035	1.58	362.2	22.7	162	7.02	362.2	22.4	-	7.16	462.2	22.9	345	6.48	374	22.5	89	6.35	462.2	24.5	37
Jan	2036	1.56	336.7	24	-	7.04	361.2	26.2	100	7.11	347.2	26.7	-	6.32	366.7	26.7	51	6.35	465.2	25.7	40
Jan	2037	1.58	362.9	22.2	88	7.12	321.2	24.4	-	7.26	321.4	24.4	112	6.87	412.4	24.9	71	6.46	468.2	24.9	35
Jan	2038	1.55	325.2	24.7	373	6.88	421.7	24.4	-	7.26	388.7	24.1	588	6.75	426.2	24.1	38	7.02	427.7	24.2	31
Jan	2039	1.65	388.9	22	-	6.82	289.9	22.1	-	6.88	389.9	22.9	-	6.94	424.1	22.7	-	6.75	422.4	22.9	-
Jan	2040	1.75	367.9	22	-	6.94	323.2	22.2	-	6.84	327.7	22	-	6.87	423.9	22.9	-	6.87	468.2	22	-
Jan	2041	1.54	368.9	22.9	-	6.97	344.1	24.2	229	6.95	364.4	24.2	-	6.75	461.9	24.9	54	6.75	465.2	24.9	39
Jan	2042	1.58	379.3	21.9	124	7.08	319.4	24.7	-	7.26	447.4	24.9	794	6.57	426.9	24.9	73	6.51	465.2	24.6	34
Jan	2043	1.67	345	25.4	-	7.04	463.4	27.2	257	7.08	462.7	27.1	-	6.88	333.9	27.2	47	6.32	471.6	27.2	31
Jan	2044	1.72	327	25.4	58	6.75	388	25.4	-	6.8	375.4	25.4	388	6.8	452.9	22.9	47	6.84	472	25.2	38
Jan	2045	1.68	324.9	25.4	54	6.38	462.7	22.2	-	4.54	272.2	22.2	122	6.32	475.2	22.9	38	6.36	465.2	22.4	33
Jan	2046	1.6	272.4	22.4	-	6.82	421.7	22.2	-	6.87	432.7	22.2	-	7.22	429.9	22.2	-	7.1	469.4	22.9	-
Jan	2047	1.71	345.2	22.1	-	6.88	321.7	22.2	-	6.87	462.9	22.2	-	6.75	467	22.9	-	7.06	461.2	22.4	-
Jan	2048	1.64	275.2	24.7	-	7	474.4	24.9	142	7.25	462.7	24.9	-	6.57	522.2	24.7	36	7.17	467	24.4	32
Jan	2049	1.71	325.4	24.9	-	6.88	362.2	27.2	-	6.82	323.2	27.2	476	6.82	468.9	27.2	25	6.27	468.2	27.4	40
Jan	2050	1.71	327.9	24	-	7.02	477.2	24.9	387	6.97	466.2	24.4	-	6.88	472.2	24	39	6.3	467.2	24.2	42
Jan	2051	1.66	362	25.1	121	6.88	462.2	21.9	-	7.01	464.1	22.4	102	6.81	475.2	21.7	42	6.71	467.9	22.2	36
Jan	2052	1.68	364.4	24.9	46	6.41	442.2	21.2	-	7.02	425.1	21.2	726	7.12	462.9	27.2	34	6.7	467.9	27.2	34
Jan	2053	1.61	365.2	21.9	-	6.84	317.7	21.4	-	6.88	274.9	21.9	-	6.75	425.4	27.4	-	6.72	467.2	27.9	-
Jan	2054	1.56	429.4	22	-	7.02	365.9	22.1	-	7.02	367.9	22.9	-	6.75	465.1	22.9	-	6.98	462.9	22.2	-
Jan	2055	1.6	316	22.1	-	7.07	363.4	22.1	254	7.07	364.4	21.9	-	6.68	425.1	22.9	40	6.47	466.1	24.1	39



Monitoring Parameters Result for STP

Month	Date	Part 1																			Part 2																												
		Water	Sludge	Sludge	Sludge	Sludge	Sludge	Sludge	Sludge	Sludge	Sludge	Sludge	Sludge	Sludge	Sludge	Sludge	Sludge	Sludge	Sludge	Sludge	Water	Water	Water	Water	Water	Water	Water	Water	Water	Water	Water	Water	Water	Water	Water	Water	Water	Water	Water	Water	Water	Water	Water	Water	Water	Water	Water		
Jan	01-01-21	1	1	1	1	1	1	1	1	1	1	1	1	1	1	1	1	1	1	1	1	1	1	1	1	1	1	1	1	1	1	1	1	1	1	1	1	1	1	1	1	1	1	1	1	1	1	1	
Feb	01-02-21	1	1	1	1	1	1	1	1	1	1	1	1	1	1	1	1	1	1	1	1	1	1	1	1	1	1	1	1	1	1	1	1	1	1	1	1	1	1	1	1	1	1	1	1	1	1	1	1
Mar	01-03-21	1	1	1	1	1	1	1	1	1	1	1	1	1	1	1	1	1	1	1	1	1	1	1	1	1	1	1	1	1	1	1	1	1	1	1	1	1	1	1	1	1	1	1	1	1	1	1	1
Apr	01-04-21	1	1	1	1	1	1	1	1	1	1	1	1	1	1	1	1	1	1	1	1	1	1	1	1	1	1	1	1	1	1	1	1	1	1	1	1	1	1	1	1	1	1	1	1	1	1	1	1
May	01-05-21	1	1	1	1	1	1	1	1	1	1	1	1	1	1	1	1	1	1	1	1	1	1	1	1	1	1	1	1	1	1	1	1	1	1	1	1	1	1	1	1	1	1	1	1	1	1	1	1
Jun	01-06-21	1	1	1	1	1	1	1	1	1	1	1	1	1	1	1	1	1	1	1	1	1	1	1	1	1	1	1	1	1	1	1	1	1	1	1	1	1	1	1	1	1	1	1	1	1	1	1	1
Jul	01-07-21	1	1	1	1	1	1	1	1	1	1	1	1	1	1	1	1	1	1	1	1	1	1	1	1	1	1	1	1	1	1	1	1	1	1	1	1	1	1	1	1	1	1	1	1	1	1	1	1
Aug	01-08-21	1	1	1	1	1	1	1	1	1	1	1	1	1	1	1	1	1	1	1	1	1	1	1	1	1	1	1	1	1	1	1	1	1	1	1	1	1	1	1	1	1	1	1	1	1	1	1	1
Sep	01-09-21	1	1	1	1	1	1	1	1	1	1	1	1	1	1	1	1	1	1	1	1	1	1	1	1	1	1	1	1	1	1	1	1	1	1	1	1	1	1	1	1	1	1	1	1	1	1	1	1
Oct	01-10-21	1	1	1	1	1	1	1	1	1	1	1	1	1	1	1	1	1	1	1	1	1	1	1	1	1	1	1	1	1	1	1	1	1	1	1	1	1	1	1	1	1	1	1	1	1	1	1	1
Nov	01-11-21	1	1	1	1	1	1	1	1	1	1	1	1	1	1	1	1	1	1	1	1	1	1	1	1	1	1	1	1	1	1	1	1	1	1	1	1	1	1	1	1	1	1	1	1	1	1	1	1
Dec	01-12-21	1	1	1	1	1	1	1	1	1	1	1	1	1	1	1	1	1	1	1	1	1	1	1	1	1	1	1	1	1	1	1	1	1	1	1	1	1	1	1	1	1	1	1	1	1	1	1	1



Monitoring Parameters Result for STP

Month	Date	Inlet-1																Outlet-2																	
		Cd	Mercury	Zinc	Arsenic	Chromium	Cadmium	Selenium	Lead	Copper	Barium	Nickel	Silver	Sulphide	Total Cyanide	Hexavalent Chromium (O6-)	Fluoride	Phosphate	Cd	Mercury	Zinc	Arsenic	Chromium	Cadmium	Selenium	Lead	Copper	Barium	Nickel	Silver	Sulphide	Total Cyanide	Hexavalent Chromium (O6-)	Fluoride	Phosphate
Standard		-	Max 0.005	Max 1	Max 0.1	Max 0.1	Max 0.05	Max 0.01	Max 0.1	Max 1.5	Max 1	Max 0.2	Max 0.5	Max 1	Max 1	Max 0.1	Max 0.1	Max 0.5	-	Max 0.005	Max 1	Max 0.1	Max 0.1	Max 0.05	Max 0.01	Max 0.1	Max 0.1	Max 1	Max 0.2	Max 0.5	Max 1	Max 0.1	Max 0.1	Max 0.5	
Unit		ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppm	
Sep	01-09-21	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	1	<0.002	0.07	<0.01	<0.002	<0.002	<0.01	<0.002	<0.002	<0.002	<0.002	<0.002	<0.002	<0.002	<0.002	<0.002	
Oct	01-10-21	2	<0.002	0.084	<0.01	<0.002	<0.002	0.001	<0.002	<0.002	0.05	<0.002	<0.002	0.027	0.002	<0.001	0.15	<0.002	1	<0.002	0.04	<0.01	<0.002	<0.002	<0.01	<0.002	<0.002	0.013	<0.002	<0.002	0.01	0.008	<0.001	0.009	<0.002
Nov	01-11-21	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	1.4	<0.002	0.028	<0.01	<0.002	<0.002	<0.01	<0.002	<0.002	0.01	<0.002	<0.002	<0.002	<0.002	<0.002	<0.002	
Dec	01-12-21	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	1.4	<0.002	0.038	<0.01	<0.002	<0.002	<0.01	<0.002	<0.002	0.004	<0.002	<0.002	0.013	0.007	<0.001	0.009	<0.002
Jan	11-01-22	2	<0.002	0.104	<0.01	<0.002	<0.002	0.001	<0.002	<0.002	0.058	<0.002	<0.002	0.001	0.004	<0.001	0.08	0.008	1.4	<0.002	0.036	<0.01	<0.002	<0.002	<0.01	<0.002	<0.002	0.022	<0.002	<0.002	0.013	0.007	<0.001	0.009	<0.002
Feb	04-02-22	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	1.4	<0.002	0.084	<0.01	<0.002	<0.002	<0.01	<0.002	<0.002	0.004	<0.002	<0.002	0.013	<0.001	0.009	<0.002	



သီလဝါအထူးစီးပွားရေးဇုန် အပိုင်း(ခ)ရှိ

စက်မှုဇုန်ဖွံ့ဖြိုးတိုးတက်ရေးအတွက်

ရေအရည်အသွေးစောင့်ကြည့်လေ့လာခြင်းအစီအရင်ခံစာ

(လုပ်ငန်းလည်ပတ်နေစဉ်ကာလ အပိုင်း ၁၊ အပိုင်း ၂ နှင့် အပိုင်း ၃)

(နှစ်လတစ်ကြိမ် စောင့်ကြည့်လေ့လာခြင်း)

၂၀၂၁ ခုနှစ်၊ အောက်တိုဘာလ

မြန်မာ့အံ့အင်တာနေရှင်နယ်လီမိတက်



မာတိကာ

အခန်း ၁ နိဒါန်း.....	၁
၁.၁ ယေဘုယျ ဖော်ပြချက်.....	၁
အခန်း ၂ ရေအရည်အသွေးစောင့်ကြည့်လေ့လာခြင်း.....	၃
၂.၁ စောင့်ကြည့်လေ့လာသည့်အမျိုးအစား.....	၃
၂.၂ ရေနမူနာရယူသည့်နေရာများ၏တည်နေရာနှင့်အချက်အလက်များဖော်ပြချက်.....	၄
၂.၃ စောင့်ကြည့်လေ့လာသည့်နည်းလမ်း.....	၆
၂.၄ စောင့်ကြည့်လေ့လာသည့်ကာလ.....	၇
၂.၅ စောင့်ကြည့်လေ့လာမှုရလဒ်များ.....	၈
အခန်း ၃ နိဂုံးချုပ် နှင့် အကြံပြုချက်များ.....	၁၃
နောက်ဆက်တွဲ ၁ ရေနမူနာရယူသည့် မှတ်တမ်းဇယား.....	က၁-၁
နောက်ဆက်တွဲ ၂ ဇယားဥပဒေရလဒ်များ.....	က၂-၁

ဇယားများစာရင်း

ဇယား ၂.၁-၁ စောင့်ကြည့်လေ့လာသည့်အမျိုးအစား.....	၃
ဇယား ၂.၂-၁ ရေနမူနာရယူသည့်နေရာများ.....	၄
ဇယား ၂.၃-၁ ရေအရည်အသွေးစစ်ဆေးသည့် နည်းလမ်းများ.....	၆
ဇယား ၂.၄-၁ နေရာတစ်ခုချင်းစီအတွက် နမူနာရယူသည့်အချိန်.....	၇
ဇယား ၂.၄-၂ မြန်မာနိုင်ငံ၊ ရန်ကုန်မြစ်၏ ဒီရေမှတ်တမ်း.....	၇
ဇယား ၂.၅-၁ စွန့်ထုတ်ရေထွက်ပေါက်နှင့်စွန့်ထုတ်ရေရောက်ရှိသော ချောင်းမှရေအရည်အသွေး စောင့်ကြည့်လေ့လာမှုရလဒ်များ.....	၉
ဇယား ၂.၅-၂ ရည်ညွှန်းရေတွင်း၏ ရေအရည်အသွေးစောင့်ကြည့်တန်ဖိုးရလဒ်.....	၁၁

ပုံများစာရင်း

ပုံ ၁.၁-၁ ရေအရည်အသွေးစောင့်ကြည့်လေ့လာမှုအတွက်နမူနာရယူသောနေရာများ၏ တည်နေရာပြပုံ.....	၂
---	---



အခန်း ၁ နိဒါန်း

၁.၁ ယေဘုယျ ဖော်ပြချက်

သီလဝါအထူးစီးပွားရေးဇုန်သည် ရန်ကုန်တိုင်းဒေသကြီး၏ တောင်ပိုင်းခရိုင်တွင်တည်ရှိပြီး ရန်ကုန်မြို့၏ အရှေ့တောင်ဘက် ၂၃ ကီလိုမီတာတွင် တည်ရှိပါသည်။ သီလဝါအထူးစီးပွားရေးဇုန်၏ အကောင်အထည် ဖော်ဆောင်သူအနေဖြင့် ဇုန်အပိုင်း(ခ)အတွင်းရှိ စက်မှုမြေနေရာအတွက် ခွင့်ပြုချက်ရရှိထားသော ပတ်ဝန်းကျင်ထိခိုက်မှုဆန်းစစ်ခြင်း အစီရင်ခံစာနှင့် ပတ်ဝန်းကျင်ဆိုင်ရာစီမံခန့်ခွဲမှုအစီအစဉ်အတိုင်း ပုံမှန်စောင့်ကြည့်စစ်ဆေးခြင်းကို ဆောင်ရွက်ရန် မြန်မာ-ဂျပန် သီလဝါဖွံ့ဖြိုးရေးလီမိတက်တွင် တာဝန်ရှိပါသည်။ မြန်မာ-ဂျပန် သီလဝါဖွံ့ဖြိုးရေးလီမိတက်သည် ဇုန်အတွင်း နှင့် အနီးပတ်ဝန်းကျင်ရှိ သဘာဝပတ်ဝန်းကျင် အခြေအနေများကို သိရှိစေရန် သဘာဝပတ်ဝန်းကျင်နှင့်သက်ဆိုင်သော အချက်အလက် စောင့်ကြည့်လေ့လာမှုများကို ရေးဆွဲထားပြီး ထိုအစီအစဉ်များအရ အကောင်အထည်ဖော် ဆောင်ရွက်ခဲ့ပါသည်။

ရေအရည်အသွေးစောင့်ကြည့်လေ့လာမှုအား စစ်တမ်းကောက်ယူရာတွင် သီလဝါအထူးစီးပွားရေးဇုန်အတွင်းနှင့် အနီးပတ်ဝန်းကျင်ရှိ စုစုပေါင်းနေရာ လေးနေရာ၊ နာမည်အားဖြင့် မြေပေါ်ရေနမူနာယူသည့် နေရာ-၂ (SW-2)၊ မြေပေါ်ရေနမူနာယူသည့် နေရာ-၄ (SW-4)၊ မြေပေါ်ရေနမူနာယူသည့် နေရာ-၇ (SW-7) နှင့် မြေအောက်ရေနမူနာယူသည့် နေရာ-၂ (GW-2) တို့တွင် စောင့်ကြည့်လေ့လာခဲ့ပါသည်။ ထိုနေရာ လေးနေရာမှ မြေပေါ်ရေနမူနာယူသည့် နေရာ-၇ (SW-7) သည် ဇုန်အပိုင်း(ခ) လုပ်ငန်းလည်ပတ်နေစဉ်ကာလတွင် အဓိကစွန့်ထုတ်ရေထွက်ပေါက် ဖြစ်ပါသည်။ ထို့အပြင် မြေအောက်ရေနမူနာယူသည့် နေရာ-၂ (GW-2) အား ဖလမ်းကျေးရွာတွင်တည်ရှိသော ဘုန်းကြီးကျောင်းပရဝဏ်အတွင်းရှိ ရေတွင်းအား ရည်ညွှန်းနိုင်ရန် စောင့်ကြည့်လေ့လာခဲ့ပါသည်။ ရေအရည်အသွေးစောင့်ကြည့်လေ့လာမှုအတွက် နမူနာရယူသော နေရာများ၏ တည်နေရာများကို ပုံ ၁.၁-၁ တွင် ဖော်ပြထားပါသည်။



သီလဝါအထူးစီးပွားရေးဇုန်အပိုင်း(ခ)ရှိစက်မှုဇုန်ဖွံ့ဖြိုးတိုးတက်မှုအတွက်ရေအရည်အသွေးစောင့်ကြည့်လေ့လာမှုအစီရင်ခံစာ
(နှစ်လတစ်ကြိမ်၊ စောင့်ကြည့်လေ့လာခြင်း၊ အောက်တိုဘာလ ၂၀၂၁ ခုနှစ်)



မူရင်း ပုံရိပ်အက်

ပုံ ၁.၁-၁ ရေအရည်အသွေးစောင့်ကြည့်လေ့လာမှုအတွက်နမူနာရယူသောနေရာများ၏ တည်နေရာပြပုံ



အခန်း ၂ ရေအရည်အသွေးစောင့်ကြည့်လေ့လာခြင်း

၂.၁ စောင့်ကြည့်လေ့လာသည့်အမျိုးအစား

ရေအရည်အသွေး စောင့်ကြည့်လေ့လာမှုအတွက် ရေနမူနာရယူသောနေရာများနှင့် ရေအရည်အသွေး အမျိုးအစားများ(Parameters)ကို ပတ်ဝန်းကျင်ထိခိုက်မှုဆန်းစစ်ခြင်းဆိုင်ရာ အစီအရင်ခံစာပါ ပတ်ဝန်းကျင်ဆိုင်ရာစောင့်ကြည့်လေ့လာမှု အစီအစဉ်အား ခြုံငုံမိစေရန်အလို့ငှာ ဆောင်ရွက်ထားပါသည်။

ရေအရည်အသွေးနမူနာစစ်တမ်းရယူမှုအား နေရာလေးနေရာတွင် ဆောင်ရွက်ခဲ့ပါသည်။ ထိုနေရာ လေးနေရာမှ ရေစီးဆင်းမှုတိုင်းတာခြင်းကို ရေစီးနှုန်းတိုင်းကိရိယာဖြင့် တိုင်းတာနိုင်သော နေရာသုံးနေရာ ဖြစ်သည့် မြေပေါ်ရေနမူနာယူသည့် နေရာ-၂ (SW-2)၊ မြေပေါ်ရေနမူနာယူသည့် နေရာ-၄ (SW-4) နှင့် မြေပေါ်ရေနမူနာယူသည့် နေရာ-၇ (SW-7) တို့တွင် တိုင်းတာခဲ့ပါသည်။ စောင့်ကြည့်လေ့လာသော ရေအရည်အသွေး အမျိုးအစားများ(Parameters)နှင့် ရေနမူနာရယူသောနေရာများကို ဇယား ၂.၁-၁ တွင် အကျဉ်းချုပ် ဖော်ပြထားပါသည်။

ဇယား ၂.၁-၁ စောင့်ကြည့်လေ့လာသည့်အမျိုးအစား

အမှတ်	ရေအရည်အသွေး အမျိုးအစား (Parameters)	မြေပေါ်ရေ နေရာ-၂ (SW-2)	မြေပေါ်ရေ နေရာ-၄ (SW-4)	မြေပေါ်ရေ နေရာ-၇ (SW-7)	မြေအောက် ရေအရည်အသွေး (GW-2)	မှတ်ချက်
၁	ရေအပူချိန် (Water Temperature)	၁	၁	၁	၁	ရေနမူနာရယူသည့်နေရာတွင် တိုက်ရိုက်တိုင်းတာခြင်း
၂	ချဉ်ဖန်ကိန်း (pH)	၁	၁	၁	၁	ရေနမူနာရယူသည့်နေရာတွင် တိုက်ရိုက်တိုင်းတာခြင်း
၃	ပျော်ဝင်အောက်စီဂျင် (DO)	၁	၁	၁	၁	ရေနမူနာရယူသည့်နေရာတွင် တိုက်ရိုက်တိုင်းတာခြင်း
၄	ဇီဝနည်းဖြင့်ဖြိုခွဲရန် အောက်စီဂျင် လိုအပ်ချက် (၅ ရက်) (BOD ₅)	၁	၁	၁	၁	ဓာတ်ခွဲစမ်းသပ်ခြင်း
၅	ဓာတုနည်းဖြင့် ဖြိုခွဲရန် အောက်စီဂျင် လိုအပ်ချက် (COD _{Cr})	၁	၁	၁	၁	ဓာတ်ခွဲစမ်းသပ်ခြင်း
၆	နိုက်ထရိုဂျင်စုစုပေါင်း (Total Nitrogen)	၁	၁	၁	၁	ဓာတ်ခွဲစမ်းသပ်ခြင်း
၇	ခိုင်းကြွအနယ်များ (Suspended Solids)	၁	၁	၁	၁	ဓာတ်ခွဲစမ်းသပ်ခြင်း
၈	ကိုလီဖောင်း စုစုပေါင်း (Total Coliform)	၁	၁	၁	၁	ဓာတ်ခွဲစမ်းသပ်ခြင်း
၉	ဖော့စဖောရက်စုစုပေါင်း (Total Phosphorus)	၁	၁	၁	၁	ဓာတ်ခွဲစမ်းသပ်ခြင်း
၁၀	အရောင် (Color)	၁	၁	၁	၁	ဓာတ်ခွဲစမ်းသပ်ခြင်း
၁၁	အနံ့ (Odor)	၁	၁	၁	၁	ဓာတ်ခွဲစမ်းသပ်ခြင်း



စဉ်	ရေအရည်အသွေး အမျိုးအစား (Parameters)	မြေပေါ်ရေ နမူနာယူသည့် နေရာ-၂ (SW-2)	မြေပေါ်ရေ နမူနာယူသည့် နေရာ-၄ (SW-4)	မြေပေါ်ရေ နမူနာယူသည့် နေရာ-၇ (SW-7)	မြေအောက် ရေ နမူနာယူသည့် နေရာ-၂ (GW-2)	မှတ်ချက်
၁၂	ဆီနှင့်အမဲဆီ (Oil and Grease) (ကိုယ်တိုင်စောင့်ကြည့်လေ့လာခြင်း)	၀	၀	၀	၀	ဓာတ်ခွဲခန်းသစ်ခြင်း
၁၃	ပျော်ဝင်အနည်စုစုပေါင်း (Total Dissolved Solids) (ကိုယ်တိုင်စောင့်ကြည့်လေ့လာခြင်း)	၀	၀	၀	၀	ဓာတ်ခွဲခန်းသစ်ခြင်း
၁၄	သံဆာတ် (Iron) (ကိုယ်တိုင်စောင့်ကြည့်လေ့လာခြင်း)	၀	၀	၀	၀	ဓာတ်ခွဲခန်းသစ်ခြင်း
၁၅	ပြဒါဇောတ် (Mercury) (ကိုယ်တိုင်စောင့်ကြည့်လေ့လာခြင်း)	၀	၀	၀	၀	ဓာတ်ခွဲခန်းသစ်ခြင်း
၁၆	ဓမီးကိုက်ရောဂါကိုဖြစ်စေသော ကိုလီဖော့င်း ဘက်တီးရီးယား (Escherichia Coli) (ကိုယ်တိုင်စောင့်ကြည့်လေ့လာခြင်း)	-	-	၀	၀	ဓာတ်ခွဲခန်းသစ်ခြင်း
၁၇	ရေစီးဆင်းနှုန်း	၀	၀	၀	-	ရေနမူနာရယူသည့်နေရာတွင် တိုက်ရိုက်တိုင်းတာခြင်း

မူရင်း၊ မြန်မာ့သမ္မတနိုင်ငံတော်အစိုးရအဖွဲ့၊ နယ်လီမီတာ

၂.၂ ရေနမူနာရယူသည့်နေရာများ၏တည်နေရာနှင့်အချက်အလက်များဖော်ပြချက်

ရေနမူနာယူသည့်နေရာများကို ဇယား ၂.၂-၁ တွင် ဖော်ပြထားပါသည်။ ရေနမူနာရယူသည့်နေရာ တစ်ခုစီတွင် စစ်တမ်းရယူခဲ့သည့်မှတ်တမ်းပုံများကို နောက်ဆက်တွဲ-၁ တွင်ဖော်ပြထားသည်။

ဇယား ၂.၂-၁ ရေနမူနာရယူသည့်နေရာများ

စဉ်	တည်နေရာ	အသေးစိတ်အချက်အလက်
၁	မြေပေါ်ရေနမူနာယူသည့် နေရာ-၂ (SW-2)	ကိုဩဒိနိတ် - မြောက်လတ္တီတွဒ် - ၁၆° ၄၀' ၂၃.၆၉"၊ အရှေ့လောင်ဂျီတွဒ် - ၉၆° ၁၇' ၁၈.၀၄" တည်နေရာ - ရွှေပျောက်ဆောင်းအောက်ပိုင်း စစ်တမ်းကောက်ယူသော အမျိုးအစား - မြေပေါ်ရေစစ်တမ်းရယူခြင်းနှင့်ရေစီးနှုန်းတိုင်းတာခြင်း
၂	မြေပေါ်ရေနမူနာယူသည့် နေရာ-၄ (SW-4)	ကိုဩဒိနိတ် - မြောက်လတ္တီတွဒ် - ၁၆° ၃၉' ၄၂.၈၄"၊ အရှေ့လောင်ဂျီတွဒ် - ၉၆° ၁၆' ၂၇.၄၂" တည်နေရာ - ရွှေပျောက်ဆောင်းအောက်ပိုင်း စစ်တမ်းကောက်ယူသော အမျိုးအစား - မြေပေါ်ရေစစ်တမ်းရယူခြင်းနှင့်ရေစီးနှုန်းတိုင်းတာခြင်း
၃	မြေပေါ်ရေနမူနာယူသည့် နေရာ-၇ (SW-7)	ကိုဩဒိနိတ် - မြောက်လတ္တီတွဒ် - ၁၆° ၄၀' ၀၃.၂၅"၊ အရှေ့လောင်ဂျီတွဒ် - ၉၆° ၁၇' ၅.၆၆" တည်နေရာ - ရွှေပျောက်ဆောင်းသို့ မရောက်မီ ဇုန် အပိုင်း (ခ) ဆောက်လုပ်ရေးလုပ်ငန်းခွင်ရှိ ရေစိမ့်ကန်၏ ထွက်ပေါက် စစ်တမ်းကောက်ယူသော အမျိုးအစား - စွန့်ထုတ်ရေစစ်တမ်းရယူခြင်း
၄	မြေအောက်ရေနမူနာယူသည့် နေရာ-၂ (GW-2)	ကိုဩဒိနိတ် - မြောက်လတ္တီတွဒ် - ၁၆° ၃၉' ၂၅.၃၀"၊ အရှေ့လောင်ဂျီတွဒ် - ၉၆° ၁၇' ၁၅.၆၀" တည်နေရာ - ဖလမ်းကျေးရွာရှိ ဘုန်းကြီးကျောင်းပရဝတ်အတွင်း စစ်တမ်းကောက်ယူသော အမျိုးအစား - မြေအောက်ရေစစ်တမ်းရယူခြင်း

မူရင်း၊ မြန်မာ့သမ္မတနိုင်ငံတော်အစိုးရအဖွဲ့၊ နယ်လီမီတာ



မြေပေါ်ရေနမူနာယူသည့် နေရာ-၂ (SW-2) (ရည်ညွှန်းအမှတ်)

မြေပေါ်ရေနမူနာယူသည့် နေရာ-၂ (SW-2)အား ရွှေပျောက်ချောင်း၏ အတက်ပိုင်းတွင် ရယူခဲ့ခြင်းဖြစ်သည်။ အဆိုပါအမှတ်သည် ဇုန်အပိုင်း(ခ)ဧရိယာ၏ အရှေ့မြောက်ဘက်နှင့် ဒဂုံ-သီလဝါလမ်း၏ တောင်ဘက်တွင် တည်ရှိပါသည်။ အနောက်မြောက်တွင် ဇုန်အပိုင်း(က) နှင့် အရှေ့ဘက်တွင် ပြည်တွင်းစက်မှုဇုန်တို့က အသီးသီး ဝန်းရံလျက် ရှိသည်။

မြေပေါ်ရေနမူနာယူသည့် နေရာ-၄ (SW-4) (ရည်ညွှန်းအမှတ်)

ပြည်တွင်းစက်မှုဇုန်၊ ဇုန်အပိုင်း(က) နှင့် ဇုန်အပိုင်း(ခ)ရှိ ဆောက်လုပ်ရေးလုပ်ငန်းခွင်များမှ ထွက်ရှိလာသောမိုး ရေများပေါင်းစည်းရောနှောသွားသောနေရာ ရွှေပျောက်ချောင်း၏ အောက်ပိုင်းတွင် မြေပေါ်ရေနမူနာယူသည့် နေရာ-၄ (SW-4) တွင် ရယူခဲ့ခြင်းဖြစ်သည်။ ရွှေပျောက်ချောင်းသည် အရှေ့မှအနောက်သို့စီးဆင်းပြီး ရန်ကုန်မြစ် အတွင်းသို့ စီးဝင်သည်။ မြေပေါ်ရေနမူနာယူသည့် နေရာ-၄ (SW-4) သည် မြေပေါ်ရေနမူနာယူသည့် နေရာ-၂ (SW-2)၏ ချောင်းအောက်ပိုင်း ၂၁၅ ကီလိုမီတာအကွာတွင် တည်ရှိပါသည်။ အဆိုပါ ရေနမူနာရယူသည့်နေရာသည် ဇုန်အပိုင်း(ခ) ဧရိယာ၏ အနောက်ဘက်တွင်တည်ရှိပြီး ဒဂုံ-သီလဝါလမ်း၏ တောင်ဘက်တွင်တည်ရှိပါသည်။ ပတ်ဝန်းကျင်အနီးအနားတွင် အရှေ့မြောက်ဘက်တွင် ဇုန်အပိုင်း (က)၊ အရှေ့ဘက်တွင် ပြည်တွင်းစက်မှုဇုန်၊ တောင်ဘက်နှင့် အနောက်ဘက်တို့တွင် စပါးခင်းတို့ အသီးသီးတည်ရှိပါသည်။

မြေပေါ်ရေနမူနာယူသည့် နေရာ-၇ (SW-7) (စွန့်ထုတ်ရေထွက်ပေါက်)

မြေပေါ်ရေနမူနာယူသည့် နေရာ-၇ (SW-7) သည် ဇုန်အပိုင်း(ခ)၏ လုပ်ငန်းလည်ပတ်နေစဉ်ကာလအတွင်း အဓိကစွန့်ထုတ်ရေထွက်ပေါက် ဖြစ်ပါသည်။ ထိုနေရာသည် မြေပေါ်ရေနမူနာယူသည့် နေရာ-၂ (SW-2) ၏ ချောင်းအောက်ပိုင်း၊ အကွာအဝေးအားဖြင့် ၄၃၄ မီတာ အကွာတွင် တည်ရှိပါသည်။ နမူနာရယူသည့်နေရာမှာ ဇုန်အပိုင်း(ခ) ရေထိန်းကန်၏ထွက်ပေါက်၊ ဇုန်အပိုင်း(ခ) ဧရိယာ၏ မြောက်ဘက်နှင့် ဒဂုံ-သီလဝါလမ်းမကြီး၏ တောင်ဘက်တွင် တည်ရှိပါသည်။ အနီးအနားပတ်ဝန်းကျင်၌ မြောက်ဘက်တွင် ဇုန်အပိုင်း(က) နှင့် အရှေ့ဘက်တွင် ပြည်တွင်းစက်မှုဇုန်တို့ တည်ရှိပါသည်။

မြေအောက်ရေနမူနာယူသည့် နေရာ-၂ (GW-2) (မူလတည်ရှိနေသောရေတွင်းအား ရည်ညွှန်းခြင်း)

မြေအောက်ရေနမူနာယူသည့် နေရာ-၂ (GW-2) အား တူးဖော်ထားသောရေတွင်းမှ ရယူခဲ့ပါသည်။ အဆိုပါ ရေတွင်းသည် ဖလမ်းကျေးရွာရှိ ဘုန်းကြီးကျောင်းပရဝဏီအတွင်းတွင် တည်ရှိပါသည်။ အနီးအနားပတ်ဝန်းကျင်၌ မြောက်ဘက်တွင် သီလဝါအထူးစီးပွားရေးဇုန် အပိုင်း (က)၊ တောင်ဘက်တွင် ဖလမ်းကျေးရွာ၊ အနောက်ဘက်တွင် လယ်ကွင်းများ၊ အရှေ့မြောက်ဘက်တွင် ပြည်တွင်းစက်မှုဇုန်နှင့် အရှေ့နှင့်အရှေ့မြောက်ဘက်တွင် သီလဝါအထူးစီးပွားရေးဇုန် အပိုင်း (ခ)တို့ အသီးသီးတည်ရှိနေပါသည်။



၂.၃ စောင့်ကြည့်လေ့လာသည့်နည်းလမ်း

ရေနမူနာများကို ရယူပြီး သန့်စင်ထားသောဖန်ပုလင်းညှို့များဖြင့် သိမ်းဆည်းပြီး ဇယား ၂.၃-၁ တွင် ဖော်ပြထားသော နည်းလမ်းများဖြင့် ဓာတ်ခွဲခန်း၌ စစ်ဆေးပါသည်။ ရေနမူနာများကို ရေခဲပုံးများဖြင့် ၂-၄ဒီဂရီ ဆဲလ်စီးယပ်တွင် သိမ်းဆည်းထားပြီး ဓာတ်ခွဲခန်းသို့ ပို့ဆောင်ပါသည်။ တိုင်းတာသည့် ရေအရည်အသွေး အမျိုးအစားများ၌ ရေအပူချိန်၊ ချဉ်ဖန်ကိန်း နှင့် ပျော်ဝင်အောက်စီဂျင်တို့အား ရေအရည်အသွေး တိုင်းတာသောစက်ကိရိယာ (Horiba U-52)ကို အသုံးပြု၍ ရေနမူနာရယူသည့်နေရာ၌ပင် တိုက်ရိုက်တိုင်းတာခဲ့ပါသည်။ ထို့အပြင်ရေစီးဆင်းမှုနှုန်းကိုလည်း ဒီဂျစ်တယ်ရေစီးနှုန်းတိုင်းကိရိယာ (JFE Digital Current Meter)ဖြင့် ရေနမူနာရယူသည့်နေရာ၌ တိုင်းတာခဲ့ပါသည်။

ဇယား ၂.၃-၁ ရေအရည်အသွေးစစ်ဆေးသည့် နည်းလမ်းများ

စဉ်	အမျိုးအစားများ	နည်းလမ်း
၁	ရေအပူချိန် (Water Temperature)	Instrument Analysis Method (Horiba, U-52, Multi Water Quality Checker)
၂	ချဉ်ဖန်ကိန်း (pH)	Instrument Analysis Method (Horiba, U-52, Multi Water Quality Checker)
၃	ဆိုင်ကြွေးအနယ် (Suspended Solids)	APHA 2540 D (Dry at 103-105°C Method)
၄	ပျော်ဝင်အောက်စီဂျင် (Dissolved Oxygen)	Instrument Analysis Method (Horiba, U-52, Multi Water Quality Checker)
၅	စီဝနည်ဖြင့်ဖြိုခွဲရန် အောက်စီဂျင် လိုအပ်ချက် (၅-ရက်) (BOD ₅)	APHA 5210 B (5 Days BOD Test)
၆	ဓာတ်နည်ဖြင့် ဖြိုခွဲရန် အောက်စီဂျင် လိုအပ်ချက် (COD _{cr})	APHA 5220D (Close Reflux Colorimetric Method)
၇	ကိုလီဖောင်း စုစုပေါင်း (Total Coliform)	APHA 9221B (Standard Total Coliform Fermentation Technique)
၈	နိုက်ထရိုဂျင်စုစုပေါင်း (Total Nitrogen)	HACH Method 10072 (TNT Persulfate Digestion Method)
၉	ဖော့စဖောရက်စုစုပေါင်း (Total Phosphorus)	APHA 4500-P E (Ascorbic Acid Method)
၁၀	အရောင် (Color)	APHA 2120C (Spectrophotometric Method)
၁၁	အနံ့ (Odor)	APHA 2150 B (Threshold Odor Test)
၁၂	ဆီနှင့် အမဲဆီ (Oil and Grease)	APHA 5520B (Partition-Gravimetric Method)
၁၃	ပြွမ်းဓာတ် (Mercury)	APHA 3120 B (Inductively Coupled Plasma (ICP) Method)
၁၄	သံဓာတ် (Iron)	APHA 3120 B (Inductively Coupled Plasma (ICP) Method)
၁၅	ပျော်ဝင်အနည်စုစုပေါင်း (Total Dissolved Solids)	APHA 2540 C (Total Dissolved Solids Dried at 180°C Method)
၁၆	ဝမ်းကိုက်ရောဂါကိုဖြစ်စေသော ဘက်တီးရီးယား (Escherichia Coli)	APHA 9221 F (Escherichia Coli Procedure Using Fluorogenic Substrate)
၁၇	စီးဆင်းနှုန်း (Flow Rate)	Detection of Electromagnetic Elements (Real-time measurement by AEM 213-D Digital Current Meters)

ဇယား ပြန်မာဒီအင်တာနေရှင်နယ်လီမိတက်



၂.၄ စောင့်ကြည့်လေ့လာသည့်ကာလ

ရေအရည်အသွေးနှင့် ရေစီးဆင်းမှုနှုန်းအား အောက်တိုဘာလ ၆ ရက်နေ့၊ ၂၀၂၁ ခုနှစ်တွင် ဆောင်ရွက်ခဲ့ပြီး ဒီရေအတက်အကျကြောင့် ဖြစ်ပေါ်လာနိုင်သော သက်ရောက်မှုများကိုရှောင်ရှားနိုင်ရန် အောက်ပါ ဇယား ၂.၄-၁ အတိုင်း ရေနမူနာယူခဲ့သည်။ မြန်မာနိုင်ငံ၊ ရန်ကုန်မြစ်၏ အောက်တိုဘာလ ၆ ရက်နေ့၊ ၂၀၂၁ ခုနှစ် အတွက်ဒီရေ မှတ်တမ်းကို ဇယား ၂.၄-၂ တွင်ဖော်ပြထားပါသည်။

ဇယား ၂.၄-၁ နေရာတစ်ခုချင်းစီအတွက် နမူနာယူသည့်အချိန်

စဉ်	ရေနမူနာယူသည့်နေရာ	ရေနမူနာယူသည့်အချိန်
၁	မြေပေါ်ရေနမူနာယူသည့် နေရာ-၂ (SW-2)	အောက်တိုဘာလ ၆ ရက်နေ့ ၂၀၂၁ ခုနှစ် (၀၈ နာရီ : ၁၅ မိနစ်)
၂	မြေပေါ်ရေနမူနာယူသည့် နေရာ-၄ (SW 4)	အောက်တိုဘာလ ၆ ရက်နေ့ ၂၀၂၁ ခုနှစ် (၀၇ နာရီ : ၂၁ မိနစ်)
၃	မြေပေါ်ရေနမူနာယူသည့် နေရာ-၇ (SW-7)	အောက်တိုဘာလ ၆ ရက်နေ့ ၂၀၂၁ ခုနှစ် (၀၈ နာရီ : ၃၈ မိနစ်)
၄	မြေအောက်ရေနမူနာယူသည့် နေရာ ၂ (GW 2)	အောက်တိုဘာလ ၆ ရက်နေ့ ၂၀၂၁ ခုနှစ် (၁၁ နာရီ : ၃၇ မိနစ်)

မှရင်း၊ မြန်မာနိုင်ငံအထွေထွေအကျဉ်းချုပ်

ဇယား ၂.၄-၂ မြန်မာနိုင်ငံ၊ ရန်ကုန်မြစ်၏ ဒီရေမှတ်တမ်း

ရက်စွဲ	အချိန်	အမြင့်	ဒီရေအမြင့်အနေ
အောက်တိုဘာလ ၆ ရက်နေ့	၀၃:၅၈	၆.၂၂	ဒီရေအတက်
၂၀၂၁ ခုနှစ်	၀၁:၅၇	၁.၂၀	ဒီရေအကျ
	၁၆:၀၅	၆.၂၆	ဒီရေအတက်

မှရင်း၊ မြန်မာနိုင်ငံတစ်လုံးအကျဉ်းချုပ်၊ ၂၀၂၁ ခုနှစ်အတွက် ရန်ကုန်မြစ်၏ ဒီရေမှတ်တမ်း



၂.၅ စောင့်ကြည့်လေ့လာမှုရလဒ်များ

စွန့်ထုတ်ရေထွက်ပေါက်နှင့် စွန့်ထုတ်ရေရောက်ရှိသောချောင်းတွင်းရှိ ရေအရည်အသွေး စောင့်ကြည့်လေ့လာမှု ရလဒ်များကို ဇယား ၂.၅-၁ တွင် ဖော်ပြထားသည်။ ဓာတ်ခွဲခန်းဆန်းစစ်မှု ရလဒ်များကို နောက်ဆက်တွဲ-၂ တွင်ဖော်ပြထားသည်။ ရလဒ်များကို ပတ်ဝန်းကျင်ထိခိုက်မှု ဆန်းစစ်ခြင်း အစီအရင်ခံစာတွင်ပါရှိသည့် ရေအရည်အသွေးရည်မှန်းတန်ဖိုးများနှင့် နှိုင်းယှဉ်ထားပါသည်။

၂.၅.၁ စွန့်ထုတ်ရေထွက်ပေါက်နှင့် စွန့်ထုတ်ရေရောက်ရှိသောချောင်းတွင်းရှိရလဒ်များ

ရည်မှန်းတန်ဖိုးနှင့်နှိုင်းယှဉ်ရာတွင် ဆိုင်းကြွအနည်များ၊ ကိုလီဖောင်းစုစုပေါင်း နှင့် သံဓာတ်တို့မှာ ရည်မှန်းတန်ဖိုးထက် ကျော်လွန်နေကြောင်းတွေ့ရသည်။

စွန့်ထုတ်ရေထွက်ပေါက်ရှိ ရေရလဒ်များ

ဆိုင်းကြွအနည်ရလဒ် အနေဖြင့် ချောင်းတွင်းသို့မစွန့်ထုတ်ခင် ဇုန်အပိုင်း(ခ)၏ အဓိကစွန့်ထုတ်ရေထွက်ပေါက် ဖြစ်သော မြေပေါ်ရေနမူနာယူသည့် နေရာ-၇ (SW-7) ရှိ ရလဒ်များသည် ရည်မှန်းတန်ဖိုးထက် ကျော်လွန်နေခြင်းမှာ ဇုန်အပိုင်း(ခ)ရှိ မြေလွှတ်များမှ မြေမျက်နှာပြင် စီးဆင်းရေများ ကြောင့် ဖြစ်နိုင်ပါသည်။

ကိုလီဖောင်းစုစုပေါင်း ရလဒ်အနေဖြင့် ချောင်းတွင်းသို့ မစွန့်ထုတ်ခင် ဇုန်အပိုင်း(ခ)၏ အဓိကစွန့်ထုတ်ရေထွက်ပေါက် ဖြစ်သော မြေပေါ်ရေနမူနာယူသည့် နေရာ-၇ (SW-7) ရှိ ရလဒ်များမှာ ရည်မှန်းတန်ဖိုးထက် ကျော်လွန်နေကြောင်း တွေ့ရှိရပါသည်။ ဖြစ်နိုင်ချေ အလားအလာရှိသည့် အကြောင်းရင်းများမှာ ရေထိန်းကန် အတွင်းနှင့် အပြင်တလျှောက်တွင် အပင်များနှင့်ငှက်များ၊ တိရစ္ဆာန်ငယ်များ ကျင်လည်ကျက်စားခြင်းကြောင့် ဇုန်အပိုင်း(ခ)၏ ဧရိယာတွင် သဘာဝအလျှောက် ဘက်တီးရီးယားများ ရှိနေသောကြောင့် ဖြစ်နိုင်ပါသည်။

ကိုလီဖောင်းစုစုပေါင်း၏ဖြစ်တည်မှုတွင် သဘာဝမှဘက်တီးရီးယားများပါဝင်ပြီး စုစုပေါင်းကိုလီဖောင်းသည် လူတို့၏ကျန်းမာရေးကို တိုက်ရိုက်ထိခိုက်မှုမရှိသော်ငြားလည်း ကိုလီဖောင်းဘက်တီးရီးယားများမှတစ်ဆင့်ဖြစ်သည့် ကျန်းမာရေး အပေါ်သက်ရောက်မှုကိုဖော်ထုတ်ရန် ဝမ်းကိုက်ရောဂါကိုဖြစ်စေသော ကိုလီဖောင်း ဘက်တီးရီးယား(E Coli)အား သုံးသပ်ခြင်းအတွက် ကိုယ်တိုင်စောင့်ကြည့် လေ့လာမှုကိုပြုလုပ်ခဲ့ပါသည်။ ဤဝမ်းကိုက်ရောဂါကိုဖြစ်စေသော ကိုလီဖောင်းဘက်တီးရီးယား(E Coli)ရလဒ်အရ မြေပေါ်ရေနမူနာယူသည့် နေရာ-၇ (SW-7) ၏ တန်ဖိုးသည် ရည်မှန်းတန်ဖိုးအောက် နည်းပါးကြောင်းတွေ့ရှိရပါသည်။ ထို့ကြောင့် မြေပေါ်ရေနမူနာယူသည့်နေရာ-၇ (SW-7) တွင် ကိုလီဖောင်းစုစုပေါင်းသည် ရည်မှန်းတန်ဖိုးထက် များနေသော်လည်း လူ၏ကျန်းမာရေးကို သိသာထင်ရှားစွာ သက်ရောက်မှုမရှိနိုင်ကြောင်း သတ်မှတ်နိုင်ပါသည်။

စောင့်ကြည့်လေ့လာ ရည်ညွှန်းအမှတ်များ၏ ရေရလဒ်များ (စွန့်ထုတ်ရေရောက်ရှိသောချောင်း)

ဆိုင်းကြွအနည်များ၏ ရလဒ်များအရ မြေပေါ်ရေနမူနာယူသည့် နေရာ-၄ (SW-4) တို့ရှိ ရလဒ်များသည် ရည်မှန်းတန်ဖိုးထက် ကျော်လွန်နေပါသည်။ ဆိုင်းကြွအနည်များ၏ ရလဒ်များသည် ရည်မှန်းတန်ဖိုးထက် ကျော်လွန်နေခြင်းမှာ (၁) သဘာဝအလျှောက် ချောင်းအထက်ပိုင်းမှ စီးဆင်းလာခြင်းနှင့် သီလဝါအထူးစီးပွားရေးဇုန် ပြင်ပရှိ ပြည်တွင်းစက်မှုဇုန်မှ စွန့်ထုတ်လိုက်သော ရေများကြောင့်လည်းကောင်း၊



(၂)ချောင်းအောက်ဘက်ရှိ ရေများသည် ဒီရေအတက်အကျကြောင့် အထက်သို့ ပြန်လည်စီးဆင်းလာခြင်းကြောင့်လည်းကောင်း ဖြစ်နိုင်ပါသည်။

ကိုလီဖောင်းစုစုပေါင်းရလဒ်အနေဖြင့် (မြေပေါ်ရေနမူနာယူသည့် နေရာ-၂ (SW-2) နှင့် မြေပေါ်ရေနမူနာယူသည့် နေရာ-၄ (SW-4)) တို့ရှိ ရလဒ်များသည် ရည်မှန်းတန်ဖိုးထက် ကျော်လွန်နေခြင်းမှာ (၁)စွန့်ထုတ်ရေရောက်ရှိရာ ချောင်းအတွင်းနှင့် အနီးတစ်ဝိုက်တွင် ရှိနေသော အပင်အမျိုးမျိုးနှင့် သက်ရှိသတ္တဝါများဖြစ်သော ငှက်များနှင့်တိရစ္ဆာန်များကြောင့် သဘာဝ ဘက်တီးရီးယားများသည် စွန့်ထုတ်ရေရောက်ရှိရာ ချောင်းအတွင်းတွင် တည်ရှိနေခြင်းကြောင့်လည်းကောင်း၊ (၂)သီလဝါအထူးစီးပွားရေးဇုန် ပြင်ပရှိ ပြည်တွင်းစက်မှုဇုန်မှ စွန့်ထုတ်ရေများကြောင့်လည်းကောင်း၊ (၃)အနီးပတ်ဝန်းကျင်မှ ဒီရေသက်ရောက်မှုကြောင့်လည်းကောင်း ဖြစ်နိုင်ပါသည်။

သံဓာတ်ရလဒ်အနေဖြင့် (မြေပေါ်ရေနမူနာယူသည့်နေရာ-၂ (SW-2) နှင့် မြေပေါ်ရေနမူနာယူသည့်နေရာ-၄ (SW-4)) တို့ရှိ ရလဒ်သည် ရည်မှန်းတန်ဖိုးထက် ကျော်လွန်နေကြောင်း တွေ့ရှိရပါသည်။ ဖြစ်နိုင်သောကြောင့်အရာများမှာ သဘာဝ သံဓာတ် အရင်းအမြစ်၏ လွှမ်းမိုးမှု ကြောင့် ဖြစ်နိုင်ပါသည် (သံဓာတ်သည်ရေစီးဆင်းမှုကြောင့် မြေဆီလွှာအတွင်းမှ ထွက်လာနိုင်ပါသည်။)။ ရန်ကုန်မြို့၏ မြေဆီလွှာသည် သဘာဝအားဖြင့်သံဓာတ် ကြွယ်ဝပါသည်။

ဇယား ၂.၅-၁ စွန့်ထုတ်ရေထွက်ပေါက်နှင့်စွန့်ထုတ်ရေရောက်ရှိသော ချောင်းမှရေအရည်အသွေး စောင့်ကြည့်လေ့လာမှုရလဒ်များ

စဉ်	ရေအရည်အသွေး အမျိုးအစားများ (Parameters)	ယူနစ်	မြေပေါ်ရေ နမူနာယူသည့် နေရာ-၂ (SW-2)	မြေပေါ်ရေ နမူနာယူသည့် နေရာ-၄ (SW-4)	မြေပေါ်ရေ နမူနာယူသည့် နေရာ-၇ (SW-7)	စောင့်ကြည့်လေ့လာ နေရာရှိ ရည်မှန်းတန်ဖိုး
၁	ရေအပူချိန် (Water Temperature)	°C	၂၆	၂၆	၂၇	≤ ၃၅
၂	ချဉ်ဖန်တိန်း(pH)	-	၆.၈	၇.၃	၇.၂	၆-၉
၃	ဆိုင်းတြာအနယ် (Suspended Solids)	mg/L	၅၁	၃၁၂	၁၇၀	၅၀
၄	ပျော်ဝင်အောက်စီဂျင် (Dissolved Oxygen)	mg/L	၂.၅၇	၄.၃၅	၄.၅၁	-
၅	ဇီဝနည်းဖြင့်ဖြိုခွဲရန် အောက်စီဂျင် လိုအပ်ချက် (၅ ရက်) (BOD(5))	mg/L	၁၁.၄၅	၃.၅၈	၄.၆၁	၃၀
၆	ဓာတုနည်းဖြင့် ဖြိုခွဲရန် အောက်စီဂျင် လိုအပ်ချက် (COD (Cr))	mg/L	၁၂.၈	၄၁	၅.၆	၁၂၅
၇	နိုက်ယရိုဂျင်စုစုပေါင်း (Total Nitrogen)	mg/L	၁.၀	၁.၆	၁.၉	၈၀
၈	ဖော့စဖောရက်စုစုပေါင်း (Total Phosphorus)	mg/L	-	-	-	၂



သီလဝါအတွင်းပွားရေစန့်အပိုင်း(ခ)ရှိစက်မှုစန့်ဖွံ့ဖြိုးတိုးတက်မှုအတွက်ရေအရည်အသွေးစောင့်ကြည့်လေ့လာမှုအစီရင်ခံစာ
(နှစ်လတာကြိမ်၊ စောင့်ကြည့်လေ့လာခြင်း၊ အောက်တိုဘာလ ၂၀၂၁ ခုနှစ်)

စဉ်	ရေအရည်အသွေး အမျိုးအစားများ (Parameters)	ယူနစ်	မြေပေါ်ရေ စန့်စက်ယူသည့် နေရာ-၂ (SW-2)	မြေပေါ်ရေ စန့်စက်ယူသည့် နေရာ-၄ (SW-4)	မြေပေါ်ရေ စန့်စက်ယူသည့် နေရာ-၇ (SW-7)	ရည်မှန်းတန်ဖိုး (ကိတ်ယိုနိုင် စောင့်ကြည့်လေ့လာ ခြင်းအတွက် ရည်ညွှန်းတန်ဖိုး)
၉	အရောင် (Color)	TCU (True Color Unit)	၁၀.၇၇	၃.၂၃	၂.၇၉	၁၅၀
၁၈	အနံ့ (Odor)	TON (Threshold Odor Number)	၁	၁	၁	-
၁၀	ကိုလီဖောင်း စုစုပေါင်း (Total Coliform)	MPN/100ml	၁၆၀၀၀၀	၁၆၀၀၀၀.၀	၁၆၀၀၀၀	၄၀၀
၁၂	ဆီနှင့် အမဲဆီ (Oil and Grease)	mg/L	< ၃.၁	< ၃.၁	< ၃.၁	၁၀
၁၃	ပျော်ဝင်အနည်စုစုပေါင်း (Total Dissolved Solids)	mg/L	၁၁၈	၁၈၂	၁၇၄	၂၀၀၀
၁၄	သံမဏိ (Iron)	mg/L	၃.၈၄၀	၁၂၆၂၈	၀.၅၄၀	၃.၅
၁၅	မြွေးဆန် (Mercury)	mg/L	၁၀.၀၀၂	၁၀.၀၀၂	၁၀.၀၀၂	၀.၀၀၅
၁၆	လမ်းကိုက်ရောဂါကိုဖြစ်စေ သော ကိုလီဖောင်းဘက်တီးရီးယား (Escherichia Coli)	MPN/100ml	-	-	၄.၀	(၁၀၀၀)* (CFU/၁၀၀ml)
၁၇	စီးဆင်းနှုန်း (Flow Rate)	m ³ /s	၀.၃၆	၀.၇၁	၀.၁၃	-

မှတ်ချက်-အနီရောင်ဖြင့်ဖော်ပြထားသောတန်ဖိုးများသည်သတ်မှတ်ထားသည့်တန်ဖိုးများထက်ကျော်လွန်နေသည်ကိုဆိုလိုပါသည်။

စောင့်ကြည့်လေ့လာသည့် အချိန်အတွင်း မော့စမော့ရက်စုစုပေါင်း (T-P)အား ဓာတ်ခွဲခန်း၌ စမ်းသပ်၍ ဖော်ပြပါ။

*မှတ်ချက်- စန့်ထုတ်ရေများ စန့်ထုတ်လိုက်သောချောင်း၏ အသုံးပြုမှုပေါ်မူတည်၍ ၅ပန်နီငင်စက် ချိုးရေခံချိန်ခံညွှန်း (ပတ်ဝန်းကျင်ဆိုင်ရာဝန်ကြီးဌာန၊ ၁၉၉၇)ကို ဖော်ပြချက်ရောဂါကိုဖြစ်စေသော ကိုလီဖောင်းဘက်တီးရီးယား (E. coli) ၏ ရည်မှန်းတန်ဖိုးအဖြစ်သတ်မှတ်ထားပါသည်။ သို့သော်လည်း မြန်မာနိုင်ငံရှိ ဓာတ်ခွဲခန်းများ၏ လုပ်ဆောင်နိုင်မှု စန့်ထုတ်ချက်များကြောင့် စီအက်မ်ယူတန်ဖိုး "Colony Forming Unit (CFU)" အား တိုင်းတာ၍မရပါ။ ထို့ကြောင့် အမ်ပီအန် "Most Probable Number (MPN)" ရလဒ်များကို စီအက်မ်ယူတန်ဖိုးနှင့် တွည့်သည်ဟုယူဆပြီး ရည်မှန်းတန်ဖိုးနှင့် နှိုင်းယှဉ်ပါသည်။ မြန်မာနိုင်ငံတွင် စီအက်မ်ယူတန်ဖိုးဆိုသည့် သုံးသပ်နိုင်သည့်နှင့် တစ်ပြိုင်နက် သုံးသပ်သည့်နည်းလမ်းများ မပြောင်းလဲမည်ဖြစ်ပါသည်။

မှတ်ချက်- မြန်မာနိုင်ငံအင်တာနေရှင်နယ်လီမီကက်



၂.၅.၂ ရည်ညွှန်းရေတွင်း၏ ရလဒ်

ရည်ညွှန်းရေတွင်းစောင့်ကြည့်လေ့လာသောနေရာ၌ ရေအရည်အသွေးစောင့်ကြည့်လေ့လာမှုရလဒ်များကို ဇယား ၂.၅-၂ တွင်ဖော်ပြထားပါသည်။ ရည်မှန်းတန်ဖိုးနှင့်နှိုင်းယှဉ်ရာတွင် သံဓာတ်တန်ဖိုးသည် ရည်မှန်းတန်ဖိုးထက် ကျော်လွန်နေကြောင်းတွေ့ရသည်။

သံဓာတ်ရလဒ်အရ မြေအောက်ရေနမူနာယူသည့် နေရာ-၂ (GW-2) သည် ရည်မှန်းတန်ဖိုးထက် အနည်းငယ် ကျော်လွန်နေပါသည်။ မြေအောက်ရေနမူနာယူသည့် နေရာ-၂ (GW-2) ၏ ယခင် စောင့်ကြည့်လေ့လာမှုရလဒ်များ နှိုင်းယှဉ်သောအခါတွင် သံဓာတ်ရလဒ်များသည် ၃.၀၇၆ မီလီဂရမ်/လီတာ (ဩဂုတ်လ၊ ၂၀၁၉ခုနှစ်) မှ ၈.၃၁၀ မီလီဂရမ်/လီတာ (အောက်တိုဘာလ၊ ၂၀၂၁ခုနှစ်) အတွင်းရှိပါသည်။ ဩဂုတ်လ၊ ၂၀၁၉ခုနှစ်၏ သံဓာတ်ပါဝင်မှုရလဒ်မှတစ်ပါး သံဓာတ်ပါဝင်မှုရလဒ် အများစု (ဧပြီလ၊ ၂၀၁၉ခုနှစ် မှ အောက်တိုဘာလ၊ ၂၀၂၁ခုနှစ်အထိ)သည် ရည်မှန်းတန်ဖိုးထက် ကျော်လွန်နေကြောင်း တွေ့ရသည်။ ထို့ကြောင့် ဖြစ်နိုင်ချေရှိသော အကြောင်းအရာများမှာ သဘာဝမြေဆီလွှာမှ သံဓာတ် အရင်းအမြစ် လွှမ်းမိုးမှု (သံဓာတ်သည်ရေစီးဆင်းမှုကြောင့် မြေဆီလွှာအတွင်းမှ ထွက်လာနိုင်ပါသည်) ကြောင့်ဖြစ်နိုင်ပါသည်။ ရန်ကုန်မြို့ ၏မြေဆီလွှာသည် သဘာဝအားဖြင့် သံဓာတ်ကြွယ်ဝပါသည်။

ဇယား ၂.၅-၂ ရည်ညွှန်းရေတွင်း၏ ရေအရည်အသွေးစောင့်ကြည့်တန်ဖိုးရလဒ်

စဉ်	ရေအရည်အသွေး အမျိုးအစားများ (Parameters)	ယူနစ်	မြေအောက်ရေ ရလဒ် (ယူနစ်) (GW-2)	ရည်မှန်းတန်ဖိုး (လီမစ်တိုင် စောင့်ကြည့်လေ့လာ ခြင်းအတွက် ရည်ညွှန်းတန်ဖိုး)
၁	ရေအပူချိန် (water temperature)	°C	၂၆	≤ ၃၅
၂	ရေဗေဒနီတန်ဖိုး (pH)	-	၇.၀	၆ - ၉
၃	ဆိပ်ကြွအနယ် (suspended solid)	mg/L	၁၀	၅၀
၄	ပျော်ဝင်အောက်စီဂျင် (Dissolved Oxygen)	mg/L	၅.၆၉	-
၅	စီဝနည်းဖြင့်ဖြိုခွဲရန် အောက်စီဂျင် လိုအပ်ချက် (၅-ဂရမ်) (BOD ₅)	mg/L	၄.၅၉	၃၀
၆	ဓာတုနည်းဖြင့် ဖြိုခွဲရန် အောက်စီဂျင် လိုအပ်ချက် (COD _{Cr})	mg/L	၁၈.၈	၁၂၅
၇	နိုက်ယရိုဂျင်စုစုပေါင်း (Total Nitrogen)	mg/L	၂.၈	၈၀
၈	ဖော့စဖောရပ်စ်စုစုပေါင်း (Total Phosphorus)	mg/L	-	၂
၉	အရောင် (Color)	TCU (True Color Unit)	၅၈.၇၄	၁၅၀
၁၀	အနံ့ (Odor)	TON (Threshold Odor Number)	၁	-



သီလဝါအတွင်းစီးပွားရေးဇုန်အပိုင်း(ခ)စိုက်ပျိုးမှုနှင့်မြို့တိုးတက်မှုအတွက်ရေအရည်အသွေးစောင့်ကြည့်လေ့လာမှုအစီရင်ခံစာ
(နှစ်လတစ်ကြိမ်၊ စောင့်ကြည့်လေ့လာခြင်း၊ အောက်တိုဘာလ ၂၀၂၁ ခုနှစ်)

စဉ်	ရေအရည်အသွေး အမျိုးအစားများ (Parameters)	ယူနစ်	မြေအောက်ရေ နမူနာယူသည့် နေရာ-၂ (GW-2)	ရည်မှန်းတန်ဖိုး (ကိုယ်တိုင် စောင့်ကြည့်လေ့လာ ခြင်းအတွက် ရည်ညွှန်းတန်ဖိုး)
၁၁	ကိုလီဖောင်းစုစုပေါင်း (Total Coliform)	MPN/ 100ml	၇၉.၈	၄၀၀
၁၂	ဆီနှင့် အမဲဆီ (Oil and Grease)	mg/L	< ၃.၁	၁၀
၁၃	ပျော်ဝင်အနည်စုစုပေါင်း (Total Dissolved Solids)	mg/L	၁၈၀	၂၀၀၀
၁၄	သံမဏိ (Iron)	mg/L	၈.၃၁၀	၃.၅
၁၅	ပြွန်စာတ် (Mercury)	mg/L	< ၀.၀၀၂	၀.၀၀၅
၁၆	ဝမ်းကိုက်ရောဂါကိုဖြစ်စေသော ကိုလီဖောင်းဘက်တီးရီးယား (Escherichia Coli)	MPN/100ml	< ၁.၈	(၁၀၀)** (MPN/100ml)
၁၇	စီးဝင်းနှုန်း (Flow Rate)	m ³ /s	-	-

မှတ်ချက်: အနီရောင်ဖြင့်ဖော်ပြထားသောတန်ဖိုးများသည်သတ်မှတ်ထားသည့်တန်ဖိုးများထက်ကျော်လွန်နေသည်ကိုဆိုလိုပါသည်။

စောင့်ကြည့်လေ့လာသည့်အဖွဲ့၏ အတွင်း မေ့စရာစာရင်းစုစုပေါင်း (T-P)အား စာတန်းခန့်မှန်း စစ်သပ်၍ မရနိုင်ပါ။

*မှတ်ချက်: မြေအောက်ရေစောင့်ကြည့်လေ့လာသောနေရာတွင် ရေအသုံးပြုမှုပေါ်မူတည်၍ ဝိယာနမီနိုင်းရှိ မြေအောက်ရေအရည်အသွေးဆိုင်ရာ အမျိုးသားနည်းလမ်းစည်းမျဉ်းဥပဒေ ၈၁(မူရင်းပြောင်းမူ) (No. ၇၄/VIII; 2005/8TRMT) ကိုမြေအောက်ရေကိုယ်တိုင် စောင့်ကြည့်လေ့လာခြင်းအတွက် ရည်မှန်းတန်ဖိုးအဖြစ်သတ်မှတ်ပါသည်။

မူရင်း ပြန်မာစာအုပ်အင်တာနေရှင်နယ်လီမီတက်



အခန်း ၃ နိဂုံးချုပ် နှင့် အကြံပြုချက်များ

အခန်း ၂ (အပိုင်း ၂.၅) တွင်ဖော်ပြထားသကဲ့သို့ သီလဝါအထူးစီးပွားရေးဇုန်အပိုင်း(ခ) လုပ်ငန်းလည်ပတ်နေစဉ် ကာလ စောင့်ကြည့်လေ့လာသောအချိန်အတွင်း မြေပေါ်ရေနမူနာယူသည့် နေရာ-၄ (SW-4) နှင့် မြေပေါ်ရေနမူနာယူသည့် နေရာ-၇ (SW-7) တို့တွင် ဆိုင်းကြွအနယ်၊ မြေပေါ်ရေနမူနာယူသည့် နေရာ-၂ (SW-2)၊ မြေပေါ်ရေနမူနာယူသည့် နေရာ-၄ (SW-4) နှင့် မြေပေါ်ရေနမူနာယူသည့် နေရာ-၇ (SW-7) တို့တွင် ကိုလီဖောင်းစုစုပေါင်း၊ မြေအောက်ရေနမူနာယူသည့် နေရာ-၂ (GW-2) တွင် သံဓာတ်တို့သည် ရည်မှန်းတန်ဖိုးထက် ကျော်လွန်နေပါသည်။

ဆိုင်းကြွအနည်ရလဒ် နှင့် ကိုလီဖောင်းစုစုပေါင်းရလဒ် အနေဖြင့် ချောင်းတွင်းသို့မစွန့်ထုတ်ခင် ဇုန်အပိုင်း(ခ)၏ အဓိကစွန့်ထုတ်ရေထွက်ပေါက် ဖြစ်သော မြေပေါ်ရေနမူနာယူသည့် နေရာ-၇ (SW-7) ရှိ ရလဒ်များသည် ရည်မှန်းတန်ဖိုးထက် ကျော်လွန်နေခြင်းမှာ ဇုန်အပိုင်း(ခ)ရှိ မြေလွတ်များမှ မြေမျက်နှာပြင် စီးဆင်းရေများ ကြောင့် ဖြစ်နိုင်ပါသည်။

ကိုလီဖောင်းစုစုပေါင်း ရလဒ်အနေဖြင့် ချောင်းတွင်းသို့ မစွန့်ထုတ်ခင် ဇုန်အပိုင်း(ခ)၏ အဓိကစွန့်ထုတ်ရေထွက်ပေါက် ဖြစ်သော မြေပေါ်ရေနမူနာယူသည့် နေရာ-၇ (SW-7) ရှိ ရလဒ်များမှာ ရည်မှန်းတန်ဖိုးထက် ကျော်လွန်နေကြောင်း တွေ့ရှိရပါသည်။ ဖြစ်နိုင်ချေ အလားအလာရှိသည့် အကြောင်းရင်းများမှာ ရေထိန်းကန် အတွင်းနှင့် အပြင်တလျှောက်တွင် အပင်များနှင့်ငှက်များ၊ တိရစ္ဆာန်ငယ်များ ကျင်လည်ကျက်စားခြင်းကြောင့် ဇုန်အပိုင်း(ခ)၏ ဧရိယာတွင် သဘာဝအလျှောက် ဘက်တီးရီးယားများ ရှိနေသောကြောင့် ဖြစ်နိုင်ပါသည်။ ဤဝမ်းကိုက်ရောဂါကိုဖြစ်စေသော ကိုလီဖောင်းဘက်တီးရီးယား(E Coli)ရလဒ်အရ မြေပေါ်ရေနမူနာယူသည့် နေရာ-၇ (SW-7) ၏ တန်ဖိုးသည် ရည်မှန်းတန်ဖိုးအောက် နည်းပါးကြောင်းတွေ့ရှိရပါသည်။ ထို့ကြောင့် မြေပေါ်ရေနမူနာယူသည့်နေရာ-၇ (SW-7) တွင် ကိုလီဖောင်းစုစုပေါင်းသည် ရည်မှန်းတန်ဖိုးထက် များနေသော်လည်း လူ၏ကျန်းမာရေးကို သိသာထင်ရှားစွာ သက်ရောက်မှုမရှိနိုင်ကြောင်း သတ်မှတ်နိုင်ပါသည်။

ဆိုင်းကြွအနည်များ၏ ရလဒ်များအရ မြေပေါ်ရေနမူနာယူသည့် နေရာ-၄ (SW-4) တို့ရှိ ရလဒ်များသည် ရည်မှန်းတန်ဖိုးထက် ကျော်လွန်နေပါသည်။ ဆိုင်းကြွအနည်များ၏ ရလဒ်များသည် ရည်မှန်းတန်ဖိုးထက် ကျော်လွန်နေခြင်းမှာ (၁) သဘာဝအလျှောက် ချောင်းအထက်ပိုင်းမှ စီးဆင်းလာခြင်းနှင့် သီလဝါအထူးစီးပွားရေးဇုန် ပြင်ပရှိ ပြည်တွင်းစက်မှုဇုန်မှ စွန့်ထုတ်လိုက်သော ရေများကြောင့်လည်းကောင်း၊ (၂)ချောင်းအောက်ဘက်ရှိ ရေများသည် ဒီရေအတက်အကျကြောင့် အထက်သို့ ပြန်လည်စီးဆင်းလာခြင်းကြောင့်လည်းကောင်း ဖြစ်နိုင်ပါသည်။

ကိုလီဖောင်းစုစုပေါင်းရလဒ်အနေဖြင့် (မြေပေါ်ရေနမူနာယူသည့် နေရာ-၂ (SW-2) နှင့် မြေပေါ်ရေနမူနာယူသည့် နေရာ-၄ (SW-4)) တို့ရှိ ရလဒ်များသည် ရည်မှန်းတန်ဖိုးထက် ကျော်လွန်နေခြင်းမှာ (၁)စွန့်ထုတ်ရေရောက်ရှိရာ ချောင်းအတွင်းနှင့် အနီးတစ်ဝိုက်တွင် ရှိနေသော အပင်အမျိုးမျိုးနှင့် သက်ရှိသတ္တဝါများဖြစ်သော ငှက်များနှင့်တိရစ္ဆာန်များကြောင့် သဘာဝ ဘက်တီးရီးယားများသည် စွန့်ထုတ်ရေရောက်ရှိရာ ချောင်းအတွင်းတွင် တည်ရှိနေခြင်းကြောင့်လည်းကောင်း



- (၂)သီလဝါအထူးစီးပွားရေးဇုန် ပြင်ပရှိ ပြည်တွင်းစက်မှုဇုန်မှ စွန့်ထုတ်ရေများကြောင့်လည်းကောင်း၊
(၃)အနီးပတ်ဝန်းကျင်မှ ဒီရေသက်ရောက်မှုကြောင့်လည်းကောင်း ဖြစ်နိုင်ပါသည်။

သံဓာတ်ရလဒ်အနေဖြင့် (မြေပေါ်ရေနမူနာယူသည့်နေရာ-၂ (SW-2) နှင့် မြေပေါ်ရေနမူနာယူသည့်နေရာ-၄ (SW-4)) တို့ရှိ ရလဒ်သည် ရည်မှန်းတန်ဖိုးထက် ကျော်လွန်နေကြောင်း တွေ့ရှိရပါသည်။
ဖြစ်နိုင်သောအကြောင်းအရာများမှာ သဘာဝ သံဓာတ် အရင်းအမြစ်၏ လွှမ်းမိုးမှု ကြောင့် ဖြစ်နိုင်ပါသည်
(သံဓာတ်သည်ရေစီးဆင်းမှုကြောင့် မြေဆီလွှာအတွင်းမှ ထွက်လာနိုင်ပါသည်)။ ရန်ကုန်မြို့၏ မြေဆီလွှာသည်
သဘာဝအားဖြင့်သံဓာတ် ကြွယ်ဝပါသည်။

သံဓာတ်ရလဒ်အရ မြေအောက်ရေနမူနာယူသည့် နေရာ-၂ (GW-2) သည် ရည်မှန်းတန်ဖိုးထက် အနည်းငယ်
ကျော်လွန်နေပါသည်။ မြေအောက်ရေနမူနာယူသည့် နေရာ-၂ (GW-2) ၏ ယခင်
စောင့်ကြည့်လေ့လာမှုရလဒ်များ နှိုင်းယှဉ်သောအခါတွင် သံဓာတ်ရလဒ်များသည် ၃.၀၇၆ မီလီဂရမ်/လီတာ
(ဩဂုတ်လ၊ ၂၀၁၉ခုနှစ်) မှ ၈.၃၁၀ မီလီဂရမ်/လီတာ (အောက်တိုဘာလ၊ ၂၀၂၁ခုနှစ်) အတွင်းရှိပါသည်။
ဩဂုတ်လ၊ ၂၀၁၉ခုနှစ်၏သံဓာတ်ပါဝင်မှုရလဒ်မှတစ်ဆင့်သံဓာတ်ပါဝင်မှုရလဒ် အများစု (ဧပြီလ၊ ၂၀၁၉ခုနှစ်
မှ အောက်တိုဘာလ၊ ၂၀၂၁ခုနှစ်အထိ)သည် ရည်မှန်းတန်ဖိုးထက် ကျော်လွန်နေကြောင်း တွေ့ရသည်။
ထို့ကြောင့် ဖြစ်နိုင်ချေရှိသော အကြောင်းအရာများမှာ သဘာဝမြေဆီလွှာမှ သံဓာတ် အရင်းအမြစ် လွှမ်းမိုးမှု
(သံဓာတ်သည်ရေစီးဆင်းမှုကြောင့် မြေဆီလွှာအတွင်းမှ ထွက်လာနိုင်ပါသည်) ကြောင့်ဖြစ်နိုင်ပါသည်။
ရန်ကုန်မြို့ ၏မြေဆီလွှာသည် သဘာဝအားဖြင့် သံဓာတ်ကြွယ်ဝပါသည်။

အနာဂတ်တွင် သီလဝါအထူးစီးပွားရေးဇုန် အပိုင်း (ခ) ၏ အဓိကစွန့်ထုတ်ရေ ထွက်ရှိသောနေရာများမှ
ထွက်ရှိလာသော ရေအရည်အသွေးများဖြစ်သည့် ဆိုင်းကြာအနည်များ၊ ကိုလီဖောင်းစုစုပေါင်း တို့၏
သင့်တော်သော ရည်မှန်းအဆင့်ရှိနိုင်ရန် အောက်ပါဆောက်လုပ်ချက်များကိုလုပ်ဆောင်သင့်ပါသည်။

- ကိုလီဖောင်းဘက်တီးရီးယားများ၏ ကျွန်းမာရေးအပေါ်သက်ရောက်မှုကို သိရှိနိုင်ရန် ဝမ်းကိုက်ရောဂါကို
ဖြစ်စေသော ကိုလီဖောင်းဘက်တီးရီးယား (E Coli) ကို ဆက်လက်စောင့်ကြည့်ရန်။
- ဆောက်လုပ်ရေးလုပ်ငန်းများမှရေများစီးဆင်းမှု အခြေအနေ ကိုစောင့်ကြည့်လေ့လာရန် နှင့်
- ဆောက်လုပ်ရေးလုပ်ငန်းများမှအထွေထွေသုံးစွန့်ထုတ်ရေများ၏ အခြေအနေ ကိုစောင့်ကြည့်လေ့လာရန်။

ဤတွင်စာတမ်းပြီးဆုံးပါသည်။



နောက်ဆက်တွဲ ၁ ရေနမူနာရယူသည့် မှတ်တမ်းဓာတ်ပုံများ



သီလဝါအထူးစီးပွားရေးဇုန်အပိုင်း(ခ)ရိုက်မှုနဲ့ဖွံ့ဖြိုးတိုးတက်မှုအတွက်ရောရည်အသွေးစောင့်ကြည့်လေ့လာမှုဒီရင်္ဂင်ခံစာ
(နှစ်လတာခံကြိုမီ၊ စောင့်ကြည့်လေ့လာခြင်း၊ အောက်တိုဘာလ ၂၀၂၁ ခုနှစ်)

သီလဝါအထူးစီးပွားရေးဇုန် အပိုင်း (ခ) ရို ဇွန်ထုတ်ရေကမ္ဘာရယူသည့်နေရာ



မြေပေါ်ရေကမ္ဘာရယူသည့် နေရာ-၇ (SW-7) ၌ ရေကမ္ဘာရယူခြင်းနှင့်တိုင်းတာခြင်း



စွန့်ထုတ်ရေထွက်ရှိသောနေရာများနှင့် စွန့်ထုတ်ရေရောက်ရှိနိုင်သည့်ချောင်း၏ အခြေခံအချက်အလက်များကို နှိုင်းယှဉ်ရန်အတွက် ရည်ညွှန်းစောင့်ကြည့်လေ့လာသည့် နေရာများ



မြေပေါ်ရေနမူနာယူသည့် နေရာ-၂ (SW-2) ၌ ရေနမူနာရယူခြင်းနှင့်တိုင်းတာခြင်း



မြေပေါ်ရေနမူနာယူသည့် နေရာ-၄ (SW-4) ၌ ရေနမူနာရယူခြင်းနှင့်တိုင်းတာခြင်း



မြေအောက်ရေနမူနာယူသည့် နေရာ-၂ (GW-2) ရေနမူနာရယူခြင်းနှင့်တိုင်းတာခြင်း

နောက်ဆက်တွဲ ၂ ဓာတ်ခွဲခန်းရလဒ်များ



စွန့်ထုတ်ရေထွက်ရှိရာနေရာ

POWER

Journal of Management Education 32(10) 1079-1094
© 2008 Sage Publications
10.1177/1053426908318811
jme.sagepub.com



REPORT NO. - GEP-LAB-2021-062

[illegible]

Report Date : 29 October : 2023

Application No. 0403-12441

Analysis Report

Client Name	Wynntek Resources International LTD (Pvt)		
Address	No. 32/A, 1st Floor, Grand Pricemart Commercial, Pricemart Road, Tarnagudi, Tarnagudi, Wynntek		
Project Name	Environmental Monitoring report for Zone A & B		
Sample Description			
Sample Name	WRI-QW-7-10016	Sampling Date	6 October, 2001
Sample No.	W-2110027	Sampling By	Customer
Waste Profile No.		Sample Received Date	6 October, 2001

No.	Parameter	Method	Unit	Result	Log
1	SS	APHA 2540D (Dry at 103-105°C Method)	mg/l	170	-
2	BOD (5)	APHA 521B-B (5 Days-BOD Test)	mg/l	4.80	0.04
3	COD (Cr)	APHA 5220C (Close Reflux Colorimetric Method)	mg/l	5.6	0.7
4	Total Coliform	APHA 9221B (Standards Total Coliform Fermentation Technique)	MPN/100ml	160000	1.8
5	Oil and Grease	APHA 5520B (Petroleum Grease Method)	mg/l	< 3.1	3.3
6	Total Nitrogen	HACH Method 10072 (NIT Persulfate Digestion Method)	mg/l	1.9	0.5
7	Calc	APHA 2320C (Spectrophotometric Method)	TCU	1.79	0.26
8	Odor	APHA 2150-B (Threshold Odor Test)	TDN	1	0
9	TDS	APHA 2540-C (Total Dissolved Solids Dried at 180°C Method)	mg/l	174	-
10	Mercury	APHA 3120-B (Inductively Coupled Plasma (ICP) Method)	mg/l	< 0.002	0.002
11	Chromium	APHA 3120-B (Inductively Coupled Plasma (ICP) Method)	mg/l	< 0.002	0.002
12	Iron	APHA 3120-B (Inductively Coupled Plasma (ICP) Method)	mg/l	0.340	0.002
13	Extensive Col	APHA 9221-P Escherichia Coli Procedure Using Fluorogenic Substrate	MPN/100ml	4.0	1.8

Abbreviations: LOD = Limit of Quantitation
 APHA = American Public Health Association (APHA), the American Water Works Association (AWWA), and the Water Environment Federation (WEF), Standard Methods for the Examination of Water and Wastewater, 22nd edition

Assigned to
28 10 23
Cherry Point Ther
Supervisor



Approved By

To: To: Asst. Mgr. Q1 98, 90-27
Assistant Manager

သီလဝါအထူးစီးပွားရေးဇုန်အပိုင်း(ခ)ရှိစက်မှုဇုန်နှင့်မြို့တိုးတက်မှုအတွက်ရေအရည်အသွေးစောင့်ကြည့်လေ့လာမှုအစီရင်ခံစာ
(နှစ်လတစ်ကြိမ်၊ စောင့်ကြည့်လေ့လာခြင်း၊ အောက်တိုဘာလ ၂၀၂၁ ခုနှစ်)

**စွန့်ထုတ်ရေထွက်ရှိသောနေရာများနှင့် စွန့်ထုတ်ရေရောက်ရှိနိုင်သည့်ချောင်း၏
အခြေခံအချက်အလက်များကို နှိုင်းယှဉ်ရန်အတွက် ရည်ညွှန်းစောင့်ကြည့်လေ့လာသည့် နေရာများ**

DOWA

Water and Environmental Engineering Co., Ltd.
Unit 101, Tower 1, Green A, Pong Seng, Myanmar
Address: No. 101, Tower 1, Green A, Pong Seng, Myanmar




Report No.: GEM-LAB-202110019
Revised No.: 2
Report Date: 28 October, 2021
Application No.: 0801 (001)

Analysis Report


Client Name: Myanmar Rail International Ltd (MRI)
Address: No. 36/A, 1st Floor, Strand Poo Seng Condominium, Poo Seng Road, Tathar Township, Yangon, Myanmar
Project Name: Environmental Monitoring report for Zone A & B
Sample Description:
Sample Name: PK1-SW-2-1006
Sample No: W-2110019
Waste Profile No:
Sampling Date: 6 October, 2021
Sampling By: Customer
Sample Received Date: 6 October, 2021

No.	Parameter	Method	Unit	Result	LOQ
1	SS	APHA 2540D (Dry at 103-105°C Method)	mg/l	50	—
2	BOD (1)	APHA 5210 B (5 Days BOD Test)	mg/l	11.45	0.01
3	COD (1)	APHA 5220D (Open Reflux Colorimetric Method)	mg/l	12.8	0.7
4	Total Coliform	APHA 9221B (Standard Total Coliform Fermentation Technique)	MPN/100ml	> 580000	1.8
5	Oil and Grease	APHA 5520B (Petroleum Gravimetric Method)	mg/l	< 3.3	3.3
6	Total Nitrogen	HACH Method (1072) (TWT Persulfate Digestion Method)	mg/l	1.0	0.5
7	Color	APHA 2120C (Spectrophotometric Method)	PCU	15.77	0.01
8	Odor	APHA 2131 B (Threshold Odor Test)	TCU	1	0
9	TSS	APHA 2545 C (Total Dissolved Solids (Dried at 180°C Method)	mg/l	118	—
10	Mercury	APHA 2120 B (Inductively Coupled Plasma (ICP) Method)	mg/l	< 0.002	0.002
11	Chromium	APHA 2120 B (Inductively Coupled Plasma (ICP) Method)	mg/l	< 0.002	0.002
12	Cadmium	APHA 2120 B (Inductively Coupled Plasma (ICP) Method)	mg/l	3.840	0.002

Remark: LOQ - Limit of Quantitation
APHA - American Public Health Association (APHA), the American Water Works Association (AWWA), and the Water Environment Federation (WEF), Standard Methods for the Examination of Water and Wastewater, 22nd edition

Analyzed By:

Cherry Hsiao
Supervisor



Approved By:

N. N. Aye
Assistant Manager



သီလဝါးထူးစီးပွားရေးနှင့်ဆိုင်ရာ (ခ) ကိုဗစ်ဗိုင်းကုန်သွယ်ရေးတိုးတက်ရေးအဖွဲ့ကြည့်ရှုရေးလမ်းညွှန်အစီရင်ခံစာ
(နှစ်လစာစီကြိုက် စောင့်ကြည့်ရှုလေ့လာခြင်း၊ ဆောက်တိုတာလ် ၂၀၂၁ ခုနှစ်)

DOWA

OSCEM DOWA Laboratory (Pvt) Ltd
10th Floor, 10th Floor, 10th Floor, 10th Floor
10th Floor, 10th Floor, 10th Floor, 10th Floor



Report No: OSM LAB 2021/0000
Revision No: 1
Report Date: 18 October, 2021
Applicant No: OSM-0001

Analysis Report

Client Name: Myanmar Kay International LTD (MKI)
Address: No. 35/A, 1st Floor, Grand Pina Spin Condominium, Pina Spin Road, Tanaka Township, Yangon, Myanmar
Project Name: Environmental Monitoring report for Zone A & B
Sample Description:
Sample Name: MKI Day 4 (2018)
Sample No: W-2110025
Sample Profile No: -
Sampling Date: 8 October, 2021
Sampling By: Customer
Sample Received Date: 8 October, 2021

No.	Parameter	Method	Unit	Result	LOQ
1	SS	APHA 2540D (Dry at 103-105°C Method)	mg/L	311	-
2	BOD (5)	APHA 5210 B (5 Days BOD Test)	mg/L	1.58	0.00
3	COD (Cr)	APHA 5210D (Closed Reflux Colorimetric Method)	mg/L	4.1	0.3
4	Total Calcium	APHA 9218 (Standard Total Calcium Determination Technique)	mg/L (20m)	162000.0	1.8
5	Oil and Grease	APHA 5520A (Partition-Gravimetric Method)	mg/L	4.5.1	2.1
6	Total Nitrogen	HRCH Method 10012 (TNB Persulfate Digestion Method)	mg/L	1.8	0.5
7	Copper	APHA 2120C (Spectrophotometric Method)	TCU	3.23	0.20
8	DOO	APHA 2120 B (Thimochol Oden Test)	TDO	1	0
9	TDS	APHA 2540 C (Total Dissolved Solids Dried at 180°C Method)	mg/L	182	-
10	Mercury	APHA 3120 B (Inductively Coupled Plasma (ICP) Method)	mg/L	5.0.002	0.002
11	Chromium	APHA 3120 B (Inductively Coupled Plasma (ICP) Method)	mg/L	5.0.002	0.002
12	Iron	APHA 3120 B (Inductively Coupled Plasma (ICP) Method)	mg/L	13.628	0.002

Remark: LOQ - Limit of Quantization

APHA - American Public Health Association (APHA), the American Water Works Association (AWWA), and the Water Environment Federation (WEF). Standard Methods for the Examination of Water and Wastewater, 22nd edition

Analyzed By:

Cherrin Myint Thinn
Supervisor



Approved By:

Aye Aye Win
Assistant Manager



သီလဝါအထူးစီးပွားရေးဇုန် အပိုင်း(ခ)ရှိ
စက်မှုဇုန်ဖွံ့ဖြိုးတိုးတက်ရေးအတွက်
ရေအရည်အသွေးစောင့်ကြည့်လေ့လာခြင်းအစီရင်ခံစာ
(လုပ်ငန်းလည်ပတ်နေစဉ်ကာလ အပိုင်း ၁၊ အပိုင်း ၂ နှင့် အပိုင်း ၃)

(တစ်နှစ်နှစ်ကြိမ် စောင့်ကြည့်လေ့လာခြင်း)

၂၀၂၁ ခုနှစ်၊ ဒီဇင်ဘာလ

မြန်မာ့အံ့အင်တာနေရှင်နယ်လီမိတက်



မာတိကာ

အခန်း ၁ နိဒါန်း	၁
၁.၁ ယေဘုယျ ဖော်ပြချက်	၁
အခန်း ၂ ရေအရည်အသွေးစောင့်ကြည့်လေ့လာခြင်း	၃
၂.၁ စောင့်ကြည့်လေ့လာသည့်အမျိုးအစား	၃
၂.၂ ရေနမူနာရယူသည့်နေရာများ၏တည်နေရာနှင့်အချက်အလက်များဖော်ပြချက်	၅
၂.၃ စောင့်ကြည့်လေ့လာသည့်နည်းလမ်း	၇
၂.၄ စောင့်ကြည့်လေ့လာသည့်ကာလ	၉
၂.၅ စောင့်ကြည့်လေ့လာမှုရလဒ်များ	၁၀
အခန်း ၃ နိဂုံးချုပ် နှင့် အကြံပြုချက်များ	၁၆
နောက်ဆက်တွဲ ၁ ရေနမူနာရယူသည့် မှတ်တမ်းဇာတ်ပုံများ	က၁-၁
နောက်ဆက်တွဲ ၂ ဇာတ်ခွဲခန်းရလဒ်များ	က၂-၁

ဇယားများစာရင်း

ဇယား ၂.၁-၁ စောင့်ကြည့်လေ့လာသည့်အမျိုးအစား	၃
ဇယား ၂.၂-၁ ရေနမူနာရယူသည့်နေရာများ	၅
ဇယား ၂.၃-၁ ရေအရည်အသွေးစစ်ဆေးသည့် နည်းလမ်းများ	၇
ဇယား ၂.၄-၁ နေရာတစ်ခုချင်းစီအတွက် နမူနာရယူသည့်အချိန်	၉
ဇယား ၂.၄-၂ မြန်မာနိုင်ငံ၊ ရန်ကုန်မြစ်၏ ဒီရေမှတ်တမ်း	၉
ဇယား ၂.၅-၁ စွန့်ထုတ်ရေထွက်ပေါက်နှင့်စွန့်ထုတ်ရေရောက်ရှိသော ချောင်းမှရေအရည်အသွေး စောင့်ကြည့်လေ့လာမှုရလဒ်များ	၁၁
ဇယား ၂.၅-၂ ရည်ညွှန်းရေတွင်း၏ ရေအရည်အသွေးစောင့်ကြည့်ကန်ဖိုးရလဒ်	၁၄

ပုံများစာရင်း

ပုံ ၁.၁-၁ ရေအရည်အသွေးစောင့်ကြည့်လေ့လာမှုအတွက်နမူနာရယူသောနေရာများ၏ တည်နေရာပြပုံ	၂
--	---



အခန်း ၁ နိဒါန်း

၁.၁ ယေဘုယျ ဖော်ပြချက်

သီလဝါအထူးစီးပွားရေးဇုန်သည် ရန်ကုန်တိုင်းဒေသကြီး၏ တောင်ပိုင်းခရိုင်တွင်တည်ရှိပြီး ရန်ကုန်မြို့၏ အရှေ့တောင်ဘက် ၂၃ ကီလိုမီတာတွင် တည်ရှိပါသည်။ သီလဝါအထူးစီးပွားရေးဇုန်၏ အကောင်အထည် ဖော်ဆောင်သူအနေဖြင့် ဇုန်အပိုင်း(ခ)အတွင်းရှိ စက်မှုမြေနေရာအတွက် ခွင့်ပြုချက်ရရှိထားသော ပတ်ဝန်းကျင်ထိခိုက်မှုဆန်းစစ်ခြင်း အစီရင်ခံစာနှင့် ပတ်ဝန်းကျင်ဆိုင်ရာစီမံခန့်ခွဲမှုအစီအစဉ်အတိုင်း ပုံမှန်စောင့်ကြည့်စစ်ဆေးခြင်းကို ဆောင်ရွက်ရန် မြန်မာ-ဂျပန် သီလဝါဖွံ့ဖြိုးရေးလီမိတက်တွင် တာဝန်ရှိပါသည်။ မြန်မာ-ဂျပန် သီလဝါဖွံ့ဖြိုးရေးလီမိတက်သည် ဇုန်အတွင်း နှင့် အနီးပတ်ဝန်းကျင်ရှိ သဘာဝပတ်ဝန်းကျင် အခြေအနေများကို သိရှိစေရန် သဘာဝပတ်ဝန်းကျင်နှင့်သက်ဆိုင်သော အချက်အလက် စောင့်ကြည့်လေ့လာမှုများကို ရေးဆွဲထားပြီး ထိုအစီအစဉ်များအရ အကောင်အထည်ဖော် ဆောင်ရွက်ခဲ့ပါသည်။

ရေအရည်အသွေးစောင့်ကြည့်လေ့လာမှုအား စစ်တမ်းကောက်ယူရာတွင် သီလဝါအထူးစီးပွားရေးဇုန်အတွင်းနှင့် အနီးပတ်ဝန်းကျင်ရှိ စုစုပေါင်းနေရာ လေးနေရာ၊ နာမည်အားဖြင့် မြေပေါ်ရေနမူနာယူသည့် နေရာ-၂ (SW-2)၊ မြေပေါ်ရေနမူနာယူသည့် နေရာ-၄ (SW-4)၊ မြေပေါ်ရေနမူနာယူသည့် နေရာ-၇ (SW-7) နှင့် မြေအောက်ရေနမူနာယူသည့် နေရာ-၂ (GW-2) တို့တွင် စောင့်ကြည့်လေ့လာခဲ့ပါသည်။ ထိုနေရာ လေးနေရာမှ မြေပေါ်ရေနမူနာယူသည့် နေရာ-၇ (SW-7) သည် ဇုန်အပိုင်း(ခ) လုပ်ငန်းလည်ပတ်နေစဉ်ကာလတွင် အဓိကစွန့်ထုတ်ရေထွက်ပေါက် ဖြစ်ပါသည်။ ထို့အပြင် မြေအောက်ရေနမူနာယူသည့် နေရာ-၂ (GW-2) အား ဖလမ်းကျေးရွာတွင်တည်ရှိသော ဘုန်းကြီးကျောင်းပရဝဏ်အတွင်းရှိ ရေတွင်းအား ရည်ညွှန်းနိုင်ရန် စောင့်ကြည့်လေ့လာခဲ့သည်။ ရေအရည်အသွေးစောင့်ကြည့်လေ့လာမှုအတွက် နမူနာရယူသော နေရာများ၏ တည်နေရာများကို ပုံ ၁.၁-၁ တွင် ဖော်ပြထားပါသည်။





မူရင်း ပုံကတ်အက်

ပုံ ၁.၁-၁ ရေအရည်အသွေးစောင့်ကြည့်လေ့လာမှုအတွက်နမူနာရယူသောနေရာများ၏ တည်နေရာပြပုံ

အခန်း ၂ ရေအရည်အသွေးစောင့်ကြည့်လေ့လာခြင်း

၂.၁ စောင့်ကြည့်လေ့လာသည့်အမျိုးအစား

ရေအရည်အသွေး စောင့်ကြည့်လေ့လာမှုအတွက် ရေနမူနာရယူသောနေရာများနှင့် ရေအရည်အသွေး အမျိုးအစားများ(Parameters)ကို ပတ်ဝန်းကျင်ထိခိုက်မှုဆန်းစစ်ခြင်းဆိုင်ရာ အစီအရင်ခံစာပါ ပတ်ဝန်းကျင်ဆိုင်ရာစောင့်ကြည့်လေ့လာမှု အစီအစဉ်အား ခြုံငုံမိစေရန်အလို့ငှာ ဆောင်ရွက်ထားပါသည်။

ရေအရည်အသွေးနမူနာစစ်တမ်းရယူမှုအား နေရာလေးနေရာတွင် ဆောင်ရွက်ခဲ့ပါသည်။ ထိုနေရာ လေးနေရာမှ ရေစီးဆင်းမှုတိုင်းတာခြင်းကို ရေစီးနှုန်းတိုင်းကိရိယာဖြင့် တိုင်းတာနိုင်သော နေရာတစ်နေရာ ဖြစ်သည့် မြေပေါ်ရေနမူနာယူသည့်နေရာ-၄ (SW-4) တို့တွင် တိုင်းတာခဲ့ပါသည်။ စောင့်ကြည့်လေ့လာသော ရေအရည်အသွေး အမျိုးအစားများ(Parameters)နှင့် ရေနမူနာရယူသောနေရာများကို ဇယား ၂.၁-၁ တွင် အကျဉ်းချုပ် ဖော်ပြထားပါသည်။

ဇယား ၂.၁-၁ စောင့်ကြည့်လေ့လာသည့်အမျိုးအစား

စဉ်	ရေအရည်အသွေး အမျိုးအစား (Parameters)	မြေပေါ်ရေ နမူနာယူသည့် နေရာ-၂ (SW-2)	မြေပေါ်ရေ နမူနာယူသည့် နေရာ-၄ (SW-4)	မြေပေါ်ရေ နမူနာယူသည့် နေရာ-၇ (SW-7)	မြေအောက် ရေနမူနာယူသည့်နေရာ-၂ (GW-2)	မှတ်ချက်
၁	ရေအပူချိန် (Water Temperature)	၀	၀	၀	၀	ရေနမူနာရယူသည့်နေရာ တွင်တိုက်ရိုက်တိုင်းတာ ခြင်း
၂	ရေဌာန်ကိန်း (pH)	၀	၀	၀	၀	ရေနမူနာရယူသည့်နေရာ တွင်တိုက်ရိုက်တိုင်းတာ ခြင်း
၃	ပျော်ဝင်အောက်စီဂျင် (DO)	၀	၀	၀	၀	ရေနမူနာရယူသည့်နေရာ တွင်တိုက်ရိုက်တိုင်းတာ ခြင်း
၄	ဒီဇင်နပ်စ်ဖြင့် ဖြိုခွဲရန် အောက်စီဂျင် လိုအပ်ချက် (၅ ရက်) (BOD ₅)	၀	၀	၀	၀	ဓာတ်ခွဲစမ်းသပ်ခြင်း
၅	ဓာတုနည်းဖြင့် ဖြိုခွဲရန် အောက်စီဂျင် လိုအပ်ချက် (COD _{Cr})	၀	၀	၀	၀	ဓာတ်ခွဲစမ်းသပ်ခြင်း
၆	နိုက်ထရိုဂျင်စုစုပေါင်း (Total Nitrogen)	၀	၀	၀	၀	ဓာတ်ခွဲစမ်းသပ်ခြင်း
၇	ဆိုင်ကြွေအနယ်များ (Suspended Solids)	၀	၀	၀	၀	ဓာတ်ခွဲစမ်းသပ်ခြင်း
၈	ကိုလီဖောင်း ဖုနပေါင်း (Total Coliform)	၀	၀	၀	၀	ဓာတ်ခွဲစမ်းသပ်ခြင်း
၉	ဖော့စဖောရက်စုစုပေါင်း (Total Phosphorus)	၀	၀	၀	၀	ဓာတ်ခွဲစမ်းသပ်ခြင်း

သီလဝါအထူးစီးပွားရေးနှင့်အပိုင်း(ခ)ရှိစက်မှုစနစ်မြို့ပြတိုးတက်မှုအတွက်ရေအရည်အသွေးစောင့်ကြည့်လေ့လာမှုအစီရင်ခံစာ
(တစ်နှစ်နှစ်ကြိမ် စောင့်ကြည့်လေ့လာခြင်း၊ ဒီဇင်ဘာလ ၂၀၂၁ ခုနှစ်)

စဉ်	ရေအရည်အသွေး အမျိုးအစား (Parameters)	မြေပေါ်ရေ နမူနာယူသည့် နေရာ-၂ (SW-2)	မြေပေါ်ရေ နမူနာယူသည့် နေရာ-၄ (SW-4)	မြေပေါ်ရေ နမူနာယူသည့် နေရာ-၇ (SW-7)	မြေအောက် ရေနမူနာယူ သည့်နေရာ-၂ (GW-2)	မှတ်ချက်
၁၀	အရောင် (Color)	၀	၀	၀	၀	ဓာတ်ခွဲစမ်းသပ်ခြင်း
၁၁	အနံ့ (Odor)	၀	၀	၀	၀	ဓာတ်ခွဲစမ်းသပ်ခြင်း
၁၂	သွပ် (Zinc)	၀	၀	၀	၀	ဓာတ်ခွဲစမ်းသပ်ခြင်း
၁၃	အာဆီနစ် (Arsenic)	၀	၀	၀	၀	ဓာတ်ခွဲစမ်းသပ်ခြင်း
၁၄	ခရိုမီယမ် (Chromium)	၀	၀	၀	၀	ဓာတ်ခွဲစမ်းသပ်ခြင်း
၁၅	ကက်ဒမီယမ် (Cadmium)	၀	၀	၀	၀	ဓာတ်ခွဲစမ်းသပ်ခြင်း
၁၆	ဆယ်လီနီယမ် (Selenium)	၀	၀	၀	၀	ဓာတ်ခွဲစမ်းသပ်ခြင်း
၁၇	မဲ (Lead)	၀	၀	၀	၀	ဓာတ်ခွဲစမ်းသပ်ခြင်း
၁၈	ကြေးနီ (Copper)	၀	၀	၀	၀	ဓာတ်ခွဲစမ်းသပ်ခြင်း
၁၉	ဗေရီယမ် (Barium)	၀	၀	၀	၀	ဓာတ်ခွဲစမ်းသပ်ခြင်း
၂၀	နစ်ကယ် (Nickel)	၀	၀	၀	၀	ဓာတ်ခွဲစမ်းသပ်ခြင်း
၂၁	ဆိုင်းယာနိုက်ဒ် (Cyanide)	၀	၀	၀	၀	ဓာတ်ခွဲစမ်းသပ်ခြင်း
၂၂	ဆိုင်းယာနိုက်ဒ်စုစုပေါင်း (Total Cyanide)	၀	၀	၀	၀	ဓာတ်ခွဲစမ်းသပ်ခြင်း
၂၃	လွတ်လပ်ကလိုရင်း (Free Chlorine)	၀	၀	၀	၀	ဓာတ်ခွဲစမ်းသပ်ခြင်း
၂၄	ဆာလဖိုက်ဒ် (Sulphide)	၀	၀	၀	၀	ဓာတ်ခွဲစမ်းသပ်ခြင်း
၂၅	ဖော်မယ်ဒီဟိုက် (Formaldehyde)	၀	၀	၀	၀	ဓာတ်ခွဲစမ်းသပ်ခြင်း
၂၆	ဖီနော (Phenols)	၀	၀	၀	၀	ဓာတ်ခွဲစမ်းသပ်ခြင်း
၂၇	ကြွင်းကျန်သောကလိုရင်းစုစုပေါင်း (Total Residual Chlorine)	၀	၀	၀	၀	ဓာတ်ခွဲစမ်းသပ်ခြင်း
၂၈	ခရိုမီယမ် (Chromium Hexavalent)	၀	၀	၀	၀	ဓာတ်ခွဲစမ်းသပ်ခြင်း
၂၉	အမိုးနီးယား (Ammonia)	၀	၀	၀	၀	ဓာတ်ခွဲစမ်းသပ်ခြင်း
၃၀	ဖလူရိုက် (Fluoride)	၀	၀	၀	၀	ဓာတ်ခွဲစမ်းသပ်ခြင်း
၃၁	ဓဋ္ဌ (Silver)	၀	၀	၀	၀	ဓာတ်ခွဲစမ်းသပ်ခြင်း
၃၂	ဆီနှင့်အမဲဆီ (Oil and Grease)	၀	၀	၀	၀	ဓာတ်ခွဲစမ်းသပ်ခြင်း
၃၃	ပျော်ဝင်အနည်စုစုပေါင်း (Total Dissolved Solids)	၀	၀	၀	၀	ဓာတ်ခွဲစမ်းသပ်ခြင်း
၃၄	သံဓာတ် (Iron)	၀	၀	၀	၀	ဓာတ်ခွဲစမ်းသပ်ခြင်း

သီလဝါအထူးစီးပွားရေးဇုန်အပိုင်း(ခ)ရှိစက်မှုနုနံ့ဖွံ့ဖြိုးတိုးတက်မှုအတွက်ရေအနည်အသွေးစောင့်ကြည့်လေ့လာမှုအစီရင်ခံစာ
(တစ်နှစ်နှစ်ကြိမ် စောင့်ကြည့်လေ့လာခြင်း ဒီဇင်ဘာလ ၂၀၂၁ ခုနှစ်)

စဉ်	ရေအရည်အသွေး အမျိုးအစား (Parameters)	မြေပေါ်ရေ နမူနာယူသည့် နေရာ-၂ (SW-2)	မြေပေါ်ရေ နမူနာယူသည့် နေရာ-၄ (SW-4)	မြေပေါ်ရေ နမူနာယူသည့် နေရာ-၇ (SW-7)	မြေအောက် ရေနမူနာယူ သည့်နေရာ-၂ (GW-2)	မှတ်ချက်
၃၅	ပြဒါးဓာတ် (Mercury)	၀	၀	၀	၀	ဓာတ်ခွဲစမ်းသပ်ခြင်း
၃၆	ဝမ်းကိုက်ရောဂါကိုဖြစ်စေသော ကိုလီဖော့စ်ဘက်တီးရီးယား (Escherichia Coli) (ကိုယ်တိုင်စောင့်ကြည့်လေ့လာ ခြင်း)	-	-	၀	၀	ဓာတ်ခွဲစမ်းသပ်ခြင်း
၃၇	ရေဒီးဆင်းနှုန်း	၀	၀	၀	-	ရေနမူနာရယူသည့်နေရာ တွင်တိုက်ရိုက်တိုင်းတာ ခြင်း

မှရင်း၊ မြန်မာ့သို့အင်တာနေရှင်နယ်လီမိတက်

၂.၂ ရေနမူနာရယူသည့်နေရာများ၏တည်နေရာနှင့်အချက်အလက်များဖော်ပြချက်

ရေနမူနာယူသည့်နေရာများကို ဇယား ၂.၂-၁ တွင် ဖော်ပြထားပါသည်။ ရေနမူနာရယူသည့်နေရာ တစ်ခုစီတွင် စစ်တမ်းရယူခဲ့သည့်မှတ်တမ်းပုံများကို နောက်ဆက်တွဲ-၁ တွင်ဖော်ပြထားသည်။

ဇယား ၂.၂-၁ ရေနမူနာရယူသည့်နေရာများ

စဉ်	တည်နေရာ	အသေးစိတ်အချက်အလက်
၁	မြေပေါ်ရေနမူနာရယူသည့် နေရာ-၂ (SW-2)	ကိုဩဒိနိတ် - မြောက်လတ္တီတွဒ် - ၁၆° ၄၁' ၂၀.၆၅"၊ အရှေ့လောင်ဂျီတွဒ် - ၉၆° ၁၇' ၁၈.၈၄" တည်နေရာ - ရွှေပျောက်ချောင်းအထက်ပိုင်း စစ်တမ်းကောက်ယူသော အမျိုးအစား - မြေပေါ်ရေစစ်တမ်းရယူခြင်း
၂	မြေပေါ်ရေနမူနာရယူသည့် နေရာ-၄ (SW-4)	ကိုဩဒိနိတ် - မြောက်လတ္တီတွဒ် - ၁၆° ၃၅' ၄၂.၈၄"၊ အရှေ့လောင်ဂျီတွဒ် - ၉၆° ၁၆' ၂၇.၄၂" တည်နေရာ - ရွှေပျောက်ချောင်းအောက်ပိုင်း စစ်တမ်းကောက်ယူသော အမျိုးအစား - မြေပေါ်ရေစစ်တမ်းရယူခြင်းနှင့်ရေစီးနှုန်းတိုင်းတာခြင်း
၃	မြေပေါ်ရေနမူနာရယူသည့် နေရာ-၇ (SW-7)	ကိုဩဒိနိတ် - မြောက်လတ္တီတွဒ် - ၁၆° ၄၀' ၁၃.၂၅"၊ အရှေ့လောင်ဂျီတွဒ် - ၉၆° ၁၇' ၅.၆၆" တည်နေရာ - ရွှေပျောက်ချောင်းသို့ မရောက်မီ နုနံ့ အပိုင်း (ခ) ဆောက်လုပ်ရေးလုပ်ငန်းခွင်ရှိ ရေထိန်းကန်၏ ထွက်ပေါက် စစ်တမ်းကောက်ယူသော အမျိုးအစား - စွန့်ထုတ်ရေစစ်တမ်းရယူခြင်း
၄	မြေအောက်ရေနမူနာရယူသည့် နေရာ-၂ (GW-2)	ကိုဩဒိနိတ် - မြောက်လတ္တီတွဒ် - ၁၆° ၃၉' ၂၅.၃၀"၊ အရှေ့လောင်ဂျီတွဒ် - ၉၆° ၁၇' ၁၅.၆၀" တည်နေရာ - ဖလမ်းကျေးရွာရှိ ၁၇နံးကြီးကျောင်းပရဝဏ်အတွင်း စစ်တမ်းကောက်ယူသော အမျိုးအစား - မြေအောက်ရေစစ်တမ်းရယူခြင်း

မှရင်း၊ မြန်မာ့သို့အင်တာနေရှင်နယ်လီမိတက်



မြေပေါ်ရေနမူနာယူသည့် နေရာ-၂ (SW-2) (ရည်ညွှန်းအမှတ်)

မြေပေါ်ရေနမူနာယူသည့် နေရာ-၂ (SW-2)အား ရွှေပျောက်ချောင်း၏ အထက်ပိုင်းတွင် ရယူခဲ့ခြင်းဖြစ်သည်။ အဆိုပါအမှတ်သည် ဇုန်အပိုင်း(ခ)ဧရိယာ၏ အရှေ့မြောက်ဘက်နှင့် ဒဂုံ-သီလဝါလမ်း၏ တောင်ဘက်တွင် တည်ရှိပါသည်။ အနောက်မြောက်တွင် ဇုန်အပိုင်း(က) နှင့် အရှေ့ဘက်တွင် ပြည်တွင်းစက်မှုဇုန်တို့က အသီးသီး ဝန်းရံလျက် ရှိသည်။

မြေပေါ်ရေနမူနာယူသည့် နေရာ-၄ (SW-4) (ရည်ညွှန်းအမှတ်)

ပြည်တွင်းစက်မှုဇုန်၊ ဇုန်အပိုင်း(က) နှင့် ဇုန်အပိုင်း(ခ)ရှိ ဆောက်လုပ်ရေးလုပ်ငန်းခွင်များမှ ထွက်ရှိလာသောမိုး ရေများပေါင်းစည်းနေရာသွားသောနေရာ ရွှေပျောက်ချောင်း၏ အောက်ပိုင်းတွင် မြေပေါ်ရေနမူနာယူသည့် နေရာ-၄ (SW-4) တွင် ရယူခဲ့ခြင်းဖြစ်သည်။ ရွှေပျောက်ချောင်းသည် အရှေ့မှအနောက်သို့စီးဆင်းပြီး ရန်ကုန်မြစ် အတွင်းသို့ စီးဝင်သည်။ မြေပေါ်ရေနမူနာယူသည့် နေရာ-၄ (SW-4) သည် မြေပေါ်ရေနမူနာယူသည့် နေရာ-၂ (SW-2)၏ ချောင်းအောက်ပိုင်း ၂.၁၅ ကီလိုမီတာအကွာတွင် တည်ရှိပါသည်။ အဆိုပါ ရေနမူနာရယူသည့်နေရာသည် ဇုန်အပိုင်း(ခ) ဧရိယာ၏ အနောက်ဘက်တွင်တည်ရှိပြီး ဒဂုံ-သီလဝါလမ်း၏ တောင်ဘက်တွင်တည်ရှိပါသည်။ ပတ်ဝန်းကျင်အနီးအနားတွင် အရှေ့မြောက်ဘက်တွင် ဇုန်အပိုင်း (က)၊ အရှေ့ဘက်တွင် ပြည်တွင်းစက်မှုဇုန်၊ တောင်ဘက်နှင့် အနောက်ဘက်တို့တွင် စပါးခင်းတို့ အသီးသီးတည်ရှိပါသည်။

မြေပေါ်ရေနမူနာယူသည့် နေရာ-၇ (SW-7) (စွန့်ထုတ်ရေထွက်ပေါက်)

မြေပေါ်ရေနမူနာယူသည့် နေရာ-၇ (SW-7) သည် ဇုန်အပိုင်း(ခ)၏ လုပ်ငန်းလည်ပတ်နေစဉ်ကာလအတွင်း အဓိကစွန့်ထုတ်ရေထွက်ပေါက် ဖြစ်ပါသည်။ ထိုနေရာသည် မြေပေါ်ရေနမူနာယူသည့် နေရာ-၂ (SW-2) ၏ ချောင်းအောက်ပိုင်း၊ အကွာအဝေးအားဖြင့် ၄၃၄ မီတာ အကွာတွင် တည်ရှိပါသည်။ နမူနာရယူသည့်နေရာမှာ ဇုန်အပိုင်း(ခ) ရေထိန်းကန်၏ထွက်ပေါက်၊ ဇုန်အပိုင်း(ခ) ဧရိယာ၏ မြောက်ဘက်နှင့် ဒဂုံ-သီလဝါလမ်းမကြီး၏ တောင်ဘက်တွင် တည်ရှိပါသည်။ အနီးအနားပတ်ဝန်းကျင်၌ မြောက်ဘက်တွင် ဇုန်အပိုင်း(က) နှင့် အရှေ့ဘက်တွင် ပြည်တွင်းစက်မှုဇုန်တို့ တည်ရှိပါသည်။

မြေအောက်ရေနမူနာယူသည့် နေရာ-၂ (GW-2) (မူလတည်ရှိနေသောရေတွင်းအား ရည်ညွှန်းခြင်း)

မြေအောက်ရေနမူနာယူသည့် နေရာ-၂ (GW-2) အား တူးဖော်ထားသောရေတွင်းမှ ရယူခဲ့ပါသည်။ အဆိုပါ ရေတွင်းသည် ဖလမ်းကျေးရွာရှိ ဘုန်းကြီးကျောင်းပရဝတ်အတွင်းတွင် တည်ရှိပါသည်။ အနီးအနားပတ်ဝန်းကျင်၌ မြောက်ဘက်တွင် သီလဝါအထူးစီးပွားရေးဇုန် အပိုင်း (က)၊ တောင်ဘက်တွင် ဖလမ်းကျေးရွာ၊ အနောက်ဘက်တွင် လယ်ကွင်းများ၊ အရှေ့မြောက်ဘက်တွင် ပြည်တွင်းစက်မှုဇုန်နှင့် အရှေ့နှင့်အရှေ့မြောက်ဘက်တွင် သီလဝါအထူးစီးပွားရေးဇုန် အပိုင်း (ခ)တို့ အသီးသီးတည်ရှိနေပါသည်။

၂.၃ စောင့်ကြည့်လေ့လာသည့်နည်းလမ်း

ရေနမူနာများကို ရယူပြီး သန့်စင်ထားသောဖန်ပုလင်းညှို့များဖြင့် သိမ်းဆည်းပြီး ဇယား ၂.၃-၁ တွင် ဖော်ပြထားသော နည်းလမ်းများဖြင့် ဓာတ်ခွဲခန်း၌ စစ်ဆေးပါသည်။ ရေနမူနာများကို ရေခဲပုံးများဖြင့် ၂-၄ဒီဂရီ ဆဲလ်စီးရပ်တွင် သိမ်းဆည်းထားပြီး ဓာတ်ခွဲခန်းသို့ ပို့ဆောင်ပါသည်။ တိုင်းတာသည့် ရေအရည်အသွေး အမျိုးအစားများ၌ ရေအပူချိန်၊ ချဉ်ဖန်ကိန်း နှင့် ပျော်ဝင်အောက်စီဂျင်တို့အား ရေအရည်အသွေး တိုင်းတာသောစက်ကိရိယာ (Horiba U-52)ကို အသုံးပြု၍ ရေနမူနာရယူသည့်နေရာ၌ပင် တိုက်ရိုက်တိုင်းတာခဲ့ပါသည်။ ထို့အပြင်ရေစီးဆင်းမှုနှုန်းကိုလည်း ဒီဂျစ်တယ်ရေစီးနှုန်းတိုင်းကိရိယာ (JFE Digital Current Meter)ဖြင့် ရေနမူနာရယူသည့်နေရာ၌ တိုင်းတာခဲ့ပါသည်။

ဇယား ၂.၃-၁ ရေအရည်အသွေးစစ်ဆေးသည့် နည်းလမ်းများ

စဉ်	အမျိုးအစားများ	နည်းလမ်း
၁	ရေအပူချိန် (Water Temperature)	Instrument Analysis Method (Horiba, U-52, Multi Water Quality Checker)
၂	ချဉ်ဖန်ကိန်း (pH)	Instrument Analysis Method (Horiba, U-52, Multi Water Quality Checker)
၃	ဆိုင်းတြပ်စ်အနယ် (Suspended Solids)	APHA 2540 D (Dry at 103-105°C Method)
၄	ပျော်ဝင်အောက်စီဂျင် (Dissolved Oxygen)	Instrument Analysis Method (Horiba, U-52, Multi Water Quality Checker)
၅	ဒီဇင်မြင့်မြင့်ဖြူရန် အောက်စီဂျင် လိုအပ်ချက် (၅-ရက်) (BOD ₅)	APHA 5210 B (5 Days BOD Test)
၆	ဓာတ်နည်းဖြင့် ဖြူရန် အောက်စီဂျင် လိုအပ်ချက် (COD _{Cr})	APHA 5220D (Close Reflux Colorimetric Method)
၇	ကိုလီဖော်မစ် စုစုပေါင်း (Total Coliform)	APHA 9221B (Standard Total Coliform Fermentation Technique)
၈	နိုက်ထရိုဂျင်စုစုပေါင်း (Total Nitrogen)	HACH Method 10072 (TNT Persulfate Digestion Method)
၉	ဖော့စဖောရက်စုစုပေါင်း (Total Phosphorus)	APIA 4500-P E (Ascorbic Acid Method)
၁၀	အရောင် (Color)	APHA 2120C (Spectrophotometric Method)
၁၁	အနံ့ (Odor)	APHA 2150 B (Threshold Odor Test)
၁၂	ဆီနှင့် အမဲဆီ (Oil and Grease)	APHA 5520B (Partition-Gravimetric Method)
၁၃	မြွေးဓာတ် (Mercury)	APHA 3120 B (Inductively Coupled Plasma (ICP) Method)
၁၄	သွပ် (Zinc)	APHA 3120 B (Inductively Coupled Plasma (ICP) Method)
၁၅	အာဆီနစ် (Arsenic)	APHA 3120 B (Inductively Coupled Plasma (ICP) Method)
၁၆	ခရိုမီယမ် (Chromium)	APHA 3120 B (Inductively Coupled Plasma (ICP) Method)
၁၇	ကက်ဒမီယမ် (Cadmium)	APHA 3120 B (Inductively Coupled Plasma (ICP) Method)
၁၈	ဆယ်လီနီယမ် (Selenium)	APHA 3120 B (Inductively Coupled Plasma (ICP) Method)



သီလဝါအသွေးစီးပွားရေးနှင့်အပိုင်း(ခ)ရှိစက်မှုနှင့်မြို့တော်တက်မှုအတွက်ရေအရည်အသွေးစောင့်ကြည့်လေ့လာမှုအစီရင်ခံစာ
(တစ်နှစ်နှစ်ကြိမ် စောင့်ကြည့်လေ့လာခြင်း၊ ဒီဇင်ဘာလ ၂၀၂၁ ခုနှစ်)

စဉ်	အမျိုးအစားများ	နည်းလမ်း
၁၉	ခဲ (Lead)	APHA 3120 B (Inductively Coupled Plasma (ICP) Method)
၂၀	ကြေးနီ (Copper)	APHA 3120 B (Inductively Coupled Plasma (ICP) Method)
၂၁	ဗေရီယမ် (Barium)	APHA 3120 B (Inductively Coupled Plasma (ICP) Method)
၂၂	နစ်ကယ် (Nickel)	APHA 3120 B (Inductively Coupled Plasma (ICP) Method)
၂၃	ဆိုင်းယာနိုက်ဒ် (Cyanide)	HACH 8027 (Pyridine-Pyrazalone Method)
၂၄	ဆိုင်းယာနိုက်ဒ်စုစုပေါင်း (Total Cyanide)	Distillation process: APHA 4500-CN-C. Total Cyanide after Distillation, Determined cyanide Concentration Process: HACH 8027 (Pyridine - Pyrazalone Method)
၂၅	လွတ်လပ်ကလိုရင်း (Free Chlorine)	APHA 4500-CL G (DPD Colorimetric Method)
၂၆	ဆာလဖိုက်ဒ် (Sulphide)	HACH 8131 (USEPA Methylene Blue Method)
၂၇	ဖော်မယ်ဒီဟိုက် (Formaldehyde)	HACH 8110 (MBTH Method)
၂၈	ဖီနော (Phenols)	USEPA Method 420.1 (Phenolics (Spectrophotometric, Manual 4 AAP With Distillation))
၂၉	သံဓာတ် (Iron)	APHA 3120 B (Inductively Coupled Plasma (ICP) Method)
၃၀	ပျော်ဝင်အနည်စုစုပေါင်း (Total Dissolved Solids)	APHA 2540 C (Total Dissolved Solids Dried at 180°C Method)
၃၁	ကြွင်းကျန်သောကလိုရင်းစုစုပေါင်း (Total Residual Chlorine)	APHA 4500-CL G (DPD Colorimetric Method)
၃၂	ခရိုမီယမ် (Chromium Hexavalent)	ISO 11083:1994 (Determination of chromium (VI) Spectrometric method using 1,5-diphenylcarbazide)
၃၃	အမိုးနီးယား (Ammonia)	HACH Method 10205 (Siliclylate TNT Plus Method)
၃၄	ဖလူဆိုက်ဒ် (Fluoride)	APHA 4110 B (Ion Chromatography with Chemical Suppression of Eluent Conductivity)
၃၅	ဓဋ္ဌ (Silver)	APHA 3120 B (Inductively Coupled Plasma (ICP) Method)
၃၆	စမ်းကိုက်ရောဂါကိုဖြစ်စေသော ဘက်တီးရီးယား (Escherichia Coli)	APHA 9221 F (Escherichia Coli Procedure Using Fluorogenic Substrate)
၃၇	စီးဆင်းနှုန်း (Flow Rate)	Detection of Electromagnetic Elements (Real-time measurement by AEM 213-D Digital Current Meters)

မူရင်း မြန်မာနိုင်ငံအစိုးရအဖွဲ့မှတစ်ဆင့်



၂.၄ စောင့်ကြည့်လေ့လာသည့်ကာလ

ရေအရည်အသွေးနှင့် ရေစီးဆင်းမှုနှုန်းအား ဒီဇင်ဘာလ ၁၄ ရက်နေ့၊ ၂၀၂၁ ခုနှစ်တွင် ဆောင်ရွက်ခဲ့ပြီး ဒီရေအောက်အကျကြောင့် ဖြစ်ပေါ်လာနိုင်သော သက်ရောက်မှုများကိုရှောင်ရှားနိုင်ရန် အောက်ပါ ဇယား ၂.၄-၁ အတိုင်း ရေနမူနာယူခဲ့သည်။ မြန်မာနိုင်ငံ၊ ရန်ကုန်မြစ်၏ ဒီဇင်ဘာလ ၁၄ ရက်နေ့၊ ၂၀၂၁ ခုနှစ် အတွက်ဒီရေ မှတ်တမ်းကို ဇယား ၂.၄-၂ တွင်ဖော်ပြထားပါသည်။

ဇယား ၂.၄-၁ နေရာတစ်ခုချင်းစီအတွက် နမူနာရယူသည့်အချိန်

စဉ်	ရေနမူနာရယူသည့်နေရာ	ရေနမူနာရယူသည့်အချိန်
၁	မြေပေါ်ရေနမူနာယူသည့် နေရာ-၂ (SW-2)	ဒီဇင်ဘာလ ၁၄ ရက်နေ့ ၂၀၂၁ ခုနှစ် (၀၈ နာရီ : ၅၄ မိနစ်)
၂	မြေပေါ်ရေနမူနာယူသည့် နေရာ-၄ (SW-4)	ဒီဇင်ဘာလ ၁၄ ရက်နေ့ ၂၀၂၁ ခုနှစ် (၀၈ နာရီ : ၀၂ မိနစ်)
၃	မြေပေါ်ရေနမူနာယူသည့် နေရာ-၇ (SW-7)	ဒီဇင်ဘာလ ၁၄ ရက်နေ့ ၂၀၂၁ ခုနှစ် (၀၉ နာရီ : ၂၁ မိနစ်)
၄	မြေအောက်ရေနမူနာယူသည့် နေရာ-၂ (GW-2)	ဒီဇင်ဘာလ ၁၄ ရက်နေ့ ၂၀၂၁ ခုနှစ် (၁၂ နာရီ : ၃၆ မိနစ်)

မှတ်။ မြန်မာမိမိအင်တာနေရှင်းနယ်လီမိတက်

ဇယား ၂.၄-၂ မြန်မာနိုင်ငံ၊ ရန်ကုန်မြစ်၏ ဒီရေမှတ်တမ်း

ရက်စွဲ	အချိန်	အမြင့်	ဒီရေအမြေအနေ
ဒီဇင်ဘာလ ၁၄ ရက်နေ့ ၂၀၂၁ ခုနှစ်	၀၁:၁၀	၄.၈၄	ဒီရေအောက်
	၀၈:၂၅	၁.၁၁	ဒီရေအကျ
	၁၃:၄၄	၄.၄၅	ဒီရေအောက်
	၂၀:၂၅	၁.၀၉	ဒီရေအကျ

မှတ်။ မြန်မာမိမိတမ်းအားသင့်၊ ၂၀၂၁ ခုနှစ်အတွက် ရန်ကုန်မြစ်၏ ဒီရေမှတ်တမ်း



၂.၅ စောင့်ကြည့်လေ့လာမှုရလဒ်များ

စွန့်ထုတ်ရေထွက်ပေါက်နှင့် စွန့်ထုတ်ရေရောက်ရှိသောချောင်းတွင်းရှိ ရေအရည်အသွေး စောင့်ကြည့်လေ့လာမှု ရလဒ်များကို ဇယား ၂.၅-၁ တွင်ဖော်ပြထားသည်။ ဓာတ်ခွဲခန်းဆန်းစစ်မှု ရလဒ်များကို နောက်ဆက်တွဲ-၂ တွင် ဖော်ပြထားသည်။ ရလဒ်များကို ပတ်ဝန်းကျင်ထိခိုက်မှု ဆန်းစစ်ခြင်း အစီအရင်ခံစာတွင်ပါရှိသည့် ရေအရည်အသွေးရည်မှန်းတန်ဖိုးများနှင့် နှိုင်းယှဉ်ထားပါသည်။

၂.၅.၁ စွန့်ထုတ်ရေထွက်ပေါက်နှင့် စွန့်ထုတ်ရေရောက်ရှိသောချောင်းတွင်းရှိရလဒ်များ

ရည်မှန်းတန်ဖိုးနှင့်နှိုင်းယှဉ်ရာတွင် ဆိုင်းကြအနည်များ၊ ကိုလီဖောင်းစုစုပေါင်း နှင့် သံဓာတ်တို့မှာ ရည်မှန်းတန်ဖိုးထက် ကျော်လွန်နေကြောင်းတွေ့ရသည်။

စွန့်ထုတ်ရေထွက်ပေါက်ရှိ ရေရလဒ်များ

ဆိုင်းကြအနည်ရလဒ် အနေဖြင့် ချောင်းတွင်းသို့မစွန့်ထုတ်ခင် ဇုန်အပိုင်း(ခ)၏ အဓိကစွန့်ထုတ်ရေထွက်ပေါက် ဖြစ်သော မြေပေါ်ရေနမူနာယူသည့် နေရာ-၇ (SW-7) ရှိ ရလဒ်များသည် ရည်မှန်းတန်ဖိုးထက် ကျော်လွန်နေခြင်းမှာ ဇုန်အပိုင်း(ခ)ရှိ မြေလွတ်များမှ မြေမျက်နှာပြင် စီးဆင်းရေများ ကြောင့် ဖြစ်နိုင်ပါသည်။

ကိုလီဖောင်းစုစုပေါင်း ရလဒ်အနေဖြင့် ချောင်းတွင်းသို့ မစွန့်ထုတ်ခင် ဇုန်အပိုင်း(ခ)၏ အဓိကစွန့်ထုတ်ရေထွက်ပေါက် ဖြစ်သော မြေပေါ်ရေနမူနာယူသည့် နေရာ-၇ (SW-7) ရှိ ရလဒ်များမှာ ရည်မှန်းတန်ဖိုးထက် ကျော်လွန်နေကြောင်း တွေ့ရှိရပါသည်။ ဖြစ်နိုင်ချေ အလားအလာရှိသည့် အကြောင်းရင်းများမှာ ရေထိန်းကန် အတွင်းနှင့် အပြင်တလျှောက်တွင် အပင်များနှင့်ငှက်များ၊ တိရစ္ဆာန်ငယ်များ ကျင်လည်ကျက်စားခြင်းကြောင့် ဇုန်အပိုင်း(ခ)၏ ဧရိယာတွင် သဘာဝအလျောက် ဘက်တီးရီးယားများ ရှိနေသောကြောင့် ဖြစ်နိုင်ပါသည်။

ကိုလီဖောင်းစုစုပေါင်း၏ ဖြစ်တည်မှုတွင် သဘာဝမှဘက်တီးရီးယားများပါဝင်ပြီး စုစုပေါင်းကိုလီဖောင်းသည် လူတို့၏ကျန်းမာရေးကို တိုက်ရိုက်ထိခိုက်မှု မရှိသော်ငြားလည်း ကိုလီဖောင်း ဘက်တီးရီးယားများမှ တမျိုးဖြစ်သည့် ကျွန်းမာရေး အပေါ်သက်ရောက်မှုကို ဖော်ထုတ်ရန် ဝမ်းကိုက်ရောဂါကိုဖြစ်စေသော ကိုလီဖောင်း ဘက်တီးရီးယား(E Coli)အား သုံးသပ်ခြင်းအတွက် ကိုယ်တိုင်စောင့်ကြည့် လေ့လာမှုကို ပြုလုပ်ခဲ့ပါသည်။ ဤဝမ်းကိုက်ရောဂါကိုဖြစ်စေသော ကိုလီဖောင်းဘက်တီးရီးယား(E Coli)ရလဒ်အရ မြေပေါ်ရေနမူနာယူသည့် နေရာ-၇ (SW-7) ၏ တန်ဖိုးသည် ရည်မှန်းတန်ဖိုးအောက် နည်းပါးကြောင်းတွေ့ရှိရပါသည်။ ထို့ကြောင့် မြေပေါ်ရေနမူနာယူသည့်နေရာ-၇ (SW-7) တွင် ကိုလီဖောင်းစုစုပေါင်းသည် ရည်မှန်းတန်ဖိုးထက် များနေသော်လည်း လူ၏ကျန်းမာရေးကို သိသာထင်ရှားစွာ သက်ရောက်မှုမရှိနိုင်ကြောင်း သတ်မှတ်နိုင်ပါသည်။

စောင့်ကြည့်လေ့လာ ရည်ညွှန်းအမှတ်များ၏ ရေရလဒ်များ (စွန့်ထုတ်ရေရောက်ရှိသောချောင်း)

ဆိုင်းကြအနည်များ၏ ရလဒ်များအရ (မြေပေါ်ရေနမူနာယူသည့်နေရာ-၂ (SW-2) နှင့် မြေပေါ်ရေနမူနာယူသည့် နေရာ-၄ (SW-4)) တို့ရှိ ရလဒ်များသည် ရည်မှန်းတန်ဖိုးထက် ကျော်လွန်နေခြင်းမှာ (၁) သဘာဝအလျောက် ချောင်းအထက်ပိုင်းမှ စီးဆင်းလာခြင်းနှင့် သီလဝါအထူးစီးပွားရေးဇုန် ပြင်ပရှိ ပြည်တွင်းစက်မှုဇုန်မှ စွန့်ထုတ်လိုက်သော ရေများကြောင့်လည်းကောင်း၊ (၂)ချောင်းအောက်ဘက်ရှိ ရေများသည် ဒီရေအတက်အကျကြောင့် အထက်သို့ ပြန်လည်စီးဆင်းလာခြင်းကြောင့်လည်းကောင်း ဖြစ်နိုင်ပါသည်။

ကိုလီဖောင်းစုစုပေါင်းရလဒ်အနေဖြင့် မြေပေါ်ရေနမူနာယူသည့် နေရာ-၂ (SW-2) နှင့် မြေပေါ်ရေနမူနာယူသည့် နေရာ-၄ (SW-4) တို့ရှိ ရလဒ်များသည် ရည်မှန်းတန်ဖိုးထက် ကျော်လွန်နေခြင်းမှာ (၁)စွန့်ထုတ်ရေရောက်ရှိရာ ချောင်းအတွင်းနှင့် အနီးတစ်ဝိုက်တွင် ရှိနေသော အပင်အမျိုးမျိုးနှင့် သက်ရှိသတ္တဝါများဖြစ်သော ငှက်များနှင့်တိရစ္ဆာန်များကြောင့် သဘာဝ ဘက်တီးရီးယားများသည် စွန့်ထုတ်ရေရောက်ရှိရာ ချောင်းအတွင်းတွင် တည်ရှိနေခြင်းကြောင့် လည်းကောင်း၊ (၂)သီလဝါးအထူးစီးပွားရေးဇုန် ပြင်ပရှိ ပြည်တွင်းစက်မှုဇုန်မှ စွန့်ထုတ်ရေများကြောင့် လည်းကောင်း၊ (၃)အနီးပတ်ဝန်းကျင်မှ ဒီရေသက်ရောက်မှုကြောင့် လည်းကောင်း ဖြစ်နိုင်ပါသည်။

သံဓာတ်ရလဒ်အနေဖြင့် (မြေပေါ်ရေနမူနာယူသည့်နေရာ-၄ (SW-4)) တို့ရှိ ရလဒ်သည် ရည်မှန်းတန်ဖိုးထက် ကျော်လွန်နေကြောင်း တွေ့ရှိရပါသည်။ ဖြစ်နိုင်သောအကြောင်းအရာများမှာ သဘာဝ သံဓာတ် အရင်းအမြစ်၏ လွှမ်းမိုးမှု ကြောင့် ဖြစ်နိုင်ပါသည်။ (သံဓာတ်သည်ရေစီးဆင်းမှုကြောင့် မြေဆီလွှာအတွင်းမှ ထွက်လာနိုင်ပါသည်။)။ ဂျပန်နိုင်ငံ လူနေမှုပတ်ဝန်းကျင်စံနှုန်းတန်ဖိုးများတွင် (၁) ကျွန်းမာရေ (၂) လူနေမှုပတ်ဝန်းကျင်ဟူ၍ အမျိုးအစားနှစ်ခု သတ်မှတ်ထားပါသည်။ ကျွန်းမာရေအမျိုးအစားတွင် သံဓာတ်အတွက် စံတန်ဖိုးသတ်မှတ်ထားခြင်းမတွေ့ရှိရပါ။ သို့သော် လူနေမှုပတ်ဝန်းကျင်အတွက်မူ ပျော်ဝင်နိုင်သောသံဓာတ် စံတန်ဖိုးအား ၁၀ မီလီဂရမ်/လီတာ ဟူ၍သတ်မှတ်ထားသည်။ ဂျပန်နိုင်ငံ၏ လူနေမှုပတ်ဝန်းကျင်အတွက် သံဓာတ်စံတန်ဖိုးနှင့် နှိုင်းယှဉ်ရာတွင် မြေပေါ်ရေနမူနာယူသည့်နေရာ-၄ (SW-4) ရှိ သံဓာတ်တန်ဖိုးသည် စံတန်ဖိုးအောက်နည်းပါးနေကြောင်း တွေ့ရှိရပါသည်။ ထို့ကြောင့် လူနေမှုပတ်ဝန်းကျင်တွင် သိသာထင်ရှားသောထိခိုက်မှုမရှိကြောင်း သတ်မှတ်နိုင်ပါသည်။

ဇယား ၂.၅-၁ စွန့်ထုတ်ရေထွက်ပေါက်နှင့်စွန့်ထုတ်ရေရောက်ရှိသော ချောင်းမှရေအရည်အသွေး စောင့်ကြည့်လေ့လာမှုရလဒ်များ

စဉ်	ရေအရည်အသွေး အမျိုးအစားများ (Parameters)	ယူနစ်	မြေပေါ်ရေ နမူနာယူသည့် နေရာ-၂ (SW-2)	မြေပေါ်ရေ နမူနာယူသည့် နေရာ-၄ (SW-4)	မြေပေါ်ရေ နမူနာယူသည့် နေရာ-၇ (SW-7)	ရည်မှန်းတန်ဖိုး (လိုယ်တိုင် စောင့်ကြည့်လေ့လာ ခြင်းအတွက် ရည်ညွှန်းတန်ဖိုး)
၁	ရေအပူချိန် (Water Temperature)	°C	၁၉	၂၁	၂၁	၄၃၅
၂	ရေ၏အက်စစ် (pH)	-	၇.၂	၇.၂	၈.၀	၆ - ၉
၃	ဆိုင်ကြွေအနုပျက် (Suspended Solids)	mg/L	၇၈	၁၉၄	၅၈	၅၀
၄	ပျော်ဝင်အောက်စီဂျင် (Dissolved Oxygen)	mg/L	၃.၃၆	၄.၆၆	၆.၃၁	-
၅	စီဝနည်းဖြင့်ဖြိုခွဲရန် အောက်စီဂျင် လိုအပ်ချက် (၅-ရက်) (BOD(5))	mg/L	၇.၉၉	၃.၄၇	၆.၂၆	၃၀
၆	ဓာတုနည်းဖြင့် ဖြိုခွဲရန် အောက်စီဂျင် လိုအပ်ချက် (COD (Cr))	mg/L	၃၀.၉	၁၉.၈	၁၃.၆	၁၂၅
၇	ကိုလီဖောင်း ဗဟုပေါင်း (Total Coliform)	MPN/100ml	၁၂၀၀၀	၁၂၆၈၀၀	၁၆၈၀	၄၀၀

သီလဝါအလှူအသွေးစနစ်အပိုင်း (ခ) ရှိစက်မှုစနစ်ဖြူတိုက်ဟက်မှုအတွက် ရေအရည်အသွေးစောင့်ကြည့်လေ့လာမှုအစီရင်ခံစာ
(တစ်နှစ်နှစ်ကြိမ် စောင့်ကြည့်လေ့လာခြင်း၊ ဒီဇင်ဘာလ ၂၀၂၁ ခုနှစ်)

စဉ်	ရေအရည်အသွေး အမျိုးအစားများ (Parameters)	ယူနစ်	မြေပေါ်ရေ နမူနာယူသည့် နေရာ-၂ (SW-2)	မြေပေါ်ရေ နမူနာယူသည့် နေရာ-၄ (SW-4)	မြေပေါ်ရေ နမူနာယူသည့် နေရာ-၇ (SW-7)	မည်မျှနားကနိန်း (ကိုယ်တိုင် စောင့်ကြည့်လေ့လာ ခြင်းအတွက် မည်မျှနားကနိန်း)
၈	နိုက်ထရိုဂျင်စုစုပေါင်း (Total Nitrogen)	mg/L	၇.၀	၆.၄	၇.၁	၈၀
၉	ဖော့စဖောရက်စုစုပေါင်း (Total Phosphorus)	mg/L	-	-	-	၂
၁၀	အရောင် (Color)	TCU (True Color Unit)	၁၇.၀၆	၇.၈၆	၄.၃၁	၁၅၀
၁၁	အနံ့ (Odor)	TON (Threshold Odor Number)	၁	၁	၁	-
၁၂	ဆီနှင့် အမဲဆီ (Oil and Grease)	mg/L	< ၃.၁	< ၃.၁	< ၃.၁	၁၀
၁၃	ဩဇာတီ (Mercury)	mg/L	≤ ၀.၀၀၂	≤ ၀.၀၀၂	≤ ၀.၀၀၂	၀.၀၀၅
၁၄	သွပ် (Zinc)	mg/L	၀.၀၂၆	၀.၀၆၀	၀.၀၀၆	၂
၁၅	အာဆီနစ် (Arsenic)	mg/L	≤ ၀.၀၁၀	≤ ၀.၀၁၀	≤ ၀.၀၁၀	၀.၁
၁၆	ခရိုမီယမ် (Chromium)	mg/L	≤ ၀.၀၀၂	≤ ၀.၀၀၂	≤ ၀.၀၀၂	၀.၅
၁၇	ကက်သမီယမ် (Cadmium)	mg/L	≤ ၀.၀၀၂	≤ ၀.၀၀၂	≤ ၀.၀၀၂	၀.၀၃
၁၈	ဆယ်လီနီယမ် (Selenium)	mg/L	≤ ၀.၀၁၀	≤ ၀.၀၁၀	≤ ၀.၀၁၀	၀.၀၂
၁၉	ခဲ (Lead)	mg/L	≤ ၀.၀၀၂	≤ ၀.၀၀၂	≤ ၀.၀၀၂	၀.၁
၂၀	ကြေးနီ (Copper)	mg/L	≤ ၀.၀၀၂	≤ ၀.၀၀၂	≤ ၀.၀၀၂	၀.၅
၂၁	ဘေရီယမ် (Barium)	mg/L	၀.၀၆၂	၀.၀၂၈	၀.၀၁၈	၁
၂၂	နစ်ကယ် (Nickel)	mg/L	≤ ၀.၀၀၂	≤ ၀.၀၀၂	≤ ၀.၀၀၂	၀.၂
၂၃	ဆိုင်းယာနိုက် (Cyanide)	mg/L	< ၀.၀၀၂	၀.၀၀၂	< ၀.၀၀၂	၀.၁
၂၄	ဆိုင်းယာနိုက်စုစုပေါင်း (Total Cyanide)	mg/L	၀.၀၀၆	၀.၀၁၅	၀.၀၀၃	၁
၂၅	လွတ်တပ်ကလိုရင်း (Free Chlorine)	mg/L	၀.၁	< ၀.၁	< ၀.၁	၁
၂၆	ဆာလဖိုင် (Sulphide)	mg/L	၀.၀၆၈	၀.၃၇၇	၀.၀၅၄	၁
၂၇	ဖော်မယ်ဒီဟိုက် (Formaldehyde)	mg/L	၀.၀၁၅	၀.၀၇၂	၀.၀၁၉	၁
၂၈	ဖီနော (Phenols)	mg/L	၀.၀၀၇	၀.၀၀၂	၀.၀၀၄	၀.၅
၂၉	သံဓာတ် (Iron)	mg/L	၁.၆၃၂	၆.၈၈၄	၁.၅၀၀	၃.၅
၃၀	ပျော်ဝင်အရည်စုစုပေါင်း (Total Dissolved Solids)	mg/L	၁၀၂၆	၆၂၄	၁၀၀၈	၂၀၀၀

သီလဝါအထူးစီးပွားရေးဇုန်အပိုင်း(ခ)ရှိစက်မှုဇုန်၌မြို့တော်တက်မှုအတွက်ရေအရည်အသွေးစောင့်ကြည့်လေ့လာမှုအစီရင်ခံစာ
(တစ်နှစ်နှစ်ကြိမ် စောင့်ကြည့်လေ့လာခြင်း၊ ဒီဇင်ဘာလ ၂၀၂၁ ခုနှစ်)

ဇယား ၂.၅-၂ ရည်ညွှန်းရေတွင်း၏ ရေအရည်အသွေးစောင့်ကြည့်တန်ဖိုးရလဒ်

စဉ်	ရေအရည်အသွေး အမျိုးအစားများ (Parameters)	ယူနစ်	မြေအောက်ရေ နမူနာယူသည့် နေရာ-၂ (GW-2)	ရည်မှန်းတန်ဖိုး (ကိုယ်တိုင် စောင့်ကြည့်လေ့လာ ခြင်းအတွက် ရည်ညွှန်းတန်ဖိုး)
၁	ရေအပူချိန် (Water Temperature)	°C	၂၄	≤ ၃၅
၂	ချပ်ဖန်ကိန်း(pH)	-	၆.၉	၆ - ၉
၃	ဆိုင်ကြွအနယ် (Suspended Solid)	mg/L	၄	၅၀
၄	ပျော်ဝင်အောက်စီဂျင် (Dissolved Oxygen)	mg/L	၇.၁၃	-
၅	စီစနည်းဖြင့်ဖြိုခွဲရန် အောက်စီဂျင် လိုအပ်ချက် (၅-ရက်) (BOD ₅)	mg/L	၆.၈၂	၃၀
၆	စာတုနည်းဖြင့် ဖြိုခွဲရန် အောက်စီဂျင် လိုအပ်ချက် (COD _{cr})	mg/L	၁၀.၇	၁၂၅
၇	ကိုလီဖောင်းစုစုပေါင်း (Total Coliform)	MPN/100ml	၇.၈	၄၀၀
၈	နိုက်ထရိုဂျင်စုစုပေါင်း (Total Nitrogen)	mg/L	၀.၈	၈၀
၉	ဖော့စဖောရက်စုစုပေါင်း (Total Phosphorus)	mg/L	-	၂
၁၀	အရောင် (Color)	TCU (True Color Unit)	၄၂.၃၄	၁၅၀
၁၁	အနံ့ (Odor)	TON (Threshold Odor Number)	၁	-
၁၂	ဝီနှင့် အမဲဆီ (Oil and Grease)	mg/L	၁၃.၁	၁၀
၁၃	ပြာဆေး (Mercury)	mg/L	၁၀.၀၀၂	၀.၀၀၅
၁၄	သွပ် (Zinc)	mg/L	၀.၀၀၈	၂
၁၅	အာဆီနစ် (Arsenic)	mg/L	၁၀.၀၁၀	၀.၁
၁၆	ခရိုမီယမ် (Chromium)	mg/L	၁၀.၀၀၂	၀.၅
၁၇	ကက်ဒမီယမ် (Cadmium)	mg/L	၁၀.၀၀၂	၀.၀၃
၁၈	ဆယ်လီနီယမ် (Selenium)	mg/L	၁၀.၀၁၀	၀.၀၂
၁၉	မဲ (Lead)	mg/L	၁၀.၀၀၂	၀.၁

သီလဝါအထူးစီးပွားရေးဇုန်အပိုင်း(ခ)ရှိစက်မှုဇုန်ဖွံ့ဖြိုးတိုးတက်မှုအတွက်ရေအရည်အသွေးစောင့်ကြည့်လေ့လာမှုအစီအစဉ်
(တစ်နှစ်နှစ်ကြိမ် စောင့်ကြည့်လေ့လာခြင်း၊ ဝီဒင်ဘာလ ၂၀၂၁ ခုနှစ်)

စဉ်	ရေအရည်အသွေး အမျိုးအစားများ (Parameters)	ယူနစ်	မြေအောက်ရေ နမူနာယူသည့် နေရာ ၂ (SW-2)	ရည်မှန်းတန်ဖိုး (ကိုယ်တိုင် စောင့်ကြည့်လေ့လာခြင်းအတွက် ရည်မှန်းတန်ဖိုး)
၂၀	ကြေးနီ (Copper)	mg/L	≤ ၀.၀၀၂	၀.၅
၂၁	ဗေဇီယမ် (Barium)	mg/L	၀.၀၀၆	၀
၂၂	နစ်ကယ် (Nickel)	mg/L	≤ ၀.၀၀၂	၀.၂
၂၃	ဆိုင်းယာနိုက်ဒ် (Cyanide)	mg/L	≤ ၀.၀၀၂	၀.၁
၂၄	ဆိုင်းယာနိုက်ဒ်စုစုပေါင်း (Total Cyanide)	mg/L	၀.၀၀၃	၁
၂၅	လွတ်လပ်ကလိုရင်း (Free Chlorine)	mg/L	≤ ၀.၁	၀
၂၆	ဆာလဖိုက်ဒ် (Sulphide)	mg/L	၀.၀၀၆	၁
၂၇	ဖော်မယ်ဒီဟိုက် (Formaldehyde)	mg/L	၀.၀၀၃	၁
၂၈	ဖီနော (Phenols)	mg/L	၀.၀၀၄	၀.၅
၂၉	သံဓာတ် (Iron)	mg/L	၃.၅၆၆	၃.၅
၃၀	ပျော်ဝင်အနည်စုစုပေါင်း (Total Dissolved Solids)	mg/L	၁၅၂	၂၀၀၀
၃၁	ကြွင်းကျန်သောက်လိုရင်းစုစုပေါင်း (Total Residual Chlorine)	mg/L	≤ ၀.၁	၀.၂
၃၂	ခရိုမီယမ် (Chromium Hexavalent)	mg/L	≤ ၀.၀၅	၀.၁
၃၃	အမိုးနီးယား (Ammonia)	mg/L	၀.၂၂	၁၀
၃၄	ဖလူအိုဆိုက် (Fluoride)	mg/L	၀.၀၁၄	၂၀
၃၅	ဓွတ် (Silver)	mg/L	≤ ၀.၀၀၂	၀.၅
၃၆	ငမ်းကိုက်ရောဂါကိုဖြစ်စေသော ကိုလီဖောင်းဘက်တီးရီးယား (Escherichia Coli)	MPN/100ml	≤ ၁.၈	(၁၀၀)*** (MPN/100ml)
၃၇	စီးဆင်းနှုန်း (Flow Rate)	m³/s	-	-

မှတ်ချက်။ အမှီရောင်ဖြင့်ဖော်ပြထားသောတန်ဖိုးများသည်သတ်မှတ်ထားသည့်တန်ဖိုးများတက်ကျော်လွန်နေသည်ကိုဆိုလိုပါသည်။

*မှတ်ချက်။ မြေအောက်ရေစောင့်ကြည့်လေ့လာသောနေရာတွင် ခရိုမီယမ်၊ ပြုမူပေါ်မူတည်၍ စီယက်နစ်နိုင်ငံရှိ မြေအောက်ရေအရည်အသွေးဆိုင်ရာ အမျိုးသားနည်းစည်းချဉ်းဥပဒေ B1(ဆည်မြောင်းရေး) (No. QCYN.08: 2008/BTNMT) ကိုမြေအောက်ရေကိုယ်တိုင် စောင့်ကြည့်လေ့လာခြင်းအတွက် ရည်မှန်းတန်ဖိုးအဖြစ်သတ်မှတ်ပါသည်။
မှရှင်း။ ခြံခံမာရုံအဆင်တာနေရင်နယ်လီမိတက်



အခန်း ၃ နိဂုံးချုပ် နှင့် အကြံပြုချက်များ

အခန်း ၂ (အပိုင်း ၂.၅) တွင်ဖော်ပြထားသကဲ့သို့ သီလဝါအထူးစီးပွားရေးဇုန်အပိုင်း(ခ) လုပ်ငန်းလည်ပတ်နေစဉ် ကာလ စောင့်ကြည့်လေ့လာသော အချိန်အတွင်း မြေပေါ်ရေနမူနာယူသည့် နေရာ-၂ (SW-2)၊ မြေပေါ်ရေနမူနာယူသည့် နေရာ-၄ (SW-4) နှင့် စွန့်ထုတ်ရေထွက်ပေါက် ဖြစ်သော မြေပေါ်ရေနမူနာယူသည့် နေရာ-၇ (SW-7) တွင် ဆိုင်းကြွအနည်များ၊ ကိုလီဖောင်းစုစုပေါင်း နှင့် မြေပေါ်ရေနမူနာယူသည့် နေရာ ၄ (SW-4) ရှိ သံဓာတ်တို့ သည် ရည်မှန်းတန်ဖိုးထက် ကျော်လွန်နေပါသည်။

ဆိုင်းကြွအနည်ရလဒ် အနေဖြင့် ချောင်းတွင်းသို့မစွန့်ထုတ်ခင် ဇုန်အပိုင်း(ခ)၏ အဓိကစွန့်ထုတ်ရေထွက်ပေါက် ဖြစ်သော မြေပေါ်ရေနမူနာယူသည့် နေရာ-၇ (SW-7) ရှိ ရလဒ်များသည် ရည်မှန်းတန်ဖိုးထက် ကျော်လွန်နေခြင်းမှာ ဇုန်အပိုင်း(ခ)ရှိ မြေလွတ်များမှ မြေမျက်နှာပြင် စီးဆင်းရေများ ကြောင့် ဖြစ်နိုင်ပါသည်။

ကိုလီဖောင်းစုစုပေါင်း ရလဒ်အနေဖြင့် ချောင်းတွင်းသို့ မစွန့်ထုတ်ခင် ဇုန်အပိုင်း(ခ)၏ အဓိကစွန့်ထုတ်ရေထွက်ပေါက် ဖြစ်သော မြေပေါ်ရေနမူနာယူသည့် နေရာ-၇ (SW-7) ရှိ ရလဒ်များမှာ ရည်မှန်းတန်ဖိုးထက် ကျော်လွန်နေကြောင်း တွေ့ရှိရပါသည်။ ဖြစ်နိုင်ချေ အလားအလာရှိသည့် အကြောင်းရင်းများမှာ ရေထိန်းကန် အတွင်းနှင့် အပြင်တလျှောက်တွင် အပင်များနှင့်ငှက်များ၊ တိရစ္ဆာန်ငယ်များ ကျင်လည်ကျက်စားခြင်းကြောင့် ဇုန်အပိုင်း(ခ)၏ ဧရိယာတွင် သဘာဝအလျောက် ဘက်တီးရီးယားများ ရှိနေသောကြောင့် ဖြစ်နိုင်ပါသည်။ ဤပမ်းကိုက်ရောဂါကိုဖြစ်စေသော ကိုလီဖောင်းဘက်တီးရီးယား(E Coli)ရလဒ်အရ မြေပေါ်ရေနမူနာယူသည့် နေရာ-၇ (SW-7) ၏ တန်ဖိုးသည် ရည်မှန်းတန်ဖိုးအောက် နည်းပါးကြောင်းတွေ့ရှိရပါသည်။ ထို့ကြောင့် မြေပေါ်ရေနမူနာယူသည့်နေရာ-၇ (SW-7) တွင် ကိုလီဖောင်းစုစုပေါင်းသည် ရည်မှန်းတန်ဖိုးထက် များနေသော်လည်း လူ၏ကျန်းမာရေးကို သိသာထင်ရှားစွာ သက်ရောက်မှုမရှိနိုင်ကြောင်း သတ်မှတ်နိုင်ပါသည်။

ရည်ညွှန်းစောင့်ကြည့်လေ့လာသည့် မြေပေါ်ရေနမူနာယူသည့်နေရာများ (မြေပေါ်ရေနမူနာယူသည့်နေရာ-၂ (SW-2) နှင့် မြေပေါ်ရေနမူနာယူသည့် နေရာ-၄ (SW-4)) တွင် ဆိုင်းကြွအနည်များ၊ ကိုလီဖောင်းစုစုပေါင်း နှင့် သံဓာတ်တို့၏ ရလဒ်များသည် ရည်မှန်းတန်ဖိုးထက် ကျော်လွန်နေပါသည်။ (မြေပေါ်ရေနမူနာယူသည့်နေရာ-၂ (SW-2) နှင့် မြေပေါ်ရေနမူနာယူသည့် နေရာ-၄ (SW-4)) တို့ရှိ ဆိုင်းကြွအနည်များ၏ ရလဒ်များသည် ရည်မှန်းတန်ဖိုးထက် ကျော်လွန်နေခြင်းမှာ သဘာဝအလျောက် ချောင်းအထက်ပိုင်းမှ စီးဆင်းလာခြင်းနှင့် သီလဝါအထူးစီးပွားရေးဇုန် ပြင်ပရှိ ပြည်တွင်းစက်မှုဇုန်မှ စွန့်ထုတ်လိုက်သော ရေများကြောင့်လည်းကောင်း၊ ချောင်းအောက်ဘက်ရှိ ရေများသည် ဒီရေအတက်အကျကြောင့် အထက်သို့ ပြန်လည်စီးဆင်းလာခြင်းကြောင့်လည်းကောင်း ဖြစ်နိုင်ပါသည်။

မြေပေါ်ရေနမူနာယူသည့် နေရာ-၂ (SW-2) နှင့် မြေပေါ်ရေနမူနာယူသည့် နေရာ-၄ (SW-4) တို့တွင် ကိုလီဖောင်းစုစုပေါင်းရလဒ် သည် ရည်မှန်းတန်ဖိုးထက် ကျော်လွန်နေခြင်းမှာ (၁)စွန့်ထုတ်ရေရောက်ရှိရာ ချောင်းအတွင်းနှင့် အနီးတစ်ဝိုက်တွင် ရှိနေသော အပင်အမျိုးမျိုးနှင့် သက်ရှိသတ္တဝါများဖြစ်သော ငှက်များနှင့် တိရစ္ဆာန်များကြောင့် သဘာဝ ဘက်တီးရီးယားများသည် စွန့်ထုတ်ရေရောက်ရှိရာ ချောင်းအတွင်းတွင် တည်ရှိနေခြင်းကြောင့်လည်းကောင်း၊ (၂)သီလဝါအထူးစီးပွားရေးဇုန် ပြင်ပရှိ ပြည်တွင်းစက်မှုဇုန်မှ



စွန့်ထုတ်ရေများကြောင့်လည်းကောင်း၊ (၃)အနီးပတ်ဝန်းကျင်မှ ဒီရေသက်ရောက်မှုကြောင့်လည်းကောင်း ဖြစ်နိုင်ပါသည်။

သံဓာတ်ရလဒ်အနေဖြင့် (မြေပေါ်ရေနမူနာယူသည့်နေရာ-၄ (SW-4)) တို့ရှိ ရလဒ်သည် ရည်မှန်းတန်ဖိုးထက် ကျော်လွန်နေကြောင်း တွေ့ရှိရပါသည်။ ဖြစ်နိုင်သောအကြောင်းအရာများမှာ သဘာဝ သံဓာတ် အရင်းအမြစ်၏ လွှမ်းမိုးမှု ကြောင့် ဖြစ်နိုင်ပါသည်။ (သံဓာတ်သည်ရေစီးဆင်းမှုကြောင့် မြေဆီလွှာအတွင်းမှ ထွက်လာနိုင်ပါသည်။)။ ဂျပန်နိုင်ငံ လူနေမှုပတ်ဝန်းကျင်စံနှုန်းတန်ဖိုးများတွင် (၁) ကျန်းမာရေး (၂) လူနေမှုပတ်ဝန်းကျင်ဟူ၍ အမျိုးအစားနှစ်ခု သတ်မှတ်ထားပါသည်။ ကျန်းမာရေးအမျိုးအစားတွင် သံဓာတ်အတွက် စံတန်ဖိုးသတ်မှတ်ထားခြင်းမတွေ့ရှိရပါ။ သို့သော် လူနေမှုပတ်ဝန်းကျင်အတွက်မူ ပျော်ဝင်နိုင်သောသံဓာတ် စံတန်ဖိုးအား ၁၀ မီလီဂရမ်/လီတာ ဟူ၍သတ်မှတ်ထားသည်။ ဂျပန်နိုင်ငံ၏ လူနေမှုပတ်ဝန်းကျင်အတွက် သံဓာတ်စံတန်ဖိုးနှင့် နှိုင်းယှဉ်ရာတွင် မြေပေါ်ရေနမူနာယူသည့်နေရာ-၄ (SW-4) ရှိ သံဓာတ်တန်ဖိုးသည် စံတန်ဖိုးအောက်နည်းပါးနေကြောင်း တွေ့ရှိရပါသည်။ ထို့ကြောင့် လူနေမှုပတ်ဝန်းကျင်တွင် သိသာထင်ရှားသောထိခိုက်မှုမရှိကြောင်း သတ်မှတ်နိုင်ပါသည်။

သံဓာတ်ရလဒ်အရ မြေအောက်ရေနမူနာယူသည့် နေရာ-၂ (GW-2) သည် ရည်မှန်းတန်ဖိုးထက် အနည်းငယ် ကျော်လွန်နေပါသည်။ မြေအောက်ရေနမူနာယူသည့် နေရာ-၂ (GW-2) ၏ ယခင် စောင့်ကြည့်လေ့လာမှုရလဒ်များ နှိုင်းယှဉ်သောအခါတွင် သံဓာတ်ရလဒ်များသည် ၃.၀၇၆ မီလီဂရမ်/လီတာ (သြဂုတ်လ၊ ၂၀၁၉ခုနှစ်) မှ ၈.၃၁၀ မီလီဂရမ်/လီတာ (အောက်တိုဘာလ၊ ၂၀၂၁ခုနှစ်) အတွင်းရှိပါသည်။ သြဂုတ်လ၊ ၂၀၁၉ခုနှစ်၏ သံဓာတ်ပါဝင်မှုရလဒ်မှတစ်ဆင့် သံဓာတ်ပါဝင်မှုရလဒ် အများစု (ပေရယ်လ၊ ၂၀၁၉ခုနှစ် မှ ဒီဇင်ဘာလ၊ ၂၀၂၁ခုနှစ်အထိ)သည် ရည်မှန်းတန်ဖိုးထက် ကျော်လွန်နေကြောင်း တွေ့ရသည်။ ထို့ကြောင့် ဖြစ်နိုင်ချေရှိသော အကြောင်းအရာများမှာ သဘာဝမြေဆီလွှာမှ သံဓာတ် အရင်းအမြစ် လွှမ်းမိုးမှု (သံဓာတ်သည်ရေစီးဆင်းမှုကြောင့် မြေဆီလွှာအတွင်းမှ ထွက်လာနိုင်ပါသည်) ကြောင့်ဖြစ်နိုင်ပါသည်။ ရန်ကုန်မြို့ ၏မြေဆီလွှာသည် သဘာဝအားဖြင့် သံဓာတ်ကြွယ်ဝပါသည်။

အနာဂတ်တွင် သီလဝါအထူးစီးပွားရေးဇုန် အပိုင်း (ခ) ၏ အဓိကစွန့်ထုတ်ရေ ထွက်ရှိသောနေရာများမှ ထွက်ရှိလာသော ရေအရည်အသွေးများဖြစ်သည့် ဆိုင်းကြွအနယ်များ နှင့် ကိုလီဖောင်းစုစုပေါင်း တို့၏ သင့်တော်သော ရည်မှန်းအဆင့်ရရှိနိုင်ရန် အောက်ပါဆောက်လုပ်ချက်များကိုလုပ်ဆောင်သင့်ပါသည်။

- ၁) ကိုလီဖောင်းဘက်တီးရီးယားများ၏ ကျန်းမာရေးအပေါ်သက်ရောက်မှုကို သိရှိနိုင်ရန် ဝမ်းကိုက်ရောဂါကို ဖြစ်စေသော ကိုလီဖောင်းဘက်တီးရီးယား (E Coli) ကို ဆက်လက်စောင့်ကြည့်ရန်။
- ၂) ဆောက်လုပ်ရေးလုပ်ငန်းများမှရေများစီးဆင်းမှုအခြေအနေကိုစောင့်ကြည့်လေ့လာရန် နှင့်
- ၃) ဆောက်လုပ်ရေးလုပ်ငန်းများမှအထွေထွေသုံးစွန့်ထုတ်ရေများ၏အခြေအနေကိုစောင့်ကြည့်လေ့လာရန်။

ဤတွင်စာတမ်းပြီးဆုံးပါသည်။



နောက်ဆက်တွဲ ၁ ရေနမူနာရယူသည့် မှတ်တမ်းဓာတ်ပုံများ



သီလဝါအထူးစီးပွားရေးဇုန်အပိုင်း(ခ)ရှိစက်မှုဇုန်ဖွံ့ဖြိုးတိုးတက်မှုအတွက်ရေအရည်အသွေးစောင့်ကြည့်လေ့လာမှုအစီရင်ခံစာ
(ဟစ်နစ်နစ်ကြိမ် စောင့်ကြည့်လေ့လာခြင်း၊ ဒီဇင်ဘာလ ၂၀၂၁ ခုနှစ်)

သီလဝါအထူးစီးပွားရေးဇုန် အပိုင်း (ခ) ရှိ စွန့်ထုတ်ရေနမူနာရယူသည့်နေရာ



မြေပေါ်ရေနမူနာယူသည့် နေရာ-၇ (SW-7) ၌ ရေနမူနာရယူခြင်းနှင့်တိုင်းတာခြင်း

**စွန့်ထုတ်ရေထွက်ရှိသောနေရာများနှင့် စွန့်ထုတ်ရေရောက်ရှိနိုင်သည့်ချောင်း၏
 အခြေခံအချက်အလက်များကို နှိုင်းယှဉ်ရန်အတွက် ရည်ညွှန်းစောင့်ကြည့်လေ့လာသည့် နေရာများ**



မြေပေါ်ရေနမူနာယူသည့် နေရာ-၂ (SW-2) ၌ ရေနမူနာရယူခြင်းနှင့်တိုင်းတာခြင်း



မြေပေါ်ရေနမူနာယူသည့် နေရာ-၄ (SW-4) ၌ ရေနမူနာရယူခြင်းနှင့်တိုင်းတာခြင်း



မြေအောက်ရေနမူနာယူသည့် နေရာ-၂ (GW-2) ရေနမူနာရယူခြင်းနှင့်တိုင်းတာခြင်း

နောက်ဆက်တွဲ ၂ ဓာတ်ခွဲခန်းရလဒ်များ



သီလဝါအထူးစီးပွားရေးဇုန်အပိုင်း၊ခရိုင်စက်မှုနှင့်မြို့ပြတိုးတက်မှုအတွက်ရေအရည်အသွေးစောင့်ကြည့်လေ့လာမှုအစီရင်ခံစာ
(တစ်နှစ်နှစ်ကြိမ် စောင့်ကြည့်လေ့လာခြင်း၊ ဒီဇင်ဘာလ ၂၀၂၁ ခုနှစ်)

DWA

ANALYSIS REPORT (WATER ANALYSIS) - 112
1st Floor, 112 Road, 112 Street, Yangon Region, Myanmar
Phone No. (95) 9 112 112



Report No. : DPM LAB-001/11194
Revision No. : 1
Report Date : 28 December, 2021
Application No. : 0001-0001

Analysis Report

Client Name : Myanmar Civil International LTD (MCIL)
Address : No. 3A/A, 1st Floor, Grand Plaza, 112 Street, Yangon Region, Myanmar
Project Name : Environmental Monitoring report for Zone A & B
Sample Description :
Sample Name : WQ-SW-A-1214
Sample No. : W-1120077
Water Works No. :
Sampling Date : 14 December, 2021
Sampling By : Customer
Sample Received Date : 14 December, 2021

No.	Parameter	Method	Unit	Result	LDQ
1	SS	APHA 2540D (Dry at 100-105°C Method)	mg/L	108	-
2	BOD (5)	APHA 5210 B (5 Days BOD Test)	mg/L	5.47	5.00
3	COD (Cr)	APHA 5220B (Closed Reflux Colorimetric Method)	mg/L	59.8	0.0
4	Total Calcium	APHA 9221B (Standard Total Calcium Determination Technique)	mg/L (ppm)	45.000	1.8
5	Oil and Grease	APHA 9220B (Petroleum-Ether Method)	mg/L	4.3	3.1
6	Total Nitrogen	INDH Method (05/3) (TNT Persulfate Digestion Method)	mg/L	8.4	0.5
7	Escherichia coli	APHA 2120C (Spectrophotometric Method)	TCU	1.96	0.00
8	Color	APHA 2150 B (Threshold Color Test)	TCU	1	0
9	TDS	APHA 2540 C (Total Dissolved Solids Direct at 180°C Method)	mg/L	624	-
10	Mercury	APHA 3120 B (Inductively Coupled Plasma (ICP) Method)	mg/L	4.9-001	0.001
11	Zinc	APHA 3120 B (Inductively Coupled Plasma (ICP) Method)	mg/L	0.040	0.002
12	Arsenic	APHA 3120 B (Inductively Coupled Plasma (ICP) Method)	mg/L	4.9-002	0.010
13	Chromium	APHA 3120 B (Inductively Coupled Plasma (ICP) Method)	mg/L	4.9-003	0.002
14	Cadmium	APHA 3120 B (Inductively Coupled Plasma (ICP) Method)	mg/L	4.9-002	0.001
15	Selenium	APHA 3120 B (Inductively Coupled Plasma (ICP) Method)	mg/L	4.9-002	0.010
16	Copper	APHA 3120 B (Inductively Coupled Plasma (ICP) Method)	mg/L	4.9-003	0.002
17	Lead	APHA 3120 B (Inductively Coupled Plasma (ICP) Method)	mg/L	4.9-002	0.001
18	Barium	APHA 3120 B (Inductively Coupled Plasma (ICP) Method)	mg/L	0.010	0.001
19	Strontium	APHA 3120 B (Inductively Coupled Plasma (ICP) Method)	mg/L	4.9-003	0.002
20	Silver	APHA 3120 B (Inductively Coupled Plasma (ICP) Method)	mg/L	4.9-002	0.001
21	Iron	APHA 3120 B (Inductively Coupled Plasma (ICP) Method)	mg/L	4.884	0.002
22	Cyanide	INDH 8020 (Pyridine - Pyrazole Method)	mg/L	0.001	0.002
23	Total Cyanide	Standard Method 4500-CN-C, Total Cyanide after Distillation, Inductively Coupled Plasma Atomic Fluorescence (ICP-AFS) (Pyridine - Pyrazole Method)	mg/L	0.015	0.002
24	Ammonia	INDH Method 10205 (Nesslerization Method)	mg/L	1.44	0.02
25	Hexavalent Chromium (Cr6+)	IND 31002-1094 (Determination of chromium(VI) Spectrophotometric method using L-Ascorbic acid)	mg/L	4.825	0.05
26	Fluoride	APHA 4500-F (Ion Chromatography with Chloride Suppression of Eluent Conductivity)	mg/L	1.325	0.014
27	Total Chlorine	APHA 4500-CL-2 (DPD Colorimetric Method)	mg/L	4.8	0.1
28	Total Residual Chlorine	APHA 4500-CL-2 (DPD Colorimetric Method)	mg/L	0.1	0.1
29	Sulfide	INDH 8130 (Methylene Blue Method)	mg/L	0.377	0.001
30	Formaldehyde	INDH 8130 (MBTH Method)	mg/L	0.072	0.001
31	Phenols	INDH Method 4201 (Phenols) (Spectrophotometric Method with 4-Aminodiphenylamine)	mg/L	0.002	0.001

Remark : LDQ - Limit of Quantitation
APHA - American Public Health Association (APHA), the American Water Works Association (AWWA), and the Water Environment Federation (WEF), Standard Methods for the Examination of Water and Wastewater, 22nd edition

Analyst By :
B. H. Aye Win
Assistant Manager



Approved By :
B. H. Aye Win
Manager



သီလဝါအထူးစီးပွားရေးဇုန် အပိုင်း(ခ)ရှိ
စက်မှုဇုန်ဖွံ့ဖြိုးတိုးတက်ရေးအတွက်
လေထုအရည်အသွေးစောင့်ကြည့်လေ့လာခြင်းအစီရင်ခံစာ
(လုပ်ငန်းလည်ပတ်နေစဉ်ကာလ အပိုင်း ၁၊ အပိုင်း ၂ နှင့် အပိုင်း ၃)

(တစ်နှစ် နှစ်ကြိမ်စောင့်ကြည့်လေ့လာခြင်း)

၂၀၂၁ ခုနှစ်၊ ဒီဇင်ဘာလ
မြန်မာ့သိုအဲ အင်တာနေရှင်နယ် လီမိတက်



မာတိကာ

အခန်း ၁ စောင့်ကြည့်လေ့လာသောအစီအစဉ်နှင့်အကျဉ်းချုပ်	၁
၁.၁ ယေဘုယျဖော်ပြချက်	၁
၁.၂ စောင့်ကြည့်လေ့လာသောအစီအစဉ်ဖော်ပြချက်များ	၁
အခန်း ၂ လေထုအရည်အသွေးစောင့်ကြည့်လေ့လာခြင်း	၂
၂.၁ စောင့်ကြည့်လေ့လာသည့်အမျိုးအစား	၂
၂.၂ စောင့်ကြည့်လေ့လာသည့်တည်နေရာ	၂
၂.၃ စောင့်ကြည့်လေ့လာသည့်ကာလ	၃
၂.၄ စောင့်ကြည့်လေ့လာသည့်နည်းလမ်း	၃
၂.၅ စောင့်ကြည့်လေ့လာမှုရလဒ်များ	၄
အခန်း ၃ နိဂုံးချုပ် နှင့် အကြံပြုချက်များ	၁၃
နောက်ဆက်တွဲ-၁ ခာနီပျမ်းမျှလေထုအရည်အသွေးတန်ဖိုး	က၁-၁
နောက်ဆက်တွဲ-၂ လေထုအရည်အသွေးတိုင်းတာသည့်စက်ကို စံကိုက်ညီထားသောလက်မှတ်	က၂-၁

ဇယားများစာရင်း

ဇယား ၁.၂-၁ လေထုအရည်အသွေးစောင့်ကြည့်လေ့လာသောအစီအစဉ်	၁
ဇယား ၂.၅-၁ လေထုအရည်အသွေးစောင့်ကြည့်လေ့လာမှုရလဒ် (နေ့စဉ်ပျမ်းမျှ)	၅
ဇယား ၂.၅-၂ ကျော်လွန်သောအချိန်စုစုပေါင်း	၈
ဇယား ၂.၅-၃ ကျော်လွန်သောအချိန်စုစုပေါင်း နှင့် အမှုန်အမွှား (PM _{2.5}) ၏ လေတိုက်ခတ်ရာအရပ်အကျဉ်းချုပ်	၈
ဇယား ၂.၅-၄ ကျော်လွန်သောအချိန်စုစုပေါင်း နှင့် အမှုန်အမွှား (PM ₁₀) ၏ လေတိုက်ခတ်ရာအရပ်အကျဉ်းချုပ်	၁၁
ဇယား ၂.၅-၅ ကျော်လွန်သောအချိန်စုစုပေါင်း နှင့် ဆာလဖာဒိုင်အောက်ဆိုက် (SO ₂) ၏ လေတိုက်ခတ်ရာအရပ်အကျဉ်းချုပ်	၁၁
ဇယား ၂.၅-၆ နေရာ-၁ (AQ-1) ၏ လေတိုက်ခတ်ရာအရပ်အကျဉ်းချုပ်	၁၂

ပုံများစာရင်း

ပုံ ၂.၂-၁ လေထုအရည်အသွေးစောင့်ကြည့်လေ့လာသည့်တည်နေရာ	၃
ပုံ ၂.၄-၁ လေထုအရည်အသွေးစောင့်ကြည့်လေ့လာခြင်းအခြေအနေ	၄
ပုံ ၂.၅-၁ လေထုအရည်အသွေးစောင့်ကြည့်လေ့လာသောတည်နေရာ နှင့် လေတိုက်ခတ်ရာအရပ်အခြေအနေ	၆



အခန်း ၁ စောင့်ကြည့်လေ့လာသောအစီအစဉ်နှင့်အကျဉ်းချုပ်

၁.၁ ယေဘုယျဖော်ပြချက်

သီလဝါအထူးစီးပွားရေးဇုန်သည် ရန်ကုန်တိုင်းဒေသကြီး၏ တောင်ပိုင်းခရိုင်တွင်တည်ရှိပြီး ရန်ကုန်မြို့၏ အရှေ့တောင်ဘက် ၂၃ ကီလိုမီတာတွင် တည်ရှိပါသည်။ သီလဝါအထူးစီးပွားရေးဇုန်၏ အကောင်အထည် ဖော်ဆောင်သူအနေဖြင့် ဇုန်အပိုင်း(ခ)အတွင်းရှိ စက်မှုမြေနေရာအတွက် ခွင့်ပြုချက်ရရှိထားသော ပတ်ဝန်းကျင်ထိခိုက်မှုဆန်းစစ်ခြင်း အစီရင်ခံစာနှင့် ပတ်ဝန်းကျင်ဆိုင်ရာ စီမံခန့်ခွဲမှုအစီအစဉ်အတိုင်း ပုံမှန်စောင့်ကြည့်စစ်ဆေးခြင်းကို ဆောင်ရွက်ရန် မြန်မာ-ဂျပန် သီလဝါဖွံ့ဖြိုးရေးလီမိတက်တွင် တာဝန်ရှိပါသည်။ မြန်မာ-ဂျပန် သီလဝါဖွံ့ဖြိုးရေးလီမိတက်သည် ဇုန်အတွင်းနှင့် အနီးပတ်ဝန်းကျင်ရှိ သဘာဝပတ်ဝန်းကျင် အခြေအနေများကို သိရှိစေရန် သဘာဝပတ်ဝန်းကျင်နှင့်သက်ဆိုင်သော အချက်အလက်စောင့်ကြည့် လေ့လာမှုများကို ရေးဆွဲထားပြီး ထိုအစီအစဉ်များအရ အကောင်အထည်ဖော် ဆောင်ရွက်ခဲ့ပါသည်။

၁.၂ စောင့်ကြည့်လေ့လာသောအစီအစဉ်ဖော်ပြချက်များ

သီလဝါအထူးစီးပွားရေးဇုန် အပိုင်း(ခ) စက်မှုဇုန် လုပ်ငန်း လည်ပတ် နေခြင်းကြောင့် စက်မှုဇုန်အတွင်း နှင့် အပြင်ရှိ ပတ်ဝန်းကျင်အခြေအနေအား အကဲဖြတ်နိုင်ရန်အတွက် အောက်ပါဇယားတွင် ဖော်ပြထားသည့်အတိုင်း ၂၀၂၁ခုနှစ်၊ ဒီဇင်ဘာလ ၂၂ ရက်နေ့ မှ ဒီဇင်ဘာလ ၂၉ ရက်နေ့အထိ လေထုအရည်အသွေးအား စောင့်ကြည့်လေ့လာခဲ့သည်။

ဇယား ၁.၂-၁ လေထုအရည်အသွေးစောင့်ကြည့်လေ့လာသောအစီအစဉ်

စောင့်ကြည့်လေ့လာ ရေးရက်စွဲ	စောင့်ကြည့်လေ့ လာမှုအမျိုးအစား	တိုင်းတာသော အမျိုးအစားများ	တိုင်းတာသောနေရာ အရေအတွက်	ကြာချိန်	စောင့်ကြည့်လေ့လာသော နည်းလမ်း
၂၂ရက် ဒီဇင်ဘာလ - ၂၉ရက် ဒီဇင်ဘာလ ၂၀၂၁ခုနှစ်	လေထုအရည် အသွေး	ကာဗွန်မိုနောက်ဆိုဒ် (CO) နိုက်ထရိုဂျင်ဒိုင်အောက်ဆိုဒ် (NO ₂)၊ အမွန်အမ္မား (PM ₁₀)၊ အမွန်အမ္မား (PM _{2.5}) နှင့် ဆာလဖာဒိုင်အောက်ဆိုဒ် (SO ₂)	၁	၇ ရက်	ပတ်ဝန်းကျင်လေအရည်အသွေး တိုင်းတာသည့်စက်ကိရိယာ (Haze-scanner EPAS) ဖြင့် ဖြေဖြင့်တွင်တွင်းဆင်းတိုင်းတာ ခြင်း

မှတ်ချက်- မြန်မာနိုင်ငံအင်တာနေရှင်နယ်လီမိတက်

အခန်း ၂ လေထုအရည်အသွေးစောင့်ကြည့်လေ့လာခြင်း

၂.၁ စောင့်ကြည့်လေ့လာသည့်အမျိုးအစား

လေထုအရည်အသွေး စောင့်ကြည့်လေ့လာသော အမျိုးအစားများမှာ ကာဗွန်မီနောက်ဆိုဒ် (CO)၊ နိုက်ထရိုဂျင်ဒိုင်အောက်ဆိုဒ် (NO₂)၊ အမှုန်အမွှား (PM_{2.5})၊ အမှုန်အမွှား (PM₁₀) နှင့် ဆာလဖာဒိုင်အောက်ဆိုဒ် (SO₂) တို့ဖြစ်သည်။

၂.၂ စောင့်ကြည့်လေ့လာသည့်တည်နေရာ

ပတ်ဝန်းကျင်လေထုအရည်အသွေးတိုင်းတာသည့် စက်ကိရိယာဖြစ်သည့် "Haz-Scanner Environmental Perimeter Air Station (EPAS)" ဖြင့် သီလဝါအထူးစီးပွားရေးဇုန်၏ တောင်(S)ဘက်၊ မြောက်လတ္တီတွဒ် ၁၆°၃၉'၂၄.၂၀"၊ အရှေ့လောင်ဂျီတွဒ် ၉၆°၁၇'၁၅.၈၀"၊ ဖလမ်းကျေးရွာ၊ ဖလမ်းရွာဦး ကျောင်းဝန်းထဲတွင် တပ်ဆင်ထားပြီး တောင်(S)ဘက်တွင် ဖလမ်းကျေးရွာရှိလူနေအိမ်များ၊ အနောက်(W)ဘက်တွင် လယ်ကွင်းများ၊ မြောက်(N) ဘက်တွင် သီလဝါအထူးစီးပွားရေးဇုန်အပိုင်း(က)၊ အရှေ့မြောက်(NE)ဘက်တွင် ပြည်တွင်းသီလဝါစက်မှုဇုန်နှင့် အရှေ့(E)၊ မြောက်(N)၊ မြောက်-အနောက်မြောက်(NNW)၊ အနောက်မြောက်(NW) နှင့် အရှေ့မြောက်(NE) ဘက်တို့တွင် တည်ဆောက်ဆဲ သီလဝါအထူးစီးပွားရေးဇုန် အပိုင်း(ခ)တို့ဖြင့် ဝန်းရံထားသည်။ လေထုအရည်အသွေး စောင့်ကြည့်လေ့လာမှုကို ဖလမ်းကျေးရွာရှိ လူနေအိမ်များနှင့် အနီးဆုံးနေရာဖြစ်သော အထက်မါနေရာ၌ ဆောင်ရွက်ခဲ့သည်။ အဓိကလေထုညစ်ညမ်းမှုကို ဖြစ်နိုင်သောစွန့်ထုတ်ဓာတ်ငွေ့များ ထုတ်လွှတ်ရာ အရင်းမြစ်များမှာ ဆောက်လုပ်ရေလုပ်ငန်းစဉ်များမှ ဖုန်များထွက်ရှိခြင်း၊ ဆောက်လုပ်ရေးလုပ်ငန်းသုံး ယာဉ်များနှင့် ဖလမ်းကျေးရွာရှိ နေထိုင်သူများ၏ နေ့စဉ်လုပ်ငန်းဆောင်တာများကြောင့် ဖြစ်နိုင်ပါသည်။ လေထုအရည်အသွေး စောင့်ကြည့် လေ့လာသောနေရာကို ပုံ ၂.၂-၁ တွင်ပြသထားပါသည်။





ပုံ ၂-၂-၁ လေထုအရည်အသွေးစောင့်ကြည့်လေ့လာသည့်တည်နေရာ

၂.၃ စောင့်ကြည့်လေ့လာသည့်ကာလ

လေထုအရည်အသွေး စောင့်ကြည့်လေ့လာမှုကို ၂၀၂၁ ခုနှစ်၊ ဒီဇင်ဘာလ ၂၂ ရက်နေ့မှ ဒီဇင်ဘာလ ၂၉ ရက်နေ့ အထိ (၇)ရက် ဆက်တိုက် ဆောင်ရွက်ခဲ့သည်။

၂.၄ စောင့်ကြည့်လေ့လာသည့်နည်းလမ်း

ပတ်ဝန်းကျင်လေထုအရည်အသွေး စံနမူနာရယူခြင်းနှင့် ဆန်းစစ်လေ့လာခြင်းများကို အမေရိကန် ပတ်ဝန်းကျင်ဆိုင်ရာ ထိန်းသိမ်းရေးအေဂျင်စီ (U.S. EPA) ၏ အကြံပြုချက်များကို ကိုးကား၍ ကာဗွန်မိုနောက်ဆိုဒ် (CO)၊ နိုက်ထရိုဂျင်ဒိုင်အောက်ဆိုဒ် (NO₂)၊ အမှုန်အမွှား (PM_{2.5})၊ အမှုန်အမွှား (PM₁₀) နှင့် ဆာလဖာဒိုင်အောက်ဆိုဒ် (SO₂)တို့အား စောင့်ကြည့်လေ့လာမှုများ လုပ်ဆောင်ခဲ့သည်။ ပတ်ဝန်းကျင်လေထုအရည်အသွေးကို စောင့်ကြည့်တိုင်းတာ၍ အချက်အလက်ရယူရန်အတွက် The Haz-Scanner Environmental Perimeter Air Station (EPAS)ကို အသုံးပြုခဲ့ပါသည်။ လေထုအရည်အသွေး အချက်အလက်များကို တစ်မိနစ်တိုင်း အလိုအလျောက်တိုင်းတာသည့် အရည်အသွေးအမျိုးအစား၏ အချက်အလက်များ (ကာဗွန်မိုနောက်ဆိုဒ် (CO))



သီလဝါအထူးစီးပွားရေးဇုန်အပိုင်း(ခ)ရှိစက်မှုဇုန်ဖွံ့ဖြိုးတိုးတက်ရေးအတွက်လေထုအရည်အသွေးစောင့်ကြည့်လေ့လာခြင်းအစီရင်ခံစာ
(လုပ်ငန်းလည်ပတ်နေစဉ်ကာလ အပိုင်း ၁၊ အပိုင်း ၂ နှင့် အပိုင်း ၃၊ ဒီဇင်ဘာလ ၂၀၂၁ခုနှစ်)

နိုက်ထရိုဂျင်ဒိုင်အောက်ဆိုဒ် (NO_2)၊ အမှုန်အမွှား ($\text{PM}_{2.5}$)၊ အမှုန်အမွှား (PM_{10}) နှင့် ဆာလဖာဒိုင်အောက်ဆိုဒ် (SO_2) ကို မှတ်တမ်းတင် သိမ်းဆည်းထားပါသည်။ လေထုအရည်အသွေး စောင့်ကြည့်လေ့လာသော အခြေအနေကို ပုံ ၂.၄-၁ တွင် ပြသထားပါသည်။



မှရင်း၊ ပြန်မာပျံးအင်တာနေရှင်နယ်လီမီတက်

ပုံ ၂.၄-၁ လေထုအရည်အသွေးစောင့်ကြည့်လေ့လာခြင်းအခြေအနေ

၂.၅ စောင့်ကြည့်လေ့လာမှုရလဒ်များ

ကာဗွန်မိုနောက်ဆိုဒ် (CO)၊ နိုက်ထရိုဂျင်ဒိုင်အောက်ဆိုဒ် (NO_2)၊ အမှုန်အမွှား ($\text{PM}_{2.5}$)၊ အမှုန်အမွှား (PM_{10}) နှင့် ဆာလဖာဒိုင်အောက်ဆိုဒ် (SO_2) တို့၏ လေထုအ ရည်အသွေး စောင့်ကြည့်လေ့လာမှုရလဒ်များမှ နေ့စဉ်ပျမ်းမျှ တန်ဖိုးများကို ဇယား ၂.၅-၁ တွင် ဖော်ပြထားပါသည်။ သီလဝါအထူးစီးပွားရေးဇုန် ဖွံ့ဖြိုးတိုးတက်ရေးစီမံကိန်း အပိုင်း(ခ)၏ ပတ်ဝန်းကျင်ထိခိုက်မှုဆန်းစစ်ခြင်း အစီအရင်ခံစာတွင်ပါရှိသည့် ကာဗွန်မိုနောက်ဆိုဒ် (CO)၊ နိုက်ထရိုဂျင်ဒိုင်အောက်ဆိုဒ် (NO_2)၊ အမှုန်အမွှား ($\text{PM}_{2.5}$)၊ အမှုန်အမွှား (PM_{10}) နှင့် ဆာလဖာဒိုင်အောက်ဆိုဒ် (SO_2) တို့၏ ရည်မှန်းတန်ဖိုးနှင့် နှိုင်းယှဉ်ရာ၌ ကာဗွန်မိုနောက်ဆိုဒ် (CO)၊ နိုက်ထရိုဂျင်ဒိုင်အောက်ဆိုဒ် (NO_2)၊ အမှုန်အမွှား (PM_{10}) နှင့် ဆာလဖာဒိုင်အောက်ဆိုဒ် (SO_2) တို့၏ (၇)ရက်ပျမ်းမျှတန်ဖိုးများသည် ရည်မှန်းတန်ဖိုးထက်လျော့နည်းနေသည်ကို တွေ့ရှိရသည်။ သို့သော်လည်း အမှုန်အမွှား (PM_{10}) ၏ (၁)ရက်တိုင်းတာထားသော နေ့စဉ် ပျမ်းမျှတန်ဖိုး နှင့် ဆာလဖာဒိုင်အောက်ဆိုဒ် (SO_2) ၏ (၂)ရက်တိုင်းတာထားသော နေ့စဉ် ပျမ်းမျှတန်ဖိုးမှာ ရည်မှန်း တန်ဖိုးထက် ကျော်လွန်နေသည်ကို တွေ့ရှိရသည်။ အမှုန်အမွှား ($\text{PM}_{2.5}$) ၏ (၇)ရက်ပျမ်းမျှတန်ဖိုး နှင့် (၆)ရက်တိုင်းတာထားသော နေ့စဉ် ပျမ်းမျှတန်ဖိုး သည် ရည်မှန်းတန်ဖိုးထက်ကျော်လွန်နေသည်ကို တွေ့ရှိရသည်။ သို့သော်လည်း အမှုန်အမွှား ($\text{PM}_{2.5}$) ၏ နေ့စဉ် ပျမ်းမျှတန်ဖိုးအား ဂျပန်နိုင်ငံရှိ ပတ်ဝန်းကျင်ထိန်းသိမ်းရေးဝန်ကြီးဌာန (MOEJ) ၏ ပတ်ဝန်းကျင်စံတန်ဖိုး $25 \mu\text{g}/\text{m}^3$ ($0.035 \text{ mg}/\text{m}^3$) နှင့် နှိုင်းယှဉ်ရာ၌ (၃)ရက်တိုင်းတာထားသော နေ့စဉ် ပျမ်းမျှတန်ဖိုးသာ စံတန်ဖိုးထက် ကျော်လွန်နေသည်ကို တွေ့ရှိရသည်။

ဇယား ၂.၅-၁ လေထုအရည်အသွေးစောင့်ကြည့်လေ့လာမှုရလဒ် (နေ့စဉ်ပျမ်းမျှ)

မူရင်း	ကာဗွန်မိုနောက်ဆိုက် (CO)	နိုက်ထရိုဂျင်ဒိုင်အောက်ဆိုက် (NO ₂)	အမှုန်အမွှား (PM ₁₀)	အမှုန်အမွှား (PM _{2.5})	ဆာလဖာဒိုင်အောက်ဆိုက် (SO ₂)
	mg/m ³	mg/m ³	mg/m ³	mg/m ³	mg/m ³
၂၄-၂၄ စီစဉ်ကာလ၊ ၂၀၂၁	၀.၁၀၀	၀.၀၉၂	၀.၀၃၅	၀.၀၄၃	၀.၀၂၂
၂၄-၂၄ စီစဉ်ကာလ၊ ၂၀၂၁	၀.၀၄၆	၀.၀၈၅	၀.၀၁၅	၀.၀၂၇	၀.၀၁၆
၂၄-၂၅ စီစဉ်ကာလ၊ ၂၀၂၁	၀.၁၁၇	၀.၀၈၆	၀.၀၃၃	၀.၀၄၁	၀.၀၁၅
၂၅-၂၆ စီစဉ်ကာလ၊ ၂၀၂၁	၀.၂၀၀	၀.၀၇၆	၀.၀၃၈	၀.၀၄၇	၀.၀၂၇
၂၆-၂၇ စီစဉ်ကာလ၊ ၂၀၂၁	၀.၁၂၂	၀.၀၈၂	၀.၀၄၉	၀.၀၅၇	၀.၀၂၀
၂၇-၂၈ စီစဉ်ကာလ၊ ၂၀၂၁	၀.၁၁၂	၀.၀၈၀	၀.၀၃၈	၀.၀၄၅	၀.၀၁၈
၂၈-၂၉ စီစဉ်ကာလ၊ ၂၀၂၁	၀.၁၃၀	၀.၀၈၂	၀.၀၃၅	၀.၀၄၂	၀.၀၂၀
၇၂ရက် ပျမ်းမျှတန်ဖိုး	၀.၀၃၂	၀.၀၈၃	၀.၀၃၅	၀.၀၄၃	၀.၀၂၀
စည်မှန်းတန်ဖိုး	၁၀.၂၆	၀.၁	၀.၀၂၅	၀.၀၅	၀.၀၂

မှတ်ချက်။ အနီရောင်ဖြင့် ဖော်ပြထားသော တန်ဖိုးများသည် စည်မှန်းတန်ဖိုးထက် ကျော်လွန်နေသော PM₁₀၊ PM_{2.5} နှင့် SO₂ ၏ တန်ဖိုးဖြစ်သည်။
CO (ND) နှင့် SO₂ တို့၏ စည်မှန်းတန်ဖိုးများကို (ppm) ယူနစ်မှ (mg/m³) ယူနစ်သို့ ပြောင်းလဲထားပါသည်။ ပြောင်းလဲမှုညွှန်းခြင်းမှာ အောက်ပါအတိုင်းဖြစ်ပါသည်။
(၁) (CO, mg/m³) = (CO, ppm) * (CO မော်လီကျူး၏အလေးချိန် (၂၈) / ၂၄.၄၅ (အပူချိန် ၂၅ ဒီဂရီစင်တီဂရိတ်နှင့် ၁ atm အခြေအနေ))
(၂) (NO₂, mg/m³) = (NO₂, ppm) * (NO₂ မော်လီကျူး၏အလေးချိန် (၄၆) / ၂၄.၄၅ (အပူချိန် ၂၅ ဒီဂရီစင်တီဂရိတ်နှင့် ၁ atm အခြေအနေ))
(၃) (SO₂, mg/m³) = (SO₂, ppm) * (SO₂ မော်လီကျူး၏အလေးချိန် (၆၄) / ၂၄.၄၅ (အပူချိန် ၂၅ ဒီဂရီစင်တီဂရိတ်နှင့် ၁ atm အခြေအနေ))
မူရင်း၊ မြန်မာ့သမ္မတနိုင်ငံကာလအရည်အသွေးစံချိန်စာညွှန်း

လေထုအရည်အသွေးစောင့်ကြည့်လေ့လာသည့် နေရာ-၁ (AQ-1)တွင် လေတိုက်ခတ်ရာအရပ်နှင့် လေတိုက်နှုန်းကို တိုင်းတာခဲ့ပါသည်။ တိုင်းတာထားသော လေတိုက်ခတ်ရာအရပ်နှင့် လေတိုက်နှုန်းတို့၏ တစ်နာရီပျမ်းမျှ တန်ဖိုးများကို နောက်ဆက်တွဲ-၁ တွင်ဖော်ပြထားပါသည်။ လေထုအရည်အသွေး စောင့်ကြည့်လေ့လာသော တည်နေရာ၏ အခြေအနေနှင့် လေတိုက်ခတ်ရာအရပ်တို့အား ပုံ ၂.၅-၁ တွင် ပြသထားပါသည်။ လေတိုက်ခတ်ရာအရပ်ပေါ်မူတည်၍ အနောက်-အနောက်မြောက် (WNW)၊ အနောက်မြောက်(NW)၊ မြောက်-အနောက်မြောက်(NNW)၊ မြောက်(N)၊ မြောက်-အရှေ့မြောက် (NNE)၊ အရှေ့မြောက်(NE)၊ အရှေ့-အရှေ့မြောက်(ENE) နှင့် အရှေ့(E) အရပ်တို့မှ တိုက်ခတ်သောလေမှာ ဇုန်အပိုင်း(ခ)၏ လုပ်ငန်းခွင်မှ တိုက်ခတ်ကြောင်းခန့်မှန်းနိုင်ပါသည်။

သီလဝါအထူးစီးပွားရေးဇုန်အပိုင်း(ခ)ရိုက်ဖူးနိမ့်ခြံတိုက်ကပ်ရာအတွက်လေထုအရည်အသွေးစောင့်ကြည့်လေ့လာခြင်းအစီရင်ခံစာ
(လုပ်ငန်းလည်ပတ်နေစဉ်ကာလ အပိုင်း ၁၊ အပိုင်း ၂ နှင့် အပိုင်း ၃၊ ဒီဇင်ဘာလ ၂၀၂၁ခုနှစ်)



ပုံ ၂.၅-၁ လေထုအရည်အသွေးစောင့်ကြည့်လေ့လာသောတည်နေရာ နှင့် လေတိုက်ခတ်ရာအရပ်အခြေအနေ

မှတ်ချက်။ မြေတောင်(N) မြောက်-အရှေ့မြေတောင်(NNE) အရှေ့မြေတောင်(NE) အရှေ့-အရှေ့မြေတောင်(ENE) အရှေ့(E) အရှေ့-အရှေ့တောင်(ESE) အရှေ့တောင်(SE) တောင်-အရှေ့တောင်(SSE) တောင်(S) တောင်-အနောက်တောင်(SSW) အနောက်တောင်(SW) အနောက်-အနောက်တောင်(WSW) အနောက်(W) အနောက်-အနောက်မြေတောင်(WNW) အနောက်မြေတောင်(NW) မြေတောင်အနောက်မြေတောင်(NNW)

စောင့်ကြည့်လေ့လာသည့်ကာလအတွင်း ဆောက်လုပ်ရေးလုပ်ငန်းများဆောင်ရွက်ခြင်းမရှိပါ။

စောင့်ကြည့်လေ့လာသည့် (၇)ရက်အတွင်း ကျွန်ုပ်တို့နေသော အချိန်စုစုပေါင်း ခြုံငုံသုံးသပ်ချက်များကို ဇယား ၂.၅-၂ တွင် ဖော်ပြထားပါသည်။ တိုင်းတာထားသော နေ့စဉ် ပျမ်းမျှတန်ဖိုးများအရ အမှုန်အမွှား (PM_{10}) ၏ နေ့စဉ်ပျမ်းမျှတန်ဖိုး (ပထမနေ့ နှင့် တတိယနေ့ မှ သတ္တမနေ့အထိ) ရလဒ်များ၊ အမှုန်အမွှား ($PM_{2.5}$) ၏ နေ့စဉ်ပျမ်းမျှတန်ဖိုး (ပဉ္စမနေ့) ရလဒ်များ နှင့် ဆာလဖာဒိုင်အောက်ဆိုဒ်(SO_2)၏ နေ့စဉ်ပျမ်းမျှတန်ဖိုး (ပထမနေ့ နှင့် စတုတ္ထနေ့အထိ) ရလဒ်များသည် ရည်မှန်းတန်ဖိုး ထက် ကျော်လွန်နေသည်ကို တွေ့ရှိရသည်။

သီလဝါအထူးစီးပွားရေးဇုန်အပိုင်း(ခ)စိုက်ပျိုးမှုဇုန်၊ ပြိုလဲတိုက်ရေအတွက်လေထုအရည်အသွေးစောင့်ကြည့်လေ့လာခြင်းအစီရင်ခံစာ
(လုပ်ငန်းစဉ်ပတ်နေ့စဉ်ကာလ အပိုင်း ၁၊ အပိုင်း ၂ နှင့် အပိုင်း ၃၊ စီမံကိန်းကာလ ၂၀၂၁ခုနှစ်)

ဇယား ၂.၅-၂ ကျော်လွန်သောအချိန်စုစုပေါင်း

	တိုင်းတာသော အမျိုးအစားများ	ကျော်လွန်သော အချိန်စုစုပေါင်း
ပထမနေ့မှ သတ္တမနေ့အထိ	အမှုန်အမွှား (PM ₁₀)	၈၂
	အမှုန်အမွှား (PM _{2.5})	၆၃
	ဆာလဖာဒိုင်အောက်ဆိုက် (SO ₂)	၃၁

မှရင်း၊ ပြန်လည်အင်တာနေရှင်နယ်လ်မိကက်

ဇယား ၂.၅-၃ ကျော်လွန်သောအချိန်စုစုပေါင်း နှင့် အမှုန်အမွှား (PM_{2.5}) ၏ လေတိုက်ခတ်ရာအရပ်အကျဉ်းချုပ်

နေ့	အချိန်	အမှုန်အမွှား (PM _{2.5})	လေတိုက်ရပ်
ပထမနေ့	၁၂:၀၀ - ၁၂:၅၉	၀.၁၁၃၉	တောင်-အနောက်တောင် (SSW)
	၁၄:၀၀ - ၁၄:၅၉	၀.၀၃၇၇	အရှေ့တောင် (SE)
	၁၅:၀၀ - ၁၅:၅၉	၀.၀၃၇၅	အရှေ့တောင် (SE)
	၁၆:၀၀ - ၁၆:၅၉	၀.၀၇၇၇	အရှေ့ (E)
	၁၉:၀၀ - ၁၉:၅၉	၀.၀၈၈၈	တောင်-အနောက်တောင် (SSW)
	၂၀:၀၀ - ၂၀:၅၉	၀.၀၇၁၁	အရှေ့တောင် (SE)
	၂၁:၀၀ - ၂၁:၅၉	၀.၀၅၅၈	အရှေ့-အရှေ့မြောက် (ENE)
	၀၂:၀၀ - ၀၂:၅၉	၀.၀၆၇၃	အနောက်-အနောက်တောင် (WSW)
	၀၃:၀၀ - ၀၃:၅၉	၀.၀၄၄၄	အနောက်တောင် (SW)
	၀၄:၀၀ - ၀၄:၅၉	၀.၀၆၇၄	အရှေ့ (E)
တတိယနေ့	၀၂:၀၀ - ၁၂:၅၉	၀.၀၆၇၃	အရှေ့ (E)
	၁၃:၀၀ - ၁၃:၅၉	၀.၀၇၇၈	အရှေ့တောင် (SE)
	၁၅:၀၀ - ၁၅:၅၉	၀.၀၈၇၄	တောင်-အနောက်တောင် (SSW)
	၁၆:၀၀ - ၁၆:၅၉	၀.၀၃၇၇	တောင် (S)
	၁၈:၀၀ - ၁၈:၅၉	၀.၀၆၆၆	အနောက်တောင် (SW)
	၁၉:၀၀ - ၁၉:၅၉	၀.၀၉၁၁	အရှေ့-အရှေ့တောင် (ESE)
	၂၀:၀၀ - ၂၀:၅၉	၀.၁၀၈၈	အရှေ့တောင် (SE)
	၂၁:၀၀ - ၂၁:၅၉	၀.၀၆၇၇	အနောက်-အနောက်မြောက် (WNW)
	၁၄:၀၀ - ၁၄:၅၉	၀.၀၄၄၄	အနောက်တောင် (SW)
စတုတ္ထနေ့	၁၅:၀၀ - ၁၅:၅၉	၀.၀၇၁၁	အနောက်-အနောက်တောင် (WSW)
	၁၆:၀၀ - ၁၆:၅၉	၀.၀၄၄၄	အနောက်-အနောက်တောင် (WSW)
	၁၇:၀၀ - ၁၇:၅၉	၀.၀၂၇၈	အနောက်တောင် (SW)
	၁၈:၀၀ - ၁၈:၅၉	၀.၀၈၂၂	အနောက် (W)
	၁၉:၀၀ - ၁၉:၅၉	၀.၀၉၇၀	အနောက် (W)
	၂၀:၀၀ - ၂၀:၅၉	၀.၀၅၇၈	အရှေ့မြောက် (NE)
	၂၁:၀၀ - ၂၁:၅၉	၀.၁၀၈၈	အရှေ့-အရှေ့မြောက် (ENE)
	၂၂:၀၀ - ၂၂:၅၉	၀.၁၁၃၉	အရှေ့တောင် (SE)
	၂၃:၀၀ - ၂၃:၅၉	၀.၀၆၇၃	အနောက်-အနောက်မြောက် (WNW)
	၀၆:၀၀ - ၀၆:၅၉	၀.၀၂၇၈	အရှေ့-အရှေ့တောင် (ESE)
	၀၇:၀၀ - ၀၇:၅၉	၀.၀၆၇၇	အနောက်မြောက် (NW)
	၀၅:၀၀ - ၀၅:၅၉	၀.၀၆၇၈	အနောက်တောင် (SW)
ပဉ္စမနေ့	၁၆:၀၀ - ၁၆:၅၉	၀.၀၅၄၄	တောင်-အနောက်တောင် (SSW)

သီလဝါအတွင်းပွားများနေ့နှင့်အပိုင်း(၁)ရှိစက်မှုနှင့်မြို့တော်ဟက်ရေအတွက်လေထုအရည်အသွေးစောင့်ကြည့်လေ့လာခြင်းအစီရင်ခံစာ
(လုပ်ငန်းလည်ပတ်နေဆဲကာလ အပိုင်း ၁၊ အပိုင်း ၂ နှင့် အပိုင်း ၃၊ စီစဉ်ကာလ ၂၀၂၁ခုနှစ်)

နေ့	အချိန်	အမှန်အမှား (PM ₁₀)	မလတိုက်ရပ်
	၁၇:၀၀ - ၁၇:၅၅	၀.၁၀၅	တောင်-အနောက်တောင် (SSW)
	၁၈:၀၀ - ၁၈:၅၅	၀.၀၄၃	အနောက်တောင် (SW)
	၁၉:၀၀ - ၁၉:၅၅	၀.၀၂၈	တောင် (S)
	၂၀:၀၀ - ၂၀:၅၅	၀.၀၆၂	တောင်-အနောက်တောင် (SSW)
	၂၁:၀၀ - ၂၁:၅၅	၀.၀၅၁	အနောက် (W)
	၂၂:၀၀ - ၂၂:၅၅	၀.၀၅၄	အနောက် (W)
	၂၃:၀၀ - ၂၃:၅၅	၀.၀၆၁	အနောက်မြောက် (NW)
	၀၀:၀၀ - ၀၀:၅၅	၀.၀၇၈	အရှေ့မြောက် (NE)
	၀၁:၀၀ - ၀၁:၅၅	၀.၀၇၀	အရှေ့မြောက် (NE)
	၀၂:၀၀ - ၀၂:၅၅	၀.၀၃၇	တောင်-အနောက်တောင် (SSW)
	၀၃:၀၀ - ၀၃:၅၅	၀.၀၆၅	အရှေ့ (E)
	၀၄:၀၀ - ၀၄:၅၅	၀.၀၅၅	အရှေ့မြောက် (NE)
	၀၅:၀၀ - ၀၅:၅၅	၀.၀၇၃	အနောက်-အနောက်မြောက် (WNW)
	၀၆:၀၀ - ၀၆:၅၅	၀.၀၆၄	အနောက်-အနောက်တောင် (WSW)
	၀၇:၀၀ - ၀၇:၅၅	၀.၀၃၀	အရှေ့-အရှေ့မြောက် (ENE)
အညွှန်း	၁၈:၀၀ - ၁၈:၅၅	၀.၀၄၇	အရှေ့တောင် (SE)
	၁၉:၀၀ - ၁၉:၅၅	၀.၀၂၈	အရှေ့တောင် (SE)
	၁၉:၀၀ - ၁၉:၅၅	၀.၀၄၆	အရှေ့တောင် (SE)
	၁၉:၀၀ - ၁၉:၅၅	၀.၀၅၅	အရှေ့-အရှေ့တောင် (ESE)
	၂၀:၀၀ - ၂၀:၅၅	၀.၀၅၄	တောင် (S)
	၂၁:၀၀ - ၂၁:၅၅	၀.၀၈၅	အနောက်တောင် (SW)
	၂၂:၀၀ - ၂၂:၅၅	၀.၀၈၅	တောင်- အရှေ့တောင် (SSE)
	၂၃:၀၀ - ၂၃:၅၅	၀.၀၃၄	အရှေ့ (E)
	၀၀:၀၀ - ၀၀:၅၅	၀.၀၇၇	အရှေ့-အရှေ့မြောက် (ENE)
	၀၁:၀၀ - ၀၁:၅၅	၀.၀၄၁	အရှေ့တောင် (SE)
	၀၂:၀၀ - ၀၂:၅၅	၀.၀၅၇	တောင် (S)
	၀၃:၀၀ - ၀၃:၅၅	၀.၀၅၆	အနောက် (W)
	၀၄:၀၀ - ၀၄:၅၅	၀.၀၅၁	မြောက်- အရှေ့မြောက် (NNE)
	၀၅:၀၀ - ၀၅:၅၅	၀.၀၄၈	အရှေ့တောင် (SE)
	၀၆:၀၀ - ၀၆:၅၅	၀.၀၄၄	အနောက် (W)
အညွှန်း	၀၇:၀၀ - ၀၇:၅၅	၀.၀၄၃	မြောက် (N)
	၁၇:၀၀ - ၁၇:၅၅	၀.၀၃၅	အရှေ့ (E)
	၁၇:၀၀ - ၁၇:၅၅	၀.၀၄၄	တောင်- အရှေ့တောင် (SSE)
	၁၈:၀၀ - ၁၈:၅၅	၀.၀၇၆	တောင်- အရှေ့တောင် (SSE)
	၁၉:၀၀ - ၁၉:၅၅	၀.၀၇၇	အရှေ့-အရှေ့တောင် (ESE)
	၂၀:၀၀ - ၂၀:၅၅	၀.၀၆၇	အရှေ့ (E)
	၂၁:၀၀ - ၂၁:၅၅	၀.၀၇၇	အရှေ့ (E)
	၂၂:၀၀ - ၂၂:၅၅	၀.၀၅၁	အရှေ့-အရှေ့တောင် (ESE)
	၂၃:၀၀ - ၂၃:၅၅	၀.၀၆၈	အရှေ့-အရှေ့မြောက် (ENE)
	၀၀:၀၀ - ၀၀:၅၅	၀.၀၄၇	အနောက်-အနောက်တောင် (WSW)
	၀၂:၀၀ - ၀၂:၅၅	၀.၀၃၁	တောင်-အနောက်တောင် (SSW)

သီလဝါအထူးစီးပွားရေးဇုန်အပိုင်း(ခ)ရှိစက်မှုဇုန်၌ဖြူးတိုးတက်ရေးအတွက်လေထုအရည်အသွေးစောင့်ကြည့်စောင့်ရှောက်ခြင်းအစီရင်ခံစာ
(လုပ်ငန်းလည်ပတ်နေဆဲကာလ အပိုင်း ၁၊ အပိုင်း ၂ နှင့် အပိုင်း ၃၊ ဒီဇင်ဘာလ ၂၀၂၁ခုနှစ်)

မန.	အချိန်	အမှုန်အမွှား (PM ₁₀)	လေတိုက်ရပ်
	၀၃:၀၀ ~ ၀၃:၅၉	၀.၀၃၈	အရှေ့-အရှေ့တောင် (ESE)
	၀၄:၀၀ ~ ၀၄:၅၉	၀.၀၃၁	အနောက်-အနောက်မြောက် (WNW)
	၀၅:၀၀ ~ ၀၅:၅၉	၀.၀၃၈	အနောက်တောင် (SW)
	၀၆:၀၀ ~ ၀၆:၅၉	၀.၀၄၁	အနောက်-အနောက်တောင် (WSW)

မှတ်ချက်- အချိန် များသည် ရွှေ့ဖုန်းတန်းဖိုး (15.၀၂၅ m/s)၊ ထက် အကွက်ပုံနှိပ်နေသော PM₁₀ ၏ အချိန် များ ဖြစ်သည်။

မှတ်ချက်- ပြန်မာဦးအင်တာနေရှင်နယ်လီမိတက်

သီလဝါအတွင်းစီးပွားရေးဇုန်အပိုင်း(ခ)ရှိဇက်မှုဇုန်နှင့်ပြီးတိုးတက်ရေးအတွက်လေ့လာရည်အသွေးစောင့်ကြည့်လေ့လာခြင်းအစီရင်ခံစာ
(လုပ်ငန်းလည်ပတ်နေစဉ်ကာလ အပိုင်း ၁- အပိုင်း ၂ နှင့် အပိုင်း ၃၊ ဒီဇင်ဘာလ ၂၀၂၁ခုနှစ်)

ဇယား ၂.၅-၆ နေရာ-၁ (AQ-1)၏ လေတိုက်ခတ်ရာအရပ်အကျဉ်းချုပ်

လေတိုက်ရပ်	(၇)ရက်	နေ့အဖို့နံ	ညအဖို့နံ	စုန်အပိုင်း (ခ) အတွင်း/အပြင်	
မြောက် (N)	၁၆.၁ ရာခိုင်နှုန်း	၁၉.၆ ရာခိုင်နှုန်း	၁၂.၅ ရာခိုင်နှုန်း	၄၉.၈ ရာခိုင်နှုန်း	စုန်အပိုင်း (ခ) အတွင်းမှ တိုက်ခတ် သောလေ
မြောက်-အရှေ့မြောက် (NNE)	၇.၉ ရာခိုင်နှုန်း	၉.၇ ရာခိုင်နှုန်း	၆.၂ ရာခိုင်နှုန်း		
အရှေ့မြောက် (NE)	၁၂.၈ ရာခိုင်နှုန်း	၉.၅ ရာခိုင်နှုန်း	၁၆.၁ ရာခိုင်နှုန်း		
အရှေ့-အရှေ့မြောက် (ENE)	၉.၄ ရာခိုင်နှုန်း	၃.၆ ရာခိုင်နှုန်း	၁၅.၃ ရာခိုင်နှုန်း		
အရှေ့ (E)	၃.၆ ရာခိုင်နှုန်း	၂.၆ ရာခိုင်နှုန်း	၄.၆ ရာခိုင်နှုန်း		
အရှေ့-အရှေ့တောင် (ESE)	၄.၅ ရာခိုင်နှုန်း	၂.၆ ရာခိုင်နှုန်း	၆.၃ ရာခိုင်နှုန်း	၃၄.၀ ရာခိုင်နှုန်း	စုန်အပိုင်း (ခ) အပြင်မှ တိုက်ခတ် သောလေ
အရှေ့တောင် (SE)	၅.၄ ရာခိုင်နှုန်း	၆.၀ ရာခိုင်နှုန်း	၄.၈ ရာခိုင်နှုန်း		
တောင်-အရှေ့တောင် (SSE)	၂.၅ ရာခိုင်နှုန်း	၃.၀ ရာခိုင်နှုန်း	၂.၀ ရာခိုင်နှုန်း		
တောင် (S)	၁.၈ ရာခိုင်နှုန်း	၁.၆ ရာခိုင်နှုန်း	၂.၀ ရာခိုင်နှုန်း		
တောင်-အနောက်တောင် (SSW)	၂.၁ ရာခိုင်နှုန်း	၂.၈ ရာခိုင်နှုန်း	၁.၄ ရာခိုင်နှုန်း		
အနောက်တောင် (SW)	၅.၇ ရာခိုင်နှုန်း	၆.၂ ရာခိုင်နှုန်း	၅.၂ ရာခိုင်နှုန်း		
အနောက်-အနောက်တောင် (WSW)	၇.၄ ရာခိုင်နှုန်း	၆.၅ ရာခိုင်နှုန်း	၈.၃ ရာခိုင်နှုန်း		
အနောက် (W)	၄.၈ ရာခိုင်နှုန်း	၃.၈ ရာခိုင်နှုန်း	၅.၈ ရာခိုင်နှုန်း		
အနောက်-အနောက်မြောက် (WNW)	၃.၂ ရာခိုင်နှုန်း	၃.၆ ရာခိုင်နှုန်း	၂.၈ ရာခိုင်နှုန်း	၁၆.၂ ရာခိုင်နှုန်း	စုန်အပိုင်း (ခ) အတွင်းမှ တိုက်ခတ် သောလေ
အနောက်မြောက် (NW)	၄.၃ ရာခိုင်နှုန်း	၆.၃ ရာခိုင်နှုန်း	၂.၂ ရာခိုင်နှုန်း		
မြောက်အနောက်မြောက် (NNW)	၈.၇ ရာခိုင်နှုန်း	၁၂.၇ ရာခိုင်နှုန်း	၄.၈ ရာခိုင်နှုန်း		

မှရင်း၊ မြန်မာ့သို့အင်တာနေရှင်နယ်တီမီတင်

အခန်း ၃ နိဂုံးချုပ် နှင့် အကြံပြုချက်များ

စောင့်ကြည့်လေ့လာသော (၇)ရက်ကာလအတွင်း ကာဗွန်မိုနောက်ဆိုဒ် (CO)၊ နိုက်ထရိုဂျင်ဒိုင်အောက်ဆိုဒ် (NO₂)၊ အမှုန်အမွှား (PM₁₀) နှင့် ဆာလဖာဒိုင်အောက်ဆိုဒ် (SO₂) တို့၏ (၇)ရက်ပျမ်းမျှ လေထုအရည်အသွေး ရလဒ်များသည် ရည်မှန်းတန်ဖိုးထက် ကျော်လွန်နေခြင်း မရှိသောကြောင့် ဘေးအန္တရာယ်ပတ်ဝန်းကျင်သို့ ထိခိုက်မှုမရှိပါ။ အမှုန်အမွှား (PM_{2.5}) ၏ (၇)ရက်ပျမ်းမျှတန်ဖိုး သည် ရည်မှန်း တန်ဖိုးထက် ကျော်လွန်နေသည်ကို တွေ့ရှိရသည်။ ထို့အပြင် အမှုန်အမွှား (PM_{2.5})၏ (၆)ရက်တိုင်းတာထားသော နေ့စဉ် ပျမ်းမျှတန်ဖိုး၊ ထို့အပြင် အမှုန်အမွှား (PM₁₀)၏ (၁)ရက်တိုင်းတာထားသော နေ့စဉ် ပျမ်းမျှတန်ဖိုး နှင့် ဆာလဖာဒိုင်အောက်ဆိုဒ် (SO₂) ၏ (၂)ရက်တိုင်းတာထားသော နေ့စဉ် ပျမ်းမျှတန်ဖိုး တို့သည် ရည်မှန်း တန်ဖိုးထက် ကျော်လွန်နေသည်ကို တွေ့ရှိရသည်။ စောင့်ကြည့်လေ့လာသည့် (၇)ရက်အတွင်း အမှုန်အမွှား (PM_{2.5}) ၏ နေ့စဉ်ပျမ်းမျှတန်ဖိုး (ပထမနေ့ နှင့် တတိယနေ့ မှ သတ္တမနေ့အထိ) ရလဒ်များ၊ အမှုန်အမွှား (PM₁₀) ၏ နေ့စဉ်ပျမ်းမျှတန်ဖိုး (ပဉ္စမနေ့ ရလဒ်များ နှင့် ဆာလဖာဒိုင်အောက်ဆိုဒ်(SO₂)၏ နေ့စဉ်ပျမ်းမျှတန်ဖိုး (ပထမနေ့ နှင့် စတုတ္ထနေ့အထိ) ရလဒ်များသည် ရည်မှန်းတန်ဖိုး ထက် ကျော်လွန်နေသည်ကို တွေ့ရှိရသည်။

စောင့်ကြည့်လေ့လာသည့် (၇)ရက်တာကာလအတွင်း အမှုန်အမွှား (PM_{2.5}) ၏ ကျော်လွန်သောအချိန်စုစုပေါင်းမှာ (၈၂) နာရီ ဖြစ်ပါသည်။ လေတိုက်ခတ်ရာအရပ်ကို တိုင်းတာသောကိရိယာ၏ တိုင်းတာသော ရလဒ်အရ ကျော်လွန်သော အချိန်စုစုပေါင်းမှာ (၇၇) နာရီ ဖြစ်ပြီး မြောက် (N)၊ မြောက်- အရှေ့မြောက် (NNE)၊ အရှေ့မြောက် (NE)၊ အရှေ့-အရှေ့မြောက် (ENE)၊ အရှေ့ (E)၊ အရှေ့-အရှေ့တောင် (ESE)၊ အရှေ့တောင် (SE)၊ တောင်- အရှေ့တောင် (SSE)၊ တောင် (S)၊ တောင်-အနောက်တောင် (SSW)၊ အနောက်တောင် (SW)၊ အနောက်- အနောက်တောင် (WSW)၊ အနောက် (W)၊ အနောက်-အနောက်မြောက် (WNW) နှင့် အနောက်မြောက် (NW) တို့မှ တိုက်ခတ်ခြင်း ဖြစ်ပါသည်။

စောင့်ကြည့်လေ့လာသည့် (၇)ရက်တာကာလအတွင်း အမှုန်အမွှား (PM₁₀) ၏ ကျော်လွန်သောအချိန်စုစုပေါင်းမှာ (၆၃) နာရီ ဖြစ်ပါသည်။ လေတိုက်ခတ်ရာအရပ်ကို တိုင်းတာသောကိရိယာ၏ တိုင်းတာသော ရလဒ်အရ ကျော်လွန်သော အချိန်စုစုပေါင်းမှာ (၁၃) နာရီ ဖြစ်ပြီး အရှေ့မြောက် (NE)၊ အရှေ့ (E)၊ တောင်-အနောက်တောင် (SSW)၊ အနောက်တောင် (SW)၊ အနောက်-အနောက်တောင် (WSW)၊ အနောက် (W)၊ အနောက်-အနောက်မြောက် (WNW) နှင့် အနောက်မြောက် (NW) မှ တိုက်ခတ်ခြင်း ဖြစ်ပါသည်။

အမှုန်အမွှား (PM_{2.5}) နှင့် အမှုန်အမွှား (PM₁₀) တို့၏ ထုတ်လွှတ်နိုင်ခြေ ရှိသော အရင်းမြစ်များမှာ ဇုန်အပိုင်း(၁)၏ အပြင်ဘက်တွင်ရှိသော မြေသားလမ်းများမှ သဘာဝအတိုင်း ဖြစ်ပေါ်လာသော ဇုန်မှုန်များကြောင့်လည်းကောင်း၊ စောင့်ကြည့်လေ့လာသော ဧရိယာ သယ်ယူပို့ဆောင်ရေး လုပ်ငန်းများ လုပ်ဆောင်ခြင်းကြောင့် လည်းကောင်း ဖြစ်နိုင်ပါသည်။

အမေရိကန် ပတ်ဝန်းကျင် ထိန်းသိမ်းရေး အေဂျင်စီ (EPA) နှင့် WHO တို့၏ ကျန်းမာရေး အကျိုးသက်ရောက်မှု အရ အန္တရာယ်ကင်းသော ထိတွေ့မှုအဆင့် သို့မဟုတ် ဆိုးရွားသော ကျန်းမာရေးဆိုင်ရာ ဆိုးကျိုးများ မဖြစ်ပေါ်နိုင်သည့်



အနိမ့်ဆုံး သတ်မှတ်ထားသည့် အထောက်အထားမရှိပါ။ အမှုန်အမွှား (PM_{2.5}) နှင့် အမှုန်အမွှား (PM₁₀) ထိတွေ့မှုကြောင့် ဒေသလူဦးရေ၏ သက်တမ်းမှာ ပျမ်းမျှအားဖြင့် ၈.၆ လ အထိ လျော့နည်းစေသည်။ အမှုန်အမွှား (PM_{2.5}) နှင့် အမှုန်အမွှား (PM₁₀) တို့၏ ခဏတာထိတွေ့မှု (နာရီ၊ ရက်) သည် အဆုတ်ရောဂါကို ပိုမိုဆိုးရွားစေပြီး ပန်းနာရင်ကျပ်ရောဂါနှင့် စူးရှသော ရောင်ရမ်းနာ ရောင်ရမ်းခြင်းများ ဖြစ်စေနိုင်သည်။ နှလုံးရောဂါ ရှိသူများအနေဖြင့် ထိုခဏတာ ထိတွေ့မှုသည် နှလုံးရောဂါနှင့် မူမမှန်မကန်ဖြစ်ခြင်း တို့နှင့် ဆက်စပ်လျက်ရှိသည်။ သို့သော် ကျန်းမာသော ကလေးများနှင့် အရွယ်ရောက်ပြီးသော လူများသည် ထိုခဏတာ ထိတွေ့မှုကြောင့် ပြင်းထန်သော သက်ရောက်မှုများခံစားခဲ့ရခြင်းမရှိပါ။ ရေရှည်ထိတွေ့မှု (လများ၊ နှစ်များ)သည် အဆုတ်၏ လုပ်ဆောင်မှု လျော့ချခြင်း၊ နာတာရှည် လည်ချောင်းနာခြင်းနှင့် အချိန်မတိုင်မှီ သေဆုံးခြင်း ကဲ့သို့သော ပြဿနာများနှင့် ဆက်စပ်နေသည်။ နေ့စဉ် ပျမ်းမျှတန်ဖိုးသည် ရည်မှန်း တန်ဖိုးထက် ကျော်လွန်နေသော်လည်း ကျွန်ုပ်တို့၏ ဝန်ကြီးဌာန (MOE) မှ သတ်ပေးချက်လမ်းညွှန်ချက်အဆင့် ၁ (Level 1 Guideline for alert) မှ ထုတ်ပြန်ထားသောတန်ဖိုးဖြစ်သော ၇၀ $\mu\text{g}/\text{m}^3$ (၀.၀၇ mg/m^3) နှင့် တူညီသော (သို့မဟုတ်)လျော့နည်းသောတန်ဖိုး ထက်မကျော်လွန်ကြောင်း တွေ့ရှိရသည်။ ထို့ကြောင့် ကျန်းမာရေးကို ဆိုးရွားစွာ ထိခိုက်မှုမရှိဟု ယူဆကာ ပြင်ပလူဝင်ရှားမှုများကိုလည်း ရောင်ရှားရန် မလိုအပ်ပါ။ သို့သော်လည်း ထိခိုက်လွယ်သော သက်ရောက်ခံများ (sensitive receptors) အတွက် ၎င်းတို့၏ကျန်းမာရေးအခြေအနေအပေါ်ကို ဖြစ်နိုင်သော သက်ရောက်မှု ဂရုပြုရန်လိုအပ်သည်။

စောင့်ကြည့်လေ့လာသည့် (၇)ရက်တာကာလအတွင်း ဆာလဖာဒိုင်အောက်ဆိုဒ် (SO₂)၏ ကျော်လွန်သော အချိန်စုစုပေါင်းမှာ (၃၁) နာရီ ဖြစ်ပါသည်။ လေတိုက်ခတ်ရာအရပ်ကို တိုင်းတာသောကိရိယာ၏ တိုင်းတာသော ရလဒ်အရ ကျော်လွန်သော အချိန်စုစုပေါင်းမှာ (၁၂) နာရီ ဖြစ်ပြီး အရှေ့တောင် (SE)၊ တောင်- အရှေ့တောင် (SSE)၊ တောင်-အနောက်တောင် (SSW)၊ အနောက်တောင် (SW)၊ အနောက်-အနောက်တောင် (WSW)၊ အနောက် (W) နှင့် အနောက်မြောက် (WNW) တို့မှ တိုက်ခတ်ခြင်း ဖြစ်ပါသည်။ ဆာလဖာဒိုင်အောက်ဆိုဒ် (SO₂) စာတိငွေ ထုတ်လွှတ်နိုင်ခြေ ရှိသော အရင်းမြစ်များမှာ စောင့်ကြည့်လေ့လာသော နေရာ၏ အနီးတစ်ဝိုက်ရှိ ကားလမ်းမပေါ်တွင် သွားလာနေသော ယာဉ်များမှ လောင်စာများ လောင်ကျွမ်းခြင်းနှင့် သီလဝါဆိပ်ကမ်း၏ လုပ်ငန်း ဆောင်ရွက်မှုများကြောင့် ဖြစ်ပေါ်လာသောဓာတ်ငွေ့များ၊ ပြည်တွင်းစက်မှုဇုန်၏ လုပ်ငန်း ဆောင်ရွက်မှုများနှင့် ဇုန်အပိုင်း(ခ)၏ လုပ်ငန်းဆောင်ရွက်မှုများကြောင့် ဖြစ်နိုင်ပါသည်။ အမေရိကန်ပြည်ထောင်စုတွင် အဆိပ်အတောက် ဖြစ်စေသော ပစ္စည်းများနှင့် ရောဂါများဆိုင်ရာ မှတ်ပုံတင်ဌာနမှ အများပြည်သူ ကျန်းမာရေးကြေငြာချက်တွင် အစီရင်ခံတင်ပြထားသော ဆာလဖာဒိုင်အောက်ဆိုဒ် (SO₂) ပမာဏ ၁၀၀ ppm (၂၆၁.၈ mg/m^3)သည် အသက်အန္တရာယ်နှင့် ကျန်းမာရေးအတွက် ချက်ချင်းအန္တရာယ်ပေးနိုင်ပါသည်။ ၀.၄ ppm မှ ၃ ppm (၁.၀၅ mg/m^3 မှ ၇.၈၅ mg/m^3) အထိပမာဏကို နှစ်(၂၀)နှင့်အထက် ရေရှည်ထိတွေ့သောအခါတွင် အဆုတ်၏လုပ်ဆောင်နိုင်မှုများသည် ပြောင်းလဲလာနိုင်ပါသည်။ ထို့ကြောင့် စောင့်ကြည့်လေ့လာသော ကာလအတွင်း ဆာလဖာဒိုင်အောက်ဆိုဒ် (SO₂)၏တန်ဖိုးမှာ ရည်မှန်းတန်ဖိုးထက် ကျော်လွန်နေကြောင်း တွေ့ရှိရသော်လည်း လူကျန်းမာရေးအပေါ် ထိခိုက်နိုင်သည့် ထင်ရှားသော သက်ရောက်မှုများ မရှိကြောင်း တွေ့ရှိရပါသည်။



နောက်ဆက်တွဲ-၁ ၁ နာရီပျမ်းမျှလေထုအရည်အသွေးတန်ဖိုး



နောက်ဆက်တွဲ-၂ လေထုအရည်အသွေးတိုင်းတာသည့်စက်ကို
စံကိုက်ညီထားသောလက်မှတ်



သီလဝါအတွေးစီးပွားရေးနှင့်ဆိုင်ရာပြန်လှန်မှုနှင့် ပြုပြင်ထိန်းသိမ်းရေးအတွက် လေထုအရည်အသွေးစောင့်ကြည့်ရေးလက်မှတ်အစီရင်ခံစာ
(လုပ်ငန်းအည်ပတ်နေစဉ်ကာလ အပိုင်း ၁၊ အပိုင်း ၂ နှင့် အပိုင်း ၃၊ ဒီဇင်ဘာလ ၂၀၂၁ခုနှစ်)



SYSTEM HEALTH CHECK REPORT

INFORMATION

Instrument: F30-0231001

Model: FPA5

Serial number: 014010

Unit Sensor: CO, NO2, VOC, NO, NH3, PM2.5, PM2.5

Customer: AGRANASA EGYPT (INTERNATIONAL) LTD

Date: 21st December 2021

Check List

Physical Check: OK

Supply Voltage Check: OK

PM10 Air Flow Check: OK

PM2.5 Air Flow Check: OK

Internal Backup Battery Voltage Check: OK

NH3 Sensor Health Check: Moderate

CO, VOC, NO2, NO Sensor Health Check: All Good

Lithium Battery Voltage Check: OK

Data Logging Check: OK

Data Downloading Check: OK

Recommend

Need to replace sensor of gas scrubber (schedule is 6 month)

Need to replace internal battery (schedule is 6 month)

Need to perform battery calibration (in field) calibration (schedule is 12 month)



Performed by

Thaw Saad Hoss

Technical Service Engineer



Approved by

Maysa El

Technical Service Manager



သီလဝါအထူးစီးပွားရေးဇုန် အပိုင်း(ခ)ရှိ
စက်မှုဇုန်ဖွံ့ဖြိုးတိုးတက်ရေးအတွက်
ဆူညံသံ နှင့် တုန်ခါမှု စောင့်ကြည့်လေ့လာခြင်း အစီရင်ခံစာ
(လုပ်ငန်းလည်ပတ်နေစဉ်ကာလ အပိုင်း ၁၊ အပိုင်း ၂ နှင့် အပိုင်း ၃)

(တစ်နှစ်နှစ်ကြိမ် စောင့်ကြည့်လေ့လာခြင်း)

၂၀၂၁ ခုနှစ်၊ ဒီဇင်ဘာလ
မြန်မာ့အိအေ အင်တာနေရှင်နယ် လီမိတက်



ဇယားစာတိုက်

အခန်း ၁ စောင့်ကြည့်လေ့လာသော အစီအစဉ်နှင့်အကျဉ်းချုပ်	၁
၁.၁ ယေဘုယျဖော်ပြချက်	၁
၁.၂ စောင့်ကြည့်လေ့လာသော အစီအစဉ်ဖော်ပြချက်များ	၁
အခန်း ၂ ဆူညံသံနှင့်တုန်ခါမှု စောင့်ကြည့်လေ့လာခြင်း	၂
၂.၁ စောင့်ကြည့်လေ့လာသည့် အမျိုးအစား	၂
၂.၂ စောင့်ကြည့်လေ့လာသည့် တည်နေရာ	၂
၂.၃ စောင့်ကြည့်လေ့လာသည့် နည်းလမ်း	၃
၂.၄ စောင့်ကြည့်လေ့လာမှု ရလဒ်များ	၄
အခန်း ၃ နိဂုံးချုပ်နှင့်အကြံပြုချက်များ	၁၂

ဇယားများစာရင်း

ဇယား ၁.၂-၁ ဆူညံသံနှင့်တုန်ခါမှုအဆင့် စောင့်ကြည့်လေ့လာသောအစီအစဉ်	၁
ဇယား ၂.၄-၁ နေရာ-၁ (NV-1) ၏ဆူညံသံအဆင့် စောင့်ကြည့်လေ့လာမှုရလဒ်များ (LAeq)	၄
ဇယား ၂.၄-၂ နေရာ-၂ (NV-2) ၏ဆူညံသံအဆင့် စောင့်ကြည့်လေ့လာမှုရလဒ်များ (LAeq)	၅
ဇယား ၂.၄-၃ နေရာ-၁ (NV-1) ၏နာရီအလိုက်ဆူညံသံအဆင့် စောင့်ကြည့်လေ့လာမှုရလဒ်များ (LAeq)	၅
ဇယား ၂.၄-၄ နေရာ-၂ (NV-2) ၏နာရီအလိုက်ဆူညံသံအဆင့် စောင့်ကြည့်လေ့လာမှုရလဒ်များ (LAeq)	၆
ဇယား ၂.၄-၅ နေရာ-၁ (NV-1) ၏တုန်ခါမှုအဆင့် စောင့်ကြည့်လေ့လာမှုရလဒ်များ (LV10)	၈
ဇယား ၂.၄-၆ နေရာ-၂ (NV-2) ၏တုန်ခါမှုအဆင့် စောင့်ကြည့်လေ့လာမှုရလဒ်များ (LV10)	၈
ဇယား ၂.၄-၇ နေရာ-၁ (NV-1) ၏နာရီအလိုက်တုန်ခါမှုအဆင့် စောင့်ကြည့်လေ့လာမှုရလဒ်များ (LV10)	၉
ဇယား ၂.၄-၈ နေရာ-၂ (NV-2) ၏နာရီအလိုက်တုန်ခါမှုအဆင့် စောင့်ကြည့်လေ့လာမှုရလဒ်များ (LV10)	၁၀

ပုံများစာရင်း

ပုံ ၂.၂-၁ ဆူညံသံနှင့်တုန်ခါမှု စောင့်ကြည့်လေ့လာသည့်တည်နေရာများ	၂
ပုံ ၂.၃-၁ ဆူညံသံနှင့်တုန်ခါမှုအဆင့် စောင့်ကြည့်လေ့လာမှုအခြေအနေ	၄
ပုံ ၂.၄-၁ နေရာ-၁ (NV-1) ၏ဆူညံသံအဆင့်စောင့်ကြည့်လေ့လာမှုရလဒ်	၅
ပုံ ၂.၄-၂ နေရာ-၂ (NV-2) ၏ဆူညံသံအဆင့်စောင့်ကြည့်လေ့လာမှုရလဒ်	၅
ပုံ ၂.၄-၃ နေရာ-၁ (NV-1) ၏တုန်ခါမှုအဆင့် စောင့်ကြည့်လေ့လာမှုရလဒ်	၁၁
ပုံ ၂.၄-၄ နေရာ-၂ (NV-2) ၏တုန်ခါမှုအဆင့် စောင့်ကြည့်လေ့လာမှုရလဒ်	၁၁

အခန်း ၁ စောင့်ကြည့်လေ့လာသော အစီအစဉ်နှင့်အကျဉ်းချုပ်

၁.၁ ယေဘုယျဖော်ပြချက်

သီလဝါအထူးစီးပွားရေးဇုန်သည် ရန်ကုန်တိုင်းဒေသကြီး၏ တောင်ပိုင်းခရိုင်တွင်တည်ရှိပြီး ရန်ကုန်မြို့၏ အရှေ့တောင်ဘက် ၂၃ ကီလိုမီတာတွင် တည်ရှိပါသည်။ သီလဝါအထူးစီးပွားရေးဇုန်၏ အကောင်အထည်ဖော်ဆောင်သူအနေဖြင့် ဇုန်အပိုင်း(ခ)အတွင်းရှိ စက်မှုမြေနေရာများအတွက် ခွင့်ပြုချက်ရရှိထားသော ပတ်ဝန်းကျင်ထိခိုက်မှုဆန်းစစ်ခြင်း အစီရင်ခံစာနှင့် ပတ်ဝန်းကျင်ဆိုင်ရာစီမံခန့်ခွဲမှုအစီအစဉ်အတိုင်း ပုံမှန်စောင့်ကြည့်စစ်ဆေးခြင်းကို ဆောင်ရွက်ရန် မြန်မာ-ဂျပန် သီလဝါဖွံ့ဖြိုးရေးလီမိတက်တွင် တာဝန်ရှိပါသည်။ မြန်မာ-ဂျပန် သီလဝါဖွံ့ဖြိုးရေးလီမိတက်သည် ဇုန်အတွင်းနှင့် အနီးပတ်ဝန်းကျင်ရှိ သဘာဝပတ်ဝန်းကျင်အခြေအနေများကို သိရှိစေရန် သဘာဝပတ်ဝန်းကျင်နှင့်သက်ဆိုင်သော အချက်အလက် စောင့်ကြည့်လေ့လာမှုများကို ရေးဆွဲပြီး ထိုအစီအစဉ်များအရ အကောင်အထည်ဖော် ဆောင်ရွက်ခဲ့ပါသည်။

၁.၂ စောင့်ကြည့်လေ့လာသော အစီအစဉ်ဖော်ပြချက်များ

သီလဝါအထူးစီးပွားရေးဇုန် အပိုင်း(ခ) စက်မှုဇုန်လုပ်ငန်းလည်ပတ်နေခြင်းကြောင့် စက်မှုဇုန်အတွင်းနှင့်အပြင်ရှိ ပတ်ဝန်းကျင်အခြေအနေအား အကဲဖြတ်နိုင်ရန်အတွက် အောက်ပါဇယားတွင် ဖော်ပြထားသည့်အတိုင်း ၂၀၂၁ ခုနှစ်၊ ဒီဇင်ဘာလ ၂၂ ရက်နေ့မှ ဒီဇင်ဘာလ ၂၃ ရက်နေ့အထိ ဆူညံသံနှင့်တုန်ခါမှုအဆင့်အား စောင့်ကြည့်လေ့လာခဲ့သည်။

ဇယား ၁.၂-၁ ဆူညံသံနှင့်တုန်ခါမှုအဆင့် စောင့်ကြည့်လေ့လာသောအစီအစဉ်

စောင့်ကြည့်လေ့လာရေးရက်စွဲ	စောင့်ကြည့်လေ့လာမှုအမျိုးအစား	တိုင်းတာသော အမျိုးအစားများ	တိုင်းတာသော နေရာအရေအတွက်	ကြာချိန်	စောင့်ကြည့်လေ့လာသော နည်းလမ်း
ဒီဇင်ဘာလ ၂၃ ရက်နေ့၊ ၂၀၂၁ ခုနှစ်	ဆူညံမှုအဆင့်	L_{Aeq} (dB)	၁ (NV-1)	၈ နာရီ	Rion NL-42 အသံအဆင့်တိုင်းတာသည့်ကိရိယာဖြင့် မြေပြင်တွင်ကွင်းဆင်းတိုင်းတာခြင်း
ဒီဇင်ဘာလ ၂၂ ရက်နေ့၊ ၂၀၂၁ ခုနှစ်	ဆူညံမှုအဆင့်	L_{Aeq} (dB)	၁ (NV-2)	၈ နာရီ	Rion NL-42 အသံအဆင့်တိုင်းတာသည့်ကိရိယာဖြင့် မြေပြင်တွင်ကွင်းဆင်းတိုင်းတာခြင်း
ဒီဇင်ဘာလ ၂၃ ရက်နေ့၊ ၂၀၂၁ ခုနှစ်	တုန်ခါမှုအဆင့်	L_{vib} (dB)	၁ (NV-1)	၈ နာရီ	VM-53A တုန်ခါမှုအဆင့်တိုင်းတာသည့်ကိရိယာဖြင့် မြေပြင်တွင်ကွင်းဆင်းတိုင်းတာခြင်း
ဒီဇင်ဘာလ ၂၂ ရက်နေ့၊ ၂၀၂၁ ခုနှစ်	တုန်ခါမှုအဆင့်	L_{vib} (dB)	၁ (NV-2)	၈ နာရီ	VM-53A တုန်ခါမှုအဆင့်တိုင်းတာသည့်ကိရိယာဖြင့် မြေပြင်တွင်ကွင်းဆင်းတိုင်းတာခြင်း

မှတ်ချက်: မြန်မာ့သီအိုဆင်တာနေရှင်နယ်လီမိတက်

အခန်း ၂ ဆူညံသံနှင့်တုန်ခါမှု စောင့်ကြည့်လေ့လာခြင်း

၂.၁ စောင့်ကြည့်လေ့လာသည့် အမျိုးအစား

ဆူညံသံနှင့်တုန်ခါမှုစောင့်ကြည့်လေ့လာသော အမျိုးအစားများအား ဇယား ၂.၁-၁ တွင် ဖော်ပြထားပါသည်။

ဇယား ၂.၁-၁ ဆူညံသံနှင့်တုန်ခါမှုအဆင့် စောင့်ကြည့်လေ့လာသောအမျိုးအစားများ

စဉ်	စောင့်ကြည့်လေ့လာမှု	အမျိုးအစား
၁	ဆူညံသံ	အသံကြိမ်နှုန်း "အေ"နှင့် ညီမျှသော ကျယ်လောင်မှု (LAeq)
၂	တုန်ခါမှု	တုန်ခါမှုအဆင့် (L _{vib})

မှရင်း၊ မြန်မာ့သံအင်တာနေရှင်နယ်လီမိတက်

၂.၂ စောင့်ကြည့်လေ့လာသည့် တည်နေရာ

ယာဉ်သွားလာမှုကြောင့်ဖြစ်ပေါ်လာသော ဆူညံသံနှင့်တုန်ခါမှုများကို အဓိကထားတိုင်းတာနိုင်ရန် သီလဝါအထူးစီးပွားရေးဇုန် အပိုင်း(ခ)၏ အရှေ့မြောက်ဘက်ထောင့် မြောက်လတ္တီတွဒ် ၁၆°၄၀'၁၈.၂၂"၊ အရှေ့လောင်ဂျီတွဒ် ၉၆°၁၇'၁၈.၁၈" တွင် စောင့်ကြည့်လေ့လာသည့် နေရာ-၁ (NV-1) နှင့် သီလဝါအထူးစီးပွားရေးဇုန် အပိုင်း(ခ)၏ တောင်ဘက် ဖလမ်းကျေးရွာ၊ ဖလမ်းရွာဦးကျောင်းဝန်းအတွင်း မြောက်လတ္တီတွဒ် ၁၆°၃၉'၂၄-၉၀" ၊ အရှေ့လောင်ဂျီတွဒ် ၉၆°၁၇'၁၆.၇၀" တွင် စောင့်ကြည့်လေ့လာသည့် နေရာ-၂ (NV-2)ဟူ၍ ဆူညံသံနှင့်တုန်ခါမှုအဆင့်များကို နှစ်နေရာ တိုင်းတာခဲ့ပါသည်။ ဆူညံသံနှင့်တုန်ခါမှု စောင့်ကြည့် လေ့လာခဲ့သည့် တည်နေရာများကို ပုံ ၂.၂-၁ တွင် ပြသထားပါသည်။



မှရင်း၊ ဂျင်ဂလီယက်

ပုံ ၂.၂-၁ ဆူညံသံနှင့်တုန်ခါမှု စောင့်ကြည့်လေ့လာသည့်တည်နေရာများ

ဆူညံသံနှင့်တုန်ခါမှု စောင့်ကြည့်လေ့လာသည့်နေရာ-၁ (NV-1)

စောင့်ကြည့်လေ့လာသည့် နေရာ-၁ (NV-1)သည် သီလဝါဖွံ့ဖြိုးရေးလမ်း၏ ဘေးဘက်တွင်ရှိသော သီလဝါအထူးစီးပွားရေးဇုန် အပိုင်း(ခ)ရှိ လည်ပတ်နေသောလုပ်ငန်းခွင်၏ ယာယီဂိတ်ပေါက်အရှေ့ဘက်၌ ရှိပါသည်။ စောင့်ကြည့်လေ့လာသည့် နေရာကို အနောက်မြောက်ဘက်တွင် ဇုန်အပိုင်း(က)နှင့် အရှေ့ဘက်တွင် ပြည်တွင်းစက်မှုဇုန်တို့ဖြင့် ဝန်းရံထားပါသည်။ ဤစောင့်ကြည့်လေ့လာသည့်နေရာ၏ အဓိကဆူညံသံနှင့်တုန်ခါမှု ဖြစ်နိုင်သော အရင်းအမြစ်များမှာ ဆောက်လုပ်ရေးလုပ်ငန်းကြောင့်ဖြစ်သော ဆူညံမှုနှင့်တုန်ခါမှုများနှင့် ယာဉ်သွားလာမှုများကြောင့် ဖြစ်နိုင်ပါသည်။

ဆူညံသံနှင့်တုန်ခါမှု စောင့်ကြည့်လေ့လာသည့်နေရာ-၂ (NV-2)

စောင့်ကြည့်လေ့လာသည့် နေရာ-၂ (NV-2) သည် သီလဝါအထူးစီးပွားရေးဇုန် အပိုင်း(ခ)၏ တောင်ဘက် ဖလမ်းကျေးရွာ၊ ဖလမ်းရွာဦးကျောင်းဝန်းအတွင်းတွင် တည်ရှိပြီး တောင်ဘက်တွင် ဖလမ်းကျေးရွာ၏ လူနေအိမ်များ၊ အနောက်ဘက်တွင် လယ်ကွင်းများ တည်ရှိပြီး မြောက်ဘက်တွင် သီလဝါ အထူးစီးပွားရေးဇုန် အပိုင်း(က)နှင့် အရှေ့မြောက်ဘက်တွင် ပြည်တွင်းစက်မှုဇုန်တို့ဖြင့် ဝန်းရံထားပါသည်။ ဤစောင့်ကြည့် လေ့လာသည့်နေရာ၏ အဓိကဆူညံသံနှင့် တုန်ခါမှု ဖြစ်နိုင်သော အရင်းအမြစ်များမှာ ဇုန်အပိုင်း(ခ)ရှိ ဆောက်လုပ်ရေး လုပ်ငန်းများနှင့် ဖလမ်းကျေးရွာရှိ နေထိုင်သူများ၏ နေ့စဉ် လုပ်ငန်းဆောင်တာများကြောင့် ဖြစ်နိုင်ပါသည်။

၂.၃ စောင့်ကြည့်လေ့လာသည့် နည်းလမ်း

ဆူညံသံအဆင့်အား “Rion NL-42 အသံအဆင့်တိုင်းတာသည့်ကိရိယာ” ဖြင့်တိုင်းတာပြီး ၁၀မိနစ်တိုင်း အလိုအလျောက်တိုင်းတာပြီး စက်အတွင်းရှိ မန်မိုရီကဒ်အတွင်း မှတ်သားထားပါသည်။ တုန်ခါမှုအဆင့် တိုင်းတာသည့် ကိရိယာ “Rion VM-53A” ဝင်ရိုးသုံးခုပါဝင်သော တုန်ခါမှုအဆင့် သတ်မှတ်သည့် ကိရိယာအား မြေကြီးပေါ်တွင် ထားရှိပါသည်။ တုန်ခါမှု (L_a)အား နေရာ-၁ (NV-1)နှင့် နေရာ-၂ (NV-2)တို့၌ အလိုက်အသင့် ပြောင်းလဲနိုင်သောအဆင့် (၁၀-၇၀) dB အတွင်းထားရှိပြီး ၁၀ မိနစ်တိုင်း အလိုအလျောက် တိုင်းတာပြီး စက်အတွင်းရှိ မန်မိုရီကဒ်အတွင်း မှတ်သားထားပါသည်။

စောင့်ကြည့်လေ့လာသော နေရာတစ်ခုစီတွင် ဆူညံသံနှင့်တုန်ခါမှု စောင့်ကြည့်လေ့လာမှုအား ၈ နာရီ တိုင်းတာပါသည်။ နေရာ-၁ (NV-1) နှင့် နေရာ-၂ (NV-2) ရှိ ဆူညံသံနှင့်တုန်ခါမှုအဆင့် စောင့်ကြည့် လေ့လာသောအခြေအနေကို ပုံ ၂.၃-၁ တွင် ပြသထားပါသည်။





ဗုရင်း၊ မြန်မာ့အိမ်အင်တာနေရှင်နယ်လီမီတက်

**ပုံ ၂.၃-၁ ဆူညံသံနှင့်တုန်ခါမှုအဆင့် စောင့်ကြည့်လေ့လာမှုအခြေအနေ
၂.၄ စောင့်ကြည့်လေ့လာမှု ရလဒ်များ**

ဆူညံသံစောင့်ကြည့်လေ့လာမှုရလဒ်များ

ဆူညံသံစောင့်ကြည့်လေ့လာမှုရလဒ်များအတွက် နေရာ-၁ (NV-1) တွင် နေ့အချိန် (မနက် ၆ နာရီ မှ ည ၁၀ နာရီ) နှင့် ညအချိန် (ည ၁၀ နာရီ မှ မနက် ၆ နာရီ) ဟု အချိန်အပိုင်းအခြား ခွဲခြားသတ်မှတ်ထားပြီး နေရာ-၂ (NV-2) တွင် နေ့အချိန် (မနက် ၇ နာရီ မှ ည ၇ နာရီ)၊ ညနေခင်းအချိန် (ည ၇ နာရီ မှ ည ၁၀ နာရီ) နှင့် ညအချိန် (ည ၁၀ နာရီ မှ မနက် ၇ နာရီ) ဟူ၍ အချိန်အပိုင်းအခြား ခွဲခြားသတ်မှတ်ထားပါသည်။ ဆူညံသံ တိုင်းတာမှုအား သတ်မှတ်ထားသောနေရာတွင် ၂၄ နာရီကြာ တိုင်းတာမည့်အစား ဘေးအန္တရာယ်ကင်းရှင်းစေရန် နှင့် ဘေးကင်းလုံခြုံမှုရရှိစေရန် အလုပ်ချိန်အနေဖြင့် ၈ နာရီ (မနက် ၈ နာရီ မှ ညနေ ၄ နာရီ) ကြာ တိုင်းတာခဲ့ပါသည်။ စောင့်ကြည့်လေ့လာသောရလဒ်များအား ဇယား ၂.၄-၁ နှင့် ဇယား ၂.၄-၂ တွင် အကျဉ်းချုပ် ဖော်ပြထားပါသည်။ နေရာ-၁ (NV-1) နှင့် နေရာ-၂ (NV-2) ရှိ တစ်နာရီဆူညံမှုအဆင့် (L_{Aeq}) ၏ စောင့်ကြည့်လေ့လာမှုရလဒ်များကို ဇယား ၂.၄-၃ နှင့် ဇယား ၂.၄-၄ တွင် ဖော်ပြထားပါသည်။ ပုံ ၂.၄-၁ နှင့် ပုံ ၂.၄-၂ တွင် နေရာ-၁ (NV-1) နှင့် နေရာ-၂ (NV-2) ၏ ဆူညံမှုအဆင့် (L_{Aeq}) ရလဒ်များအား ပြသထားပါသည်။ သီလဝါ အထူးစီးပွားရေးဇုန် ဖွံ့ဖြိုးမှု စီမံကိန်း အပိုင်း(ခ) ၏ ပတ်ဝန်းကျင် ထိခိုက်မှု ဆန်းစစ်ခြင်း အစီအရင်ခံစာတွင် ပါရှိသော လုပ်ငန်းလည်ပတ်နေစဉ် အဆင့်၌ ရည်မှန်းထားသော ဆူညံသံအဆင့်နှင့် နှိုင်းယှဉ်ရာတွင် ရလဒ်များသည် ရည်မှန်းတန်ဖိုးထက်လျော့နည်းကြောင်း တွေ့ရှိရသည်။ ။

ဇယား ၂.၄-၁ နေရာ-၁ (NV-1) ၏ဆူညံသံအဆင့် စောင့်ကြည့်လေ့လာမှုရလဒ်များ (L_{Aeq})

ရက်စွဲ	ယာဉ်အသွားအလာကြောင့်ဖြစ်ပေါ်သောဆူညံသံအဆင့် (L_{Aeq} dB)	
	နေ့အချိန် (မနက် ၆ နာရီ မှ ည ၁၀ နာရီ)	ညအချိန် (ည ၁၀ နာရီ မှ မနက် ၆ နာရီ)
၂၃ ဒီဇင်ဘာလ ၂၀၂၁	၆၁	-
ရည်မှန်းတန်ဖိုး	၇၅	၇၀

မှတ်ချက်- ရည်မှန်းတန်ဖိုးများကို ဆူညံသံစည်းညစ်ညမ်းမှု (ဂျပန်) တွင်ဖော်ပြထားသော အဓိကလမ်းကြီးတစ်လျှောက်ရှိ ဆူညံသံခံနှုန်းဖြင့် ကျဉ်းသုံးထားပါသည်။ (၁၉၆၈ ခုနှစ် ဥပဒေအမှတ် ၉၈၊ နောက်ဆုံးပြင်ဆင်ချက် ၂၀၀၈ ခုနှစ် ဥပဒေအမှတ် ၉၀)

ဗုရင်း၊ မြန်မာ့အိမ်အင်တာနေရှင်နယ်လီမီတက်

သီလဝံအထူးစီးပွားရေးဇုန်အပိုင်း(ခ)ရိုစက်မှုဇုန်ဖွံ့ဖြိုးတိုးတက်မှုအတွက်ဆူညံသံနှင့်တုန်ခါမှုစောင့်ကြည့်လေ့လာခြင်းအစီရင်ခံစာ
(လုပ်ငန်းလည်ပတ်နေစဉ်ကာလ အပိုင်း ၁၊ အပိုင်း ၂ နှင့် အပိုင်း ၃၊ ဒီဇင်ဘာလ ၂၀၂၁ ခုနှစ်)

ဇယား ၂.၄-၂ နေရာ-၂ (NV-2) ၏ဆူညံသံအဆင့် စောင့်ကြည့်လေ့လာမှုရလဒ်များ (LAeq)

ရက်စွဲ	ဆောက်လုပ်ရေးလုပ်ငန်းခွင်မှ မီတာ ၁၅၀ အတွင်းတွင် ရှိသော လူနေအိမ်များနှင့် တူန်းကြီးကောင်း (LAeq, dB)		
	နေအချိန် (မနက် ၇ နာရီ မှ ည ၇ နာရီ)	ညနေခင်းအချိန် (ည ၇ နာရီ မှ ည ၁၀ နာရီ)	ညအချိန် (ည ၁၀ နာရီ မှ မနက် ၇ နာရီ)
၂ ဒီဇင်ဘာလ ၂၀၂၁	၄၃	-	-
ရည်မှန်းတန်ဖိုး	၆၀	၅၅	၅၀

မှတ်ချက်။ ရည်မှန်းတန်ဖိုးများကို သီလဝံအထူးစီးပွားရေးဇုန် ဖွံ့ဖြိုးတိုးတက်မှုစီမံကိန်း အပိုင်း(ခ) အတွက် လုပ်ငန်းလည်ပတ်နေစဉ် အဆင့်တွင်ရှိရမည့် ဆူညံသံအဆင့် ရည်မှန်းတန်ဖိုးကို အသုံးပြုထားပါသည်။

မူရင်း။ မြန်မာ့သို့အင်္ဂလိပ်ဘာသာပြန်စာရင်း

ဇယား ၂.၄-၃ နေရာ-၁ (NV-1) ၏နာရီအလိုက်ဆူညံသံအဆင့် စောင့်ကြည့်လေ့လာမှုရလဒ်များ (LAeq)

ရက်စွဲ	အချိန်	(LAeq, dB)	(LAeq, dB) အချိန်အပိုင်းအခြား တစ်ခုစီအတွက်	(LAeq, dB) ရည်မှန်းတန်ဖိုး	မှတ်ချက်
၂၃ ဒီဇင်ဘာလ ၂၀၂၁	၆:၀၀-၇:၀၀	-	၆၁	၇၅	
	၇:၀၀-၈:၀၀	-			
	၈:၀၀-၉:၀၀	၆၃			
	၉:၀၀-၁၀:၀၀	၆၂			
	၁၀:၀၀-၁၁:၀၀	၆၂			
	၁၁:၀၀-၁၂:၀၀	၆၀			
	၁၂:၀၀-၁၃:၀၀	၆၀			
	၁၃:၀၀-၁၄:၀၀	၆၁			
	၁၄:၀၀-၁၅:၀၀	၆၁			
	၁၅:၀၀-၁၆:၀၀	၆၁			
	၁၆:၀၀-၁၇:၀၀	-	၆၁	၇၅	ဆောက်လုပ်ရေးလုပ်ငန်း လုပ်ဆောင်နေခြင်းမရှိပါ။
	၁၇:၀၀-၁၈:၀၀	-			
	၁၈:၀၀-၁၉:၀၀	-			
	၁၉:၀၀-၂၀:၀၀	-			
	၂၀:၀၀-၂၁:၀၀	-			
	၂၁:၀၀-၂၂:၀၀	-			
	၂၂:၀၀-၂၃:၀၀	-			
	၂၃:၀၀-၂၄:၀၀	-			
	၂၄:၀၀-၀၁:၀၀	-			
	၀၁:၀၀-၀၂:၀၀	-			
	၀၂:၀၀-၀၃:၀၀	-			
	၀၃:၀၀-၀၄:၀၀	-			
	၀၄:၀၀-၀၅:၀၀	-			
	၀၅:၀၀-၀၆:၀၀	-			
	၀၆:၀၀-၀၇:၀၀	-			

မူရင်း။ မြန်မာ့သို့အင်္ဂလိပ်ဘာသာပြန်စာရင်း




သီလဝါအထူးစီးပွားရေးဇုန်အပိုင်း (ခ)ရှိဇုန်မှတစ်ဆင့်အတွက်ဆွဲသံနှင့်တူနီဇီးမူဆောင်ကြည့်လေ့လာခြင်းအစီရင်ခံစာ
(လုပ်ငန်းလည်ပတ်နေသောကာလ အပိုင်း ၁၊ အပိုင်း ၂ နှင့် အပိုင်း ၃ ၊ ဒီဇင်ဘာလ ၂၀၂၁ မှစ၍)

ဇယား ၂.၄-၄ နေရာ-၂ (NV-2)၏နာရီအလိုက်ဆွဲသံအဆင့် စောင့်ကြည့်လေ့လာမှုရလဒ်များ (LAeq)

ရက်စွဲ	အချိန်	(L_{Aeq} dB)	(L_{Aeq} dB) အချိန်အပိုင်းအခြား တစ်ခုစီအတွက်	(L_{Aeq} dB) ရည်မှန်းတန်ဖိုး	မှတ်ချက်
၂၂ ဒီဇင်ဘာလ ၂၀၂၁	၇:၀၀-၈:၀၀	-	၄၃	၆၀	ဆောက်လုပ်ရေးလုပ်ငန်း လုပ်ဆောင်နေခြင်းမရှိပါ။
	၈:၀၀-၉:၀၀	၄၇			
	၉:၀၀-၁၀:၀၀	၄၇			
	၁၀:၀၀-၁၁:၀၀	၄၂			
	၁၁:၀၀-၁၂:၀၀	၄၁			
	၁၂:၀၀-၁:၃၀	၄၁			
	၁:၃၀-၁:၄၅	၄၀			
	၁:၄၅-၁:၅၅	၄၁			
	၁:၅၅-၂:၀၀	၄၅			
	၂:၀၀-၂:၁၅	-			
	၂:၁၅-၂:၃၀	-			
	၂:၃၀-၂:၄၅	-			
	၂:၄၅-၂:၅၅	-	၅၀		
	၂:၅၅-၃:၀၀	-			
	၃:၀၀-၃:၁၅	-			
	၃:၁၅-၃:၃၀	-	၅၀		
	၃:၃၀-၃:၄၅	-			
	၃:၄၅-၄:၀၀	-			
	၄:၀၀-၄:၁၅	-			
	၄:၁၅-၄:၃၀	-			
	၄:၃၀-၄:၄၅	-			
	၄:၄၅-၅:၀၀	-			
	၅:၀၀-၅:၁၅	-			
	၅:၁၅-၅:၃၀	-			
	၅:၃၀-၅:၄၅	-			
	၅:၄၅-၆:၀၀	-			


မှတ်ချက်- ပြန်မာနိုင်ငံအင်တာနေရှင်နယ်လီမီတာလီ

သီလဝံသဝတ္ထုစီးပွားရေးဗဟိုအဖွဲ့အစည်း(ခ) ရှိဧကန်မှုစနစ်နှင့် ပြီးစီးတက်မှုအတွက် ဆူညံသံနှင့် တုန်ခါမှုစောင့်ကြည့်လေ့လာခြင်းစာစီရင်ခံစာ
(လုပ်ငန်းလည်ပတ်နေစဉ်ကာလ အပိုင်း ၁၊ အပိုင်း ၂ နှင့် အပိုင်း ၃၊ ဒီဇင်ဘာလ ၂၀၂၁ မှစ၍)



မှရင်း၊ ဖြန့်ဖြူးသည့်အခါအတွက်အမှတ်တံဆိပ်ပါရှိသည်။

ပုံ ၂.၄-၁ နေရာ-၁ (NV-1) ၏ဆူညံသံအဆင့်စောင့်ကြည့်လေ့လာမှုရလဒ်



မှရင်း၊ ဖြန့်ဖြူးသည့်အခါအတွက်အမှတ်တံဆိပ်ပါရှိသည်။

ပုံ ၂.၄-၂ နေရာ-၂ (NV-2) ၏ဆူညံသံအဆင့်စောင့်ကြည့်လေ့လာမှုရလဒ်

သီလဝါအထူးစီးပွားရေးဇုန်အပိုင်း(ခ)ရှိစက်မှုဇုန်ဖွံ့ဖြိုးတိုးတက်မှုအတွက်ဆည်သံနှင့်တုန်ခါမှုစောင့်ကြည့်လေ့လာခြင်းအစီရင်ခံစာ
(လုပ်ငန်းလည်ပတ်နေစဉ်ကာလ အပိုင်း ၁၊ အပိုင်း ၂ နှင့် အပိုင်း ၃၊ ဒီဇင်ဘာလ ၂၀၂၁ ခုနှစ်)

တုန်ခါမှုစောင့်ကြည့်လေ့လာမှု ရလဒ်များ

တုန်ခါမှုစောင့်ကြည့်လေ့လာမှုရလဒ်များအား နေရာ-၁ (NV-1) နှင့် နေရာ-၂ (NV-2) နှစ်ခုလုံးအတွက် နေ့အချိန် (မနက် ၇ နာရီ မှ ည ၇ နာရီ)၊ ညနေခင်းအချိန် (ည ၇ နာရီ မှ ည ၁၀ နာရီ) နှင့် ညအချိန် (ည ၁၀ နာရီ မှ မနက် ၇ နာရီ)ဟူ၍ အချိန်အပိုင်းအခြား ခွဲခြားသတ်မှတ်ထားပါသည်။ တုန်ခါမှုတိုင်းတာခြင်းအား သတ်မှတ်ထားသောနေရာတွင် ၂၄ နာရီကြာ တိုင်းတာမည့်အစား ဘေးအန္တရာယ်ကင်းရှင်းစေရန် နှင့် ဘေးကင်းလုံခြုံမှုရှိစေရန် အလုပ်ချိန်အနေဖြင့် ၈ နာရီ (မနက် ၈ နာရီ မှ ညနေ ၄ နာရီ) ကြာ တိုင်းတာခဲ့ပါသည်။ နေရာ-၁ (NV-1) နှင့် နေရာ-၂ (NV-2) ၏ တုန်ခါမှုအဆင့် (L_{10}) စောင့်ကြည့်လေ့လာမှုရလဒ်များအား ဇယား ၂.၄-၅ နှင့် ဇယား ၂.၄-၆ တွင် ဖော်ပြထားပါသည်။ နေရာ-၁ (NV-1) နှင့် နေရာ-၂ (NV-2) ရှိ တစ်နာရီတုန်ခါမှုအဆင့် (L_{10})၏ စောင့်ကြည့်လေ့လာမှုရလဒ်များကို ဇယား ၂.၄-၇ နှင့် ဇယား ၂.၄-၈ တွင် ဖော်ပြထားပါသည်။ ပုံ ၂.၄-၃ နှင့် ပုံ ၂.၄-၄ တွင် နေရာ-၁ (NV-1) နှင့် နေရာ-၂ (NV-2) ၏ တုန်ခါမှုအဆင့်စောင့်ကြည့်လေ့လာမှု ရလဒ်များအတွက် ပြသထားပါသည်။ သီလဝါအထူးစီးပွားရေးဇုန်ဖွံ့ဖြိုးမှု စီမံကိန်း အပိုင်း(ခ)၏ ပတ်ဝန်းကျင်ထိခိုက်မှုဆန်းစစ်ခြင်းအစီအရင်ခံစာတွင်ပါရှိသော လုပ်ငန်းလည်ပတ်နေစဉ် အဆင့်တွင် ရည်မှန်းထားသော တုန်ခါမှုအဆင့်နှင့် နှိုင်းယှဉ်ရာ၌ ရလဒ်များသည် ရည်မှန်းတန်ဖိုးထက် လျော့နည်းသည်ကို တွေ့ရှိရသည်။

ဇယား ၂.၄-၅ နေရာ-၁ (NV-1) ၏တုန်ခါမှုအဆင့် စောင့်ကြည့်လေ့လာမှုရလဒ်များ (L_{10})

ရက်စွဲ	လူနေထိမ်များ စီးပွားရေးဆိုင်ရာနေရာများနှင့် စက်မှုဇုန်များ (L_{10} , dB)		
	နေ့အချိန် (မနက် ၇ နာရီ မှ ည ၇ နာရီ)	ညနေခင်းအချိန် (ည ၇ နာရီ မှ ည ၁၀ နာရီ)	ညအချိန် (ည ၁၀ နာရီ မှ မနက် ၇ နာရီ)
၂၃ ဒီဇင်ဘာလ ၂၀၂၁	၄၀	-	-
ရည်မှန်းတန်ဖိုး	၇၀	၆၅	၆၅

မှတ်ချက်- ရည်မှန်းတန်ဖိုးများကို သီလဝါအထူးစီးပွားရေးဇုန် ဖွံ့ဖြိုးတိုးတက်မှုစီမံကိန်း အပိုင်း(ခ)အတွက် လုပ်ငန်းလည်ပတ်နေစဉ် အဆင့်တွင်ရှိရမည့် တုန်ခါမှုအဆင့် ရည်မှန်းတန်ဖိုးကို အသုံးပြုထားပါသည်။

မူရင်း မြန်မာစာအုပ်အင်တာနက်နေရင်းနယ်လီမီတက်

ဇယား ၂.၄-၆ နေရာ- ၂ (NV-2) ၏တုန်ခါမှုအဆင့် စောင့်ကြည့်လေ့လာမှုရလဒ်များ (L_{10})

ရက်စွဲ	ဆောက်လုပ်ရေးလုပ်ငန်းခွင်မှ မိတာ-၁၅၀ အတွင်းတွင် ရှိသော လူနေထိမ်များနှင့် ကုန်ကြီးကျောင်း (L_{10} , dB)		
	နေ့အချိန် (မနက် ၇ နာရီ မှ ည ၇ နာရီ)	ညနေခင်းအချိန် (ည ၇ နာရီ မှ ည ၁၀ နာရီ)	ညအချိန် (ည ၁၀ နာရီ မှ မနက် ၇ နာရီ)
၂၂ ဒီဇင်ဘာလ ၂၀၂၁	၃၃	-	-
ရည်မှန်းတန်ဖိုး	၆၅	၆၀	၆၀

မှတ်ချက်- ရည်မှန်းတန်ဖိုးများကို သီလဝါအထူးစီးပွားရေးဇုန် ဖွံ့ဖြိုးတိုးတက်မှုစီမံကိန်း အပိုင်း(ခ)အတွက် လုပ်ငန်းလည်ပတ်နေစဉ် အဆင့်တွင်ရှိရမည့် တုန်ခါမှုအဆင့် ရည်မှန်းတန်ဖိုးကို အသုံးပြုထားပါသည်။

မူရင်း မြန်မာစာအုပ်အင်တာနက်နေရင်းနယ်လီမီတက်

သီလဝါအထူးစီးပွားရေးဇုန်အပိုင်း(ခ)ရှိခက်ခဲနေသည့်မြို့တိုးတက်မှုအတွက်ဆူညံသံနှင့်တုန်ခါမှုစောင့်ကြည့်လေ့လာခြင်းအစီရင်ခံစာ
(လုပ်ငန်းလည်ပတ်နေစဉ်ကာလ အပိုင်း ၁၊ အပိုင်း ၂ နှင့် အပိုင်း ၃၊ ဒီဇင်ဘာလ ၂၀၂၁ မှစ၍)

ဇယား ၂.၄-၇ နေရာ-၁ (NV-1) ၏နာရီအလိုက်တုန်ခါမှုအဆင့် စောင့်ကြည့်လေ့လာမှုရလဒ်များ (Lv₁₀)

ရက်စွဲ	အချိန်	(L _{act} , dB)	(L _{vis} , dB) အချိန်အပိုင်းအခြား တစ်ခုစီအတွက်	(L _{no} , dB) ရည်မှန်းတန်ဖိုး	မှတ်ချက်
၂၃ ဒီဇင်ဘာလ ၂၀၂၁	၇:၀၀-၈:၀၀	-	၄၁	၇၀	ဆောက်လုပ်ရေးလုပ်ငန်း လုပ်ဆောင်နေခြင်းမရှိပါ။
	၈:၀၀-၉:၀၀	၄၁			
	၉:၀၀-၁၀:၀၀	၄၈			
	၁၀:၀၀-၁၁:၀၀	၄၁			
	၁၁:၀၀-၁၂:၀၀	၃၉			
	၁၂:၀၀-၁:၃၀	၃၉			
	၁:၃၀-၁:၄၅	၄၁			
	၁:၄၅-၁:၅၅	၄၁			
	၁:၅၅-၂:၀၀	၃၉			
	၂:၀၀-၂:၁၅	-			
	၂:၁၅-၂:၃၀	-			
	၂:၃၀-၂:၄၅	-			
	၂:၄၅-၂:၅၅	-			
	၂:၅၅-၃:၁၀	-			
	၃:၁၀-၃:၃၀	-			
	၃:၃၀-၃:၄၅	-			
	၃:၄၅-၄:၀၀	-			
	၄:၀၀-၄:၁၅	-			
	၄:၁၅-၄:၃၀	-			
	၄:၃၀-၄:၄၅	-			
	၄:၄၅-၅:၀၀	-			
	၅:၀၀-၅:၁၅	-			
	၅:၁၅-၅:၃၀	-			
	၅:၃၀-၅:၄၅	-			
၅:၄၅-၆:၀၀	-				

မှတ်ချက်: ပြန်စာဆိုအင်တာနေရှင်နယ်လီမီတက်

သီလဝါအထူးစီးပွားရေးဇုန်အပိုင်း(ခ)ရှိစက်မှုဇုန်မှမြို့တိုးတက်မှုအတွက်ဆူညံသံနှင့်တုန်ခါမှုစောင့်ကြည့်လေ့လာခြင်းအစီရင်ခံစာ
(လုပ်ငန်းလည်ပတ်နေသည့်ကာလ အပိုင်း ၁၊ အပိုင်း ၂ နှင့် အပိုင်း ၃ ၊ ဒီဇင်ဘာလ ၂၀၂၁ ခုနှစ်)


ဇယား ၂.၄-ဂ နေရာ-၂ (NV-2) ၏နာရီအလိုက်တုန်ခါမှုအဆင့် စောင့်ကြည့်လေ့လာမှုရလဒ်များ (LV₁₀)

ရက်စွဲ	အချိန်	(L _{eq} , dB)	(L _{max} , dB) အချိန်အပိုင်းအခြား တစ်ခုစီအတွက်	(L _{max} , dB) ရည်မှန်းတန်ဖိုး	မှတ်ချက်
၂၂ ဒီဇင်ဘာလ ၂၀၂၁	၇:၀၀-၈:၀၀	-	၂၃	၆၅	ဆောက်လုပ်ရေးလုပ်ငန်း လုပ်ဆောင်နေခြင်းမရှိပါ။
	၈:၀၀-၉:၀၀	၂၁			
	၉:၀၀-၁၀:၀၀	၂၄			
	၁၀:၀၀-၁၁:၀၀	၂၅			
	၁၁:၀၀-၁၂:၀၀	၂၃			
	၁၂:၀၀-၁:၃၀	၂၂			
	၁:၃၀-၁:၄၅	၂၁			
	၁:၄၅-၁:၅၅	၂၂			
	၁:၅၅-၂:၀၀	၂၁			
	၂:၀၀-၂:၁၅	-			
	၂:၁၅-၂:၃၀	-			
	၂:၃၀-၂:၄၅	-			
	၂:၄၅-၂:၅၅	-	-	၆၀	
	၂:၅၅-၃:၀၀	-			
	၃:၀၀-၃:၁၅	-			
	၃:၁၅-၃:၃၀	-			
	၃:၃၀-၃:၄၅	-	-	၆၀	
	၃:၄၅-၃:၅၅	-			
	၃:၅၅-၄:၀၀	-			
	၄:၀၀-၄:၁၅	-			
	၄:၁၅-၄:၃၀	-			
	၄:၃၀-၄:၄၅	-			
	၄:၄၅-၄:၅၅	-			
	၄:၅၅-၅:၀၀	-			
	၅:၀၀-၅:၁၅	-			
	၅:၁၅-၅:၃၀	-			
	၅:၃၀-၅:၄၅	-			

မှတ်ချက်- မြန်မာ့မိုးအင်တာနေရှင်နယ်လီမီတက်




သီလဝါအသွေးဦးပွားရေးစနစ်အပိုင်း(ခ)ရှိစက်မှုစနစ်ဖြိုးတိုးတက်မှုအတွက်ဆုညွှတ်နှင့်တုန်ခါမှုစောင့်ကြည့်လေ့လာခြင်းစာစီရင်ခံစာ
(လုပ်ငန်းလည်ပတ်နေစဉ်ကာလ အပိုင်း ၁၊ အပိုင်း ၂ နှင့် အပိုင်း ၃ ၊ ဒီဇင်ဘာလ ၂၀၂၁ ခုနှစ်)



မှရင်း၊ ပြန်မာ့သံအင်တာနေရှင်နယ်လီမိတက်

ပုံ ၂.၄-၃ နေရာ-၁ (NV-1) ၏တုန်ခါမှုအဆင့် စောင့်ကြည့်လေ့လာမှုရလဒ်



မှရင်း၊ ပြန်မာ့သံအင်တာနေရှင်နယ်လီမိတက်

ပုံ ၂.၄-၄ နေရာ-၂ (NV-2) ၏တုန်ခါမှုအဆင့် စောင့်ကြည့်လေ့လာမှုရလဒ်

အခန်း ၃ နိဂုံးချုပ်နှင့်အကြံပြုချက်များ

သီလဝါ အထူးစီးပွားရေးဇုန် ဖွံ့ဖြိုးမှုစီမံကိန်း အပိုင်း(ခ)၏ ပတ်ဝန်းကျင် ထိခိုက်မှု ဆန်းစစ်ခြင်း အစီအရင်ခံစာတွင် ပါရှိသည့် လုပ်ငန်း လည်ပတ်နေစဉ် ကာလအတွက် သတ်မှတ်ထားသော ဆူညံသံနှင့် တုန်ခါမှုအဆင့်များနှင့် နှိုင်းယှဉ်ရာ၌ နေရာ-၁ (NV-1) နှင့် နေရာ-၂ (NV-2) ၏ ရလဒ်များသည် ရည်မှန်း တန်ဖိုးထက် လျော့နည်းနေသည်ကို တွေ့ရှိရသည်။ ထို့ကြောင့် ဇုန်အပိုင်း(ခ)မှ လည်ပတ်နေသော လုပ်ငန်းများကြောင့် ဖြစ်ပေါ်လာသော ဆူညံသံနှင့် တုန်ခါမှုသည် ဘေးပတ်ဝန်းကျင်အား သက်ရောက်မှုမရှိပါ။

ဤပတ်ဝန်းကျင် စောင့်ကြည့်လေ့လာမှုအား ကောက်ချက်ချရာတွင် စောင့်ကြည့်လေ့လာသော ကာလအတွင်း သီလဝါအထူးစီးပွားရေးဇုန် အပိုင်း(ခ)အတွင်းရှိ စက်မှုမြေနေရာများမှ ဘေးပတ်ဝန်းကျင်အား သိသာထင်ရှားသော ဆူညံသံ နှင့်တုန်ခါမှုဆိုင်ရာ သက်ရောက်မှုများ မရှိကြောင်းတွေ့ရှိရပါသည်။

သီလဝါအထူးစီးပွားရေးဇုန် အပိုင်း(ခ)ရှိ
စက်မှုဇုန်ဖွံ့ဖြိုးတိုးတက်ရေးအတွက်
ယာဉ်သွားလာမှုနှုန်းစောင့်ကြည့်လေ့လာခြင်းအစီရင်ခံစာ
(လုပ်ငန်းလည်ပတ်နေစဉ်ကာလ အပိုင်း ၁၊ အပိုင်း ၂ နှင့် အပိုင်း ၃)

(တစ်နှစ်နှစ်ကြိမ် စောင့်ကြည့်လေ့လာခြင်း)

၂၀၂၁ ခုနှစ်၊ ဒီဇင်ဘာလ
မြန်မာ့သို့အဲ အင်တာနေရှင်နယ် လီမိတက်



မာတိကာ

အခန်း ၁ စောင့်ကြည့်လေ့လာသော အစီအစဉ်နှင့်အကျဉ်းချုပ်	၁
၁.၁ ယေဘုယျ ဖော်ပြချက်	၁
၁.၂ စောင့်ကြည့်လေ့လာသောအစီအစဉ်ဖော်ပြချက်များ	၁
အခန်း ၂ ယာဉ်သွားလာမှုနှုန်း စောင့်ကြည့်လေ့လာခြင်း	၂
၂.၁ စောင့်ကြည့်လေ့လာသည့် အမျိုးအစား	၂
၂.၂ စောင့်ကြည့်လေ့လာသည့် တည်နေရာ	၃
၂.၃ စောင့်ကြည့်လေ့လာသည့် နည်းလမ်း	၄
၂.၄ စောင့်ကြည့်လေ့လာမှု ရလဒ်များ	၄
အခန်း ၃ စိုက်ပျိုးရေးနှင့်အကြံပြုချက်များ	၈

ဇယားများစာရင်း

ဇယား ၁.၂-၁ ယာဉ်သွားလာမှုနှုန်း စောင့်ကြည့်လေ့လာသောအစီအစဉ်	၁
ဇယား ၂.၁-၁ ယာဉ်သွားလာမှုနှုန်းအတွက် စောင့်ကြည့်လေ့လာသောအမျိုးအစားများ	၂
ဇယား ၂.၁-၂ ယာဉ်အမျိုးအစားခွဲခြားခြင်း	၂
ဇယား ၂.၄-၁ နေရာ-၁ (TV-1) ၌ယာဉ်သွားလာမှုနှုန်း မှတ်တမ်းအကျဉ်းချုပ်	၅
ဇယား ၂.၄-၂ နေရာ-၁ (TV-1)၌ နာရီအလိုက် ယာဉ်သွားလာမှုနှုန်းရလဒ် (ဖလမ်းကျေးရွာမှ ဒဂုံ-သီလဝါလမ်းသို့)	၆
ဇယား ၂.၄-၃ နေရာ-၁ (TV-1)၌ နာရီအလိုက် ယာဉ်သွားလာမှုနှုန်းရလဒ် (ဒဂုံ-သီလဝါလမ်းမှ ဖလမ်းကျေးရွာသို့)	၇

ပုံများစာရင်း

ပုံ ၂.၂-၁ ယာဉ်သွားလာမှုနှုန်း စောင့်ကြည့်လေ့လာသည့်တည်နေရာ	၃
ပုံ ၂.၃-၁ နေရာ-၁ (TV-1) ၌ယာဉ်သွားလာမှုနှုန်း စောင့်ကြည့်လေ့လာခြင်းအခြေအနေ	၄

အခန်း ၁ စောင့်ကြည့်လေ့လာသော အစီအစဉ်နှင့်အကျဉ်းချုပ်

၁.၁ ယေဘုယျ ဖော်ပြချက်

သီလဝါအထူးစီးပွားရေးဇုန်သည် ရန်ကုန်တိုင်းဒေသကြီး၏ တောင်ပိုင်းခရိုင်တွင်တည်ရှိပြီး ရန်ကုန်မြို့၏ အရှေ့တောင်ဘက် ၂၃ ကီလိုမီတာတွင် တည်ရှိပါသည်။ သီလဝါအထူးစီးပွားရေးဇုန်၏ အကောင်အထည် ဖော်ဆောင်သူအနေဖြင့် ဇုန်အပိုင်း(ခ)အတွင်းရှိ စက်မှုမြေနေရာများအတွက် ခွင့်ပြုချက်ရရှိထားသော ပတ်ဝန်းကျင်ထိခိုက်မှုဆန်းစစ်ခြင်း အစီရင်ခံစာနှင့် ပတ်ဝန်းကျင်ဆိုင်ရာစီမံခန့်ခွဲမှုအစီအစဉ်အတိုင်း ပုံမှန်စောင့်ကြည့်စစ်ဆေးခြင်းကို ဆောင်ရွက်ရန် မြန်မာ-ဂျပန် သီလဝါဖွံ့ဖြိုးရေးလီမိတက်တွင် တာဝန်ရှိပါသည်။ မြန်မာ-ဂျပန် သီလဝါဖွံ့ဖြိုးရေးလီမိတက်သည် ဇုန်အတွင်းနှင့် အနီးပတ်ဝန်းကျင်ရှိ သဘာဝပတ်ဝန်းကျင် အခြေအနေများကို သိရှိစေရန် သဘာဝပတ်ဝန်းကျင်နှင့်သက်ဆိုင်သော အချက်အလက်စောင့်ကြည့် လေ့လာမှုများကို ရေးဆွဲထားပြီး ထိုအစီအစဉ်များအရ အကောင်အထည်ဖော် ဆောင်ရွက်ခဲ့ပါသည်။

၁.၂ စောင့်ကြည့်လေ့လာသောအစီအစဉ်ဖော်ပြချက်များ

သီလဝါအထူးစီးပွားရေးဇုန် အပိုင်း(ခ) စက်မှုဇုန်လည်ပတ်နေခြင်းကြောင့် စက်မှုဇုန်အတွင်းနှင့်အပြင်ရှိ ပတ်ဝန်းကျင်အခြေအနေအား အကဲဖြတ်နိုင်ရန်အတွက် ယာဉ်သွားလာမှုနှုန်း တိုင်းတာမှုအား သတ်မှတ်ထားသောနေရာတွင် ၂၄ နာရီကြာ တိုင်းတာမည့်အစား ဘေးအန္တရာယ်ကင်းရှင်းစေရန် နှင့် ဘေးကင်းလုံခြုံမှုရရှိစေရန် အလုပ်ချိန်အနေဖြင့် ၈ နာရီ (မနက် ၈ နာရီ မှ ညနေ ၄ နာရီ) ကြာ တိုင်းတာခဲ့ပါသည်။ ယာဉ်သွားလာမှုနှုန်း တိုင်းတာမှုအား အကဲဖြတ်နိုင်ရန်အတွက် အောက်ပါဇယားတွင် ဖော်ပြထားသည့်အတိုင်း ၂၀၂၁ ခုနှစ်၊ ဒီဇင်ဘာလ ၂၃ ရက်နေ့တွင် ယာဉ်သွားလာမှုနှုန်းအား စောင့်ကြည့်လေ့လာခဲ့သည်။

ဇယား ၁.၂-၁ ယာဉ်သွားလာမှုနှုန်း စောင့်ကြည့်လေ့လာသောအစီအစဉ်

စောင့်ကြည့်လေ့လာရေး ရက်စွဲ	စောင့်ကြည့်လေ့လာမှု အမျိုးအစား	တိုင်းတာသော အမျိုးအစားများ	တိုင်းတာသောနေရာ အရေအတွက်	ကြာချိန်	စောင့်ကြည့်လေ့လာသော နည်းလမ်း
၂၃ ဒီဇင်ဘာလ ၂၀၂၁	ယာဉ်သွားလာမှုနှုန်း	.	နေရာ-၁ (TV-1)	၈ နာရီ	လူကိုယ်တိုင် တိုက်ရိုက်စောင့်ကြည့်၍ တာလီချိုးမှတ်သားခြင်း

မူရင်း။ မြန်မာ့စွယ်စုံကျမ်းအင်္ဂလိပ်စာအုပ်

အခန်း ၂ ယာဉ်သွားလာမှုနှုန်း စောင့်ကြည့်လေ့လာခြင်း

၂.၁ စောင့်ကြည့်လေ့လာသည့် အမျိုးအစား

ယာဉ်သွားလာမှုနှုန်း စောင့်ကြည့်လေ့လာသော အမျိုးအစားကို ဇယား ၂.၁-၁ တွင် ဖော်ပြထားပါသည်။
ယာဉ်များကို ဇယား ၂.၁-၂ တွင် အသေးစိတ်ဖော်ပြထားသည့်အတိုင်း အမျိုးအစား ၄ မျိုး ခွဲခြားထားပါသည်။

ဇယား ၂.၁-၁ ယာဉ်သွားလာမှုနှုန်းအတွက် စောင့်ကြည့်လေ့လာသောအမျိုးအစားများ

စဉ်	စောင့်ကြည့်လေ့လာမှု	အမျိုးအစား
၁	ယာဉ်သွားလာမှုနှုန်း	ယာဉ်အမျိုးအစား (၄ မျိုး)

မူရင်း၊ မြန်မာ့သို့အင်တာနေရှင်နယ်လီမိတက်

ဇယား ၂.၁-၂ ယာဉ်အမျိုးအစားခွဲခြားခြင်း

စဉ်	အမျိုးအစားခွဲခြားခြင်း		ဖော်ပြချက်
၁	နှစ်ဘီးတပ်ယာဉ်		ဆိုင်ကယ်၊ ဆိုင်ကယ်တက္ကစီ
၂	လေးဘီးတပ်ယာဉ်ငယ်		ပစ်ကပ်ကား၊ ကျစ်ကား၊ အငှားယာဉ်၊ ဆလွန်းကား၊ လိုက်ထရက်၊ ၂ တန်အောက်)
၃	လေးဘီးတပ်ယာဉ်ကြီး		ဘတ်စ်ကားအလတ်၊ မှန်လိုကား၊ ဘတ်စ်ကားအကြီး၊ ထရပ်ကားအလတ်၊ ဝင်ရိုး ၂၉၊ ၃၉ နှင့် ၄၉ထက်ပိုသော ထရပ်ကားအကြီး နှင့် နောက်တွဲယာဉ် (၄.၅ တန်အထက်)
၄	အခြား		လယ်ထွန်စက်

မူရင်း၊ မြန်မာ့သို့အင်တာနေရှင်နယ်လီမိတက်

၂.၂ စောင့်ကြည့်လေ့လာသည့် တည်နေရာ

ယာဉ်သွားလာမှုနှုန်းအား သီလဝါအထူးစီးပွားရေးဇုန် အပိုင်း(ခ)၏ အရှေ့မြောက်ဘက်ထောင့်၊ မြောက်လတ္တီတွဒ် ၁၆°၄၅'၁၇.၉၀" ၊ အရှေ့လောင်ဂျီတွဒ် ၉၆°၁၇'၁၈.၂၀"နေရာ၌ စောင့်ကြည့်လေ့လာခဲ့ပါသည်။ ယာဉ်သွားလာမှုနှုန်း စောင့်ကြည့်လေ့လာသော တည်နေရာကို ပုံ ၂.၂-၁ တွင် ပြသထားပါသည်။



ပုံ ၂.၂-၁ ယာဉ်သွားလာမှုနှုန်း စောင့်ကြည့်လေ့လာသည့်တည်နေရာ

ယာဉ်သွားလာမှုနှုန်း စောင့်ကြည့်လေ့လာသည့်နေရာ-၁ (TV-1)

စောင့်ကြည့်လေ့လာသည့် နေရာ-၁ (TV-1)သည် သီလဝါအထူးစီးပွားရေးဇုန် အပိုင်း(ခ)ရှိ လည်ပတ်နေသော လုပ်ငန်းခွင်၏ ပင်မဂိတ်ပေါက်အရှေ့ဘက်ခြမ်းတွင်ရှိသော၊ သီလဝါပွဲခြားရေးလမ်း၏ ဘေးဘက်တွင်ရှိပါသည်။ စောင့်ကြည့်လေ့လာသည့်နေရာ၏ အနောက်မြောက်ဘက်တွင် ဇုန်အပိုင်း(က)နှင့် အရှေ့ဘက်တွင် ပြည်တွင်းစက်မှုဇုန်တို့ တည်ရှိပါသည်။

၂.၃ စောင့်ကြည့်လေ့လာသည့် နည်းလမ်း

ယာဉ်သွားလာမှုနှုန်း စောင့်ကြည့်လေ့လာခြင်း ဆောင်ရွက်နေစဉ်တွင် ယာဉ်သွားလာမှုကြောင့် ဖြစ်ပေါ်နိုင်သော ဆူညံသံနှင့်တူနံခါမှုတိုင်းတာခြင်းကိုပါ တစ်ပြိုင်နက်တည်း ၈ နာရီကြာ ဆောင်ရွက်ခဲ့ပါသည်။ ယာဉ်သွားလာမှုနှုန်း စောင့်ကြည့်လေ့လာမှုကို ဖလမ်းကျေးရွာမှ ဒဂုံ-သီလဝါလမ်းသို့ လာသော ယာဉ်အရေအတွက်နှင့် ဒဂုံ-သီလဝါလမ်းမှ ဖလမ်းကျေးရွာသို့ လာသောယာဉ်အရေအတွက် အသီးသီးကို ရေတွက်ခဲ့ပါသည်။ ယာဉ်အရေအတွက်ကို လူကိုယ်တိုင် တိုက်ရိုက်စောင့်ကြည့်၍ တာလီချိုးမှတ်သားခြင်းဖြင့် မှတ်သားခဲ့ပါသည်။ နေရာ-၁ (TV-1)၌ ယာဉ်သွားလာမှုနှုန်း စောင့်ကြည့်လေ့လာခြင်း အခြေအနေကို ပုံ ၂.၃-၁ တွင် ပြသထားသည်။



မှရင်း၊ မြန်မာ့မိမိအင်တာနေရှင်နယ်လီမိတက်

ပုံ ၂.၃-၁ နေရာ-၁ (TV-1) ၌ယာဉ်သွားလာမှုနှုန်း စောင့်ကြည့်လေ့လာခြင်းအခြေအနေ

၂.၄ စောင့်ကြည့်လေ့လာမှု ရလဒ်များ

ယာဉ်သွားလာမှုနှုန်း စောင့်ကြည့်လေ့လာမှုရလဒ်များအား ဇယား ၂.၄-၁ တွင် အကျဉ်းချုပ် ဖော်ပြထားသည်။ ယာဉ်တစ်မျိုးချင်းစီအတွက် တစ်နာရီအလိုက် အရေအတွက်ကို မှတ်သားထားပါသည်။ ရုံးဖွင့်ရက်များ (တနင်္လာနေ့ မှ သောကြာနေ့)၌ လေးဘီးတပ်ယာဉ်ငယ်များကို ပိုမိုအသုံးပြုမှုများကြောင်း ဇယား ၂.၄-၁ တွင် တွေ့နိုင်ပါသည်။ ဖလမ်းကျေးရွာမှ ဒဂုံ-သီလဝါ လမ်းသို့ သွားရာလမ်းတွင် လေးဘီးတပ် ယာဉ်ကြီးများ အရေအတွက်သည် လေးဘီးတပ် ယာဉ်ငယ်များ အရေအတွက်ထက် သုံးဆ ပိုမိုနည်းပါးပြီး ဒဂုံ-သီလဝါလမ်းမှ ဖလမ်းကျေးရွာသို့ သွားရာလမ်းတွင် လေးဘီးတပ် ယာဉ်ကြီးများ အရေအတွက်သည် လေးဘီးတပ် ယာဉ်ငယ်များ အရေအတွက်ထက် သုံးဆ ပိုမိုနည်းပါးကြောင်း တွေ့ရသည်။

ဇယား ၂.၄-၁ နေရာ-၁ (TV-1) ၌ယာဉ်သွားလာမှုနှုန်း မှတ်တမ်းအကျဉ်းချုပ်

စစ်တမ်း ကောက်ယူ သောနေရာ	ဦးတည်ရာ	ရက်စွဲ	ဖုံးဖွင့်ရက်များ (တနင်္လာနေ့ မှ သောကြာနေ့)	နှစ်ဘီးတပ် ယာဉ်	လေးဘီး တပ် ယာဉ်ငယ်	လေးဘီး တပ် ယာဉ်ကြီး	အခြား	စုစုပေါင်း
နေရာ-၁ (TV-1)	ဖလမ်းကျေးရွာ မှ ဒဂုံ-သီလဝါလမ်း	၂၃ ဒီဇင်ဘာလ	ကြာသပတေးနေ့	၅၃၃	၆၄၉	၂၀၀	၂၁	၁,၄၀၃
	ဒဂုံ-သီလဝါလမ်း မှ ဖလမ်းကျေးရွာ	၂၀,၂၁		၅၁၈	၆၉၁	၂၂၇	၂၃	၁,၄၅၉

မှတ်ချက်- မြန်မာနိုင်ငံအင်တာနေရှင်နယ်လီမိတက်

နေရာ-၁ (TV-1) ၌တစ်ဖက်ရပ်အလိုက် ယာဉ်သွားလာမှုနှုန်း၏ စောင့်ကြည့်လေ့လာမှုရလဒ်များ အကျဉ်းချုပ်ကို ဇယား ၂.၄-၂ နှင့် ဇယား ၂.၄-၃ တွင် ဖော်ပြထားသည်။ မနက်ပိုင်းယာဉ်သွားလာမှု အများဆုံးအချိန်ဖြစ်သည့် ၈:၀၀ မှ ၉:၀၀ နှင့် နေ့လည်ခင်းယာဉ်သွားလာမှု အများဆုံးအချိန်ဖြစ်သည့် ၁၅:၀၀ မှ ၁၆:၀၀ ကို နှိုင်းယှဉ်ရာ၌ နေ့လည်ခင်း ယာဉ်သွားလာမှု အများဆုံးအချိန်တွင် ဖလမ်းကျေးရွာမှ ဒဂုံ-သီလဝါလမ်းသို့ သွားသည့် လမ်းကြောင်းတွင် ယာဉ်သွားလာမှုနှုန်းသည် အမြားလမ်းကြောင်းနှင့် နှိုင်းယှဉ်ပါက အရေအတွက် ပိုမိုများပါသည်။ သို့သော်လည်း မနက်ပိုင်း ယာဉ်သွားလာမှု အများဆုံးအချိန်တွင် ဒဂုံ-သီလဝါလမ်းမှ ဖလမ်းကျေးရွာသို့ သွားသည့် လမ်းကြောင်းတွင် ယာဉ်သွားလာမှုနှုန်းသည် အမြားလမ်းကြောင်းနှင့် နှိုင်းယှဉ်ပါက အရေအတွက် တူညီကြောင်း တွေ့ရှိရပါသည်။ ထိုသို့ ယာဉ်အရေအတွက် တူညီခြင်းမှာ အဆိုပါ စောင့်ကြည့် လေ့လာသော ကာလအတွင်း ဒဂုံ-သီလဝါလမ်းမှ ဖလမ်းကျေးရွာသို့ သွားသည့်လမ်းကြောင်း၌ မနက်ပိုင်းယာဉ်သွားလာမှု နှင့် ဖလမ်းကျေးရွာမှ ဒဂုံ-သီလဝါလမ်းသို့ သွားသည့်လမ်းကြောင်း၌ နေ့လည်ခင်း ယာဉ်သွားလာမှု အချိန်တို့တွင် အလုပ်သွားအလုပ်ပြန်ယာဉ်များ ဖြတ်သန်းသွားလာမှုကြောင့် ဖြစ်နိုင်ပါသည်။

သီလဝါအထူးစီးပွားရေးစနစ်အပိုင်း(ခ)ရှိကော်မရှုစနစ်ဖြင့်ပြောတိုးတက်မှုအတွက်ယာဉ်သွားလာမှုနှုန်းစောင့်ကြည့်လေ့လာခြင်းအစီရင်ခံစာ
(လုပ်ငန်းလည်ပတ်နေစဉ်ကာလ အပိုင်း ၁၊ အပိုင်း ၂ နှင့် အပိုင်း ၃ ၊ ဒီဇင်ဘာလ ၂၀၂၁ ခုနှစ်)

ဇယား ၂.၄.၂ နေရာ-၁ (TV-1)၌ နာရီအလိုက် ယာဉ်သွားလာမှုနှုန်းရလဒ် (မလမ်းကျေးရွာမှ ဒဂုံ-သီလဝါလမ်းသို့)

မှ	အထိ	အမျိုးအစားခွဲခြားခြင်း				စုစုပေါင်း
		ယာဉ်အမျိုးအစား				
		နှစ်သီးတော်ယာဉ်	လေးသီးတော်ယာဉ် ငယ်	လေးသီးတော်ယာဉ် ကြီး	အခြား	
၇:၀၀	၈:၀၀	-	-	-	-	-
၈:၀၀	၉:၀၀	၁၀၈	၇၉	၂၁	၃	၂၁၀
၉:၀၀	၁၀:၀၀	၇၁	၆၁	၂၇	၄	၁၆၃
၁၀:၀၀	၁၁:၀၀	၇၈	၈၆	၃၁	၃	၁၉၈
၁၁:၀၀	၁၂:၀၀	၇၃	၁၀၇	၂၈	၂	၂၁၀
၁၂:၀၀	၁၃:၀၀	၆၆	၇၄	၂၆	၃	၁၆၉
၁၃:၀၀	၁၄:၀၀	၃၈	၇၁	၂၁	၀	၁၃၀
၁၄:၀၀	၁၅:၀၀	၃၁	၆၄	၂၇	၂	၁၂၄
၁၅:၀၀	၁၆:၀၀	၆၈	၁၀၇	၁၉	၄	၁၉၈
၁၆:၀၀	၁၇:၀၀	-	-	-	-	-
၁၇:၀၀	၁၈:၀၀	-	-	-	-	-
၁၈:၀၀	၁၉:၀၀	-	-	-	-	-
၁၉:၀၀	၂၀:၀၀	-	-	-	-	-
၂၀:၀၀	၂၁:၀၀	-	-	-	-	-
၂၁:၀၀	၂၂:၀၀	-	-	-	-	-
၂၂:၀၀	၂၃:၀၀	-	-	-	-	-
၂၃:၀၀	၀၁:၀၀	-	-	-	-	-
၀၁:၀၀	၀၂:၀၀	-	-	-	-	-
၀၂:၀၀	၀၃:၀၀	-	-	-	-	-
၀၃:၀၀	၀၄:၀၀	-	-	-	-	-
၀၄:၀၀	၀၅:၀၀	-	-	-	-	-
၀၅:၀၀	၀၆:၀၀	-	-	-	-	-
၀၆:၀၀	၀၇:၀၀	-	-	-	-	-
၀၇:၀၀	၀၈:၀၀	-	-	-	-	-
စုစုပေါင်း		၅၃၃	၆၄၉	၂၀၀	၂၁	၁,၄၀၃

မူရင်း၊ ပြန်မသုံးအင်တာနေရှင်နယ်လီမီတက်



သီလဝါအထူးစီးပွားရေးဇုန်အပိုင်း(ခ)ရှိခက်မှုနှင့်ဖွံ့ဖြိုးတိုးတက်မှုအတွက်ယာဉ်သွားလာမှုနှုန်းစောင့်ကြည့်လေ့လာခြင်းအစီရင်ခံစာ
(လုပ်ငန်းလည်ပတ်နေစဉ်ကာလ အပိုင်း ၁၊ အပိုင်း ၂ နှင့် အပိုင်း ၃ ၊ ဒီဇင်ဘာလ ၂၀၂၁ ခုနှစ်)

ဇယား ၂.၄-၃ နေရာ-၁ (TV-1)၌ နာရီအလိုက် ယာဉ်သွားလာမှုနှုန်းရလဒ် (ဒဂုံ-သီလဝါလမ်းမှ မလမ်းကျေးရွာသို့)

မှ	ထိ	အမျိုးအစားခွဲခြားခြင်း				စုစုပေါင်း
		ယာဉ်အမျိုးအစား				
		နှစ်ဘီးတပ်ယာဉ်	လေးဘီးတပ်ယာဉ် ငယ်	လေးဘီးတပ်ယာဉ် ကြီး	အခြား	
၇:၀၀	၈:၀၀	-	-	-	-	-
၈:၀၀	၉:၀၀	၈၃	၁၀၇	၁၇	၄	၂၁၁
၉:၀၀	၁၀:၀၀	၈၁	၉၄	၃၆	၁	၂၁၂
၁၀:၀၀	၁၁:၀၀	၄၁	၉၈	၃၂	၂	၁၇၃
၁၁:၀၀	၁၂:၀၀	၈၀	၉၈	၂၅	၅	၂၀၈
၁၂:၀၀	၁:၃၀မန	၆၂	၇၇	၂၃	၁	၁၆၃
၁:၃၀မန	၁:၄၅မန	၅၃	၆၆	၃၄	၃	၁၅၆
၁:၄၅မန	၁:၅၀မန	၄၃	၈၃	၃၂	၃	၁၆၁
၁:၅၀မန	၁:၆၀မန	၇၅	၇၆	၂၈	၄	၁၈၃
၁:၆၀မန	၁:၇၅မန	-	-	-	-	-
၁:၇၅မန	၁:၈၀မန	-	-	-	-	-
၁:၈၀မန	၁:၉၀မန	-	-	-	-	-
၁:၉၀မန	၂:၀၀မန	-	-	-	-	-
၂:၀၀မန	၂:၁၀မန	-	-	-	-	-
၂:၁၀မန	၂:၂၀မန	-	-	-	-	-
၂:၂၀မန	၂:၃၀မန	-	-	-	-	-
၂:၃၀မန	၂:၄၀မန	-	-	-	-	-
၂:၄၀မန	၂:၅၀မန	-	-	-	-	-
၂:၅၀မန	၃:၀၀မန	-	-	-	-	-
၃:၀၀မန	၃:၁၀မန	-	-	-	-	-
၃:၁၀မန	၃:၂၀မန	-	-	-	-	-
၃:၂၀မန	၃:၃၀မန	-	-	-	-	-
၃:၃၀မန	၃:၄၀မန	-	-	-	-	-
၃:၄၀မန	၃:၅၀မန	-	-	-	-	-
၃:၅၀မန	၄:၀၀မန	-	-	-	-	-
၄:၀၀မန	၄:၁၀မန	-	-	-	-	-
၄:၁၀မန	၄:၂၀မန	-	-	-	-	-
၄:၂၀မန	၄:၃၀မန	-	-	-	-	-
၄:၃၀မန	၄:၄၀မန	-	-	-	-	-
၄:၄၀မန	၄:၅၀မန	-	-	-	-	-
၄:၅၀မန	၅:၀၀မန	-	-</			

မှတ်ချက်။ မြန်မာ့ဆိုင်ခရိုင်တာဝန်ရှိသူက



အခန်း ၃ နိဂုံးချုပ်နှင့်အကြံပြုချက်များ

စောင့်ကြည့်လေ့လာသည့်ကာလအတွင်း ယာဉ်သွားလာမှုနှုန်းရလဒ်များအရ လေးဘီးတပ်ယာဉ်ငယ်များ ပိုမိုအသုံးပြုမှုများကြောင်း တွေ့ရှိရပါသည်။ လမ်းကြောင်းအသီးသီးတွင် သွားလာနေကြသော လေးဘီးတပ်ယာဉ်ကြီး အရေအတွက်မှာ လေးဘီးတပ်ယာဉ်ငယ် အရေအတွက်ထက် သုံးဆ သိသိသာသာနည်းပါးကြောင်း တွေ့ရှိရသည်။ စောင့်ကြည့်လေ့လာသည့်ကာလအတွင်း ဆောက်လုပ်ရေး လုပ်ငန်းသုံးယာဉ် (လေးဘီးတပ်ယာဉ်ကြီးများ) အရေအတွက်ထက် အလုပ်သွားအလုပ်ပြန် အသုံးပြုသော ယာဉ်အရေအတွက်သည် ပိုများကြောင်း တွေ့ရှိနိုင်ပါသည်။

သီလဝါအထူးစီးပွားရေးဇုန်အပိုင်း(ခ)၏ လုပ်ငန်း လည်ပတ်နေစဉ်ကာလအတွင်း ယာဉ်သွားလာမှုနှုန်း အချက်အလက်များရှိနိုင်ရန် ပုံမှန်စောင့်ကြည့်လေ့လာမှုများ လိုအပ်ပါသည်။ ယာဉ်သွားလာမှုနှုန်း အချက်အလက်များ လုံလောက်စွာ ရရှိပြီးနောက် အနာဂတ်တွင် ယာဉ်သွားလာမှုနှုန်း စီမံခန့်ခွဲမှုအတွက် သင့်တော်သောနည်းလမ်းများကို ထည့်သွင်းစဉ်းစားနိုင်ပါသည်။

End of Document

